STATE ENVIRONMENTAL QUALITY REVIEW (SEQR)

FINAL SITE SPECIFIC/GENERIC ENVIRONMENTAL IMPACT STATEMENT FEIS

Proposed Action: City of Rochester Port Public Marina and Mixed Use Development Project

> SEQR Environmental Impact Statement NEPA Environmental Assessment

LEAD AGENCY:
Thomas S. Richards
Mayor, City of Rochester
City Hall, Room 307A, 30 Church Street
Rochester, NY 14614-1290

Appendix A

Rochester Environmental Commission
Public Comment Summary and
Disposition Recommendations
Report

LIST OF COMMENTERS

Written Comments:

Louise Altobelli 109 Orenda Dr. Rochester, NY 14622

Frank Ardino fardino2@rochester.rr.com

Chris Capella-Peters NYS Historic Preservation Office P.O. Box 189, Peebles Island Waterford, NY 12188-0189

Susan Dauenhauer Ciriello 167 Valley Street Rochester, NY 14612

Dorothea de Zafra Atwell 16 Boulevard Parkway Rochester, NY 14612

Douglas A. Fisher, Esq 111 East Avenue, #937 Rochester, NY 14604

Donald Fuffell, Chairman Monroe County Fisheries Advisory Board City Place, 50 West Main Street, Ste. 8100

Sarah Gallivan 35 Corrigan Street Rochester, NY 14612

Fred Glaser fglaser48@hotmail.com

David C. Goehring, P.E., Regional Traffic Engineer NYS Department of Transportation Region Four 1530 Jefferson Road Rochester, NY 14623-3161

Wayne Goodman Landmark Society of WNY 133 South Fitzhugh Rochester, NY 14608

Thomas P. Haley NYS Department of Environmental Conservation Division of Environmental Permits, Region 8 6274 East Avon-Lima Roa Nancy Herter, Scientist, Archaeology NYS Historic Preservation Office P.O. Box 189, Peebles Island Waterford, NY 12188-0189

Catherine James 5359 St. Paul Blvd Rochester, NY 14617

Peter LePore, Charlotte Resident

Anthony Mittiga 211 Edgerton Rochester, NY 14607

Patrick O'Neil 35 Stutson Street Rochester, NY 14612

John Osowski, PE, Director of Facilities SUNY/ College at Brockport Planning/Construction Office of Facilities and Planning Rochester, NY 14614-1225

Sean Schiano 35 Corrigan Street Rochester, NY 14612

Richard Szwabczynski Swacen aka EarthGuy, NY 228 River Street Rochester, NY 14612

Gary Tajkowski Town of Greece Dept. of Development Services 1 Vince Tofany Blvd. Greece, NY 14612-5016

Kevin Quinn Monroe County Department of Environmental Services KQuinn@monroecounty.gov

Terrance J. Rice, P.E., Director of Transportation Monroe County Department of Transportation 6100 City Place, 50 West Main Street Rochester, NY 14614-1231

Frank J. Sanza, Vice Chairman/MCFAB MC Fishery Advisory Board

Richard Vance ucby@localnet.com

Verbal Comments

Fred Amato Genesee Charlotte Lighthouse 70 Lighthouse Street Rochester, NY 14612

Douglas A. Fisher, Esq 111 East Avenue, #937 Rochester, NY 14604

Bill Grey 59 Hincher Street Rochester, NY 14612

Virginia Kobylarz 193 River Street Rochester, NY

Michael May Genesee Charlotte Lighthouse 70 Lighthouse Street Rochester, NY 14612

Mike Parker 3165 Lake Avenue Rochester, NY 14612

Andy Rau 560 Birr St Rochester, NY

Kathy Strauss Charlotte Community Association & Team Charlotte

Richard Szwabczynski Swacen aka EarthGuy, NY 228 River Street Rochester, NY 14612

Visual Survey Comments

19 participants

Comment Disposition Terminology

1. No Response Required - not a substantive issue

- a) Comment expresses opinion and/or does not raise a substantive issue; acknowledge, but No Response Required not a substantive issue.
- b) Comment addresses an issue that is outside the purview of the DEIS.

2. <u>Correction Required</u>

The comment points out an omission or inaccuracy in the DEIS that needs to be corrected.

3. Explanation/Clarification Required

The comment raises an issue which was addressed in the environmental impact statement. The issue needs a simple explanation and reference to the section in the DEIS where it is discussed.

4. Additional Analysis Required

The comment raises an issue which has not been thoroughly addressed. Further analysis is believed necessary to offer a proper response.

5. <u>Alternative Suggested</u>

The comment suggests an alternative which merits evaluation.

COMMENT SUMMARY/ DISPOSITION RECOMMENDATIONS

COMMENT	COMMENTER	DISPOSITION RECOMMENDATION
COMMENT CATEGORY: Proposed Action	To do #11 house at the fill	
We strongly support and encourage a phased approach to the proposed development	K. Strauss	Explanation/Clarification Required
Boat owners will be insisting on good security for their boats, so appropriate decorative fencing should be planned now rather than later.	D. Fisher, M. Parker	Explanation/Clarification Required
Is the City committing to having a replacement launch facility, or multiple if deemed necessary, with equivalent launching and parking capacity, fully operating prior to the closing of the existing ramp an commencement of Phase II?	T. Haley	Explanation/Clarification Required
While we do not have concerns with the proposed dates, the September 30, 2011 letter indicates that the reconfigured boat ramp is expected to be completed by May of 2012 whereas the DEIS suggests that this will not occur until May 2013 (Table S-1).	T. Haley	Explanation/Clarification Required
Marina Operations and Maintenance Plan: In the City's September 30, 2011 letter you indicate that a Marina Operations and Maintenance Plan would be included in the DEIS. We were unable to locate the referenced plan.	T. Haley	Correction Required
Thank you very much for sending the draft document to us for our review and comments. The only discrepancy of note that should be corrected in the final version is the proposed name of Brockport's planned facility at the Port. The name has changed several times over the years and the correct version is "Lake Ontario Research Center." We noted that the facility is incorrectly called the "Lake Ontario Resource Center."	J. Osowski	Correction Required
I feel that the current plan is now of the appropriate mix of type and scale to help leverage rather than detract from or overshadow our existing local amenities of nature and man. For these and other good reasons, I feel it is critical that some version of the Lake Ontario Resource Center be strongly encouraged and assisted.	R. Swacen	No response Required
Right now the Charlotte beach area is free to all residents and there is abundant parking for all people. There is a great view of the beach and it is easy to get to. I am concerned that this new project will not enable people the full access that they are used to. I understand parking will be limited and there will be a parking fee. This will be a hardship for people with limited funds.	F. Glaser	Explanation/Clarification Required
The other concern is for the present businesses, and future retail and residential development in relationship to parking and patron convenience.	F. Ardino	Explanation/Clarification Required
We are seeing less people interested in boating and less interest in larger sized boats. The size of the proposed marina should be looked at.	F. Ardino	Explanation/Clarification Required
If we sell public land then the developers will have a field day and build as many units as they can simply to use up any and all available space.	F. Glaser	Explanation/Clarification Required

In this economy who is going to buy/rent high priced units? I am afraid the	F. Glaser	Explanation/Clarification
demand is not there and these units will sit idle and partially constructed creating	1. Glasci	Required
an eyesore for the city. I think this project needs to be viewed very closely and		Required
take in the concerns of the people and not focus on money.		
Constitute the marking let at Charlette to a marking and condex will depoin	R. Vance	No gornance Deguired
Converting the parking lot at Charlotte to a marina and condos will deprive	R. vance	No response Required
thousands of area residents of a delightful place to spend a day or an hour at the		
harbor and beach. The Monroe County Fishery Advisory Board supports the concept of a public	F. Sanza & D.	No response Required
marina at Charlotte. We feel it will be good for the community and a boon for both		No response Required
sports fisherman and boaters. We hope the marina will attract many visitors and	Turien, D. Orey	
enhance business opportunities in the Charlotte area.		
We are concerned with the relocation, size (3 of pads) and parking facilities for the	F. Sanza & D.	Explanation/Clarification
new boat launch. We request that the new (boat) launch have four pads.	Fuffell	Required
We are also concerned with slip availability. We request that some percentage, (of	F. Sanza & D.	Explanation/Clarification
	Fuffell	Required
boat slips), ten percent perhaps, be made available for charter boat operators in Monroe County. If the current 85 slip marina is realized this would reserve 8 slips	runen	Required
for charter boats. We further request that these slips be adjacent to each other. This		
is a common situation at ocean-side marinas. It is an attraction for people to visit		
the marinas when the charters return with their catches.		
Concerned that w/in 2 yrs. Developers will want to develop parking lots to serve	B. Grey	Explanation/Clarification
	b. Gicy	Required
private commercial & residential development The plan must detail how an effective security program for the area will be	P. O'Neill	Explanation/Clarification
provided. This program should also specify how noise, especially music,	r. O Nem	Required
motorcycle and muscle car noise is to be controlled. In addition, the plan should		Required
contain specifics for handling unlawful tenant and overnight without		
accommodations persons.		
The waterfront, in my opinion, belongs to the general public.	L. Altobelli	No response Required
The Monroe County storage facility has already been discussed to be built near the	S. Schiano, K.	Explanation/Clarification
Charlotte baseball fields by Corrigan and Estes. This would be a travesty for the	Strauss, S.	Required
local residents as well as the youngsters who play soccer and baseball on these	Gallivan, B.Grey,	Required
fields all summer long. This is also a huge parking area for overflow that will only	Gainvan, B.Giey,	
increase with even the Phase 1 development. This facility is not well kept and a		
complete eyesore. It should be kept on a main access road and not in the backyards		
of Charlotte residents.		
Given the historic lack of development in Charlotte, I am skeptical of these plans	A. Mittiga	Explanation/Clarification
coming to fruition. I don't know where the occupants of the housing units will	The strategy	Required
come from, and why they would locate in Charlotte. I don't want to see it become		1104
necessary to subsidize the units, through tax waivers to the developers, or other		
means. If there hasn't been a survey specific to the proposed housing, then one		
needs to be done. While studies may show a market for hundreds of lake front		
units, I'd want to see one for this project alone. Have the two yacht clubs, or area		
boaters, especially those now docking in the River, been surveyed about marina		
use, and the desire to live in the project.		
Lighthouse Trail project- Why would the City spend \$ 150,000 to build a trail	M. May, K.	Additional Analysis Required
when the site is already accessible. Rather for smaller port related activities. The	Strauss	,
Lighthouse should be accessed by the historic route of lighthouse street.		
Decorative lighting needs to be a part of the plan	B. Grey	No response Required
Private residential development should occur along Lake Avenue	M. May	Explanation/Clarification Required
COMMENT CATEGORY: Alternatives		Required
Concentrate new residential in a tall tower at the former miniature golf course.	D. Fisher, P.	Explanation/Clarification
Height is preferable to a sprawling footprint, giving the additional advantage of	O'Neil	Required

hetel" there with function rooms and avhibit rooms that would accommodate	T	
hotel" there, with function rooms and exhibit rooms that would accommodate		
lighthouse functions and a site visitor's center.		
People do not visit the port area to visit parking lots. That function can best be accomplished in a long parking garage along Lake Avenue, as I testified at the public session. Instead of acres of asphalt, that area is best given over to expansion of that very popular park. So much macadam & so many parking spaces —	D. Fisher	Explanation/Clarification Required
Shouldn't parking be concentrated in a structure? That would free up more land for the park. The current Parks maintenance facility site is a good spot for parking structure		
The plan should include more parking, not less than is currently available. This may involve a low parking garage built into the embankment at the current Monroe County park service location.	P. O'Neil	Explanation/Clarification Required
An iconic boardwalk along the waterfront should be considered; preferably in the area north of the port terminal building,	D. Fisher	Explanation/Clarification Required
I don't feel that the project encourages or promotes a ferry operation, which would draw people to the port, not the development of private residences. This area needs port activity, possibly light shipping. In other words, it should function as a PORT.	L. Altobelli, D. Fisher	Explanation/Clarification Required
There is great opportunity here for a small scale hotel.	D.Fisher	No response Required
COMMENT CATEGORY: Community Character	E VERSEN DE GROEF DEN	
		FERENCE OF OUR LEADER STREET
I am concerned about how existing businesses & buildings would fit in with the proposed project. There are a number of existing businesses and buildings in the Charlotte neighborhood that are in desperate need of makeovers. I fear that if there are not resources to help fix up their businesses - it will take away from all the work being invested in the marina and will negatively affect economic stimulus in the area.	S. Gallivan	No response Required
A select number of businesses should be allowed to develop but not to the point of taking away from the family businesses that have been in this area for years, who are also members of this community, including Mr. Dominic's, Abbott's, and Windjammers. There are also businesses in the Port of Rochester that have struggled to survive with the failure of the ferry and these businesses should also be given consideration. One exception would be Pier 45, this is an example of a business that I fear. the city has been running this establishment at an enormous loss each year, at tax payer costs. your plan wants to add businesses to this area where many are struggling as it is. Small, family businesses that have been in this community for years and decades should be given consideration prior to letting private developers do with our local community as they wish, and unfortunately the EIS as it stands is vague enough for developers to do just this.	S. Schiano	Explanation/Clarification Required
12 story apartment like buildings will diminish community and Port character.	K. Strauss, D. Fisher, M. Parker, S. Gallivan	No response Required
The Port site is a major public waterfront attraction as is and little has to be done to attract users. Facilities developed here should be water oriented, residential can happen on surrounding lands.	D.Fisher	No response Required
The proposed code is not acceptable to the neighborhood, it does not correlate with the Design guidelines that the community developed and submitted to the City during the other recent port project. Villages have been working to protect & enhance village character Height restriction is important to protect Village character Any building must fit into look of Village. Respect history of shipping in the	V. Kobylarz	Explanation/Clarification Required
	V. Kobylarz	No response Required
Village The history of Charlotte is based on Port and recreational activity	V. Kobylarz	No response Required

How can noise pollution from beach concerts, nighttime partying at the marina, and additional restaurants and recreation venues be restricted or contained for the	D. de Zafra Atwell	Explanation/Clarification Required
benefit of the anticipated residents in the mixed-use development?		
It is desirable that Charlotte retains and enhances its "Seaside Village" structure and appearance. This would include improvement and additions to the various shops, restaurants and buildings currently in existence on Lake Avenue. Residents	P. O'Neil	No response Required
and visitors alike would benefit from the addition of a hardware/general store,		
sporting goods, bakery, marine goods, bike rental etc.		
I am very concerned with the height that your special codes would allow for. I firmly believe these should be taken out of your EIS, because leaving them in only leaves the opportunity for private developers to take away the beauty of the water that is Charlotte and what attracts people to our small community. Charlotte is not a big city, it is a small close knit local community. There does not presently exist a building higher than three stories, nor should one ever be allowed to be built.		Explanation/Clarification Required
The community needs to maintain some architectural overview on private development	B. Grey	Explanation/Clarification Required
Noise level from the Bands. Each year they get louder and louder. The sound systems are very sophisticated. Nola's outdoor bandstand, and the battle of the bands along the river at each bar. Certain types of music are worse than others. Jazz, oldies, soft rock, folk, county or swing seem better But the loud rock and rap only seem to amplify the noise across the river. Please remember this is still a residential area, we pay taxes, and there are sound ordinances that should be considered and respected. An overly hyped up crowd isn't always good!		Explanation/Clarification Required
There is a perception by many people that Charlotte is a party place, drug infested and after dark it only gets worse. Please work to change the dynamics in Charlotte and address crime that goes on. Camera's, policing?	C. James	Explanation/Clarification Required
COMMENT CATEGORY: Construction		
	T II 1	A 11'' 1 A 1 ' D ' 1
IV.A.3.1.3 (p 58): This section acknowledges the high hydraulic conductivity of the subsurface soils and fills material. Since the groundwater depths are very shallow it will be necessary to manage a fairly high volume of groundwater during construction below the groundwater level. The DEIS contains few details on how groundwater will be managed. Has the City determined an approximately volume of water that will need to be managed during construction? Considering the potential volume of water and the potential contamination (SVOC's) of groundwater in certain areas additional details should be provided. The DEIS indicates that groundwater will be managed through a sump, pumping and possible treatment in accordance with the storm water pollution prevention plan (SWPPP). The SWPPP pertains to the discharge of storm water and not groundwater. Groundwater needs to be managed, treated and if necessary, discharged in accordance with a point source SPDES permit.	T. Haley	Additional Analysis Required
IV.S.1.2 (p 361): This section indicates that groundwater entering excavations will be pumped to specific areas elsewhere within the project site developed to promote percolation to the local groundwater aquifer. This description of groundwater management does not appear to be consistent with other sections of the DEIS (also see comments above regarding Section IV.a.3.1.3).	T. Haley	Correction Required
Our first concern is the four pad public boat launch on the Genesee River. We request that because of the relative scarcity of access to Lake Ontario to boaters in Monroe County, that the current launch be maintained and utilized during the construction phase of the proposed marina.	F. Sanza & D. Fuffell	Explanation/Clarification Required
COMMENT CATEGORY: Economic/Fiscal		
As noted in the DEIS, County storm sewers will need to be relocated. All costs	K. Quinn	Explanation/Clarification

associated with relocation of the public sewers to accommodate the layout of the proposed marina as well as the additional sewer flow from the development are the responsibility of the developer.		Required
You also need a Marina that will pay for itself. We pay for so many things as taxpayers that keep Rochester functioning as one of the best medium-sized cities in the U.S., but there is only so much we can take. If you go forward with this plan, we as taxpayers have to pay to make it run smoothly. What you need to do is leave the Port the way it is. The City needs to think of a plan that makes sense in these tough economic times when people are struggling to survive and cannot afford to pay for things that are not essential. I am familiar with the Port of Rochester and have placed my boat at marinas for more than 50 years and this plan is not the right way to go. This is the wrong project to pursue.	P. LePore	Explanation/Clarification Required
I am in favor of development in this area and agree that we should use our great resource in our favor, but not to the point that we would take away from the beautiful lake and river that surrounds us. I believe the Phase 1 development would be a great resource, as long as all the funding is there to actually pay for this project. I do not want the people of this city to be stuck with another huge bill based on grandiose plans that can never come to fruition. I am also in favor of limited private development with absolutely no public funding.	S. Schiano	Explanation/Clarification Required
I am concern about cost – the project is not yet fully funded, and where will the money come from and at what cost to other city initiatives. Where will the money come from to finance the project and will the cost as usually happens end up exceeding the current estimate of \$19.7M?	A. Rau	Explanation/Clarification Required
COMMENT CATEGORY: Geology		
Slag Material Clarification: Hydrogen sulfide exposure?	K. Strauss, M. Parker	Explanation/Clarification Required
COMMENT CATEGORY: Historic Resources		i nes mes A e establistica de la
The Lighthouse derives historic significance in large part from its relationship to Lake Ontario; and although physically separated from it due to operational modifications made over time, the property nevertheless retains strong visual links to the great lake. These views and vistas to and from the property are among its most important contributing features and they should not be compromised. Of particular concern in this regard is the +/- 12 story building proposed immediately north of the property. The mass and scale of the structure will block dominant vistas from the lighthouse grounds, tower and keeper's house. Additionally, tree plantings proposed along the North River Street Extension and the NY Central Railroad corridor will substantially obscure these same vistas. Equally important, the building and tree plantings also will alter historic views from Ontario Beach Park, US Coast Guard Station Rochester and Auxiliary, the Genesee River and Lake Ontario to the Lighthouse – and thereby diminish its historic position within the port environs. These visual impacts must be avoided and/or mitigated.	C. Capella-Peters, W. Goodman, M. May, K. Strauss, F. Amato, D. Fisher	Additional Analysis Required
The specific location, alignment and details for the Lighthouse Trail must respect the historic character and features of the lighthouse property. The SHPO recently advised the Charlotte-Genesee Lighthouse Historical Society on the merits of preparing a cultural landscape report for the property, the results of which should be used in planning any future physical projects, including the proposed trail. Absent such a document, research regarding historic and existing conditions must be sufficient to ensure the contemporary trail is appropriate for the property. The SHPO will continue consultation regarding this component of the Port project upon receipt of a more detailed design concept.	C. Capella-Peters	Additional Analysis Required

presented in the Phase I public development should be reevaluated. The Landmark Society encourages the City of Rochester to involve the Charlotte-Genesee Lighthouse in further discussion to refine the proposed design, configuration, and location of the Lighthouse Trail. Staff and board members' knowledge of the Lighthouse Paral. Staff and board members' knowledge of the Lighthouse Paral. Staff and board members' knowledge of the Lighthouse Paral. Staff and board members' knowledge of the Lighthouse Paral. Staff and board members' knowledge of the Lighthouse Paral. Staff and board members' knowledge of the Lighthouse Paral. Staff and board members' knowledge of the public. Instanta board with the Paral Par	The trail from Lake Avenue to the Charlotte-Genesee Lighthouse as currently		Additional Analysis Required
Lighthouse in further discussion to refine the proposed design, configuration, and location of the Lighthouse Trail. Staff and board members' knowledge of the Lighthouse Shistory, potential archeological resources, visitors' use of the site, and future plans for use of the historic site, would better inform plans for the trail, leading to a more sensible and sensitively placed trail that best meets the needs of the public. Instead build a rail which more readily accesses Lighthouse St. The DEIS states dredged/spoil materials will be stockpiled on municipal property for unnamed public works projects. However, at public meetings and press events these materials have been linked to the infill of the linner Loop and therefore require consideration pursuant to Section 106/Section 14.09. Please provide site location plans, bhotographs, and marrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge as a spring find the site of the Charlotte Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge as a spring find the site of Rochester. The Hojack Swing Bridge as a spring find the Society strong Bridge as a spring find to the Charlotte of the Society of the Charlotte Orts of			
location of the Lighthouse Trail. Staff and board members 'knowledge of the Lighthouse's history, potential archeological resources, visitors' use of the site, and future plans for use of the historic stite, would better inform plans for the trail, leading to a more sensible and sensitively placed trail that best meets the needs of the public. Instead build a trail which more readily accesses Lighthouse St. The DEIS states dredged/spoil materials will be stockpiled on municipal property for unnamed public works projects. However, at public meetings and press events these materials have been linked to the infill of the funer Loop and therefore require consideration pursuant to Section 1065-8cetion 14.09. Please provide site location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge is a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. I rehabilitated or stabilized, the bridge could serve as a prominent Local landmark, attracting visitors and contriburing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (refer filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. While I realize the ORFRPH signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871)) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy		1	
Lighthouse's history, potential archeological resources, visitors' use of the site, and future plans for the trail, leading to a more sensible and sensitively placed trail that best meets the needs of the public. Instead build a ratial which more readily accesses Lighthouse St. The DEIS states dredged/spoil materials will be stockpiled on municipal property for unnamed public works projects. However, at public meetings and press events these materials have been linked to the infill of the laner Loop and therefore require consideration pursuant to Section 106/Section 14.09. Please provide site location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge as a part of the redevelopment plans for the Port of Rochester. The Hojack Swing Bridge is a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a morning to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that profrions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft of fill exists versus 20 ft. While I realize the OPRIP signed off on the December 2000 Rochester Museum Phase I Report (Opro8002 & APRIRIST) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (i) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground trailities. b) A large scale			
Inture plans for use of the historic site, would better inform plans for the trail, leading to a more sensible and sensitively placed trail that best meets the needs of the public. Instead build a trail which more readily accesses Lighthouse St. The DEIS states derdged/spoin untacrials will be suckpiled on runnicipal property for unnamed public works projects. However, at public meetings and press events these materials have been linked to the infill of the liner Loop and therefore require consideration pursuant to Section 1069-Section 14.09. Please provide site location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hogack Swing Bridge is a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. I rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Fort community. Look at what was done at the Hyline in NYC. 1 understand from the 2000 Phase I Report that portions of this parced were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (recoff filled waterways) were located have relocated have not been provided. For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the ORFRH 9 signed off on the December 2000 Rochester Museum Phase I Report the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground the			
leading to a more sensible and sensitively placed trail that best meets the needs of the public. Instead build a trail which more readily accesses Elighhouse St. The DEIS states dredged/spoil materials will be stockpiled on municipal property for unnamed public works projects. However, at public meetings and press events these materials have been linked to the infill of the Inner Loop and therefore require consideration pursuant to Section 1060/Section 14.09. Please provide site location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge as a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rebabilistated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (000PR0502 & 40PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Parklands IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed			
the public. Instead build a trail which more readily accesses Lighthouse St. The DEIS states dredged/spoil materials will be stockpilled no municipal property for unnamed public works projects. However, at public meetings and press events these materials have been linked to the infill of the liner Loop and therefore require consideration pursuant to Section 106/Section 14.09, Please provide site location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge as part of the redevelopment plans for the Port of Rochester. The Hojack Swing Bridge is a significant historic resource in the area, a visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (i.e. 1829 map) and that one ft. to 20 ft. of fill (page 29) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate	leading to a more sensible and sensitively placed trail that hest meets the needs of		
The DEIS states dredged/spoil materials will be stockpiled on municipal property for unnamed public works projects. However, a public meetings and press events these materials have been linked to the infill of the Inner Loop and therefore require consideration pursuant to Section 106/Section 14.09. Please provide site location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge as part of the redevelopment plans for the Port of Rochester. The Hojack Swing Bridge as a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlottet Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR50502 & 40PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold our map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold our map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold our map that includes items 1, 2 and 3 as well as the			
for unnamed public works projects. However, at public meetings and press events these materials have been linked to the infill of the Inner Loop and therefore require consideration pursuant to Section 106/Section 14.09. Please provides its location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge as part of the redevelopment plans for the Port of Rochester. The Hojack Swing Bridge is a significant historic resource in the area, is visually prominent and highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in hYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (i.e. 1839 map) and that one ft. to 20 ft. of fill (lagge 29) have been placed across the project area. However, specific information on the depth fill and where he low, wet areas (rede filled waterways) were located have not been provided. For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Parklands COMMENT (ATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the sout		C Capalla Datara	Evalenation/Clarification
these materials have been linked to the infill of the Inner Loop and therefore require consideration pusuant to Section 106/Section 14.09. Please provide site location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge is a spart of the redevelopment plans for the Port of Rochester. The Hojack Swing Bridge is a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of fits parcel were low and wer (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. While I relaize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the o		C. Capella-Peters	Explanation/Clarification
require consideration pursuant to Section 16/6Section 14.09. Please provide site location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge as part of the redevelopment plans for the Port of Rochester. The Hojack Swing Bridge is a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exist versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PROSO2 & 04PRHSIRT)) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (I) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes (II) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes (II) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. comments are all the proposed at the south side of the new marked and the design should be discussed. COMMENT CATEGORY: Parklands Explanation/Clar			
location plans, photographs, and narrative descriptions and/or graphics of proposed conditions related to this proposal. The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge is a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. while I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impa			
Conditions related to this proposal.			
The Landmark Society strongly encourages the City of Rochester to consider including the Hojack Swing Bridge as part of the redevelopment plans for the Port of Rochester. The Hojack Swing Bridge is a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT (AFGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #			
including the Hojack Swing Bridge as part of the redevelopment plans for the Port of Rochester. The Hojack Swing Bridge is a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (OPRO502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p.88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to t		W Coodman M	Evaloration/Clarification
of Rochester. The Hojack Swing Bridge is a significant historic resource in the area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibits 8 does not show any			
area, is visually prominent and a highly recognizable part of the cultural landscape in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the OPRHY signed off on the December 2000 Rochester Museum Phase I Report (OOPR0502 & O4PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibits 8 does not show any encroachment. This inconsistency should be addressed and the design should not		May, D. Fisher	Required
in the community. If rehabilitated or stabilized, the bridge could serve as a prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (100PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the north boat launch area during the construction of pha			
prominent local landmark, attracting visitors and contributing to the unique identity of the Charlotte/Port community. Look at what was done at the Hyline in NYC. I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhi			
I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
I understand from the 2000 Phase I Report that portions of this parcel were low and wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
wet (ie. 1829 map) and that one ft. to 20 ft. of fill (page 92) have been placed across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (OPRO502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required		N. Haster M.	A d d'a1 A1 '- D ' 1
across the project area. However, specific information on the depth fill and where the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			Additional Analysis Required
the low, wet areas (reed filled waterways) were located have not been provided. For example, I cannot determine where I ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required		Parker	
For example, I cannot determine where 1 ft. of fill exists versus 20 ft. While I realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (OOPRO502 & O4PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
realize the OPRHP signed off on the December 2000 Rochester Museum Phase I Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
Report (00PR0502 & 04PR1871) our standards for documenting previous ground disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
disturbance have changed in the intervening years. Please provide: a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Explanation/Clarification Required Explanation/Clarification Required T. Haley Correction Required			
a) A large scale fold out map that includes (1) the project area limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required Correction Required			
limits, (2) soil boring locations and the corresponding depth of fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Explanation/Clarification Required T. Haley Correction Required T. Haley Correction Required T. Haley Correction Required Application, yet Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
fill and (3) below ground utilities. b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management TV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
b) A large scale fold out map that includes items 1, 2 and 3 as well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
well as the marshy areas shown on the 1829 map. I realize that this overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
overlay will not be 100% accurate because of the quality of the 1829 map. COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
COMMENT CATEGORY: Hydrologic/Coastal Management IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required	1		
IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required	overlay will not be 100% accurate because of the quality of the 1829 map.		
IV.C.2.2.2 (p 88): This section does not contain a discussion of how sediments would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required	COMMENT CATEGORY: Hydrologic/Coastal Management		
would be managed if sediment tested results prevent the use of the open-lake placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
placement area. A contingency plan should be discussed. COMMENT CATEGORY: Parklands Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required		T. Haley	
Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			Required
Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required	placement area. A contingency plan should be discussed.		
Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required	COMMENT CATECODY, D. LL.		
marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required	COMMENT CATEGORY: Parkiands		
marina entrance may encroach upon the north boat launch. The potential impacts are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required	Exhibits 7 & 8 (pp39-40): The sheet pile proposed at the south side of the new	T. Haley	Correction Required
are evident in Exhibit 7 (page #39) and the graphic attached to the City's September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			1
September 30, 2011 response to the Departments Notice of Incomplete Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
Application, yet Exhibit 8 does not show any encroachment. This inconsistency should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
should be addressed and the design should not significantly encroach upon the northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
northern launch area during the construction of phase 1 of the marina. IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
IV.H (pp 177-189): This section should include a figure/exhibit which clearly T. Haley Correction Required			
defines which areas of the marina will be accessible to the general public and	IV.H (pp 177-189): This section should include a figure/exhibit which clearly	T. Haley	Correction Required
	defines which areas of the marina will be accessible to the general public and		

which areas will be restricted access (tenants and boat owners). IV.S.2 (Figure S-1, p 369): Figure S-1 appears to suggest that during Phase 1 of the project access for only 20 boats will be provided at the existing boat launch. In the City's September 30, 2011 letter submitted in response to the Department's January 19, 2010 Notice of Incomplete Application the City indicated that the reconfigured boat launch would accommodate nearly 100 vehicles and trailers during Phase 1.	T. Haley	Explanation/Clarification Required
Provide more clarification on parkland alienation/exchange	K. Strauss	Explanation/Clarification Required
COMMENT CATEGORY: Solid Waste Management		
IV.O.3.2.2 (p 330): This section references 6 NYCRR but fails to provide the applicable part. We believe you are referring to 6 NYCRR Part 360-1.15b (8).	T. Haley	Correction Required
COMMENT CATEGORY: Traffic &Parking	Charles Specifical Control	
If the plan is put into motion you will eliminate much of the parking that is necessary for people who want to enjoy Charlotte Beach throughout the year. We need every available parking spot because as it is we do not have enough.	P. LePore	Explanation/Clarification Required
The routes to and from Sites A and B pass through residential neighborhoods in the Town. Some of these routes also include residential areas in the City (e.g., Beach Avenue, and Latta Road and Stutson Street west of Lake Avenue). Site A has been used in the past for parking and bus shuttle service to and from events at the Port, but only for one or two events per summer, and sometimes not even every year. It would be quite another thing to use Site A – not to mention the addition of Site B – for this purpose on a regular, perhaps weekly, basis. The DEIS and the Traffic and Parking Analysis address the issue solely in the context that is typical of most traffic engineering studies; that is, the language and data associated with Level of Service ("LOS"). Discussions of LOS do not consider the effects that the elevated traffic volumes will have on the residential areas through which the routes between the Port and Sites A and B will pass. If the proposed parking areas must be used, consideration must be given to limiting the routes that could be used to and from Sites A and B, so as to minimize travel on residential streets and to keep routes open for emergency responders.	G. Tajkowski	Explanation/Clarification Required
The DEIS and the Traffic and Parking Analysis do not consider the condition of Ling Road, which connects between Greenleaf Road and Dewey Avenue. It is reasonable to expect Ling Road to be used for access to and between Sites A and B. Ling Road is a relatively narrow two-lane road, with less-than-optimal pavement condition, relatively narrow, unpaved shoulders (in some places, no shoulders), imited street lighting, and portions with no sidewalk or sidewalk on only one side of the road. Although the Regional Transit Service 1/1X Lake Avenue Route includes Ling Road, only about six buses per day travel over this road, and only on weekdays. Increased numbers of vehicles on this road, particularly buses, will contribute to the deterioration of the condition of this road.	G. Tajkowski	Explanation/Clarification Required
The DEIS contains no discussion of the possibility of using the now-vacant Eastman Kodak Company ("Kodak") parking lots in the vicinity of Lake Avenue, West Ridge Road, and Maplewood Drive. This unused parking area is only about four miles from the Project site, and is on an existing mass transit route. Although there are many residences along Lake Avenue and in adjacent residential neighborhoods, the street is four lanes wide and already carries a considerable amount of vehicles on a daily basis, and even more when events occur at the Port. If the City consulted with and obtained the permission of Kodak to use the vacant	G. Tajkowski	Explanation/Clarification Required

parking lots for shuttle service to and from the Port, there would be an opportunity to reduce the traffic volumes that already occur on Lake Avenue when there are events at the Port.		
The DEIS, Volume 1, p. 277, recommends coordination among agencies for traffic control, but doesn't specifically mention whether or not such coordination would or should include the Town's Police Department.	G. Tajkowski	Explanation/Clarification Required
We have questions regarding the proposed Intelligent Transportation System (ITS) Tools and Technologies. Who will be responsible for installing and monitoring these measures? Each measure should have a defined purpose and benefit, (ie,; highway traffic mitigation, parking lot management, security). Additional through and discussions between all involved parties to determine what ITS Tools and Technologies are necessary along with their location and how they will interact to minimize traffic impacts.	D. Goehring	Explanation/Clarification Required
At the Lake Avenue/LOSP signalized intersection we noted that in the 2020 build scenario of the project, during the Friday 6:30 pm-7:30 pm peak hour, this intersection is very near its capacity, with at least one movement in every direction experiencing a volume to capacity (v/c) ration of .92 or greater. This yields to a failing level-of-service for at least one movement and excessive queue lengths on almost every approach to the intersection. These queues will extend to adjacent intersections and possibly onto the Colonel Patrick O'Rorke Memorial Bridge. Due to existing physical and right-of-way constraints at Lake Avenue/LOSP intersection and the Colonel Patrick O'Rorke Memorial Bridge traffic mitigation to offset these traffic impacts is not feasible, and monitoring/optimizing the operation of the intersection may not appreciably alleviate traffic impacts.	D. Goehring	Explanation/Clarification Required
I do not believe parking and traffic issues that will arise have or ever can be adequately addressed. My father was a former city Councilman and he has complained for years about the danger that exists due to the narrowing of Lake Avenue. This development only makes any emergency situation even more dangerous as egress roads will be busier and more crowded. And what would happen if one of these roads was blocked due to an emergency situation??	S. Schiano	Explanation/Clarification Required
People who live in high-rise will end up parking on the street when it is more convenient for them rather than entering their parking garage/facility, especially during the day. How will we stop that?	B. Grey	Explanation/Clarification Required
Provide more clarification on potential shuttle service: What is security plan? Who will provide security/maintenance? How will it be financed? What happens to the parking lots if not used?	M. Parker, K. Strauss	Explanation/Clarification Required
I do not support imposing fees for parking	B. Grey	No response Required
We have reviewed the Draft Generic/Specific Environmental Impact Statement for the Port of Rochester Public Marina and Mixed Use Development Project and we do not have any comments.	T. Rice	No response Required
COMMENT CATEGORY: Utilities		
The issue that the DEIS does not specifically address is additional demand on the sewer facilities in the area. There is a general statement on page 308 that says "the potential growthmay impactutilities However, it is important to emphasize that any growth-inducing impacts will occur over a relatively long timeframe." I would actually like to see flow rate estimates (average and peak gallons per minute) for the anticipated maximum demand on the sanitary sewer system in the	K. Quinn	Correction Required

area based on the maximum 430 dwellings and 44,000 square feet of commercial		
space.		
The sewers to be constructed/relocated as part of the proposed project will need to		
be sized to accommodate future growth in the area. It is anticipated that the new		
24" diameter pipe proposed for the project will suffice. We'd like to evaluate		
whether or not the proposed development will adversely the County's Charlotte		
Sanitary Pump Station at the south end of the project.		
2 parking lots 1-N, 1-S, East side of Lake Ave. Area is now grass. Runoff needs to	M. Parker	Explanation/Clarification
be managed. Please explain	111. I dikoi	Required
COMMENT CATEGORY: Vegetation & Wildlife		Required
COMMENT CATEGORY: Vegetation & Wildlife		NAMES OF STREET STREET,
	The secretary appears that	
II.C.2.1 (p24): in the bulleted list it is unclear what is meant by measures to	T. Haley	Additional Analysis Required
improve wildlife habitat."		
IV.D.2.2 (pp 105 & 107): The Department recommends that you seek further input	T. Haley	Correction Required
and guidance from Dawn Dittman, U.S. Fish & Wildlife Service, regarding the use		1
of the Genesee River by sturgeon. While it appears that you have reviewed some		
of the U.S. Fish & Wildlife sturgeon data, the Department questions some of		
you're the conclusions. In particular, we have concerns over the statement that		
indicates that sturgeon won't return to the Genesee River until the spring of 2020.		
CONDITION CAME CODY XI	North Control of the Control of C	AND AND AND THE AND THE AND THE AND
COMMENT CATEGORY: Visual/Aesthetics		To a Control of the C
I would like to reiterate my concern that the view of the beach not be blocked; even		Explanation/Clarification
from Lake Avenue and think even six-story condos may impair the view.	Ciriello	Required
		_
Construction of buildings right up to the side walk on the east side of Lake Avenue	F. Ardino	Explanation/Clarification
and the building heights will really impact the beautiful view of the river and lake		Required
as you drive over the bridge and approach the park and really does not preserve the		Required
historical integrity of the port or park area.	T 41. 1 11'	
Please don't ever block the view of the waterfront, whether it be from the historic	L. Altobelli	Explanation/Clarification
light house or the view from Lake Ave, looking north as we drive in to park.		Required
COMMENT CATEGORY: Water Resources	TELEVIE RESILVE A	
TVD 2.7.1.2 (- 0.4). This can be a second of the second of	T 11 1	
IV.B.3.7.1.3 (p 84): This section indicates that Phase 1 will be treated through	T. Haley	Explanation/Clarification
existing storm systems. What type of "treatment" will occur and does the existing		Required
system comply with the current MS4 (GP 0-10-002) requirements?		
The proposed marina will be a stillwater basin. How will bilge water, fuel spills,	D. de Zafra Atwell	Explanation/Clarification
and other contaminants generated at the marina be processed and disposed of		Required
without further polluting the Genesee River and Lake Ontario?		1
COMMENT CATEGORY: Other/Miscellaneous		
COMMENT CATEGORY, Other Miscenaneous		
Among additional potential economic benefits the Rochester Port Public Marina &	R. Swacen	No response Required
	IX. Swacen	140 response Required
Mixed Use Development plan will help improve and complete our River Way Trail		
system with its intimate walk and bike-way connections to land, water, forests,		
flora, fish and fauna that best immerses us in nature and allows us to appreciate and		
conserve the wondrous gifts that Mother Earth has given the Charlotte harbor		
towns area.		
Put the restaurant in the terminal building in private hands to stop the losses, put	R. Vance	No response Required
more vendors in the building.	,	110 response required
Promote the banquet hall in the beach house, weddings, etc., caterers will deliver	R. Vance	No roomanaa Dagadaad
	K. Valice	No response Required
the food.		

Promoting Charlotte as a year round destination: To the points of interest mentioned-the Riverway Trail, O'Rourke Bridge, carousel, lighthouse, and (deteriorating) railroad swing bridge – add and integrate in your planning the River Street cemetery, Charlotte walking tour of historic residential and commercial sites, and the to-be-opened Charlotte Transportation Museum.	D. deZafra Atwell	No response Required
Utilize the Port of Rochester's central location between Braddock Bay on the west	D. deZafra Atwell	No recognition Described
and Nine-Mile Point on the east to promote outdoor naturalist education for the	D. deZalia Atwell	No response Required
public, as well as research by professionals at the proposed Lake Ontario Resource		
Center. For example, the nearby ponds and lakeshore estuary are prime birding		
	,	
habitat on the migratory north/south flyway. Why not offer docent-led excursions? Encourage and facilitate venues for indoor entertainment. Could the Charlotte	D. deZafra Atwell	No see Desciud
High auditorium – with its unique and restored murals – be made available to	D. deZaira Atweii	No response Required
continue the summer beach concert series into the other three seasons? Could		
community theater productions be offered there? Could an art house movie		
theater, perhaps with a café and meeting space, be attracted to Charlotte so that northside residents with cultural interests need not always trek to the Little Theatre		
or the Dryden on East Avenue?		
	D. deZafra Atwell	N
Promoting Village Based Commerce: Definitely encourage small, Charlotte-based businesses. Boat-building and repair, bicycle sales and rentals, and Rochester-area	D. deZaira Atwell	No response Required
tour operations are examples. Perhaps working studio and gallery space for craft		
people and artists could also be built, which would be an attraction for Canadian		
tourists as well as local folk if/when a revived and more realistic trans-lake ferry		
operation becomes a reality.		
Speeding Cars, Motorcycles and especially the motorcycles referred to as the	C. James	No recogness De guired
"crotch rockets": Unfortunately this is a problem all over Monroe County, but in	C. James	No response Required
the summer is is more severe in Charlotte, Seabreeze, Summerville and along the		
Lake Ave, St. Paul corridor heading into the lake area. It is dangerous; they are		
loud, and completely obnoxious. Please slow the traffic down! Can you get control		
of this issue? Camera's, ticketing, policing?		
of this issue: Camera's, ticketing, poneing:		
Develop supportive businesses for ships. Ship building should be brought back	V. Kobylarz	No response Required
		1
Please increase policing on the waters for BWI. Over the years the boat accidents	C. James	No response Required
into the piers seem to have increased. Also, loud boats screaming, echoing all over		
there lake at all hours of the night is there anything you can do to address this?		