

# Rundel Library

115 South Avenue  
Rochester, NY  
Building ID No. 7.11

**CITY OF ROCHESTER**  
**ASBESTOS CONTAINING MATERIALS**  
**BUILDING ID NO. 7.11**  
**RUNDEL LIBRARY - 115 SOUTH AVENUE**

The mere presence of asbestos DOES NOT mean that a hazard exists. As long as the material is not disturbed or damaged to the point that fibers are released into the air, a hazard DOES NOT exist.

The purpose of this notice is to list the INTERIOR locations known or presumed to have asbestos containing materials. Some materials suspected of containing asbestos have been tested, but not every material. If in doubt, contact your supervisor for more information.

**MAG. PIPE INSULATION (WHITE HARD/COMPACT POWDER):** This insulation was tested and **does** contain asbestos. It is located throughout the library.

**FIREBRICK:** This material was tested and **does not** contain asbestos. It is located in the elevator motor rooms and the penthouse of the library.

**CORK PIPE INSULATION INTERLACED BETWEEN TARPAPER:** This material was tested and **does not** contain asbestos. It is located in the main penthouse of the library.

**DUCT INSULATION (WHITE/GREY):** This insulation was tested and **does not** contain asbestos. It is located in the penthouse area of the library.

**SPRAYED/TROWELED ON DECORATIVE PLASTER ON CEILINGS:** This ceiling material was tested and **does** contain asbestos. It is located in the Lobby area and the lobby stairwell.

**TANK INSULATION:** This insulation was tested and **does not** contain asbestos. It is located in the penthouse area of the library.

**MUDDIED ELBOWS/FITTINGS/TEES/ETC - GREY:** This insulation was tested and **does** contain asbestos. These fittings are located throughout the library.

**PLASTER WALL - GREY:** This plaster was tested and **does not** contain asbestos. It is located on the mezzanine and first floor of the library.

**PLASTER WALL - CREAM:** This plaster was tested and **does** contain asbestos. It is located on the first floor of the library in the repair inspection area, and the North and South Libraries.

**PLASTER WALL - WHITE:** This plaster was tested and **does not** contain asbestos. It is located throughout the library.

**INTERIOR WINDOW CAULK BETWEEN GLASS & FRAME - TAN (HARD):** This caulk was tested and **does** contain asbestos. It is located on the old/original windows, behind the replacement windows, on all floors of the library.

**HARDWOOD LINOLEUM:** This flooring material was tested and **does not** contain asbestos. It is located on the second floor of the library.

**INTERIOR WINDOW CAULK BETWEEN GLASS & FRAME - WHITE CRUMBLY:** This caulk was tested and **does not** contain asbestos. It is located in the facilities areas and penthouse areas of the library.

**BLACK FLOOR TILE MASTIC (UNDER 9" X 9" FLOOR TILE):** This flooring material was tested and **does not** contain asbestos. It is located on the second and third floors of the library.

**CITY OF ROCHESTER**  
**ASBESTOS CONTAINING MATERIALS**

**BUILDING ID NO. 7.11**  
**RUNDEL LIBRARY - 115 SOUTH AVENUE**

The mere presence of asbestos DOES NOT mean that a hazard exists. As long as the material is not disturbed or damaged to the point that fibers are released into the air, a hazard DOES NOT exist.

The purpose of this notice is to list the INTERIOR locations known or presumed to have asbestos containing materials. Some materials suspected of containing asbestos have been tested, but not every material. If in doubt, contact your supervisor for more information.

**PRESUMED ASBESTOS CONTAINING MATERIAL:**

- 9" x 9" Floor Tile are assumed to be positive for asbestos.
- 12" x 12" Floor Tiles and associated Mastic
- Corrugated Paper (air cell) Pipe Insulation
- Flexible Fabric Joints (Flexible Duct Connectors) - Black
- Paper Pipe Insulation- White Fibrous
- Tan Cove Molding and associated Mastic
- Drywall Ceiling (specifically the drywall tape/joint compound)
- Black Cove Molding and associated Mastic
- Maroon Cove Molding and associated Mastic
- 6" x 18" Cork-like Tiles
- 2' x 4' Suspended Acoustical Ceiling Tile (SAT)
- Drywall Wall (specifically the drywall tape/joint compound)
- Interior Door Caulk between Door & Structure - Grey
- Interior Door Caulk between Frame & Concrete Block - Cream
- Interior Window Caulk between Glass & Frame- Dark Grey (hard)
- Interior Window Caulk between Frame & Block - Black
- Felt Paper Pipe Insulation - Black
- 12" x 24" Floor Tile and associated Mastic
- Layered Paper Pipe Insulation Brown/Grey w/hairs.
- Duct caulk - Grey (Hard)
- Mudded Elbows/Fittings/Tees/etc. - White
- Duct Insulation - Grey Fibrous Panels/Sheets
- Mastic under 9" x 9" Floor Tiles
- Brown Cove Molding and associated Mastic
- Textured Stucco/Drywall Ceiling (specifically the drywall tape/joint compound)
- Grey Cove Molding and associated Mastic
- Greenish Tan Cove Molding and associated Mastic
- Carpet Adhesive/Glue
- 2' x 2' Suspended Acoustical Ceiling Tile (SAT)
- Caulk between Steel Pillar & block - White/pliable
- Interior Door Caulk between Door & Structure - Black
- Interior Window Caulk between Frame & Structure - Grey
- Interior Window Caulk between Glass & Frame- Black sticky
- Linoleum Floors and associated Mastic
- Paneling Adhesive/Glue

These materials would need further analysis to confirm the presence or absence of asbestos.

FOR FURTHER INFORMATION, INCLUDING THE CITY OF ROCHESTER'S ASBESTOS MANAGEMENT PLAN, CONTACT YOUR SUPERVISOR OR HEALTH SAFETY OFFICER.

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                    | Homogeneous Area ID No. | Room ID No. & Location             | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|-------------------------------------------------|-------------------------|------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Mag Pipe Insulation (white hard/compact powder) | A006A                   | US7.11A-Upper Stack                | Tested            | Y         | 307 LF   | 2          | 6                |             |
|                                                 |                         | US7.11B-Women's Room               |                   |           | 6 LF     | 2          | 6                |             |
|                                                 |                         | US7.11C-Men's Room                 |                   |           | 10 LF    | 2          | 6                |             |
|                                                 |                         | 7.11B-Facilities Offices           |                   |           | 12 LF    | 2          | 6                |             |
|                                                 |                         | 7.11F-Storage                      |                   |           | 89 LF    | 2          | 6                |             |
|                                                 |                         | 7.11H-Shipping Stockroom           |                   |           | 22 LF    | 2          | 6                |             |
|                                                 |                         | 7.11I-Mail Room                    |                   |           | 7 LF     | 2          | 6                |             |
|                                                 |                         | 7.11J-Work Area                    |                   |           | 15 LF    | 2          | 6                |             |
|                                                 |                         | 7.11R-Computer Room                |                   |           | 3 LF     | 2          | 6                |             |
|                                                 |                         | 7.11V-User Support                 |                   |           | 8 LF     | 2          | 6                |             |
|                                                 |                         | 7.11Y-Staging Area Closet          |                   |           | 10 LF    | 2          | 6                |             |
|                                                 |                         | M7.11E-Northwest Stairwell         |                   |           | 240 LF   | 2          | 6                |             |
|                                                 |                         | 2F7.11N-Janitor's Closet           |                   |           | 17 LF    | 5          | 3                |             |
|                                                 |                         | 2F7.11Y-Stairwell/Elevator         |                   |           | 100 LF   | 2          | 6                |             |
|                                                 |                         | 3F7.11E-Mechanical Room            |                   |           | 15 LF    | 2          | 6                |             |
|                                                 |                         | 3F7.11U-Personnel Manager's Office |                   |           | 18 LF    | 2          | 6                |             |
|                                                 |                         | 3F7.11AM-Dining Room               |                   |           | 3 LF     | 2          | 6                |             |
|                                                 |                         | 3F7.11AQ-Mechanical Shaftway       |                   |           | 100 LF   | 2          | 6                |             |
|                                                 |                         | P7.11A-Penthouse - "L"             |                   |           | 125 LF   | 3          | 5                |             |
|                                                 |                         | P7.11B-Elevator Motor Room         |                   |           | 30 LF    | 2          | 6                |             |
|                                                 |                         | P7.11E-Main Penthouse              |                   |           | 270 LF   | 2          | 6                |             |
| Total:                                          |                         |                                    |                   |           | 1407 LF  |            |                  |             |



Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                       | Homogeneous Area ID No. | Room ID No. & Location                    | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|----------------------------------------------------|-------------------------|-------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Fire Brick                                         | A94                     | P7.11B-Elevator Motor Room                | Tested            | N         | 342 SF   | 1          | 7                |             |
|                                                    |                         | P7.11C-Elevator Motor/Electric Board Room |                   |           | 396 SF   | 1          | 7                |             |
|                                                    |                         | P7.11D-Elevator Machine Room              |                   |           | 243 SF   | 1          | 7                |             |
|                                                    |                         | P7.11E-Main Penthouse                     |                   | Total:    | 1501 SF  |            | 7                |             |
| Cork Pipe Insulation                               | 0060                    | P7.11E-Main Penthouse                     | Tested            | N         | 30 LF    | 1          | 7                |             |
|                                                    |                         |                                           |                   | Total:    | 30 LF    |            |                  |             |
| Duct Insulation - White                            | 0013                    | P7.11A-Penthouse "L"                      | Tested            | N         | 8000 LF  | 1          | 7                |             |
|                                                    |                         | P7.11E-Main Penthouse                     |                   |           | 2500 LF  | 1          | 7                |             |
|                                                    |                         |                                           |                   | Total:    | 10500 LF |            |                  |             |
| Sprayed/Troweled on Decorative Plaster on Ceilings | 02                      | 1F7.11I-Lobby/Security                    | Tested            | Y         | 780 SF   | 2          | 6                |             |
|                                                    |                         | 1F7.11J-Lobby Foyer                       |                   |           | 98 SF    | 2          | 6                |             |
|                                                    |                         | 1F7.11AA-Lobby/Security Stairway          |                   |           | 52 SF    | 2          | 6                |             |
|                                                    |                         | M7.11A-Literature Manager                 |                   |           | 327 SF   | 2          | 6                |             |
|                                                    |                         | M7.11B-Central Library Office Area        |                   |           | 591 SF   | 2          | 6                |             |
|                                                    |                         | M7.11C-Central Library Office             |                   |           | 338 SF   | 2          | 6                |             |
|                                                    |                         | M7.11F-Science Balcony                    |                   |           | 491 SF   | 2          | 6                |             |
|                                                    |                         | M7.11I-Interlibrary Loan Area             |                   |           | 701 SF   | 2          | 6                |             |
|                                                    |                         | M7.11K-Interlibrary Office                |                   |           | 220 SF   | 2          | 6                |             |
|                                                    |                         | 1F7.11A-Repair/Inspection Area            |                   |           | 943 SF   | 2          | 6                |             |
|                                                    |                         |                                           |                   |           |          |            |                  |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                       | Homogeneous Area ID No. | Room ID No. & Location                            | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|----------------------------------------------------|-------------------------|---------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Sprayed/Troweled on Decorative Plaster on Ceilings | 02 (cont)               | 1F7.11B-Periodicals/Children's (North Library)    |                   |           | 3871 SF  | 2          | 6                |             |
|                                                    |                         | 1F7.11C-Fiction/Non-Fiction Area (South Library)  |                   |           | 5317 SF  | 2          | 6                |             |
|                                                    |                         | 1F7.11E-Fiction Area (Quiet Room, Listening Room) |                   |           | 2418 SF  | 2          | 6                |             |
|                                                    |                         | 1F7.11H-Reading Area                              |                   |           | 6300 SF  | 2          | 6                |             |
|                                                    |                         | 1F7.11N-Conference Room (East Side)               |                   |           | 195 SF   | 2          | 6                |             |
|                                                    |                         | 1F7.11AA-Lobby/Security Stairway                  |                   |           | 52 SF    | 2          | 6                |             |
|                                                    |                         |                                                   | Total:            |           | 22694 SF |            |                  |             |
| Tank Insulation                                    | 0028                    | P7.11E-Main Penthouse                             | Tested            | N         | 150 SF   | 1          | 7                |             |
|                                                    |                         |                                                   | Total:            |           | 150 SF   |            |                  |             |
| Elbow/Fittings/Tees & etc. - Grey Mud              | 008                     | US7.11A-Upper Slack                               | Tested            | Y         | 174 LF   | 2          | 6                |             |
|                                                    |                         | US7.11B-Women's Room                              |                   |           | 5 LF     | 2          | 6                |             |
|                                                    |                         | US7.11C-Men's Room                                |                   |           | 6 LF     | 2          | 6                |             |
|                                                    |                         | 7.11B-Facilities Offices                          |                   |           | 4 LF     | 2          | 6                |             |
|                                                    |                         | 7.11F-Storage                                     |                   |           | 37 LF    | 2          | 6                |             |
|                                                    |                         | 7.11H-Shipping Stockroom                          |                   |           | 5 LF     | 2          | 6                |             |
|                                                    |                         | 7.11I-Mail Room                                   |                   |           | 3 LF     | 2          | 6                |             |
|                                                    |                         | 7.11J-Work Area                                   |                   |           | 9 LF     | 2          | 6                |             |
|                                                    |                         | 7.11R-Computer Room                               |                   |           | 2 LF     | 2          | 6                |             |
|                                                    |                         | 7.11V-User Support                                |                   |           | 6 LF     | 2          | 6                |             |
|                                                    |                         | 2F7.11N-Janitor's Closet                          |                   |           | 8 LF     | 5          | 3                |             |
|                                                    |                         | 3F7.11AM-Dining Room                              |                   |           | 10 LF    | 2          | 6                |             |
|                                                    |                         | P7.11B-Elevator Motor Room                        |                   |           | 8 LF     | 2          | 6                |             |
|                                                    |                         | P7.11E-Main Penthouse                             |                   |           | 75 LF    | 2          | 6                |             |
|                                                    |                         |                                                   | Total:            |           | 352 LF   |            |                  |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                                                                                                                           | Tested or Assumed | ACM (Y/N) | Quantity                                                                      | AHERA Rank                           | Removal Priority                     | Date Abated |
|------------------------------|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|-------------------------------------------------------------------------------|--------------------------------------|--------------------------------------|-------------|
| Plaster Wall - Grey          | 8C                      | M7.11I-Interlibrary Loan Area<br>M7.11K-Interlibrary Office<br>1F7.11E-Fiction Area (Quiet Room, Listening Room)<br>1F7.11L-Hallway<br>1F7.11U-Custodian's Closet<br>1F7.11V-Literacy<br>1F7.11W-Stairwell Foyer<br>1F7.11X-Women's Room<br>1F7.11Y-Stairwell to Upper Stack<br>1F7.11AA-Lobby/Security Stairway | Tested            | N         | 366 SF<br>302 SF<br>3196 SF                                                   | 1<br>1<br>1                          | 7<br>7<br>7                          |             |
|                              |                         |                                                                                                                                                                                                                                                                                                                  |                   | Total:    | 5656 SF                                                                       | 1                                    | 7                                    |             |
| Plaster Wall - Cream         | 8D                      | 1F7.11A-Repair/Inspection Area<br>1F7.11B-Periodicals/Children's (North Library)<br>1F7.11C-Fiction/Non-Fiction Area (South Library)                                                                                                                                                                             | Tested            | Y         | 927 SF<br>3735 SF                                                             | 2<br>2                               | 6<br>6                               |             |
|                              |                         |                                                                                                                                                                                                                                                                                                                  |                   | Total:    | 4225 SF                                                                       | 2                                    | 6                                    |             |
| Plaster Wall - White         | 8                       | M7.11A-Literature Manager<br>M7.11B-Central Library Office Area<br>M7.11C-Central Library Office<br>M7.11F-Science Balcony<br>M7.11G-Reference Area<br>1F7.11D-Conference Room<br>1F7.11F-Hallway                                                                                                                | Tested            | N         | 8887 SF<br>426 SF<br>177 SF<br>434 SF<br>416 SF<br>388 SF<br>436 SF<br>180 SF | 1<br>1<br>1<br>1<br>1<br>1<br>1<br>1 | 7<br>7<br>7<br>7<br>7<br>7<br>7<br>7 |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                   | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Plaster Wall - White (cont)  | 8 (cont)                | 1F7.11H-Reading Area                     |                   |           | 4680 SF  | 1          | 7                |             |
|                              |                         | 1F7.11N-Conference Room (East Side)      |                   |           | 416 SF   | 1          | 7                |             |
|                              |                         | 1F7.11O-Elevator Balcony                 |                   |           | 277 SF   | 1          | 7                |             |
|                              |                         | 1F7.11P-Bathroom                         |                   |           | 190 SF   | 1          | 7                |             |
|                              |                         | 1F7.11R-Restroom Hall                    |                   |           | 400 SF   | 1          | 7                |             |
|                              |                         | 1F7.11V-Literacy                         |                   |           | 150 SF   | 1          | 7                |             |
|                              |                         | 1F7.11AB-Stairwell to Central Library    |                   |           | 836 SF   | 1          | 7                |             |
|                              |                         | 2F7.11A-Foyer to 2nd Floor               |                   |           | 1056 SF  | 1          | 7                |             |
|                              |                         | 2F7.11B-Stairwell                        |                   |           | 891 SF   | 1          | 7                |             |
|                              |                         | 2F7.11C-Hallway - 2nd Floor              |                   |           | 3432 SF  | 1          | 7                |             |
|                              |                         | 2F7.11E-Historian's Office               |                   |           | 540 SF   | 1          | 7                |             |
|                              |                         | 2F7.11F-Storage-Historian (Under Stairs) |                   |           | 377 SF   | 1          | 7                |             |
|                              |                         | 2F7.11G-Secretarial - Historian          |                   |           | 108 SF   | 1          | 7                |             |
|                              |                         | 2F7.11H-Storage                          |                   |           | 351 SF   | 1          | 7                |             |
|                              |                         | 2F7.11I-Local History/Genealogy Library  |                   |           | 2580 SF  | 1          | 7                |             |
|                              |                         | 2F7.11J-Genealogy Library                |                   |           | 1872 SF  | 1          | 7                |             |
|                              |                         | 2F7.11K-Hallway                          |                   |           | 1520 SF  | 1          | 7                |             |
|                              |                         | 2F7.11L-File Storage                     |                   |           | 1161 SF  | 1          | 7                |             |
|                              |                         | 2F7.11O-Office                           |                   |           | 530 SF   | 1          | 7                |             |
|                              |                         | 2F7.11P-Hallway (Rear)                   |                   |           | 1020 SF  | 1          | 7                |             |
|                              |                         | 2F7.11Q-Office - Local History           |                   |           | 390 SF   | 1          | 7                |             |
|                              |                         | 2F7.11R-Local History Offices            |                   |           | 963 SF   | 1          | 7                |             |
|                              |                         | 2F7.11S-Men's Bathroom                   |                   |           | 567 SF   | 1          | 7                |             |
|                              |                         | 2F7.11T-Local History Vault              |                   |           | 275 SF   | 1          | 7                |             |
|                              |                         | 2F7.11U-Local History Storage            |                   |           | 996 SF   | 1          | 7                |             |
|                              |                         | 2F7.11V-Small Hall                       |                   |           | 297 SF   | 1          | 7                |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location             | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Plaster Wall - White (cont)  | 8 (cont)                | 2F7.11W-Room 235                   |                   |           | 2134 SF  | 1          | 7                |             |
|                              |                         | 2F7.11X-Small Office               |                   |           | 418 SF   | 1          | 7                |             |
|                              |                         | 2F7.11Z-Small Hallway              |                   |           | 440 SF   | 1          | 7                |             |
|                              |                         | 2F7.11AA-Hall to Main Hallway      |                   |           | 1070 SF  | 1          | 7                |             |
|                              |                         | 2F7.11AB-Storage                   |                   |           | 624 SF   | 1          | 7                |             |
|                              |                         | 2F7.11AD-History Storage           |                   |           | 1166 SF  | 1          | 7                |             |
|                              |                         | 2F7.11AE-Small Conference          |                   |           | 1078 SF  | 1          | 7                |             |
|                              |                         | 2F7.11AF-Children's Book Storage   |                   |           | 1368 SF  | 1          | 7                |             |
|                              |                         | 2F7.11AG-Picture Book Storage      |                   |           | 846 SF   | 1          | 7                |             |
|                              |                         | 2F7.11AI-Elevator Foyer            |                   |           | 180 SF   | 1          | 7                |             |
|                              |                         | 2F7.11AJ-Outreach Offices          |                   |           | 2332 SF  | 1          | 7                |             |
|                              |                         | 2F7.11AK-Outreach Manager's Office |                   |           | 407 SF   | 1          | 7                |             |
|                              |                         | 3F7.11A-Entry                      |                   |           | 850 SF   | 1          | 7                |             |
|                              |                         | 3F7.11B-Hallway                    |                   |           | 3040 SF  | 1          | 7                |             |
|                              |                         | 3F7.11D-Auditorium                 |                   |           | 1280 SF  | 1          | 7                |             |
|                              |                         | 3F7.11F-Projection Room            |                   |           | 836 SF   | 1          | 7                |             |
|                              |                         | 3F7.11G-Serving Area               |                   |           | 319 SF   | 1          | 7                |             |
|                              |                         | 3F7.11H-Reception Area             |                   |           | 360 SF   | 1          | 7                |             |
|                              |                         | 3F7.11I-Office                     |                   |           | 1116 SF  | 1          | 7                |             |
|                              |                         | 3F7.11J-Storage Room               |                   |           | 240 SF   | 1          | 7                |             |
|                              |                         | 3F7.11K-Bathroom                   |                   |           | 180 SF   | 1          | 7                |             |
|                              |                         | 3F7.11L-Office                     |                   |           | 225 SF   | 1          | 7                |             |
|                              |                         | 3F7.11M-Office                     |                   |           | 387 SF   | 1          | 7                |             |
|                              |                         | 3F7.11N-Office                     |                   |           | 423 SF   | 1          | 7                |             |
|                              |                         | 3F7.11O-Bathroom                   |                   |           | 198 SF   | 1          | 7                |             |
|                              |                         | 3F7.11P-Office                     |                   |           | 324 SF   | 1          | 7                |             |
|                              |                         | 3F7.11Q-Hallway                    |                   |           | 1008 SF  | 1          | 7                |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

Homogeneous Area ID No. 8 (cont)

Homogeneous Area Description

Plaster Wall - White (cont)

| Room ID No. & Location                            | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|---------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| 3F7.11R-Personnel Office                          |                   |           | 840 SF   | 1          | 7                |             |
| 3F7.11S-File Storage                              |                   |           | 200 SF   | 1          | 7                |             |
| 3F7.11T-Bathroom/Storage                          |                   |           | 200 SF   | 1          | 7                |             |
| 3F7.11V-Machine Room                              |                   |           | 220 SF   | 1          | 7                |             |
| 3F7.11W-Reception - Board of Directors            |                   |           | 450 SF   | 1          | 7                |             |
| 3F7.11Y-Director's Office                         |                   |           | 558 SF   | 1          | 7                |             |
| 3F7.11Z-Bathroom                                  |                   |           | 72 SF    | 1          | 7                |             |
| 3F7.11AA-Small Meeting Room                       |                   |           | 360 SF   | 1          | 7                |             |
| 3F7.11AB-Office                                   |                   |           | 550 SF   | 1          | 7                |             |
| 3F7.11AC-Office                                   |                   |           | 585 SF   | 1          | 7                |             |
| 3F7.11AD-Small Office                             |                   |           | 378 SF   | 1          | 7                |             |
| 3F7.11AE-Office                                   |                   |           | 580 SF   | 1          | 7                |             |
| 3F7.11AF-Office                                   |                   |           | 660 SF   | 1          | 7                |             |
| 3F7.11AG-Storage Closet                           |                   |           | 154 SF   | 1          | 7                |             |
| 3F7.11AH-Office-Assistant Director for Technology |                   |           | 400 SF   | 1          | 7                |             |
| 3F7.11AI-Men's Bath/Locker Room                   |                   |           | 448 SF   | 1          | 7                |             |
| 3F7.11AJ-Janitor Closet                           |                   |           | 52 SF    | 1          | 7                |             |
| 3F7.11AK-Lounge                                   |                   |           | 810 SF   | 1          | 7                |             |
| 3F7.11AM-Dining Room                              |                   |           | 52 SF    | 1          | 7                |             |
| 3F7.11AO-Vending Room                             |                   |           | 320 SF   | 1          | 7                |             |
| 3F7.11AR-Hallway                                  |                   |           | 2800 SF  | 1          | 7                |             |
| 3F7.11AS-Office/Work Area                         |                   |           | 2400 SF  | 1          | 7                |             |
| 3F7.11AT-Offices                                  |                   |           | 39 SF    | 1          | 7                |             |
| 3F7.11AU-"Friends" Office                         |                   |           | 580 SF   | 1          | 7                |             |
| 3F7.11AV-Aquisitions Office                       |                   |           | 531 SF   | 1          | 7                |             |
| 3F7.11AW-Aquisitions Office                       |                   |           | 936 SF   | 1          | 7                |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                               | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                                                     | Tested or Assumed | ACM (Y/N) | Quantity                                                                                               | AHERA Rank                                | Removal Priority                          | Date Abated |
|------------------------------------------------------------|-------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|--------------------------------------------------------------------------------------------------------|-------------------------------------------|-------------------------------------------|-------------|
| Plaster Wall - White (con't)                               | 8 (con't)               | 3F7.11AX-Office<br>3F7.11AZ-Office/Reception<br>3F7.11BA-Work/Copy Room<br>3F7.11BB-"Development/Photo" Room<br>3F7.11BC-Storeroom<br>3F7.11BD-Office<br>3F7.11BG-Men's Room<br>3F7.11BH-Ladies Room                                       |                   |           | 160 SF<br>468 SF<br>738 SF<br>648 SF<br>380 SF<br>414 SF<br>374 SF<br>478 SF<br>Total: 70016 SF        | 1<br>1<br>1<br>1<br>1<br>1<br>1<br>1      | 7<br>7<br>7<br>7<br>7<br>7<br>7<br>7      |             |
| Black Mastic                                               | A341M                   | 2F7.11U-Local History Storage<br>3F7.11G-Serving Area<br>3F7.11Q-Hallway<br>3F7.11R-Personnel Office<br>3F7.11S-File Storage<br>3F7.11A-Men's Bath/Locker Room<br>3F7.11AK-Lounge<br>3F7.11AL-Ladies Locker Room/Bath<br>3F7.11 AR-Hallway | Tested            | N         | 616 SF<br>77 SF<br>300 SF<br>510 SF<br>91 SF<br>293 SF<br>504 SF<br>360 SF<br>859 SF<br>Total: 3610 SF | 1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1 | 7<br>7<br>7<br>7<br>7<br>7<br>7<br>7<br>7 |             |
| Interior Window Caulk - between Glass & Frame - Tan (hard) | 248C                    | M7.11A-Literature Manager<br>M7.11C-Central Library Office<br>M7.11F-Science Balcony<br>M7.11G-Reference Area<br>M7.11I-Interlibrary Loan Area<br>M7.11K-Interlibrary Office                                                               | Tested            | Y         | 82 LF<br>32 LF<br>35 LF<br>72 LF<br>128 LF<br>72 LF                                                    | 2<br>2<br>2<br>2<br>2<br>2                | 6<br>6<br>6<br>6<br>6<br>6                |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                       | Homogeneous Area ID No. | Room ID No. & Location                            | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|--------------------------------------------------------------------|-------------------------|---------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Interior Window Caulk - between Glass & Frame - Tan (hard) (con't) | 248C (con't)            | 1F7.11A-Repair/Inspection Area                    |                   |           | 744 LF   | 2          | 6                |             |
|                                                                    |                         | 1F7.11B-Periodicals/Children's (North Library)    |                   |           | 1488 LF  | 2          | 6                |             |
|                                                                    |                         | 1F7.11C-Fiction/Non-Fiction Area (South Library)  |                   |           | 2232 LF  | 2          | 6                |             |
|                                                                    |                         | 1F7.11D-Conference Room                           |                   |           | 56 LF    | 2          | 6                |             |
|                                                                    |                         | 1F7.11E-Fiction Area (Quiet Room, Listening Room) |                   |           | 930 LF   | 2          | 6                |             |
|                                                                    |                         | 1F7.11J-Lobby Foyer                               |                   |           | 54 LF    | 2          | 6                |             |
|                                                                    |                         | 1F7.11L-Hallway                                   |                   |           | 38 LF    | 2          | 6                |             |
|                                                                    |                         | 1F7.11N-Conference Room (East Side)               |                   |           | 64 LF    | 2          | 6                |             |
|                                                                    |                         | 1F7.11R-Restroom Hall                             |                   |           | 100 LF   | 2          | 6                |             |
|                                                                    |                         | 2F7.11B-Stairwell                                 |                   |           | 1118 LF  | 2          | 6                |             |
|                                                                    |                         | 2F7.11C-Hallway - 2nd Floor                       |                   |           | 1392 LF  | 2          | 6                |             |
|                                                                    |                         | 2F7.11E-Historian's Office                        |                   |           | 576 LF   | 2          | 6                |             |
|                                                                    |                         | 2F7.11F-Storage-Historian (Under Stairs)          |                   |           | 576 LF   | 2          | 6                |             |
|                                                                    |                         | 2F7.11G-Secretarial - Historian                   |                   |           | 576 LF   | 2          | 6                |             |
|                                                                    |                         | 2F7.11I-Local History/Genealogy Library           |                   |           | 3456 LF  | 2          | 6                |             |
|                                                                    |                         | 2F7.11J-Geneology Library                         |                   |           | 2880 LF  | 2          | 6                |             |
|                                                                    |                         | 2F7.11L-File Storage                              |                   |           | 2088 LF  | 2          | 6                |             |
|                                                                    |                         | 2F7.11M-File Storage                              |                   |           | 1044 LF  | 2          | 6                |             |
|                                                                    |                         | 2F7.11O-Office                                    |                   |           | 576 LF   | 2          | 6                |             |
|                                                                    |                         | 2F7.11Q-Office - Local History                    |                   |           | 576 LF   | 2          | 6                |             |
|                                                                    |                         | 2F7.11R-Local History Offices                     |                   |           | 1728 LF  | 2          | 6                |             |
|                                                                    |                         | 2F7.11T-Local History Vault                       |                   |           | 896 LF   | 2          | 6                |             |
|                                                                    |                         | 2F7.11U-Local History Storage                     |                   |           | 3088 LF  | 2          | 6                |             |



Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                      | Homogeneous Area ID No. | Room ID No. & Location                              | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|-------------------------------------------------------------------|-------------------------|-----------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Interior Window Caulk - between Glass & Frame - Tan (hard) (cont) | 248C (cont)             | 2F7.11W-Room 235                                    |                   |           | 920 LF   | 2          | 6                |             |
|                                                                   |                         | 2F7.11X-Small Office                                |                   |           | 288 LF   | 2          | 6                |             |
|                                                                   |                         | 2F7.11AC-Book Storage                               |                   |           | 896 LF   | 2          | 6                |             |
|                                                                   |                         | 2F7.11AD-History Storage                            |                   |           | 864 LF   | 2          | 6                |             |
|                                                                   |                         | 2F7.11AE-Small Conference                           |                   |           | 288 LF   | 2          | 6                |             |
|                                                                   |                         | 2F7.11AF-Children's Book Storage                    |                   |           | 876 LF   | 2          | 6                |             |
|                                                                   |                         | 2F7.11AG-Picture Book Storage                       |                   |           | 876 LF   | 2          | 6                |             |
|                                                                   |                         | 2F7.11AJ-Outreach Offices                           |                   |           | 1152 LF  | 2          | 6                |             |
|                                                                   |                         | 2F7.11AK-Outreach Manager's Office                  |                   |           | 288 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11B-Hallway                                     |                   |           | 2784 LF  | 2          | 6                |             |
|                                                                   |                         | 3F7.11I-Office                                      |                   |           | 526 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11R-Personnel Office                            |                   |           | 464 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11S-File Storage                                |                   |           | 484 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11U-Personnel Manager's Office                  |                   |           | 968 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11X-Board of Directors' Meeting Room            |                   |           | 1052 LF  | 2          | 6                |             |
|                                                                   |                         | 3F7.11Y-Director's Office                           |                   |           | 526 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11AA-Small Meeting Room                         |                   |           | 526 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11AB-Office                                     |                   |           | 526 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11AC-Office                                     |                   |           | 1026 LF  | 2          | 6                |             |
|                                                                   |                         | 3F7.11AE-Office                                     |                   |           | 526 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11AF-Office                                     |                   |           | 1026 LF  | 2          | 6                |             |
|                                                                   |                         | 3F7.11AH-Office - Assistant Director for Technology |                   |           | 526 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11AK-Lounge                                     |                   |           | 1344 LF  | 2          | 6                |             |
|                                                                   |                         | 3F7.11AM-Dining Room                                |                   |           | 896 LF   | 2          | 6                |             |
|                                                                   |                         | 3F7.11AN-Cafeteria/Kitchen                          |                   |           | 896 LF   | 2          | 6                |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                 | Homogeneous Area ID No. | Room ID No. & Location                    | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|--------------------------------------------------------------|-------------------------|-------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Interior Window - between Glass & Frame - Tan (hard) (con't) | 248C (con't)            | 3F7.11AS-Office/Work Area                 |                   |           | 2436 LF  | 2          | 6                |             |
|                                                              |                         | 3F7.11AT-Offices                          |                   |           | 348 LF   | 2          | 6                |             |
|                                                              |                         | 3F7.11AU-Friends* Office                  |                   |           | 348 LF   | 2          | 6                |             |
|                                                              |                         | 3F7.11AV-Acquisitions Office              |                   |           | 348 LF   | 2          | 6                |             |
|                                                              |                         | 3F7.11AW-Acquisitions Office              |                   |           | 796 LF   | 2          | 6                |             |
|                                                              |                         | 3F7.11AY-Office                           |                   |           | 348 LF   | 2          | 6                |             |
|                                                              |                         | 3F7.11BD-Office                           |                   |           | 348 LF   | 2          | 6                |             |
|                                                              |                         | Total:                                    |                   |           | 52213 LF |            |                  |             |
| Hardwood Linoleum                                            | A311D                   | 2F7.11E-Historian's Office                | Tested            | N         | 224 SF   | 1          | 7                |             |
|                                                              |                         | 2F7.11F-Storage-Historian (Under Stairs)  |                   |           | 140 SF   | 1          | 7                |             |
|                                                              |                         | 2F7.11G-Secretarial - Historian           |                   |           | 144 SF   | 1          | 7                |             |
|                                                              |                         | 2F7.11H-Storage                           |                   |           | 189 SF   | 1          | 7                |             |
|                                                              |                         | 2F7.11I-Office                            |                   |           | 260 SF   | 1          | 7                |             |
|                                                              |                         | 2F7.11Q-Office - Local History            |                   |           | 180 SF   | 1          | 7                |             |
|                                                              |                         | 2F7.11R-Local History Offices             |                   |           | 602 SF   | 1          | 7                |             |
|                                                              |                         | Total:                                    |                   |           | 1739 SF  |            |                  |             |
| Interior Window Caulk between frame & glass - white crumbly  | 248H                    | 7.11A-Mechanical Room                     | Tested            | N         | 120 LF   | 1          | 7                |             |
|                                                              |                         | 7.11B-Facilities Offices                  |                   |           | 60 LF    | 1          | 7                |             |
|                                                              |                         | 7.11C-Facilities Manager Office           |                   |           | 60 LF    | 1          | 7                |             |
|                                                              |                         | 7.11Z-Office                              |                   |           | 88 LF    | 1          | 7                |             |
|                                                              |                         | P7.11B-Elevator Motor Room                |                   |           | 876 LF   | 1          | 7                |             |
|                                                              |                         | P7.11C-Elevator Motor/Electric Board Room |                   |           | 576 LF   | 1          | 7                |             |
|                                                              |                         | P7.11E-Main Penthouse                     |                   |           | 3946 LF  | 1          | 7                |             |
|                                                              |                         | Total:                                    |                   |           | 5726 LF  |            |                  |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|---------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Plaster Ceiling - Grey       | 9A                      | 1F7.11V-Literacy                      | Assumed           |           | 285 SF   | 2          | 6                |             |
|                              |                         | 1F7.11W-Stairwell Foyer               |                   |           | 88 SF    | 2          | 6                |             |
|                              |                         | 1F7.11X-Women's Room                  |                   |           | 35 SF    | 2          | 6                |             |
|                              |                         | 1F7.11Y-Stairwell to Upper Stack      |                   |           | 36 SF    | 2          | 6                |             |
|                              |                         | 3F7.11E-Mechanical Room               |                   |           | 40 SF    | 2          | 6                |             |
|                              |                         | Total:                                |                   |           | 484 SF   |            |                  |             |
| Plaster Ceiling - White      | 9                       | 1F7.11F-Hallway                       | Assumed           |           | 160 SF   | 2          | 6                |             |
|                              |                         | 1F7.11L-Hallway                       |                   |           | 231 SF   | 2          | 6                |             |
|                              |                         | 1F7.11O-Elevator Balcony              |                   |           | 99 SF    | 2          | 6                |             |
|                              |                         | 1F7.11P-Bathroom                      |                   |           | 23 SF    | 2          | 6                |             |
|                              |                         | 1F7.11Q-Stairwell                     |                   |           | 100 SF   | 2          | 6                |             |
|                              |                         | 1F7.11R-Restroom Hall                 |                   |           | 173 SF   | 2          | 6                |             |
|                              |                         | 1F7.11S-Men's Room                    |                   |           | 124 SF   | 2          | 6                |             |
|                              |                         | 1F7.11T-Women's Room                  |                   |           | 147 SF   | 2          | 6                |             |
|                              |                         | 1F7.11U-Custodian's Closet            |                   |           | 39 SF    | 2          | 6                |             |
|                              |                         | 1F7.11AB-Stairwell to Central Library |                   |           | 130 SF   | 2          | 6                |             |
|                              |                         | 2F7.11A-Foyer to 2nd Floor            |                   |           | 575 SF   | 2          | 6                |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description   | Homogeneous Area ID No. | Room ID No. & Location                   | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|--------------------------------|-------------------------|------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Plaster Ceiling - White (cont) | 9 (cont)                | 2F7.11B-Stairwell                        |                   |           | 185 SF   | 2          | 6                |             |
|                                |                         | 2F7.11C-Hallway - 2nd Floor              |                   |           | 1572 SF  | 2          | 6                |             |
|                                |                         | 2F7.11E-Historian's Office               |                   |           | 224 SF   | 2          | 6                |             |
|                                |                         | 2F7.11F-Storage-Historian (Under Stairs) |                   |           | 140 SF   | 2          | 6                |             |
|                                |                         | 2F7.11G-Secretarial - Historian          |                   |           | 144 SF   | 2          | 6                |             |
|                                |                         | 2F7.11H-Storage                          |                   |           | 189 SF   | 2          | 6                |             |
|                                |                         | 2F7.11I-Local History/Genealogy Library  |                   |           | 2682 SF  | 2          | 6                |             |
|                                |                         | 2F7.11J-Genealogy Library                |                   |           | 1472 SF  | 2          | 6                |             |
|                                |                         | 2F7.11K-Hallway                          |                   |           | 660 SF   | 2          | 6                |             |
|                                |                         | 2F7.11L-File Storage                     |                   |           | 885 SF   | 2          | 6                |             |
|                                |                         | 2F7.11M- File Storage                    |                   |           | 377 SF   | 2          | 6                |             |
|                                |                         | 2F7.11N-Janitor's Closet                 |                   |           | 20 SF    | 2          | 6                |             |
|                                |                         | 2F7.11O-Office                           |                   |           | 260 SF   | 2          | 6                |             |
|                                |                         | 2F7.11P-Hallway (Rear)                   |                   |           | 270 SF   | 2          | 6                |             |
|                                |                         | 2F7.11Q-Office - Local History           |                   |           | 180 SF   | 2          | 6                |             |
|                                |                         | 2F7.11R-Local History Offices            |                   |           | 602 SF   | 2          | 6                |             |
|                                |                         | 2F7.11S-Men's Bathroom                   |                   |           | 132 SF   | 2          | 6                |             |
|                                |                         | 2F7.11T-Local History Vault              |                   |           | 154 SF   | 2          | 6                |             |
|                                |                         | 2F7.11U-Local History Storage            |                   |           | 616 SF   | 2          | 6                |             |
|                                |                         | 2F7.11V-Small Hall                       |                   |           | 162 SF   | 2          | 6                |             |
|                                |                         | 2F7.11W-Room 235                         |                   |           | 2112 SF  | 2          | 6                |             |
|                                |                         | 2F7.11X-Small Office                     |                   |           | 88 SF    | 2          | 6                |             |
|                                |                         | 2F7.11Y-Stairwell/Elevator               |                   |           | 75 SF    | 2          | 6                |             |
|                                |                         | 2F7.11Z-Small Hallway                    |                   |           | 80 SF    | 2          | 6                |             |
|                                |                         | 2F7.11AA-Hall to Main Hallway            |                   |           | 441 SF   | 2          | 6                |             |
|                                |                         | 2F7.11AB-Storage                         |                   |           | 133 SF   | 2          | 6                |             |
|                                |                         | 2F7.11AD-History Storage                 |                   |           | 1320 SF  | 2          | 6                |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description   | Homogeneous Area ID No. | Room ID No. & Location             | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|--------------------------------|-------------------------|------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Plaster Ceiling - White (cont) | 9 (cont)                | 2F7.11AE-Small Conference          |                   |           | 363 SF   | 2          | 6                |             |
|                                |                         | 2F7.11AF-Children's Book Storage   |                   |           | 1408 SF  | 2          | 6                |             |
|                                |                         | 2F7.11AG-Picture Book Storage      |                   |           | 522 SF   | 2          | 6                |             |
|                                |                         | 2F7.11AH-Staff Stairwell           |                   |           | 133 SF   | 2          | 6                |             |
|                                |                         | 2F7.11AI-Elevator Foyer            |                   |           | 96 SF    | 2          | 6                |             |
|                                |                         | 2F7.11AJ-Outreach Offices          |                   |           | 1796 SF  | 2          | 6                |             |
|                                |                         | 2F7.11AK-Outreach Manager's Office |                   |           | 165 SF   | 2          | 6                |             |
|                                |                         | 3F7.11A-Entry                      |                   |           | 713 SF   | 2          | 6                |             |
|                                |                         | 3F7.11B-Hallway                    |                   |           | 1680 SF  | 2          | 6                |             |
|                                |                         | 3F7.11C-Stairwell                  |                   |           | 75 SF    | 2          | 6                |             |
|                                |                         | 3F7.11D-Auditorium                 |                   |           | 24 SF    | 2          | 6                |             |
|                                |                         | 3F7.11E-Mechanical Room            |                   |           | 40 SF    | 2          | 6                |             |
|                                |                         | 3F7.11F-Projection Room            |                   |           | 352 SF   | 2          | 6                |             |
|                                |                         | 3F7.11G-Serving Area               |                   |           | 77 SF    | 2          | 6                |             |
|                                |                         | 3F7.11J-Storage Room               |                   |           | 32 SF    | 2          | 6                |             |
|                                |                         | 3F7.11K-Bathroom                   |                   |           | 20 SF    | 2          | 6                |             |
|                                |                         | 3F7.11L-Office                     |                   |           | 187 SF   | 2          | 6                |             |
|                                |                         | 3F7.11M-Office                     |                   |           | 210 SF   | 2          | 6                |             |
|                                |                         | 3F7.11N-Office                     |                   |           | 240 SF   | 2          | 6                |             |
|                                |                         | 3F7.11O-Bathroom                   |                   |           | 20 SF    | 2          | 6                |             |
|                                |                         | 3F7.11P-Office                     |                   |           | 160 SF   | 2          | 6                |             |
|                                |                         | 3F7.11Q-Hallway                    |                   |           | 300 SF   | 2          | 6                |             |
|                                |                         | 3F7.11R-Personnel Office           |                   |           | 510 SF   | 2          | 6                |             |
|                                |                         | 3F7.11S-File Storage               |                   |           | 91 SF    | 2          | 6                |             |
|                                |                         | 3F7.11T-Bathroom/Storage           |                   |           | 25 SF    | 2          | 6                |             |
|                                |                         | 3F7.11U-Personnel Manager's Office |                   |           | 306 SF   | 2          | 6                |             |
|                                |                         | 3F7.11V-Machine Room               |                   |           | 229 SF   | 2          | 6                |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description   | Homogeneous Area ID No. | Room ID No. & Location                            | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|--------------------------------|-------------------------|---------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Plaster Ceiling - White (cont) | 9 (cont)                | 3F7.11W-Reception - Board of Directors            |                   |           | 154 SF   | 2          | 6                |             |
|                                |                         | 3F7.11X-Board of Directors' Meeting Room          |                   |           | 660 SF   | 2          | 6                |             |
|                                |                         | 3F7.11Y-Director's Office                         |                   |           | 238 SF   | 2          | 6                |             |
|                                |                         | 3F7.11Z-Bathroom                                  |                   |           | 28 SF    | 2          | 6                |             |
|                                |                         | 3F7.11AA-Small Meeting Room                       |                   |           | 182 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AB-Office                                   |                   |           | 252 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AC-Office                                   |                   |           | 375 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AD-Small Office                             |                   |           | 160 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AE-Office                                   |                   |           | 210 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AF-Office                                   |                   |           | 420 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AG-Storage Closet                           |                   |           | 45 SF    | 2          | 6                |             |
|                                |                         | 3F7.11AH-Office-Assistant Director for Technology |                   |           | 182 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AI-Men's Bath/Locker Room                   |                   |           | 293 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AJ-Janitor Closet                           |                   |           | 25 SF    | 2          | 6                |             |
|                                |                         | 3F7.11AK-Lounge                                   |                   |           | 504 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AL-Ladies Locker Room/Bath                  |                   |           | 542 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AM-Dining Room                              |                   |           | 408 SF   | 3          | 5                |             |
|                                |                         | 3F7.11AP-Stairwell/Elevator                       |                   |           | 44 SF    | 2          | 6                |             |
|                                |                         | 3F7.11AR-Hallway                                  |                   |           | 859 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AT-Offices                                  |                   |           | 300 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AU-"Friends" Office                         |                   |           | 380 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AY-Office                                   |                   |           | 196 SF   | 2          | 6                |             |
|                                |                         | 3F7.11AZ-Office/Reception                         |                   |           | 165 SF   | 2          | 6                |             |
|                                |                         | 3F7.11BA-Work/Copy Room                           |                   |           | 493 SF   | 2          | 6                |             |
|                                |                         | 3F7.11BB-"Development/Photo" Room                 |                   |           | 299 SF   | 2          | 6                |             |
|                                |                         | 3F7.11BC-Storeroom                                |                   |           | 98 SF    | 2          | 6                |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

**Date Inspected:** 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| <u>Homogeneous Area Description</u>                        | <u>Homogeneous Area ID No.</u> | <u>Room ID No. &amp; Location</u>                                                                                                                                                 | <u>Tested or Assumed</u> | <u>ACM (Y/N)</u> | <u>Quantity</u>                                        | <u>AHERA Rank</u>               | <u>Removal Priority</u>         | <u>Date Abated</u> |
|------------------------------------------------------------|--------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|------------------|--------------------------------------------------------|---------------------------------|---------------------------------|--------------------|
| Plaster Ceiling - White (cont)                             | 9 (cont)                       | 3F7.11BD-Office<br>3F7.11BE-Stairwell<br>3F7.11BF-Custodial Closet<br>3F7.11BG-Men's Room<br>3F7.11BH-Ladies Room<br>3F7.11BI-Stairwell                                           |                          |                  | 132 SF<br>40 SF<br>16 SF<br>72 SF<br>144 SF<br>158 SF  | 2<br>2<br>2<br>2<br>2<br>2      | 6<br>6<br>6<br>6<br>6<br>6      |                    |
|                                                            |                                | <b>Total:</b>                                                                                                                                                                     |                          |                  | <b>34824 SF</b>                                        |                                 |                                 |                    |
| Duct Caulk - Grey (Hard)                                   | 013B                           | US7.11D-Elevator Mechanical Room<br>7.11H-Shipping Stockroom                                                                                                                      | Assumed                  |                  | 20 LF<br>130 LF<br>150 LF                              | 2<br>2                          | 6<br>6                          |                    |
|                                                            |                                | <b>Total:</b>                                                                                                                                                                     |                          |                  |                                                        |                                 |                                 |                    |
| Corrugated Paper (air cell) Pipe Insulation                | 001                            | 7.11F-Storage<br>P7.11A-Penthouse - "L"                                                                                                                                           | Assumed                  |                  | 15 LF<br>70 LF<br>85 LF                                | 2<br>2                          | 6<br>6                          |                    |
|                                                            |                                | <b>Total:</b>                                                                                                                                                                     |                          |                  |                                                        |                                 |                                 |                    |
| Elbow/Fittings/Tees & etc. White Mud                       | 009                            | 3F7.11E-Mechanical Room                                                                                                                                                           | Assumed                  |                  | 8 LF<br>8 LF                                           | 2                               | 6                               |                    |
|                                                            |                                | <b>Total:</b>                                                                                                                                                                     |                          |                  |                                                        |                                 |                                 |                    |
| Flexible Fabric Joints (vibration-dampening cloth) - Black | 0030                           | US7.11A-Upper Stack<br>7.11AA-Break Room<br>7.11H-Shipping Stockroom<br>7.11N-Small Mechanical Room<br>3F7.11E-Mechanical Room<br>P7.11A-Penthouse - "L"<br>P7.11E-Main Penthouse | Assumed                  |                  | 11 LF<br>5 LF<br>8 LF<br>4 LF<br>8 LF<br>15 LF<br>6 LF | 2<br>2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6 |                    |
|                                                            |                                | <b>Total:</b>                                                                                                                                                                     |                          |                  | <b>57 LF</b>                                           |                                 |                                 |                    |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                        | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                                                                                                                                                                                                                             | Tested or Assumed | ACM (Y/N) | Quantity                                                                                                                    | AHERA Rank                                                            | Removal Priority                                                      | Date Abated |
|-----------------------------------------------------|-------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|-----------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|-----------------------------------------------------------------------|-------------|
| Grey Fibrous Panels/Sheets Duct Insulation          | 0047A                   | 3F7.11A-Dining Room                                                                                                                                                                                                                                                                                                                                                                                                | Assumed           | Total:    | 50 LF<br>50 LF                                                                                                              | 2                                                                     | 6                                                                     |             |
| White Paper Pipe Insulation - Fibrous               | 0049                    | 7.11F-Hall                                                                                                                                                                                                                                                                                                                                                                                                         | Assumed           | Total:    | 75 LF<br>75 LF                                                                                                              | 2                                                                     | 6                                                                     |             |
| Brown/Grey Layered Paper Pipe Insulation with Hairs | 0050                    | 7.11G-Hallway                                                                                                                                                                                                                                                                                                                                                                                                      | Assumed           | Total:    | 70 LF<br>70 LF                                                                                                              | 2                                                                     | 6                                                                     |             |
| Felt Paper(Over Cork Pipe Insulation)               | 004                     | P7.11E- Main Penthouse                                                                                                                                                                                                                                                                                                                                                                                             | Assumed           | Total:    | 30 LF<br>30 LF                                                                                                              | 2                                                                     | 6                                                                     |             |
| Brown Cove Molding                                  | 38                      | 7.11K-Men's/Women's Handicap Bathroom<br>7.11L-Ladies Room<br>7.11V-User Support<br>7.11W-Office<br>M7.11B-Central Library Office Area<br>M7.11I-Interlibrary Loan Area<br>M7.11K-Interlibrary Office<br>1F7.11B-Periodicals/Children's (North Library)<br>1F7.11N-Conference Room (East Side)<br>1F7.11V-Literacy<br>2F7.11I-Local History/Genealogy Library<br>2F7.11J-Genealogy Library<br>2F7.11L-File Storage | Assumed           |           | 29 LF<br><br>25 LF<br>159 LF<br>44 LF<br>47 LF<br>15 LF<br>24 LF<br>290 LF<br><br>12 LF<br>35 LF<br>78 LF<br>4 LF<br>113 LF | 2<br><br>2<br>2<br>2<br>2<br>2<br>2<br>2<br><br>2<br>2<br>2<br>2<br>2 | 6<br><br>6<br>6<br>6<br>6<br>6<br>6<br>6<br><br>6<br>6<br>6<br>6<br>6 |             |



Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description    | Homogeneous Area ID No. | Room ID No. & Location             | Tested or Assumed | ACM (Y/N) | Quantity | ASHERA Rank | Removal Priority | Date Abated |
|---------------------------------|-------------------------|------------------------------------|-------------------|-----------|----------|-------------|------------------|-------------|
| Brown Cove Molding (cont)       | 38 (cont)               | 2F7.11M-File Storage               |                   |           | 7 LF     | 2           | 6                |             |
|                                 |                         | 2F7.11S-Men's Bath                 |                   |           | 25 LF    | 2           | 6                |             |
|                                 |                         | 2F7.11U-Local History Storage      |                   |           | 19 LF    | 2           | 6                |             |
|                                 |                         | 2F7.11W-Room 235                   |                   |           | 60 LF    | 2           | 6                |             |
|                                 |                         | 3F7.11I-Office                     |                   |           | 9 LF     | 2           | 6                |             |
|                                 |                         | 3F7.11R-Personnel Office           |                   |           | 20 LF    | 2           | 6                |             |
|                                 |                         | 3F7.11S-File Storage               |                   |           | 20 LF    | 2           | 6                |             |
|                                 |                         | 3F7.11U-Personnel Manager's Office |                   |           | 17 LF    | 2           | 6                |             |
|                                 |                         | 3F7.11V-Machine Room               |                   |           | 17 LF    | 2           | 6                |             |
|                                 |                         | 3F7.11AT-Offices                   |                   |           | 58 LF    | 2           | 6                |             |
| Brown Cove Mastic               | 38A                     | 3F7.11AU-"Friends" Office          |                   |           | 78 LF    | 2           | 6                |             |
|                                 |                         | 3F7.11AY-Office                    |                   |           | 53 LF    | 2           | 6                |             |
|                                 |                         | Total:                             |                   |           | 1258 LF  |             |                  |             |
|                                 |                         |                                    | Assumed           |           |          |             |                  |             |
|                                 |                         | 7.11F-Storage                      |                   |           | 57 LF    | 2           | 6                |             |
|                                 |                         | 7.11G-Hallway                      |                   |           | 85 LF    | 2           | 6                |             |
|                                 |                         | 7.11R-Computer Room                |                   |           | 20 LF    | 2           | 6                |             |
|                                 |                         | 2F7.11AC-Book Storage              |                   |           | 30 LF    | 2           | 6                |             |
|                                 |                         | 2F7.11AK-Outreach Manager's Office |                   |           | 11 LF    | 2           | 6                |             |
|                                 |                         | Total:                             |                   |           | 203 LF   |             |                  |             |
| Drywall Ceiling                 | 42                      | 1F7.11K-Lobby Elevator Hallway     |                   |           | 138 SF   | 2           | 6                |             |
|                                 |                         | Total:                             | Assumed           |           | 138 SF   |             |                  |             |
| Textured Stucco/Drywall Ceiling | 42A                     | 3F7.11D-Auditorium                 |                   |           | 300 SF   | 2           | 6                |             |
|                                 |                         | Total:                             | Assumed           |           | 300 SF   |             |                  |             |

# Asbestos Inspection Summary Table

Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                            | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|---------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Black Cove Molding           | 44                      | 7.11M-Operations                                  | Assumed           |           | 110 LF   | 2          | 6                |             |
|                              |                         | 7.11P-Office                                      |                   |           | 60 LF    | 2          | 6                |             |
|                              |                         | 7.11Q-Office                                      |                   |           | 55 LF    | 2          | 6                |             |
|                              |                         | 7.11S-Storage                                     |                   |           | 45 LF    | 2          | 6                |             |
|                              |                         | 1F7.11E-Fiction Area (Quiet Room, Listening Room) |                   |           | 120 LF   | 2          | 6                |             |
|                              |                         | 1F7.11K-Lobby Elevator Hallway                    |                   |           | 61 LF    | 2          | 6                |             |
|                              |                         | 2F7.11AC-Book Storage                             |                   |           | 30 LF    | 2          | 6                |             |
|                              |                         | 2F7.11AK-Outreach Manager's Office                |                   |           | 11 LF    | 2          | 6                |             |
|                              |                         |                                                   |                   | Total:    | 492 LF   |            |                  |             |
|                              |                         |                                                   |                   |           |          |            |                  |             |
| White Cove Mastic            | 44A                     | 7.11K-Men's/Women's Handicap Bathroom             | Assumed           |           | 29 LF    | 2          | 6                |             |
|                              |                         | 7.11L-Ladies Room                                 |                   |           | 25 LF    | 2          | 6                |             |
|                              |                         | 7.11M-Operations                                  |                   |           | 110 LF   | 2          | 6                |             |
|                              |                         | 7.11N- Small Mechanical Room                      |                   |           | 3 LF     | 2          | 6                |             |
|                              |                         | 7.11P-Office                                      |                   |           | 60 LF    | 2          | 6                |             |
|                              |                         | 7.11Q-Office                                      |                   |           | 55 LF    | 2          | 6                |             |
|                              |                         | 7.11S-Storage                                     |                   |           | 45 LF    | 2          | 6                |             |
|                              |                         | 7.11X-Staging Area                                |                   |           | 20 LF    | 2          | 6                |             |
|                              |                         | 7.11Z-Office                                      |                   |           | 65 LF    | 2          | 6                |             |
|                              |                         | M7.11B-Central Library Office Area                |                   |           | 47 LF    | 2          | 6                |             |
|                              |                         | M7.11I-Interlibrary Loan Area                     |                   |           | 15 LF    | 2          | 6                |             |
|                              |                         | M7.11K-Interlibrary Office                        |                   |           | 24 LF    | 2          | 6                |             |
|                              |                         | 1F7.11B-Periodicals/Children's (North Library)    |                   |           | 290 LF   | 2          | 6                |             |
|                              |                         | 1F7.11D-Conference Room                           |                   |           | 19 LF    | 2          | 6                |             |
|                              |                         |                                                   |                   |           |          |            |                  |             |
|                              |                         |                                                   |                   |           |          |            |                  |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description         | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                                                                                                                  | Tested or Assumed | ACM (Y/N) | Quantity                                                                                        | AHERA Rank                                          | Removal Priority                                    | Date Abated |
|--------------------------------------|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|-------------------------------------------------------------------------------------------------|-----------------------------------------------------|-----------------------------------------------------|-------------|
| White Cove Mastic (cont.)            | 44A (cont.)             | 1F7.11E-Fiction Area (Quiet Room, Listening Room)<br>1F7.11F-Hallway<br>1F7.11K-Lobby Elevator Hallway<br>1F7.11L-Hallway<br>1F7.11N-Conference Room (East Side)<br>1F7.11O-Elevator Balcony<br>1F7.11V-Literacy<br>1F7.11W-Stairwell Foyer<br>1F7.11X-Women's Room<br>1F7.11Y-Stairwell to Upper Stack |                   |           | 120 LF<br>40 LF<br>61 LF<br>8 LF<br>12 LF<br>25 LF<br>35 LF<br>4 LF<br>28 LF<br>3 LF<br>1143 LF | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6 |             |
| Black Cove Molding - 3" Wide         | 44CM                    | 7.11R-Computer Room                                                                                                                                                                                                                                                                                     | Assumed           | Total:    | 20 LF<br>20 LF                                                                                  | 2<br>2                                              | 6<br>6                                              |             |
| Black Cove Molding - Hard/Nonrubbery | 44CMA                   | 1F7.11B-Periodicals/Children's (North Library)<br>1F7.11C-Fiction/Non-Fiction Area (South Library)<br>1F7.11E-Fiction Area (Quiet Room, Listening Room)                                                                                                                                                 | Assumed           |           | 79 LF<br>1058 LF<br>150 LF<br>1287 LF                                                           | 2<br>2<br>2<br>2                                    | 6<br>6<br>6<br>6                                    |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                                                                                                                                                                                                                        | Tested or Assumed | ACM (Y/N) | Quantity                                                                                                                           | AHERA Rank                                                              | Removal Priority                                                        | Date Abated |
|------------------------------|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|-------------------------------------------------------------------------|-------------|
| Yellow Mastic                | 47A                     | 7.11AA-Break Room                                                                                                                                                                                                                                                                                                                                                                                             | Assumed           | Total:    | 55 LF<br>55 LF                                                                                                                     | 2                                                                       | 6                                                                       |             |
| Cream Cove Mastic            | 48A                     | 2F7.11I-Local History/Genealogy Library<br>2F7.11J-Genealogy Library<br>2F7.11L-File Storage<br>2F7.11M-File Storage<br>2F7.11Q-Office - Local History<br>2F7.11R-Local History Offices<br>2F7.11S-Men's Bath<br>2F7.11U-Local History Storage<br>2F7.11V-Small Hall<br>2F7.11X-Small Office<br>2F7.11Z-Small Hallway<br>2F7.11AA-Hall to Main Hallway<br>2F7.11AD-History Storage<br>2F7.11AI-Elevator Foyer | Assumed           |           | 78 LF<br>4 LF<br>113 LF<br>7 LF<br>29 LF<br>7 LF<br>25 LF<br>19 LF<br>36 LF<br>24 LF<br>42 LF<br>80 LF<br>32 LF<br>29 LF<br>525 LF | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6 |             |
| Tan Cove Mastic              | 49A                     | 7.11V-User Support<br>7.11W-Office<br>2F7.11C-Hallway - 2nd Floor<br>2F7.11G-Secretarial - Historian<br>2F7.11K-Hallway<br>2F7.11P-Hallway (Rear)<br>3F7.11D-Auditorium<br>3F7.11I-Office                                                                                                                                                                                                                     | Assumed           |           | 159 LF<br>44 LF<br>198 LF<br>33 LF<br>100 LF<br>78 LF<br>27 LF<br>9 LF                                                             | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2                                    | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6                                    |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                              | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|-----------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Tan Cove Mastic              | 49A (con't)             | 3F7.11L-Office                                      |                   |           | 9 LF     | 2          | 6                |             |
|                              |                         | 3F7.11M-Office                                      |                   |           | 9 LF     | 2          | 6                |             |
|                              |                         | 3F7.11R-Personnel Office                            |                   |           | 20 LF    | 2          | 6                |             |
|                              |                         | 3F7.11S-File Storage                                |                   |           | 20 LF    | 2          | 6                |             |
|                              |                         | 3F7.11U-Personnel Manager's Office                  |                   |           | 17 LF    | 2          | 6                |             |
|                              |                         | 3F7.11V-Machine Room                                |                   |           | 17 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AC-Office                                     |                   |           | 18 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AD-Small Office                               |                   |           | 56 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AE-Office                                     |                   |           | 12 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AF-Office                                     |                   |           | 24 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AG-Storage Closet                             |                   |           | 12 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AH-Office - Assistant Director for Technology |                   |           | 12 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AK-Lounge                                     |                   |           | 12 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AT-Offices                                    |                   |           | 58 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AU-"Friends" Office                           |                   |           | 78 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AV-Acquisitions Office                        |                   |           | 64 LF    | 2          | 6                |             |
| Grey Cove Molding            | 58                      | 3F7.11AW-Acquisitions Office                        |                   |           | 94 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AX-Office                                     |                   |           | 69 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AY-Office                                     |                   |           | 53 LF    | 2          | 6                |             |
|                              |                         | 3F7.11BA-Work/Copy Room                             |                   |           | 5 LF     | 2          | 6                |             |
|                              |                         | Total:                                              |                   |           | 1307 LF  |            |                  |             |
|                              |                         | Assumed                                             |                   |           |          |            |                  |             |
|                              |                         | 3F7.11AV-Acquisitions Office                        |                   |           | 64 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AW-Acquisitions Office                        |                   |           | 94 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AX-Office                                     |                   |           | 69 LF    | 2          | 6                |             |
|                              |                         | Total:                                              |                   |           | 227 LF   |            |                  |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                              | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|-----------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Maroon Cove Molding          | 70                      | 7.11Z-Office                                        | Assumed           |           | 65 LF    | 2          | 6                |             |
|                              |                         | 1F7.11D-Conference Room                             |                   |           | 19 LF    | 2          | 6                |             |
|                              |                         | 2F7.11C-Hallway - 2nd Floor                         |                   |           | 198 LF   | 2          | 6                |             |
|                              |                         | 2F7.11G-Secretarial - Historian                     |                   |           | 33 LF    | 2          | 6                |             |
|                              |                         | 2F7.11K-Hallway                                     |                   |           | 100 LF   | 2          | 6                |             |
|                              |                         | 2F7.11P-Hallway (Rear)                              |                   |           | 78 LF    | 2          | 6                |             |
|                              |                         | 2F7.11Q-Office - Local History                      |                   |           | 29 LF    | 2          | 6                |             |
|                              |                         | 2F7.11R-Local History Offices                       |                   |           | 7 LF     | 2          | 6                |             |
|                              |                         | 2F7.11V-Small Hall                                  |                   |           | 36 LF    | 2          | 6                |             |
|                              |                         | 2F7.11X-Small Office                                |                   |           | 24 LF    | 2          | 6                |             |
|                              |                         | 2F7.11Z-Small Hallway                               |                   |           | 42 LF    | 2          | 6                |             |
|                              |                         | 2F7.11AA-Hall to Main Hallway                       |                   |           | 80 LF    | 2          | 6                |             |
|                              |                         | 2F7.11AD-History Storage                            |                   |           | 32 LF    | 2          | 6                |             |
|                              |                         | 2F7.11AI-Elevator Foyer                             |                   |           | 32 LF    | 2          | 6                |             |
|                              |                         | 3F7.11D-Auditorium                                  |                   |           | 27 LF    | 2          | 6                |             |
|                              |                         | 3F7.11L-Office                                      |                   |           | 9 LF     | 2          | 6                |             |
|                              |                         | 3F7.11M-Office                                      |                   |           | 9 LF     | 2          | 6                |             |
|                              |                         | 3F7.11AC-Office                                     |                   |           | 18 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AD-Small Office                               |                   |           | 56 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AE-Office                                     |                   |           | 12 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AF-Office                                     |                   |           | 24 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AG-Storage Closet                             |                   |           | 12 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AH-Office - Assistant Director for Technology |                   |           | 12 LF    | 2          | 6                |             |
|                              |                         | 3F7.11AK-Lounge                                     |                   |           | 12 LF    | 2          | 6                |             |
|                              |                         | 3F7.11BA-Work/Copy Room                             |                   |           | 5 LF     | 2          | 6                |             |
| Total:                       |                         |                                                     |                   |           | 971 LF   |            |                  |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

**Date Inspected:** 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description         | Homogeneous Area ID No. | Room ID No. & Location                                                         | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|--------------------------------------|-------------------------|--------------------------------------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Tan Cove Molding                     | 73                      | 7.11AA-Break Room                                                              | Assumed           |           | 55 LF    | 2          | 6                |             |
|                                      |                         | 7.11F-Storage                                                                  |                   |           | 57 LF    | 2          | 6                |             |
|                                      |                         | 7.11G-Hallway                                                                  |                   |           | 85 LF    | 2          | 6                |             |
|                                      |                         | 7.11X-Staging Area                                                             |                   |           | 20 LF    | 2          | 6                |             |
|                                      |                         | 1F7.11F-Hallway                                                                |                   |           | 40 LF    | 2          | 6                |             |
|                                      |                         | 1F7.11L-Hallway                                                                |                   |           | 8 LF     | 2          | 6                |             |
|                                      |                         | 1F7.11O-Elevator Balcony                                                       |                   |           | 25 LF    | 2          | 6                |             |
|                                      |                         | 1F7.11W-Stairwell Foyer                                                        |                   |           | 4 LF     | 2          | 6                |             |
|                                      |                         | 1F7.11X-Women's Room                                                           |                   |           | 28 LF    | 2          | 6                |             |
|                                      |                         | 1F7.11Y-Stairwell to Upper Stack                                               |                   |           | 3 LF     | 2          | 6                |             |
|                                      |                         | Total:                                                                         |                   |           | 325 LF   |            |                  |             |
| Greenish Tan Cove Molding            | 89                      | 7.11N-Small Mechanical Room                                                    | Assumed           |           | 3 LF     | 2          | 6                |             |
|                                      |                         |                                                                                |                   |           | 3 LF     |            |                  |             |
|                                      |                         | Total:                                                                         |                   |           |          |            |                  |             |
| 6" x 18" Corklike Tiles              | 90                      | M7.11F-Science Balcony<br>1F7.11E-Fiction Area (Quiet Room,<br>Listening Room) | Assumed           |           | 491 SF   | 2          | 6                |             |
|                                      |                         |                                                                                |                   |           | 310 SF   | 2          | 6                |             |
|                                      |                         |                                                                                |                   |           | 801 SF   |            |                  |             |
|                                      |                         | Total:                                                                         |                   |           |          |            |                  |             |
| Floor Tile 12" x 12" - Oatmeal-Brown | 111                     | 3F7.11AZ-Office/Reception<br>3F7.11BA-Work/Copy Room<br>3F7.11BD-Office        | Assumed           |           | 165 SF   | 2          | 6                |             |
|                                      |                         |                                                                                |                   |           | 493 SF   | 2          | 6                |             |
|                                      |                         |                                                                                |                   |           | 132 SF   | 2          | 6                |             |
|                                      |                         |                                                                                |                   |           | 790 SF   |            |                  |             |
|                                      |                         | Total:                                                                         |                   |           |          |            |                  |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

**Date Inspected:** 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description         | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                                                                                                                                       | Tested or Assumed | ACM (Y/N) | Quantity                                                                                                                                 | AHERA Rank                                                    | Removal Priority                                         | Date Abated |
|--------------------------------------|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|----------------------------------------------------------|-------------|
| Floor Tile 12" x 12" - Grey-Oatmeal  | 117                     | 3F7.11AV-Acquisitions Office<br>3F7.11AW-Acquisitions Office<br>3F7.11AX-Office<br>3F7.11AY-Office                                                                                                                                                                                                                           | Assumed           |           | 429 SF<br>660 SF<br>432 SF<br>196 SF<br>Total: 1717 SF                                                                                   | 2<br>2<br>2<br>2                                              | 6<br>6<br>6<br>6                                         |             |
| Unknown Mastic                       | 117M                    | 3F7.11AV-Acquisitions Office<br>3F7.11AW-Acquisitions Office<br>3F7.11AX-Office<br>3F7.11AY-Office                                                                                                                                                                                                                           | Assumed           |           | 429 SF<br>660 SF<br>432 SF<br>196 SF<br>Total: 1717 SF                                                                                   | 2<br>2<br>2<br>2                                              | 6<br>6<br>6<br>6                                         |             |
| Floor Tile 12" x 12" - Cream Oatmeal | 124                     | 1F7.11B-Periodicals/Children's (North Library)<br>2F7.11L-File Storage<br>2F7.11M-File Storage<br>2F7.11O-Office<br>2F7.11S-Men's Bath<br>2F7.11T-Local History Vault<br>2F7.11U-Local History Storage<br>2F7.11V-Small Hall<br>2F7.11W-Room 235<br>2F7.11X-Small Office<br>3F7.11T-Bathroom/Storage<br>3F7.11V-Machine Room | Assumed           |           | 150 SF<br><br>885 SF<br>377 SF<br>260 SF<br>144 SF<br>154 SF<br>616 SF<br>10 SF<br>2112 SF<br>88 SF<br>25 SF<br>229 SF<br>Total: 5050 SF | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6 |             |



Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

**Date Inspected:** 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                           | Homogeneous Area ID No. | Room ID No. & Location                | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------------------------------------------------|-------------------------|---------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Floor Tile 12" x 12" - Oatmeal-Brown with Teal, Purple & Maroon Specks | 111A                    | 7.11AA-Break Room                     | Assumed           |           | 206 SF   | 2          | 6                |             |
|                                                                        |                         | 7.11K-Men's/Women's Handicap Bathroom |                   |           | 72 SF    | 2          | 6                |             |
|                                                                        |                         | 7.11L-Ladies Room                     |                   |           | 54 SF    | 2          | 6                |             |
|                                                                        |                         | M7.11G-Reference Area                 |                   |           | 320 SF   | 2          | 6                |             |
|                                                                        |                         | 1F7.11A-Repair/Inspection Area        |                   |           | 943 SF   | 2          | 6                |             |
|                                                                        |                         | 1F7.11L-Hallway                       |                   |           | 231 SF   | 2          | 6                |             |
|                                                                        |                         | 1F7.11O-Elevator Balcony              |                   |           | 99 SF    | 2          | 6                |             |
|                                                                        |                         | 1F7.11W-Stairwell Foyer               |                   |           | 88 SF    | 2          | 6                |             |
|                                                                        |                         | 1F7.11X-Women's Room                  |                   |           | 35 SF    | 2          | 6                |             |
|                                                                        |                         | Total:                                |                   |           | 2048 SF  |            |                  |             |
| Yellow Mastic                                                          | 111AM                   | 7.11AA-Break Room                     | Assumed           |           | 206 SF   | 2          | 6                |             |
|                                                                        |                         | 7.11K-Men's/Women's Handicap Bathroom |                   |           | 72 SF    | 2          | 6                |             |
|                                                                        |                         | 7.11L-Ladies Room                     |                   |           | 54 SF    | 2          | 6                |             |
|                                                                        |                         | M7.11G-Reference Area                 |                   |           | 320 SF   | 2          | 6                |             |
|                                                                        |                         | 1F7.11A-Repair/Inspection Area        |                   |           | 943 SF   | 2          | 6                |             |
|                                                                        |                         | 1F7.11L-Hallway                       |                   |           | 231 SF   | 2          | 6                |             |
|                                                                        |                         | 1F7.11O-Elevator Balcony              |                   |           | 99 SF    | 2          | 6                |             |
|                                                                        |                         | 1F7.11W-Stairwell Foyer               |                   |           | 88 SF    | 2          | 6                |             |
|                                                                        |                         | 1F7.11X-Women's Room                  |                   |           | 35 SF    | 2          | 6                |             |
|                                                                        |                         | Total:                                |                   |           | 2048 SF  |            |                  |             |
| Black Mastic                                                           | A111M                   | 3F7.11AZ-Office/Reception             | Assumed           |           | 165 SF   | 2          | 6                |             |
|                                                                        |                         | 3F7.11BA-Work/Copy Room               |                   |           | 493 SF   | 2          | 6                |             |
|                                                                        |                         | 3F7.11BD-Office                       |                   |           | 132 SF   | 2          | 6                |             |
|                                                                        |                         | Total:                                |                   |           | 790 SF   |            |                  |             |

# Asbestos Inspection Summary Table

Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area ID No. | Homogeneous Area Description | Room ID No. & Location                         | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|-------------------------|------------------------------|------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| 124A                    | Black Mastic                 | 1F7.11B-Periodicals/Children's (North Library) | Assumed           |           | 150 SF   | 2          | 6                |             |
|                         |                              | 2F7.11L-File Storage                           |                   |           | 885 SF   | 2          | 6                |             |
|                         |                              | 2F7.11M-File Storage                           |                   |           | 377 SF   | 2          | 6                |             |
|                         |                              | 2F7.11O-Office                                 |                   |           | 260 SF   | 2          | 6                |             |
|                         |                              | 2F7.11S-Men's Bath                             |                   |           | 144 SF   | 2          | 6                |             |
|                         |                              | 2F7.11T-Local History Vault                    |                   |           | 154 SF   | 2          | 6                |             |
|                         |                              | 2F7.11U-Local History Storage                  |                   |           | 616 SF   | 2          | 6                |             |
|                         |                              | 2F7.11V-Small Hall                             |                   |           | 10 SF    | 2          | 6                |             |
|                         |                              | 2F7.11W-Room 235                               |                   |           | 2112 SF  | 2          | 6                |             |
|                         |                              | 2F7.11X-Small Office                           |                   |           | 88 SF    | 2          | 6                |             |
|                         |                              | 3F7.11T-Bathroom/Storage                       |                   |           | 25 SF    | 2          | 6                |             |
|                         |                              | 3F7.11V-Machine Room                           |                   |           | 229 SF   | 2          | 6                |             |
|                         |                              |                                                |                   | Total:    | 5050 SF  |            |                  |             |
| 148                     | Carpet                       | 1F7.11D-Conference Room                        | Assumed           |           | 202 SF   | 2          | 6                |             |
|                         |                              | 1F7.11V-Literacy                               |                   |           | 104 SF   | 2          | 6                |             |
|                         |                              | 2F7.11E-Historian's Office                     |                   |           | 224 SF   | 2          | 6                |             |
|                         |                              | 2F7.11G-Secretarial - Historian                |                   |           | 144 SF   | 2          | 6                |             |
|                         |                              | 2F7.11H-Storage                                |                   |           | 189 SF   | 2          | 6                |             |
|                         |                              | 2F7.11O-Office                                 |                   |           | 260 SF   | 2          | 6                |             |
|                         |                              | 2F7.11Q-Office - Local History                 |                   |           | 180 SF   | 2          | 6                |             |
|                         |                              | 2F7.11R-Local History Offices                  |                   |           | 602 SF   | 2          | 6                |             |
|                         |                              | 2F7.11X-Small Office                           |                   |           | 88 SF    | 2          | 6                |             |
|                         |                              | 2F7.11AB-Storage                               |                   |           | 133 SF   | 2          | 6                |             |
|                         |                              | 2F7.11AJ-Outreach Offices                      |                   |           | 24 SF    | 2          | 6                |             |
|                         |                              | 3F7.11H-Reception Area                         |                   |           | 154 SF   | 2          | 6                |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                              | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|-----------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Carpet (con't)               | 148 (con't)             | 3F7.11I-Office                                      |                   |           | 662 SF   | 2          | 6                |             |
|                              |                         | 3F7.11J-Storage Room                                |                   |           | 32 SF    | 2          | 6                |             |
|                              |                         | 3F7.11K-Bathroom                                    |                   |           | 20 SF    | 2          | 6                |             |
|                              |                         | 3F7.11L-Office                                      |                   |           | 187 SF   | 2          | 6                |             |
|                              |                         | 3F7.11M-Office                                      |                   |           | 210 SF   | 2          | 6                |             |
|                              |                         | 3F7.11N-Office                                      |                   |           | 240 SF   | 2          | 6                |             |
|                              |                         | 3F7.11O-Bathroom                                    |                   |           | 20 SF    | 2          | 6                |             |
|                              |                         | 3F7.11P-Office                                      |                   |           | 160 SF   | 2          | 6                |             |
|                              |                         | 3F7.11R-Personnel Office                            |                   |           | 510 SF   | 2          | 6                |             |
|                              |                         | 3F7.11S-File Storage                                |                   |           | 91 SF    | 2          | 6                |             |
|                              |                         | 3F7.11U-Personnel Manager's Office                  |                   |           | 306 SF   | 2          | 6                |             |
|                              |                         | 3F7.11W-Reception - Board of Directors              |                   |           | 154 SF   | 2          | 6                |             |
|                              |                         | 3F7.11Y-Director's Office                           |                   |           | 238 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AA-Small Meeting Room                         |                   |           | 182 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AB-Office                                     |                   |           | 252 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AC-Office                                     |                   |           | 375 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AD-Office                                     |                   |           | 160 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AE-Office                                     |                   |           | 210 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AF-Office                                     |                   |           | 420 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AG-Storage Closet                             |                   |           | 45 SF    | 2          | 6                |             |
|                              |                         | 3F7.11AH-Office - Assistant Director for Technology |                   |           | 182 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AK-Lounge                                     |                   |           | 504 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AL-Ladies Locker Room/Bath                    |                   |           | 360 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AT-Offices                                    |                   |           | 300 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AU-"Friends" Office                           |                   |           | 380 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AY-Office                                     |                   |           | 196 SF   | 2          | 6                |             |

# Asbestos Inspection Summary Table

Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                            | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|---------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Carpet (con't)               | 148 (con't)             | 3F7.11AZ-Office/Reception                         |                   |           | 165 SF   | 2          | 6                |             |
|                              |                         | 3F7.11BB-"Development/Photo" Room                 |                   |           | 947 SF   | 2          | 6                |             |
|                              |                         | 3F7.11BD-Office                                   |                   |           | 132 SF   | 2          | 6                |             |
|                              |                         |                                                   |                   | Total:    | 9944 SF  |            |                  |             |
| Carpet on Concrete           | 148A                    | 7.11C-Facilities Manager Office                   | Assumed           |           | 211 SF   | 2          | 6                |             |
|                              |                         | 7.11M-Operations                                  |                   |           | 516 SF   | 2          | 6                |             |
|                              |                         | 7.11N-Small Mechanical Room                       |                   |           | 9 SF     | 2          | 6                |             |
|                              |                         | 7.11S-Storage                                     |                   |           | 109 SF   | 2          | 6                |             |
|                              |                         | 7.11Z-Office                                      |                   |           | 296 SF   | 2          | 6                |             |
|                              |                         | 1F7.11B-Periodicals/Children's (North Library)    |                   |           | 3500 SF  | 2          | 6                |             |
|                              |                         | 1F7.11C-Fiction/Non-Fiction Area (South Library)  |                   |           | 5317 SF  | 2          | 6                |             |
|                              |                         | 1F7.11E-Fiction Area (Quiet Room, Listening Room) |                   |           | 2418 SF  | 2          | 6                |             |
|                              |                         | 1F7.11F-Hallway                                   |                   |           | 160 SF   | 2          | 6                |             |
|                              |                         | 1F7.11H-Reading Area                              |                   |           | 6678 SF  | 2          | 6                |             |
|                              |                         | 1F7.11Y-Stairwell to Upper Stack                  |                   |           | 36 SF    | 2          | 6                |             |
|                              |                         | 1F7.11AB-Stairwell to Central Library             |                   |           | 130 SF   | 2          | 6                |             |
|                              |                         | 2F7.11I-Local History/Genealogy Library           |                   |           | 2682 SF  | 2          | 6                |             |
|                              |                         | 2F7.11J-Genealogy Library                         |                   |           | 1472 SF  | 2          | 6                |             |
|                              |                         | 2F7.11AD-History Storage                          |                   |           | 1320 SF  | 2          | 6                |             |
|                              |                         | 2F7.11AE-Small Conference                         |                   |           | 363 SF   | 2          | 6                |             |
|                              |                         | 2F7.11AF-Children's Book Storage                  |                   |           | 1408 SF  | 2          | 6                |             |
|                              |                         | 2F7.11AG-Picture Book Storage                     |                   |           | 522 SF   | 2          | 6                |             |
|                              |                         | 2F7.11AJ-Outreach Offices                         |                   |           | 1772 SF  | 2          | 6                |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                             | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                 | Tested or Assumed | ACM (Y/N) | Quantity                                                                   | AHERA Rank                 | Removal Priority           | Date Abated |
|--------------------------------------------------------------------------|-------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|----------------------------------------------------------------------------|----------------------------|----------------------------|-------------|
| Carpet on Concrete (cont)                                                | 148A (cont)             | 2F7.11AK-Outreach Manager's Office<br>3F7.11D-Auditorium                                                                                                                                               |                   |           | 165 SF<br>1620 SF<br>Total: 30704 SF                                       | 2<br>2                     | 6<br>6                     |             |
| Carpet over Red Claylike Floor<br>Leveler over Concrete                  | 148F                    | 7.11P-Office<br>7.11Q-Office                                                                                                                                                                           | Assumed           |           | 221 SF<br>187 SF<br>Total: 408 SF                                          | 2<br>2                     | 6<br>6                     |             |
| Carpet over Red Claylike Floor<br>Leveler on Paper Mesh over<br>Concrete | 148G                    | 7.11U-Training Room<br>7.11V-User Support<br>7.11W-Office                                                                                                                                              | Assumed           |           | 340 SF<br>966 SF<br>155 SF<br>Total: 1461 SF                               | 2<br>2<br>2                | 6<br>6<br>6                |             |
| Carpet on (Type 90) on Concrete                                          | 148H                    | M7.11A-Literature Manager<br>M7.11B-Central Library Office Area<br>M7.11C-Central Library Office<br>M7.11I-Interlibrary Loan Area<br>M7.11K-Interlibrary Office<br>1F7.11N-Conference Room (East Side) | Assumed           |           | 327 SF<br>591 SF<br>338 SF<br>701 SF<br>220 SF<br>195 SF<br>Total: 2372 SF | 2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6 |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                          | Homogeneous Area ID No. | Room ID No. & Location             | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|-----------------------------------------------------------------------|-------------------------|------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Suspended Acoustical Ceiling Tile<br>2' x 4' White with holes/craters | 162                     | 7.11G-Hallway                      | Assumed           |           | 316 SF   | 2          | 6                |             |
|                                                                       |                         | 7.11M-Operations                   |                   |           | 516 SF   | 2          | 6                |             |
|                                                                       |                         | 7.11P-Office                       |                   |           | 221 SF   | 2          | 6                |             |
|                                                                       |                         | 7.11Q-Office                       |                   |           | 187 SF   | 2          | 6                |             |
|                                                                       |                         | 7.11R-Computer Room                |                   |           | 233 SF   | 2          | 6                |             |
|                                                                       |                         | 3F7.11U-Personnel Manager's Office |                   |           | 306 SF   | 2          | 6                |             |
|                                                                       |                         | 3F7.11V-Machine Room               |                   |           | 204 SF   | 2          | 6                |             |
|                                                                       |                         | Total:                             |                   |           | 1983 SF  |            |                  |             |
| Suspended Acoustical Ceiling Tile<br>2' x 2' White/Bumps - Fiberglass | 171                     | 3F7.11AZ-Office/Reception          | Assumed           |           | 165 SF   | 2          | 6                |             |
|                                                                       |                         | 3F7.11BA-Work/Copy Room            |                   |           | 493 SF   | 2          | 6                |             |
|                                                                       |                         | 3F7.11BD-Office                    |                   |           | 132 SF   | 2          | 6                |             |
|                                                                       |                         | Total:                             |                   |           | 790 SF   |            |                  |             |
| Acoustical Ceiling Tile 2' x 2'<br>White/cratered/holes               | 173                     | 3F7.11AX-Office                    | Assumed           |           | 432 SF   | 2          | 6                |             |
|                                                                       |                         | 3F7.11BB-"Development/Photo" Room  |                   |           | 299 SF   | 2          | 6                |             |
|                                                                       |                         | 3F7.11BH-Ladies Room               |                   |           | 7 SF     | 2          | 6                |             |
|                                                                       |                         | Total:                             |                   |           | 738 SF   |            |                  |             |
| 2' x 2' Suspended Acoustical Tile<br>White with dots                  | A173A                   | 2F7.11AF-Children's Book Storage   | Assumed           |           | 1408 SF  | 2          | 6                |             |
|                                                                       |                         | 3F7.11AY-Office                    |                   |           | 196 SF   | 2          | 6                |             |
|                                                                       |                         | Total:                             |                   |           | 1604 SF  |            |                  |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                                                             | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                                                                                                                                                    | Tested or Assumed | ACM (Y/N) | Quantity                                                                                                                         | AHERA Rank                                                        | Removal Priority                                                  | Date Abated |
|----------------------------------------------------------------------------------------------------------|-------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|----------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|-------------------------------------------------------------------|-------------|
| Suspended Acoustical Tile 12" x 24" White with dots/holes (2 attached 2' x 2' Suspended Acoustical Tile) | 180B                    | M7.11G-Reference Area<br>1F7.11R-Restroom Hall<br>1F7.11S-Men's Room<br>1F7.11T-Women's Room<br>1F7.11V-Literacy<br>1F7.11W-Stairwell Foyer<br>1F7.11AB-Stairwell to Central Library                                                                                                                                                      | Assumed           |           | 128 SF<br>173 SF<br>124 SF<br>147 SF<br>104 SF<br>88 SF<br>51 SF<br>815 SF                                                       | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2                              | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6                              |             |
|                                                                                                          |                         |                                                                                                                                                                                                                                                                                                                                           |                   | Total:    |                                                                                                                                  |                                                                   |                                                                   |             |
| Drywall Wall                                                                                             | 198                     | US7.11D-Elevator Mechanical Room<br>7.11AA-Break Room<br>7.11C-Facilities Manager Office<br>7.11F-Storage<br>7.11G-Hallway<br>7.11H-Shipping Stockroom<br>7.11I-Mail Room<br>7.11J-Work Area<br>7.11K-Men's/Women's Handicap Bathroom<br>7.11L-Ladies Room<br>7.11M-Operations<br>7.11N-Small Mechanical Room<br>7.11O-Telecommunications | Assumed           |           | 240 SF<br>464 SF<br>367 SF<br>387 SF<br>600 SF<br>962 SF<br>808 SF<br>443 SF<br>225 SF<br><br>180 SF<br>952 SF<br>77 SF<br>65 SF | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br><br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br><br>6<br>6<br>6<br>6 |             |

# Asbestos Inspection Summary Table

Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location                         | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Drywall Wall (cont)          | 198 (cont)              | 7.11P-Office                                   |                   |           | 234 SF   | 2          | 6                |             |
|                              |                         | 7.11Q-Office                                   |                   |           | 368 SF   | 2          | 6                |             |
|                              |                         | 7.11R-Computer Room                            |                   |           | 348 SF   | 2          | 6                |             |
|                              |                         | 7.11S-Storage                                  |                   |           | 132 SF   | 2          | 6                |             |
|                              |                         | 7.11U-Training Room                            |                   |           | 85 SF    | 2          | 6                |             |
|                              |                         | 7.11W-Office                                   |                   |           | 258 SF   | 2          | 6                |             |
|                              |                         | 7.11X-Staging Area                             |                   |           | 316 SF   | 2          | 6                |             |
|                              |                         | 7.11Z-Office                                   |                   |           | 592 SF   | 2          | 6                |             |
|                              |                         | M7.11B-Central Library Office Area             |                   |           | 324 SF   | 2          | 6                |             |
|                              |                         | M7.11F-Science Balcony                         |                   |           | 24 SF    | ??         | ??               |             |
|                              |                         | M7.11I-Interlibrary Loan Area                  |                   |           | 94 SF    | 2          | 6                |             |
|                              |                         | M7.11K-Interlibrary Office                     |                   |           | 138 SF   | 2          | 6                |             |
|                              |                         | 1F7.11A-Repair/Inspection Area                 |                   |           | 438 SF   | 2          | 6                |             |
|                              |                         | 1F7.11B-Periodicals/Children's (North Library) |                   |           | 2881 SF  | 2          | 6                |             |
|                              |                         | 1F7.11O-Elevator Balcony                       |                   |           | 172 SF   | 2          | 6                |             |
|                              |                         | 1F7.11Q-Stairwell                              |                   |           | 197 SF   | 2          | 6                |             |
|                              |                         | 1F7.11R-Restroom Hall                          |                   |           | 400 SF   | 2          | 6                |             |
|                              |                         | 1F7.11V-Literacy                               |                   |           | 111 SF   | 2          | 6                |             |
|                              |                         | 1F7.11Y-Stairwell to Upper Stack               |                   |           | 40 SF    | 2          | 6                |             |
|                              |                         | 2F7.11G-Secretarial - Historian                |                   |           | 324 SF   | 2          | 6                |             |
|                              |                         | 2F7.11H-Storage                                |                   |           | 189 SF   | 2          | 6                |             |
|                              |                         | 2F7.11I-Local History/Genealogy Library        |                   |           | 162 SF   | 2          | 6                |             |
|                              |                         | 2F7.11L-File Storage                           |                   |           | 473 SF   | 2          | 6                |             |
|                              |                         | 2F7.11M-File Storage                           |                   |           | 117 SF   | 2          | 6                |             |
|                              |                         | 2F7.11O-Office                                 |                   |           | 130 SF   | 2          | 6                |             |
|                              |                         | 2F7.11Q-Office - Local History                 |                   |           | 150 SF   | 2          | 6                |             |



Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location             | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Drywall Wall (con't)         | 198 (con't)             | 2F7.11R-Local History Offices      |                   |           | 63 SF    | 2          | 6                |             |
|                              |                         | 2F7.11S-Men's Bath                 |                   |           | 252 SF   | 2          | 6                |             |
|                              |                         | 2F7.11T-Local History Vault        |                   |           | 275 SF   | 2          | 6                |             |
|                              |                         | 2F7.11U-Local History Storage      |                   |           | 396 SF   | 2          | 6                |             |
|                              |                         | 2F7.11V-Small Hall                 |                   |           | 121 SF   | 2          | 6                |             |
|                              |                         | 2F7.11AD-History Storage           |                   |           | 440 SF   | 2          | 6                |             |
|                              |                         | 2F7.11AE-Small Conference          |                   |           | 44 SF    | 2          | 6                |             |
|                              |                         | 2F7.11AI-Elevator Foyer            |                   |           | 180 SF   | 2          | 6                |             |
|                              |                         | 2F7.11AK-Outreach Manager's Office |                   |           | 165 SF   | 2          | 6                |             |
|                              |                         | 3F7.11D-Auditorium                 |                   |           | 300 SF   | 2          | 6                |             |
|                              |                         | 3F7.11F-Projection Room            |                   |           | 176 SF   | 2          | 6                |             |
|                              |                         | 3F7.11G-Serving Area               |                   |           | 77 SF    | 2          | 6                |             |
|                              |                         | 3F7.11L-Office                     |                   |           | 99 SF    | 2          | 6                |             |
|                              |                         | 3F7.11M-Office                     |                   |           | 135 SF   | 2          | 6                |             |
|                              |                         | 3F7.11N-Office                     |                   |           | 135 SF   | 2          | 6                |             |
|                              |                         | 3F7.11P-Office                     |                   |           | 144 SF   | 2          | 6                |             |
|                              |                         | 3F7.11R-Personnel Office           |                   |           | 100 SF   | 2          | 6                |             |
|                              |                         | 3F7.11S-File Storage               |                   |           | 200 SF   | 2          | 6                |             |
|                              |                         | 3F7.11U-Personnel Manager's Office |                   |           | 630 SF   | 2          | 6                |             |
|                              |                         | 3F7.11V-Machine Room               |                   |           | 522 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AA-Small Meeting Room        |                   |           | 126 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AB-Office                    |                   |           | 154 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AC-Office                    |                   |           | 135 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AD-Small Office              |                   |           | 90 SF    | 2          | 6                |             |
|                              |                         | 3F7.11AF-Office                    |                   |           | 308 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AG-Storage Closet            |                   |           | 154 SF   | 2          | 6                |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                         | Homogeneous Area ID No. | Room ID No. & Location                              | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------------------------------|-------------------------|-----------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Drywall Wall (cont)                                  | 198 (cont)              | 3F7.11AH-Office - Assistant Director for Technology |                   |           | 140 SF   | 2          | 6                |             |
|                                                      |                         | 3F7.11AL-Ladies Locker Room/Bath                    |                   |           | 63 SF    | 2          | 6                |             |
|                                                      |                         | 3F7.11AN-Cafeteria/Kitchen                          |                   |           | 432 SF   | 2          | 6                |             |
|                                                      |                         | 3F7.11AO-Vending Room                               |                   |           | 96 SF    | 2          | 6                |             |
|                                                      |                         | 3F7.11AT-Offices                                    |                   |           | 200 SF   | 2          | 6                |             |
|                                                      |                         | 3F7.11AU-"Friends" Office                           |                   |           | 200 SF   | 2          | 6                |             |
|                                                      |                         | 3F7.11AV-Acquisitions Office                        |                   |           | 297 SF   | 2          | 6                |             |
|                                                      |                         | 3F7.11AX-Office                                     |                   |           | 614 SF   | 2          | 6                |             |
|                                                      |                         | 3F7.11AY-Office                                     |                   |           | 560 SF   | 2          | 6                |             |
|                                                      |                         | 3F7.11BA-Work/Copy Area                             |                   | Total:    | 90 SF    | 2          | 6                |             |
| Paneling Adhesive - Unknown                          | 204                     | 1F7.11F-Hallway                                     | Assumed           |           | 22580 SF |            |                  |             |
|                                                      |                         |                                                     |                   | Total:    | 56 SF    | 2          | 6                |             |
| Interior Door Caulk between Door & Structure - Grey  | 241A                    | 7.11F-Storage                                       | Assumed           |           | 56 SF    |            |                  |             |
|                                                      |                         | 7.11G-Hallway                                       |                   |           | 18 LF    | 2          | 6                |             |
|                                                      |                         | 1F7.11I-Lobby/Security                              |                   |           | 18 LF    | 2          | 6                |             |
|                                                      |                         | 1F7.11J-Lobby Foyer                                 |                   |           | 22 LF    | 2          | 6                |             |
| Interior Door Caulk between Door & Structure - Black | 241B                    |                                                     |                   | Total:    | 32 LF    | 2          | 6                |             |
|                                                      |                         |                                                     |                   |           | 90 LF    |            |                  |             |
|                                                      |                         | 1F7.11J-Lobby Foyer                                 | Assumed           |           | 16 LF    | 2          | 6                |             |
|                                                      |                         |                                                     |                   | Total:    | 16 LF    |            |                  |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                               | Homogeneous Area ID No. | Room ID No. & Location                            | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------------------------------------|-------------------------|---------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Interior Door Caulk between frame & concrete block - cream | 241I                    | 7.11G-Hallway                                     | Assumed           | Total:    | 7 LF     | 2          | 6                |             |
|                                                            |                         | 7.11I-Mail Room                                   |                   |           | 7 LF     | 2          | 6                |             |
|                                                            |                         | 1F7.11J-Lobby Foyer                               |                   |           | 37 LF    | 2          | 6                |             |
|                                                            |                         |                                                   |                   |           | 51 LF    |            |                  |             |
| Interior Window Caulk between frame & structure - grey     | 245D                    | 7.11A-Mechanical Room                             | Assumed           |           | 10 LF    | 2          | 6                |             |
|                                                            |                         | 7.11B-Facilities Offices                          |                   |           | 5 LF     | 2          | 6                |             |
|                                                            |                         | 7.11C-Facilities Manager Office                   |                   |           | 5 LF     | 2          | 6                |             |
|                                                            |                         | 7.11Q-Office                                      |                   |           | 5 LF     | 2          | 6                |             |
|                                                            |                         | 7.11U-Training Room                               |                   |           | 10 LF    | 2          | 6                |             |
|                                                            |                         | 7.11V-User Support                                |                   |           | 20 LF    | 2          | 6                |             |
|                                                            |                         | 7.11W-Office                                      |                   |           | 10 LF    | 2          | 6                |             |
|                                                            |                         | M7.11G-Reference Area                             |                   |           | 15 LF    | 2          | 6                |             |
|                                                            |                         | M7.11I-Interlibrary Loan Area                     |                   |           | 15 LF    | 2          | 6                |             |
|                                                            |                         | M7.11K-Interlibrary Office                        |                   |           | 15 LF    | 2          | 6                |             |
|                                                            |                         | 1F7.11B-Periodicals/Children's (North Library)    |                   |           | 120 LF   | 2          | 6                |             |
|                                                            |                         | 1F7.11C-Fiction/Non-Fiction Area (South Library)  |                   | Y         | 180 LF   | 2          | 6                |             |
|                                                            |                         | 1F7.11E-Fiction Area (Quiet Room, Listening Room) |                   |           | 75 LF    | 2          | 6                |             |
|                                                            |                         | 2F7.11B-Stairwell                                 |                   |           | 6 LF     | 2          | 6                |             |
|                                                            |                         | 2F7.11C-Hallway - 2nd Floor                       |                   |           | 16 LF    | 2          | 6                |             |
|                                                            |                         | 2F7.11I-Local History/Genealogy Library           |                   |           | 48 LF    | 2          | 6                |             |
|                                                            |                         | 2F7.11J-Genealogy Library                         |                   |           | 32 LF    | 2          | 6                |             |
|                                                            |                         | 2F7.11L-File Storage                              |                   |           | 18 LF    | 2          | 6                |             |
|                                                            |                         | 2F7.11M-File Storage                              |                   |           | 11 LF    | 2          | 6                |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                  | Homogeneous Area ID No. | Room ID No. & Location                   | Tested Or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|---------------------------------------------------------------|-------------------------|------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Interior Window Caulk between frame & structure - grey (cont) | 245D (cont)             | 2F7.11O-Office                           |                   |           | 6 LF     | 2          | 6                |             |
|                                                               |                         | 2F7.11Q-Office - Local History           |                   |           | 4 LF     | 2          | 6                |             |
|                                                               |                         | 2F7.11R-Local History Offices            |                   |           | 18 LF    | 2          | 6                |             |
|                                                               |                         | 2F7.11T-Local History Vault              |                   |           | 8 LF     | 2          | 6                |             |
|                                                               |                         | 2F7.11U-Local History Storage            |                   |           | 24 LF    | 2          | 6                |             |
|                                                               |                         | 2F7.11W-Room 235                         |                   |           | 18 LF    | 2          | 6                |             |
|                                                               |                         | 2F7.11X-Small Office                     |                   |           | 6 LF     | 2          | 6                |             |
|                                                               |                         | 2F7.11AC-Book Storage                    |                   |           | 8 LF     | 2          | 6                |             |
|                                                               |                         | 2F7.11AD-History Storage                 |                   |           | 18 LF    | 2          | 6                |             |
|                                                               |                         | 2F7.11AE-Small Conference                |                   |           | 6 LF     | 2          | 6                |             |
|                                                               |                         | 2F7.11AF-Children's Book Storage         |                   |           | 24 LF    | 2          | 6                |             |
|                                                               |                         | 2F7.11AG-Picture Book Storage            |                   |           | 9 LF     | 2          | 6                |             |
|                                                               |                         | 2F7.11AJ-Outreach Offices                |                   |           | 12 LF    | 2          | 6                |             |
|                                                               |                         | 3F7.11B-Hallway                          |                   |           | 18 LF    | 2          | 6                |             |
|                                                               |                         | 3F7.11D-Auditorium                       |                   |           | 12 LF    | 2          | 6                |             |
|                                                               |                         | 3F7.11I-Office                           |                   |           | 8 LF     | 2          | 6                |             |
|                                                               |                         | 3F7.11M-Office                           |                   |           | 8 LF     | 2          | 6                |             |
|                                                               |                         | 3F7.11P-Office                           |                   |           | 8 LF     | 2          | 6                |             |
|                                                               |                         | 3F7.11R-Personnel Office                 |                   |           | 3 LF     | 2          | 6                |             |
|                                                               |                         | 3F7.11S-File Storage                     |                   |           | 3 LF     | 2          | 6                |             |
|                                                               |                         | 3F7.11U-Personnel Manager's Office       |                   |           | 3 LF     | 2          | 6                |             |
|                                                               |                         | 3F7.11X-Board of Directors' Meeting Room |                   |           | 10 LF    | 2          | 6                |             |
|                                                               |                         | 3F7.11Y-Director's Office                |                   |           | 5 LF     | 2          | 6                |             |
|                                                               |                         | 3F7.11AA-Small Meeting Room              |                   |           | 5 LF     | 2          | 6                |             |
|                                                               |                         | 3F7.11AB-Office                          |                   |           | 5 LF     | 2          | 6                |             |
|                                                               |                         | 3F7.11AC-Office                          |                   |           | 10 LF    | 2          | 6                |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                     | Homogeneous Area ID No. | Room ID No. & Location                              | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------------------------------------------|-------------------------|-----------------------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Interior Window Caulk between frame & structure - grey (cont)    | 245D (cont)             | 3F7.11AE-Office                                     |                   |           | 5 LF     | 2          | 6                |             |
|                                                                  |                         | 3F7.11AF-Office                                     |                   |           | 10 LF    | 2          | 6                |             |
|                                                                  |                         | 3F7.11AH-Office - Assistant Director for Technology |                   |           | 5 LF     | 2          | 6                |             |
|                                                                  |                         | 3F7.11AM-Dining Room                                |                   |           | 3 LF     | 2          | 6                |             |
|                                                                  |                         | 3F7.11AN-Cafeteria/Kitchen                          |                   |           | 6 LF     | 2          | 6                |             |
|                                                                  |                         | 3F7.11AS-Office/Work Area                           |                   |           | 28 LF    | 2          | 6                |             |
|                                                                  |                         | 3F7.11AT-Offices                                    |                   |           | 4 LF     | 2          | 6                |             |
|                                                                  |                         | 3F7.11AU-"Friends" Office                           |                   |           | 4 LF     | 2          | 6                |             |
|                                                                  |                         | 3F7.11AV-Acquisitions Office                        |                   |           | 4 LF     | 2          | 6                |             |
|                                                                  |                         | 3F7.11AY-Office                                     |                   |           | 4 LF     | 2          | 6                |             |
|                                                                  |                         | 3F7.11BD-Office                                     |                   |           | 4 LF     | 2          | 6                |             |
|                                                                  |                         | Total:                                              |                   |           | 952 LF   |            |                  |             |
| Interior Window Caulk - between Glass & Frame - Dark Grey (hard) | 248D                    | US7.11A-Upper Stack                                 | Assumed           |           | 620 LF   | 2          | 6                |             |
|                                                                  |                         | Total:                                              |                   |           | 620 LF   |            |                  |             |
| Interior Window Caulk between frame & glass - black sticky       | 248G                    | US7.11B-Women's Room                                | Assumed           |           | 9 LF     | 2          | 6                |             |
|                                                                  |                         | 7.11AA-Break Room                                   |                   |           | 88 LF    | 2          | 6                |             |
|                                                                  |                         | 7.11AD-Stairwell (South)                            |                   |           | 8 LF     | 2          | 6                |             |
|                                                                  |                         | 1F7.11K-Lobby Elevator Hallway                      |                   |           | 30 LF    | 2          | 6                |             |
|                                                                  |                         | Total:                                              |                   |           | 135 LF   |            |                  |             |
| Interior Wall (window) Caulk between frame & block - Black       | 251                     | 7.11R-Computer Room                                 | Assumed           |           | 21 LF    | 2          | 6                |             |
|                                                                  |                         | Total:                                              |                   |           | 21 LF    |            |                  |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                      | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                              | Tested or Assumed | ACM (Y/N) | Quantity                                                                     | AHERA Rank                      | Removal Priority                | Date Abated |
|---------------------------------------------------|-------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|------------------------------------------------------------------------------|---------------------------------|---------------------------------|-------------|
| 12 x 12 Floor Tile Grey with blue & pink flecks   | A301                    | 3F7.11W-Reception - Board of Directors                                                                                                                                              | Assumed           | Total:    | 154 SF<br>154 SF                                                             | 2                               | 6                               |             |
| Mastic under 301                                  | A301M                   | 3F7.11W-Reception - Board of Directors                                                                                                                                              | Assumed           | Total:    | 154 SF<br>154 SF                                                             | 2                               | 6                               |             |
| Linoleum Floor - Tan with Multicolored Starbursts | 309                     | 3F7.11AM-Dining Room<br>3F7.11AN-Cafeteria/Kitchen<br>3F7.11AO-Vending Room                                                                                                         | Assumed           | Total:    | 408 SF<br>144 SF<br>168 SF<br>720 SF                                         | 2<br>2<br>2                     | 6<br>6<br>6                     |             |
| Black Mastic                                      | 309M                    | 3F7.11AM-Dining Room<br>3F7.11AN-Cafeteria/Kitchen<br>3F7.11AO-Vending Room                                                                                                         | Assumed           | Total:    | 408 SF<br>144 SF<br>168 SF<br>720 SF                                         | 2<br>2<br>2                     | 6<br>6<br>6                     |             |
| Orange & Brick Colored Linoleum                   | A311C                   | 2F7.11C-Hallway - 2nd Floor<br>2F7.11K-Hallway<br>2F7.11P-Hallway (Rear)<br>2F7.11V-Small Hall<br>2F7.11Z-Small Hallway<br>2F7.11AA-Hall to Main Hallway<br>2F7.11AI-Elevator Foyer | Assumed           | Total:    | 1572 SF<br>660 SF<br>270 SF<br>156 SF<br>80 SF<br>441 SF<br>96 SF<br>3275 SF | 2<br>2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6 |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                                                 | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                            | Tested or Assumed | ACM (Y/N) | Quantity                                                                      | AHERA Rank                           | Removal Priority                     | Date Abated |
|----------------------------------------------------------------------------------------------|-------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|-------------------------------------------------------------------------------|--------------------------------------|--------------------------------------|-------------|
| Black Mastic                                                                                 | A311CM                  | 2F7.11C-Hallway - 2nd Floor<br>2F7.11K-Hallway<br>2F7.11P-Hallway (Rear)<br>2F7.11V-Small Hall<br>2F7.11Z-Small Hallway<br>2F7.11AA-Hall to Main Hallway<br>2F7.11AI-Elevator Foyer                               | Assumed           |           | 1572 SF<br>660 SF<br>270 SF<br>156 SF<br>80 SF<br>441 SF<br>96 SF<br>3275 SF  | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6 |             |
| Unknown Mastic/Adhesive                                                                      | A311DM                  | 2F7.11E-Historian's Office<br>2F7.11F-Storage-Historian (Under Stairs)<br>2F7.11G-Secretarial - Historian<br>2F7.11H-Storage<br>2F7.11O-Office<br>2F7.11Q-Office - Local History<br>2F7.11R-Local History Offices | Assumed           | Total:    | 224 SF<br>140 SF<br>144 SF<br>189 SF<br>260 SF<br>180 SF<br>602 SF<br>1739 SF | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6 |             |
| 12" x 12" Floor Tile Brown with Light Tan streaks                                            | A321                    | 1F7.11D-Conference Room                                                                                                                                                                                           | Assumed           | Total:    | 202 SF<br>202 SF                                                              | 2<br>2                               | 6<br>6                               |             |
| Black Mastic                                                                                 | A321M                   | 1F7.11D-Conference Room                                                                                                                                                                                           | Assumed           | Total:    | 202 SF<br>202 SF                                                              | 2<br>2                               | 6<br>6                               |             |
| 12" x 12" Floor Tile - White w/Yellow Specs & 12" x 12" Floor tile - Dark Green w/Dark Green | 323                     | 1F7.11K-Lobby Elevator Hallway                                                                                                                                                                                    | Assumed           | Total:    | 138 SF<br>138 SF                                                              | 2<br>2                               | 6<br>6                               |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

| <u>Date Inspected:</u> 8/23/01, 8/27-31/01, 9/4/01, 9/6/01 | <u>Homogeneous Area Description</u>               | <u>Homogeneous Area ID No.</u> | <u>Room ID No. &amp; Location</u>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | <u>Tested or Assumed</u> | <u>ACM (Y/N)</u> | <u>Quantity</u>                                                                                                                                                                                                                 | <u>AHERA Rank</u>                                                                                                    | <u>Removal Priority</u>                                                                                         | <u>Date Abated</u> |
|------------------------------------------------------------|---------------------------------------------------|--------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|--------------------|
|                                                            | Yellow Mastic                                     | 323M                           | 1F7.11K-Lobby Elevator Hallway                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | Assumed                  | Total:           | 138 SF<br>138 SF                                                                                                                                                                                                                | 2                                                                                                                    | 6                                                                                                               |                    |
|                                                            | 12" x 12" Tan Floor Tile with Red & Brown streaks | A338                           | 3F7.11A-Entry<br>3F7.11B-Hallway<br>3F7.11H-Reception Area<br>3F7.11I-Office<br>3F7.11J-Storage Room<br>3F7.11K-Bathroom<br>3F7.11L-Office<br>3F7.11M-Office<br>3F7.11N-Office<br>3F7.11O-Bathroom<br>3F7.11P-Office<br>3F7.11U-Personnel Manager's Office<br>3F7.11AA-Small Meeting Room<br>3F7.11AC-Office<br>3F7.11AD-Small Office<br>3F7.11AE-Office<br>3F7.11AF-Office<br>3F7.11AG-Storage Closet<br>3F7.11AS-Office/Work Area<br>3F7.11AT-Offices<br>3F7.11AU-"Friends" Office<br>3F7.11BC-Storeroom<br>3F7.11BH-Ladies Room | Assumed                  |                  | 325 SF<br>700 SF<br>52 SF<br>269 SF<br>10 SF<br>6 SF<br>66 SF<br>79 SF<br>89 SF<br>6 SF<br>71 SF<br>118 SF<br>182 SF<br>163 SF<br>57 SF<br>76 SF<br>166 SF<br>17 SF<br>1630 SF<br>140 SF<br>151 SF<br>56 SF<br>53 SF<br>4482 SF | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6<br>6 |                    |
|                                                            |                                                   |                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                          | Total:           |                                                                                                                                                                                                                                 |                                                                                                                      |                                                                                                                 |                    |



Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description | Homogeneous Area ID No. | Room ID No. & Location             | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|------------------------------|-------------------------|------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| Black Mastic                 | A338M                   | 3F7.11A-Entry                      | Assumed           |           | 713 SF   | 2          | 6                |             |
|                              |                         | 3F7.11B-Hallway                    |                   |           | 1680 SF  | 2          | 6                |             |
|                              |                         | 3F7.11H-Reception Area             |                   |           | 154 SF   | 2          | 6                |             |
|                              |                         | 3F7.11I-Office                     |                   |           | 662 SF   | 2          | 6                |             |
|                              |                         | 3F7.11J-Storage Room               |                   |           | 32 SF    | 2          | 6                |             |
|                              |                         | 3F7.11K-Bathroom                   |                   |           | 20 SF    | 2          | 6                |             |
|                              |                         | 3F7.11L-Office                     |                   |           | 187 SF   | 2          | 6                |             |
|                              |                         | 3F7.11M-Office                     |                   |           | 210 SF   | 2          | 6                |             |
|                              |                         | 3F7.11N-Office                     |                   |           | 240 SF   | 2          | 6                |             |
|                              |                         | 3F7.11O-Bathroom                   |                   |           | 20 SF    | 2          | 6                |             |
|                              |                         | 3F7.11P-Office                     |                   |           | 160 SF   | 2          | 6                |             |
|                              |                         | 3F7.11U-Personnel Manager's Office |                   |           | 306 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AA-Small Meeting Room        |                   |           | 182 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AC-Office                    |                   |           | 375 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AD-Small Office              |                   |           | 160 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AE-Office                    |                   |           | 210 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AF-Office                    |                   |           | 420 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AG-Storage Closet            |                   |           | 45 SF    | 2          | 6                |             |
|                              |                         | 3F7.11AS-Office/Work Area          |                   |           | 3500 SF  | 2          | 6                |             |
|                              |                         | 3F7.11AT-Offices                   |                   |           | 300 SF   | 2          | 6                |             |
|                              |                         | 3F7.11AU-"Friends" Office          |                   |           | 380 SF   | 2          | 6                |             |
|                              |                         | 3F7.11BC-Storeroom                 |                   |           | 98 SF    | 2          | 6                |             |
|                              |                         | 3F7.11BH-Ladies Room               |                   |           | 144 SF   | 2          | 6                |             |
|                              |                         | Total:                             |                   |           | 10198 SF |            |                  |             |

Asbestos Inspection Summary Table  
Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                              | Homogeneous Area ID No. | Room ID No. & Location             | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|-----------------------------------------------------------|-------------------------|------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| 12" x 12" Red Brown Floor Tile with cream & black streaks | A339                    | 3F7.11A-Entry                      | Assumed           |           | 325 SF   | 2          | 6                |             |
|                                                           |                         | 3F7.11B-Hallway                    |                   |           | 700 SF   | 2          | 6                |             |
|                                                           |                         | 3F7.11H-Reception Area             |                   |           | 52 SF    | 2          | 6                |             |
|                                                           |                         | 3F7.11I-Office                     |                   |           | 269 SF   | 2          | 6                |             |
|                                                           |                         | 3F7.11J-Storage Room               |                   |           | 10 SF    | 2          | 6                |             |
|                                                           |                         | 3F7.11K-Bathroom                   |                   |           | 6 SF     | 2          | 6                |             |
|                                                           |                         | 3F7.11L-Office                     |                   |           | 66 SF    | 2          | 6                |             |
|                                                           |                         | 3F7.11M-Office                     |                   |           | 79 SF    | 2          | 6                |             |
|                                                           |                         | 3F7.11N-Office                     |                   |           | 89 SF    | 2          | 6                |             |
|                                                           |                         | 3F7.11O-Bathroom                   |                   |           | 6 SF     | 2          | 6                |             |
|                                                           |                         | 3F7.11P-Office                     |                   |           | 71 SF    | 2          | 6                |             |
|                                                           |                         | 3F7.11U-Personnel Manager's Office |                   |           | 118 SF   | 2          | 6                |             |
|                                                           |                         | 3F7.11AC-Office                    |                   |           | 163 SF   | 2          | 6                |             |
|                                                           |                         | 3F7.11AD-Small Office              |                   |           | 57 SF    | 2          | 6                |             |
|                                                           |                         | 3F7.11AE-Office                    |                   |           | 76 SF    | 2          | 6                |             |
|                                                           |                         | 3F7.11AF-Office                    |                   |           | 166 SF   | 2          | 6                |             |
|                                                           |                         | 3F7.11AG-Storage Closet            |                   |           | 17 SF    | 2          | 6                |             |
|                                                           |                         | 3F7.11AS-Office/Work Area          |                   |           | 1630 SF  | 2          | 6                |             |
|                                                           |                         | 3F7.11AT-Offices                   |                   |           | 140 SF   | 2          | 6                |             |
|                                                           |                         | 3F7.11AU-"Friends" Office          |                   |           | 151 SF   | 2          | 6                |             |
|                                                           |                         | 3F7.11BH-Ladies Room               |                   |           | 53 SF    | 2          | 6                |             |
| Total:                                                    |                         |                                    |                   |           | 4244 SF  |            |                  |             |

Asbestos Inspection Summary Table  
 Rundel Library  
 115 South Avenue  
 Rochester, New York  
 Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                       | Homogeneous Area ID No. | Room ID No. & Location             | Tested or Assumed | ACM (Y/N) | Quantity | AHERA Rank | Removal Priority | Date Abated |
|--------------------------------------------------------------------|-------------------------|------------------------------------|-------------------|-----------|----------|------------|------------------|-------------|
| 12" x 24" Solid Red Brown Floor Tile Border (around A338 and A339) | A340                    | 2F7.11U-Local History Storage      | Assumed           |           | 154 SF   | 2          | 6                |             |
|                                                                    |                         | 3F7.11A-Entry                      |                   |           | 62 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11B-Hallway                    |                   |           | 280 SF   | 2          | 6                |             |
|                                                                    |                         | 3F7.11G-Serving Area               |                   |           | 36 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11H-Reception Area             |                   |           | 50 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11I-Office                     |                   |           | 124 SF   | 2          | 6                |             |
|                                                                    |                         | 3F7.11J-Storage Area               |                   |           | 125 SF   | 2          | 6                |             |
|                                                                    |                         | 3F7.11K-Bathroom                   |                   |           | 9 SF     | 2          | 6                |             |
|                                                                    |                         | 3F7.11L-Office                     |                   |           | 56 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11M-Office                     |                   |           | 58 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11N-Office                     |                   |           | 62 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11O-Bathroom                   |                   |           | 9 SF     | 2          | 6                |             |
|                                                                    |                         | 3F7.11P-Office                     |                   |           | 46 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11Q-Hallway                    |                   |           | 112 SF   | 2          | 6                |             |
|                                                                    |                         | 3F7.11R-Personnel Office           |                   |           | 94 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11S-File Storage               |                   |           | 40 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11U-Personnel Manager's Office |                   |           | 70 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11AC-Office                    |                   |           | 50 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11AD-Small Office              |                   |           | 46 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11AE-Office                    |                   |           | 58 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11AF-Office                    |                   |           | 88 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11AG-Storage Closet            |                   |           | 28 SF    | 2          | 6                |             |
|                                                                    |                         | 3F7.11AI-Men's Bath/Locker Room    |                   |           | 112 SF   | 2          | 6                |             |
|                                                                    |                         | 3F7.11AL-Ladies Locker Room/Bath   |                   |           | 132 SF   | 2          | 6                |             |
|                                                                    |                         | 3F7.11AR-Hallway                   |                   |           | 306 SF   | 2          | 6                |             |
|                                                                    |                         | 3F7.11AS-Office/Work Area          |                   |           | 240 SF   | 2          | 6                |             |
|                                                                    |                         | 3F7.11AT-Offices                   |                   |           | 70 SF    | 2          | 6                |             |

Asbestos Inspection Summary Table

Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                                              | Homogeneous Area ID No. | Room ID No. & Location                                                                                                                                                                                                   | Tested or Assumed | ACM (Y/N) | Quantity                                                                                     | AHERA Rank                           | Removal Priority                     | Date Abated |
|---------------------------------------------------------------------------|-------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------|----------------------------------------------------------------------------------------------|--------------------------------------|--------------------------------------|-------------|
| 12" x 24" Solid Red Brown Floor Tile Border (around A338 and A339) (cont) | A340 (cont)             | 3F7.11AU-"Friends" Office<br>3F7.11BC-Storeroom<br>3F7.11BH-Ladies Room                                                                                                                                                  |                   |           | 78 SF<br>42 SF<br>35 SF<br>Total: 2672 SF                                                    | 2<br>2<br>2                          | 6<br>6<br>6                          |             |
| 9" x 9" Tan Floor Tile with Red Brown & Cream Streaks                     | A341                    | 2F7.11U-Local History Storage<br>3F7.11G-Serving Area<br>3F7.11Q-Hallway<br>3F7.11R-Personnel Office<br>3F7.11S-File Storage<br>3F7.11AI-Men's Bath/Locker Room<br>3F7.11AL-Ladies Locker Room/Bath<br>3F7.11 AR-Hallway | Assumed           |           | 462 SF<br>41 SF<br>188 SF<br>208 SF<br>25 SF<br>181 SF<br>114 SF<br>277 SF<br>Total: 1496 SF | 2<br>2<br>2<br>2<br>2<br>2<br>2<br>2 | 6<br>6<br>6<br>6<br>6<br>6<br>6<br>6 |             |
| 9" x 9" Red Brown Floor Tile with Cream & Black Streaks                   | A342                    | 3F7.11Q-Hallway<br>3F7.11R-Personnel Office<br>3F7.11S-File Storage<br>3F7.11-Ladies Locker Room/Bath<br>3F7.11AR-Hallway                                                                                                | Assumed           |           | 188 SF<br>208 SF<br>25 SF<br>114 SF<br>277 SF<br>Total: 812 SF                               | 2<br>2<br>2<br>2<br>2                | 6<br>6<br>6<br>6<br>6                |             |

# Asbestos Inspection Summary Table

Rundel Library  
115 South Avenue  
Rochester, New York  
Building ID No. 7.11

Date Inspected: 8/23/01, 8/27-31/01, 9/4/01, 9/6/01

| Homogeneous Area Description                          | Homogeneous Area ID No. | Room ID No. & Location                    | Tested or Assumed | ACM (Y/N) | Quantity                    | AHERA Rank | Removal Priority | Date Abated |
|-------------------------------------------------------|-------------------------|-------------------------------------------|-------------------|-----------|-----------------------------|------------|------------------|-------------|
| 9" x 9" Chocolate Brown Floor Tile with white streaks | A343                    | 2F7.11AB-Storage<br>2F7.11AC-Book Storage | Assumed           |           | 133 SF<br>981 SF<br>1114 SF | 2<br>2     | 6<br>6           |             |
| Black Mastic                                          | A343M                   | 2F7.11AB-Storage<br>2F7.11AC-Book Storage | Assumed           | Total:    | 133 SF<br>981 SF<br>1114 SF | 2<br>2     | 6<br>6           |             |
| Caulk between Steel Pillar & Block - White/Pliable    | 402                     | 7.11R-Computer Room                       | Assumed           | Total:    | 14 LF<br>14 LF              | 2          | 6                |             |

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 457.1/A

Type of Space: UPPER STATE

Ceiling Height: 7 FT 1 INCH

HIGH MODERATE LOW/NONE

Influence of Vibration: HIGH MODERATE LOW/NONE

234' 6 X 126' 2

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable |
|----------------------------------|-------------------------|-------|---------|-------------|
| <b>Surfacing Material</b>        |                         |       |         |             |
| Ceiling Walls                    | 46                      |       |         |             |
| North                            | 40                      |       |         |             |
| South                            | 40                      |       |         |             |
| East                             | 40                      |       |         |             |
| West                             | 40                      |       |         |             |
| Other                            |                         |       |         |             |
| <b>Thermal System Insulation</b> |                         |       |         |             |
| Pipe                             | 003                     |       |         |             |
| Duct                             | A000A                   |       | ✓       |             |
| Fixture                          | 008                     |       | ✓       |             |
| <b>Miscellaneous Material</b>    |                         |       |         |             |
| Ceiling Tiles                    | 147                     |       |         |             |
| Floor Tiles                      | 248D                    | white | ✓       |             |
| Window Caulk                     | 0030                    | BLACK | ✓       |             |
| FDC                              |                         |       |         |             |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Runde!

115 South Avenue

Building ID No.:

7.11

8/28/01

**Date of Inspection:**

Influence of Vibration: HIGH MODERATE LOW/NONE

**HIGH MODERATE**

### Potential for Air Erosion:

HIGH MODERATE LOW NONE

16'2x7'7

Space ID No.:

US 7.113

**Type of Space:**

2015/5/25

**Ceiling Height:**

7 FT / INCH

[illegible]

D/D - Degree of Damage

M - Minor

**S - Significant**

**P/D - Potential for Damage**

**M - Minor (Generally Not Accessible)**

N - Not Significant (Accessible for OMO-t.)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: US7.11C  
Type of Space: MENS ROOM  
Ceiling Height: \_\_\_\_\_

Ceiling Height: 7 FT    INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Influence of Vibration:            | HIGH           | MODERATE             | LOW/NONE                       |
|------------------------------------|----------------|----------------------|--------------------------------|
| 1. Frequency of Vibration          | 100-150 Hz     | 10-100 Hz            | 10 Hz or less                  |
| 2. Amplitude of Vibration          | 0.15 g or more | 0.05-0.15 g          | 0.05 g or less                 |
| 3. Direction of Vibration          | Vertical       | Vertical, Horizontal | Vertical, Horizontal, Diagonal |
| 4. Duration of Vibration           | 10 min or more | 1-10 min             | Less than 1 min                |
| 5. Type of Vibration               | Continuous     | Intermittent         | Impulsive                      |
| 6. Exposure to Vibration           | 100% or more   | 50-100%              | Less than 50%                  |
| 7. Age of Worker                   | 18-25 years    | 26-35 years          | 36 years or older              |
| 8. Health Status of Worker         | Good           | Fair                 | Poor                           |
| 9. Training of Worker              | Yes            | No                   | None                           |
| 10. Safety of Worker               | Yes            | No                   | None                           |
| 11. Environmental Conditions       | Good           | Fair                 | Poor                           |
| 12. Maintenance of Equipment       | Yes            | No                   | None                           |
| 13. Safety of Equipment            | Yes            | No                   | None                           |
| 14. Safety of Work Area            | Yes            | No                   | None                           |
| 15. Safety of Work Process         | Yes            | No                   | None                           |
| 16. Safety of Work Environment     | Yes            | No                   | None                           |
| 17. Safety of Work Procedures      | Yes            | No                   | None                           |
| 18. Safety of Work Methods         | Yes            | No                   | None                           |
| 19. Safety of Work Tools           | Yes            | No                   | None                           |
| 20. Safety of Work Materials       | Yes            | No                   | None                           |
| 21. Safety of Work Products        | Yes            | No                   | None                           |
| 22. Safety of Work Byproducts      | Yes            | No                   | None                           |
| 23. Safety of Work Wastes          | Yes            | No                   | None                           |
| 24. Safety of Work Disposal        | Yes            | No                   | None                           |
| 25. Safety of Work Cleanup         | Yes            | No                   | None                           |
| 26. Safety of Work Shutdown        | Yes            | No                   | None                           |
| 27. Safety of Work Restart         | Yes            | No                   | None                           |
| 28. Safety of Work Completion      | Yes            | No                   | None                           |
| 29. Safety of Work Evaluation      | Yes            | No                   | None                           |
| 30. Safety of Work Review          | Yes            | No                   | None                           |
| 31. Safety of Work Improvement     | Yes            | No                   | None                           |
| 32. Safety of Work Feedback        | Yes            | No                   | None                           |
| 33. Safety of Work Communication   | Yes            | No                   | None                           |
| 34. Safety of Work Coordination    | Yes            | No                   | None                           |
| 35. Safety of Work Collaboration   | Yes            | No                   | None                           |
| 36. Safety of Work Teamwork        | Yes            | No                   | None                           |
| 37. Safety of Work Leadership      | Yes            | No                   | None                           |
| 38. Safety of Work Management      | Yes            | No                   | None                           |
| 39. Safety of Work Organization    | Yes            | No                   | None                           |
| 40. Safety of Work Culture         | Yes            | No                   | None                           |
| 41. Safety of Work Values          | Yes            | No                   | None                           |
| 42. Safety of Work Beliefs         | Yes            | No                   | None                           |
| 43. Safety of Work Attitudes       | Yes            | No                   | None                           |
| 44. Safety of Work Behaviors       | Yes            | No                   | None                           |
| 45. Safety of Work Skills          | Yes            | No                   | None                           |
| 46. Safety of Work Knowledge       | Yes            | No                   | None                           |
| 47. Safety of Work Experience      | Yes            | No                   | None                           |
| 48. Safety of Work Expertise       | Yes            | No                   | None                           |
| 49. Safety of Work Creativity      | Yes            | No                   | None                           |
| 50. Safety of Work Innovation      | Yes            | No                   | None                           |
| 51. Safety of Work Problem Solving | Yes            | No                   | None                           |
| 52. Safety of Work Decision Making | Yes            | No                   | None                           |
| 53. Safety of Work Planning        | Yes            | No                   | None                           |
| 54. Safety of Work Organizing      | Yes            | No                   | None                           |
| 55. Safety of Work Implementing    | Yes            | No                   | None                           |
| 56. Safety of Work Monitoring      | Yes            | No                   | None                           |
| 57. Safety of Work Evaluating      | Yes            | No                   | None                           |
| 58. Safety of Work Improving       | Yes            | No                   | None                           |
| 59. Safety of Work Learning        | Yes            | No                   | None                           |
| 60. Safety of Work Adapting        | Yes            | No                   | None                           |
| 61. Safety of Work Changing        | Yes            | No                   | None                           |
| 62. Safety of Work Growing         | Yes            | No                   | None                           |
| 63. Safety of Work Developing      | Yes            | No                   | None                           |
| 64. Safety of Work Sustaining      | Yes            | No                   | None                           |
| 65. Safety of Work Restoring       | Yes            | No                   | None                           |
| 66. Safety of Work Maintaining     | Yes            | No                   | None                           |
| 67. Safety of Work Protecting      | Yes            | No                   | None                           |
| 68. Safety of Work Enhancing       | Yes            | No                   | None                           |
| 69. Safety of Work Supporting      | Yes            | No                   | None                           |
| 70. Safety of Work Facilitating    | Yes            | No                   | None                           |
| 71. Safety of Work Enabling        | Yes            | No                   | None                           |
| 72. Safety of Work Encouraging     | Yes            | No                   | None                           |
| 73. Safety of Work Inspiring       | Yes            | No                   | None                           |
| 74. Safety of Work Motivating      | Yes            | No                   | None                           |
| 75. Safety of Work Empowering      | Yes            | No                   | None                           |
| 76. Safety of Work Delegating      | Yes            | No                   | None                           |
| 77. Safety of Work Participating   | Yes            | No                   | None                           |
| 78. Safety of Work Collaborating   | Yes            | No                   | None                           |
| 79. Safety of Work Networking      | Yes            | No                   | None                           |
| 80. Safety of Work Partnering      | Yes            | No                   | None                           |
| 81. Safety of Work Allowing        | Yes            | No                   | None                           |
| 82. Safety of Work Encouraging     | Yes            | No                   | None                           |
| 83. Safety of Work Supporting      | Yes            | No                   | None                           |
| 84. Safety of Work Facilitating    | Yes            | No                   | None                           |
| 85. Safety of Work Enabling        | Yes            | No                   | None                           |
| 86. Safety of Work Encouraging     | Yes            | No                   | None                           |
| 87. Safety of Work Supporting      | Yes            | No                   | None                           |
| 88. Safety of Work Facilitating    | Yes            | No                   | None                           |
| 89. Safety of Work Enabling        | Yes            | No                   | None                           |
| 90. Safety of Work Encouraging     | Yes            | No                   | None                           |
| 91. Safety of Work Supporting      | Yes            | No                   | None                           |
| 92. Safety of Work Facilitating    | Yes            | No                   | None                           |
| 93. Safety of Work Enabling        | Yes            | No                   | None                           |
| 94. Safety of Work Encouraging     | Yes            | No                   | None                           |
| 95. Safety of Work Supporting      | Yes            | No                   | None                           |
| 96. Safety of Work Facilitating    | Yes            | No                   | None                           |
| 97. Safety of Work Enabling        | Yes            | No                   | None                           |
| 98. Safety of Work Encouraging     | Yes            |                      |                                |

10'4x7'6

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

**P/D - Potential for Damage**  
**M - Minor (Generally Not Accessible)**



**Building Name:** Rüdel  
**Building Address:** 115 South Avenue

Ründer

**115 South Avenue**

Building ID No.:

## 7.11

**Date of Inspection:**

0/29/01

### Influence of Vibration: HIGH MODERATE LOW/NONE

**LOW/MONE**

### Potential for Air Erosion:

HIGH MODERATE ~~LOW~~ NONE

7/0: 0/0

Space ID No.: U.S. 7. 11D

Type of Space:

**Ceiling Height:**

3 INCH

3 INCH

$$7'8 \times 8'9$$
[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

115 South Avenue

## 7.11

10/32/81

|                                            | HIGH           | MODERATE     | LOW/NONE     |
|--------------------------------------------|----------------|--------------|--------------|
| 1. The company's financial performance is: | Very good      | Good         | Fair         |
| 2. The company's management team is:       | Very competent | Competent    | Average      |
| 3. The company's products are:             | High quality   | Good quality | Fair quality |
| 4. The company's customer service is:      | Excellent      | Good         | Fair         |
| 5. The company's reputation is:            | Very strong    | Strong       | Average      |
| 6. The company's future prospects are:     | Bright         | Good         | Fair         |
| 7. The company's overall value is:         | High           | Moderate     | Low          |

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

**Space ID No.:**

US 7,115

Type of Space:

Type of Space: SOUTH EAST STAIRWELL

**Ceiling Height:**

**Ceiling Height:**

Colfax 13'2

[illegible]

D/D - Degree of Damage

M - Minor

### S - Significant

### P/D - Potential for Damage

**M - Minor (Generally Not Accessible)**

N - Not Significant (Accessible for 0 M O<sub>2</sub>)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 457.11F

Type of Space: SUBTLEST STAIRWELL

Ceiling Height: 7 FT 1 INCH

Potential for Air Erosion: **HIGH MODERATE LOW/NONE**

9'6" x 2'1"

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O & M Only)





Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/23/07  
 Influence of Vibration: HIGH MODERATE

Space ID No.: 7.11A  
Type of Space: MECHANICAL ROOM  
Ceiling Height: \_\_\_\_\_

Potential for Air Erosion: HIGH MODERATE LOW/NONE

[illegible]

NOTE: NEW WRAP / PLASTIC FITTINGS

D/D - Degree of Damage  
M - Minor  
S - Significant





**Building Name:**  
**Building Address:**

Space ID No.: 7.11C  
Type of Space: FACILITIES MANAGER OFFICE  
Ceiling Height:

---

7.11

---

LOW NONE

**LOW NOISE**

**LOW TONE**

100

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)



Building Name:  
Building Address:

115 South Avenue

**Building ID No.:**

7.11

Date of Inspection:

8/23/07

Influence of Vibration: HIGH MODERATE LOW/NONE

~~LOW~~  
HIGH MODERATE LOW/NONE

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

CONF.

INCH

 $7' \times 18' 8$ 

Space ID No.:

7.11D

Type of Space: \_\_\_\_\_

**Ceiling Height:**

[illegible]

D/D - Degree of Damage

M - Minor

**S - Significant**

P/D - Potential for Damage  
M - Minor (General)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 7.11E  
Type of Space: HALL  
Ceiling Height: 8 FT 8 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

[illegible]

\* IN CHASE WALL: ASSUMED TO GO TO ROOF

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

115 South Avenue

7.11

23/01

**MODERATE (LOW/NONE)**

0

**HIGH MODERATE LOW/DONE**

7.11F

STK ACF

5 FT 2 INCH

[illegible]

M - Minor

**S - Significant**

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

Building Name: Rundel Space ID No.: 7.117  
 Building Address: 115 South Avenue Type of Space: NA/LO-AP  
 Building ID No.: 7.11 Ceiling Height: 8 FT 8 INCH  
 Date of Inspection: 8/23/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE Potential for Air Erosion: HIGH MODERATE LOW/NONE + (10'3 x 4'7) SOUTH END OF HALL

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |       |         | ACM/AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|------------------|-------|---------|----------------|------------------|
|                                  |                         |       |         |             | Total        | Damaged | D/D | P/D              | Total | Damaged |                |                  |
| <b>Surfacing Material</b>        |                         |       |         |             |              |         |     |                  |       |         |                |                  |
| Ceiling                          |                         |       |         |             |              |         |     |                  |       |         |                |                  |
| Walls                            |                         |       |         |             |              |         |     |                  |       |         |                |                  |
| North                            | 46                      |       |         |             |              |         |     |                  |       |         |                |                  |
| South                            | 198                     |       |         |             |              |         |     |                  |       |         |                |                  |
| East                             | 40                      |       |         |             |              |         |     |                  |       |         |                |                  |
| West                             | 198-40                  |       |         |             |              |         |     |                  |       |         |                |                  |
| Other                            | 40                      |       |         |             |              |         |     |                  |       |         |                |                  |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |         |     |                  |       |         |                |                  |
| Pipe                             |                         |       |         |             |              |         |     |                  |       |         |                |                  |
| Duct                             | 0050                    |       |         |             |              |         |     |                  |       |         |                |                  |
| Fixture                          |                         |       |         |             |              |         |     |                  |       |         |                |                  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |         |     |                  |       |         |                |                  |
| Ceiling Tiles                    | 102                     |       |         |             |              |         |     |                  |       |         |                |                  |
| Floor Tiles                      | 015/016/047             |       |         |             |              |         |     |                  |       |         |                |                  |
| Window Caulk                     |                         |       |         |             |              |         |     |                  |       |         |                |                  |
| COVE MOLDING                     | Y3                      |       |         |             |              |         |     |                  |       |         |                |                  |
| COVE MOLDING                     | 38A                     |       |         |             |              |         |     |                  |       |         |                |                  |
| DOOR CAULK                       | 24/A                    | GREEN |         |             |              |         |     |                  |       |         |                |                  |
| DOOR CAULK                       | 24/T                    | CREAM |         |             |              |         |     |                  |       |         |                |                  |

D/D - Degree of Damage  
 M - Minor  
 S - Significant  
 P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)  
 N - Not Significant (Accessible for O M Only)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.:

7114

Type of Space: SHIPDAY STOCKROOM

Ceiling Height: 3 FT 7 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

influence of vibration: HIGH MODERATE ~~LOW/NONE~~

42' x 29'Z

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

115 South Avenue

Building ID No.:

## 7.11

**Date of Inspection:**

8/23/01

Influence of Vibration: HIGH MODERATE LOW/NONE

~~LOW/MONE~~

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

14'4x 47'

LOW/NONE

8 FT 7 INCH

8 FT

8 FT 7 INCH

8 FT 7 INCH

[illegible]

D/D - Degree of Damage

M - Minor

**S - Significant**

**P/D - Potential for Damage**

**M - Minor (Generally Not Accessible)**

N - Not Significant / A - Accessible



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 7.11K

Type of Space: MENS/WOMENS HANDicap BATHROOM

Ceiling Height: 8 FT 8 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

8'10 x 8'2

**Influence of Vibration: HIGH MODERATE LOW/NONE**

8/23/01

Date of Inspection:

## 7.11

10/23/01

**MODERATE** **LOW/NONE**

[illegible]

D/D - Degree of Damage

M - Minor

S - Significant

**P/D - Potential for Damage**

M - Minor (Generally Not Accessible)

N - Not Significant (Accessible for O M Only)





**Building Name:** Rundel  
**Building Address:** 115 South Avenue

**Rundel**  
**115 Sou**

Space ID No.:

7.11.2

Type of Space: OPERATIONS  
Ceiling Height:

$$\begin{aligned} & (15'10 \times 13'6) + \\ & (10'2 \times 21'3) + \\ & (9'1 \times 9'6) \end{aligned}$$

Potential for Air Erosion: HIGH MODERATE LOW/NONE

Influence of Vibration: HIGH MODERATE ~~LOW/NONE~~

Building ID No.:  
Date of Inspection:

Ex 27/01

### HIGH MODERATE

~~LOW~~NONE

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Suspect Material |         |     |             |         |     | ACM/AHERA Y/N | Rank | Removal Priority |
|----------------------------------|-------------------------|-------|---------|-------------|------------------|---------|-----|-------------|---------|-----|---------------|------|------------------|
|                                  |                         |       |         |             | Assumed ACBM     |         |     | Tested ACBM |         |     |               |      |                  |
|                                  |                         |       |         |             | Total            | Damaged | D/D | Total       | Damaged | D/D |               |      |                  |
| <b>Surfacing Material</b>        |                         |       |         |             |                  |         |     |             |         |     |               |      |                  |
| Ceiling Walls                    | 46                      |       |         |             |                  |         |     |             |         |     |               |      |                  |
| North                            | 198                     |       | ✓       |             |                  | N       |     |             |         |     |               |      |                  |
| South                            | 198                     |       | ✓       |             |                  | N       |     |             |         |     |               |      |                  |
| East                             | 198                     |       | ✓       |             |                  | N       |     |             |         |     |               |      |                  |
| West                             | 198                     |       | ✓       |             |                  | N       |     |             |         |     |               |      |                  |
| Other                            |                         |       |         |             |                  | N       |     |             |         |     |               |      |                  |
| <b>Thermal System Insulation</b> |                         |       |         |             |                  |         |     |             |         |     |               |      |                  |
| Pipe                             |                         |       |         |             |                  |         |     |             |         |     |               |      |                  |
| Duct                             |                         |       |         |             |                  |         |     |             |         |     |               |      |                  |
| Fixture                          |                         |       |         |             |                  |         |     |             |         |     |               |      |                  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |                  |         |     |             |         |     |               |      |                  |
| Ceiling Tiles                    | 102                     |       | ✓       |             |                  | N       |     |             |         |     |               |      |                  |
| Floor Tiles                      | 46A                     |       |         |             |                  | N       |     |             |         |     |               |      |                  |
| Window Caulk                     |                         |       |         |             |                  |         |     |             |         |     |               |      |                  |
| JOIST HOLDING                    | 44                      |       |         | ✓           |                  | N       |     |             |         |     |               |      |                  |
| JOIST MASTIC                     | 44A                     |       |         | ✓           |                  | N       |     |             |         |     |               |      |                  |

**D/D** - Degree of Damage  
**M** - Minor  
**S** - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

**115 South Avenue**

Building ID No.:

7.11

**Date of Inspection:**

93-6188

**Influence of Vibration:** ~~HIGH~~ MODERATE LOW/NONE

~~SECRET~~  
MODERATE

### Potential for Air Erosion:

**LOW/NONE**

HIGH MODERATE LOW/NONE

### Potential for Air Erosion:

LOWDOWN

210, 231, 1

210, 231, 1

| Type of Material          | Homogeneous Area ID No. | Color | Friable | Non-Friable | Suspect Material |         |     |     |       |             |     |     |            |  | ACM AHERA Rank | Removal Priority |
|---------------------------|-------------------------|-------|---------|-------------|------------------|---------|-----|-----|-------|-------------|-----|-----|------------|--|----------------|------------------|
|                           |                         |       |         |             | Assumed ACBM     |         |     |     |       | Tested ACBM |     |     |            |  |                |                  |
|                           |                         |       |         |             | Total            | Damaged | D/D | P/D | Total | Damaged     | D/D | P/D | Sample No. |  |                |                  |
| Surfacing Material        |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| Ceiling                   |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| Walls                     | 46                      |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| North                     | 148/198                 |       | ✓       |             |                  | 2958    | N   |     | M     |             |     |     |            |  | 2              | 6                |
| South                     |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| East                      | 198                     |       | ✓       |             |                  | 2458    | N   |     | M     |             |     |     |            |  | 2              | 6                |
| West                      | 198                     |       | ✓       |             |                  | 2458    | N   |     | M     |             |     |     |            |  | 2              | 6                |
| Other                     |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| Thermal System Insulation |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| Pipe                      |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| Duct                      |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| Fixture                   |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| Miscellaneous Material    |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| Ceiling Tiles             |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| Floor Tiles               | 148A                    |       |         | ✓           | 9SF              | N       |     | M   |       |             |     |     |            |  | 2              | 6                |
| Window Caulk              |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
| FDC                       | 0030                    |       | ✓       |             | 4F               | N       |     | M   |       |             |     |     |            |  | 2              | 6                |
| (ONE HOLDING)             | 89                      |       | ✓       |             | 4F               | N       |     | M   |       |             |     |     |            |  | 2              | 6                |
| (ONE PLASTIC)             | 44A                     |       | ✓       |             | 4F               | N       |     | M   |       |             |     |     |            |  | 2              | 6                |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |
|                           |                         |       |         |             |                  |         |     |     |       |             |     |     |            |  |                |                  |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

**115 South Avenue**

Building ID No.:

7.11

Date of Inspection:

05/27/21

Influence of Vibration: SLIGHT HIGH MODERATE LOW NONE

**MODERATE**

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

5/7 x 11/11

7.110

### TELECOMMUNICATIONS

**Ceiling Height:**

8 FT 7 INCH

[illegible]

D/D - Degree of Damage

M - Minor

**S - Significant**

**P/D - Potential for Damage**

M - Minor (Generally Not Accessible)

Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:  
Date of Inspection:

7.11  
8/27/01

Influence of Vibration:

HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.:

7.11P

Type of Space:

OFFICE

Ceiling Height:

7 FT 11 INCH

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

16'8 x 12'11

| Type of Material          | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |       |         | ACM AHERA Y/N | Rank | Removal Priority |
|---------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|------------------|-------|---------|---------------|------|------------------|
|                           |                         |       |         |             | Total        | Damaged | D/D | P/D              | Total | Damaged |               |      |                  |
| Surfacing Material        |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Ceiling                   | 40                      |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Walls                     |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| North                     | 102-08                  |       |         |             |              |         |     |                  |       |         |               |      |                  |
| South                     | 40                      |       |         |             |              |         |     |                  |       |         |               |      |                  |
| East                      | 102-08                  |       |         |             |              |         |     |                  |       |         |               |      |                  |
| West                      | 40                      |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Other                     |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Thermal System Insulation |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Pipe                      |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Duct                      |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Fixture                   |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Miscellaneous Material    |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Ceiling Tiles             | 102                     |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Floor Tiles               | 140F                    |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Window Caulk              |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| COVE MOLDING              | 44                      |       |         |             |              |         |     |                  |       |         |               |      |                  |
| CONCRETE                  | 44A                     |       |         |             |              |         |     |                  |       |         |               |      |                  |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant / Accessible



Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:  
Date of Inspection:

7.11  
9/27/01

Influence of Vibration:

HIGH MODERATE LOW

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 7.11R  
Type of Space: OFFICE  
Ceiling Height: 7 FT 10 INCH

Potential for Air Erosion:

HIGH MODERATE LOW

10'2 x 18'4

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |         |     | ACM AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|------------------|---------|-----|----------------|------------------|
|                                  |                         |       |         |             | Total        | Damaged | D/D | Total            | Damaged | D/D |                |                  |
| <b>Surfacing Material</b>        |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Ceiling                          | 410                     |       |         |             |              |         |     |                  |         |     |                |                  |
| Walls                            | 113                     |       |         |             |              |         |     |                  |         |     |                |                  |
| North                            | 193-190A                |       |         |             |              |         |     |                  |         |     |                |                  |
| South                            | 193                     |       |         |             |              |         |     |                  |         |     |                |                  |
| East                             | 400                     |       |         |             |              |         |     |                  |         |     |                |                  |
| West                             |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Other                            |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Pipe                             | 003                     |       |         |             |              |         |     |                  |         |     |                |                  |
| Duct                             |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Fixture                          |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Ceiling Tiles                    | 142                     |       |         |             |              |         |     |                  |         |     |                |                  |
| Floor Tiles                      | 148F                    |       |         |             |              |         |     |                  |         |     |                |                  |
| Window Caulk                     | 245D                    |       |         |             |              |         |     |                  |         |     |                |                  |
| COVE MOLDED                      | 44                      |       |         |             |              |         |     |                  |         |     |                |                  |
| COVE MASTIC                      | 44A                     |       |         |             |              |         |     |                  |         |     |                |                  |

D/D - Degree of Damage

M - Minor

S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
S - Significant







Building Name:  
Building Address:

8 FT 7 INCH

CONVINCED

OUR ADVICE

9'6x 21'

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for CM Only)

D/D - Degree of Damage  
M - Minor  
S - Significant

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

**115 South Avenue**

Space ID No.:

Type of Space: TRANSITION ROOM

Ceiling Height: 9 FT 4 INCH

## 7.11

9/27/01

**Influence of Vibration: HIGH MODERATE LOW/NONE**

### Potential for Air Erosion:

(6'10 x 132)  
(12'5 x 219)

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Moderate

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/27/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 711V  
Type of Space: USER SUPPORT  
Ceiling Height: 8 FT 4 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

(11'2 x 16'8)  
(21'5 x 30'5)

| Type of Material          | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |       |         | ACM AHERA Rank | Removal Priority |     |
|---------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|------------------|-------|---------|----------------|------------------|-----|
|                           |                         |       |         |             | Total        | Damaged | D/D | P/D              | Total | Damaged |                |                  | D/D |
| Surfacing Material        |                         |       |         |             |              |         |     |                  |       |         |                |                  |     |
| Ceiling                   | 416                     |       |         |             |              |         |     |                  |       |         |                |                  |     |
| Walls                     | 40                      |       |         |             |              |         |     |                  |       |         |                |                  |     |
| North                     | 40                      |       |         |             |              |         |     |                  |       |         |                |                  |     |
| South                     | 40                      |       |         |             |              |         |     |                  |       |         |                |                  |     |
| East                      | 40                      |       |         |             |              |         |     |                  |       |         |                |                  |     |
| West                      | 40                      |       |         |             |              |         |     |                  |       |         |                |                  |     |
| Other                     |                         |       |         |             |              |         |     |                  |       |         |                |                  |     |
| Thermal System Insulation |                         |       |         |             |              |         |     |                  |       |         |                |                  |     |
| Pipe                      | 003                     |       |         |             |              |         |     |                  |       |         |                |                  |     |
| Duct                      | A000A                   |       | ✓       |             | 8F           | N       |     | M                | 8LF   | N       |                | Y                | 2   |
| Fixture                   | 00B                     |       | ✓       |             | 6LF          | N       |     | M                | 6LF   | N       |                | Y                | 2   |
| Miscellaneous Material    |                         |       |         |             |              |         |     |                  |       |         |                |                  |     |
| Ceiling Tiles             | 148G                    |       |         |             |              |         |     |                  |       |         |                |                  |     |
| Floor Tiles               | 24SD                    |       |         |             | 966SF        | N       |     | M                |       |         |                |                  |     |
| Window Caulk              | 38                      |       | ✓       |             | 20LF         | N       |     | M                |       |         |                |                  |     |
| COVE MOLDING              | 419A                    |       | ✓       |             | 159LF        | N       |     | S                |       |         |                |                  |     |
| COVE MOLDING              | 419A                    |       | ✓       |             | 159LF        | N       |     | S                |       |         |                |                  |     |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant / Accessible

## Rundel

115 South Avenue

Building ID No.:

## 7.11

Date of Inspection:

# 1

**Influence of Vibration: HIGH MODERATE LOW/NONE**

HIGH MODERATE LOW/NONE

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

HIGH MODERATE LOW/NONE

2 FT 7 INCH

7 INCH

(3'4 x 3'7) -  
U6'2 x 14'1)

(3'4 x 3'7) -  
U6'2 x 14'1)

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable |
|----------------------------------|-------------------------|-------|---------|-------------|
| <b>Surfacing Material</b>        |                         |       |         |             |
| Ceiling Walls                    | 46                      |       |         |             |
| North                            | 198                     |       | ✓       |             |
| South                            | 40                      |       |         |             |
| East                             | 198                     |       | ✓       |             |
| West                             | 40                      |       |         |             |
| Other                            |                         |       |         |             |
| <b>Thermal System Insulation</b> |                         |       |         |             |
| Pipe                             | 03                      |       |         |             |
| Duct                             |                         |       |         |             |
| Fixture                          |                         |       |         |             |
| <b>Miscellaneous Material</b>    |                         |       |         |             |
| Ceiling Tiles                    |                         |       |         |             |
| Floor Tiles                      | 1485                    |       |         |             |
| Window Caulk                     | 245D                    |       |         |             |
| COVE MOLDING                     | 38                      |       |         |             |
| COVE MASTIC                      | 7A                      |       |         |             |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for Cleaning)





**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 7.11V

Type of Space: STAGNANT AREA CASE

Ceiling Height: 8 FT 8 INCH

Potential for Air Erosion: HIGH MODERATE LOW NONE

13'5" x 4'1"

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

**115 South Avenue**

Building ID No.:

## 7.11

Date of Inspection:

2127/1

**Influence of Vibration: HIGH MODERATE LOW NONE**

~~LOW~~NONE

### Potential for Air Erosion:

**HIGH MODERATE**

**LOW/NONE**

17x12'1

Space ID No.:

7.11 ΔA

Type of Space: [

BREAK ROOM

**Ceiling Height:**

1

7 INCH

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

17X12'1

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible, 5-6 ft. O.C.)



Building Name: Rundel  
Building Address: 115 South

**Rundel**  
**115 South Avenue**

**Building ID No.:**

---

7.11

Date of Inspection:

2027/10

**Influence of Vibration:** HIGH MODERATE LOW NONE

**HIGH MODERATE LOW**

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

5'5 x 15'7

LOW/NONE

D/D - Degree of Damage  
M - Minor  
S - Significant

**P/D - Potential for Damage**  
**M - Minor (Generally Not Accessible)**

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel!

**115 South Avenue**

**Building ID No.:**

**Date of Inspection:**

**Influence of Vibration: HIGH MODERATE LOW/NONE**

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

)

### Suspect Material

1

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O.M.C.A.)



Building Name: Rundel  
Building Address: 115 South

Space ID No.: M7-11A

Type of Space: LITERATURE MANAGER  
Ceiling Height:

8 FT | INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

**Influence of Vibration:** HIGH MODERATE LOW NONE

20'3x16'2

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant / Accessible

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/28/01  
 Influence of Vibration: HIGH MODERATE (LOW/NONE)

ROOM-BY-ROOM INSPECTION FORM Space ID No.: M7-11B  
 Type of Space: CENTRAL LIBRARY OFFICE AREA  
 Ceiling Height: 8 FT 1 INCH (3'3" x 12'2")  
 Potential for Air Erosion: HIGH MODERATE (LOW/NONE) (4'4" x 13'4") (3'3" x 22'5")

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Suspect Material |         |     |             |         |         | ACM AHERA Y/N | Rank | Removal Priority |
|----------------------------------|-------------------------|-------|---------|-------------|------------------|---------|-----|-------------|---------|---------|---------------|------|------------------|
|                                  |                         |       |         |             | Assumed ACBM     |         |     | Tested ACBM |         |         |               |      |                  |
|                                  |                         |       |         |             | Total            | Damaged | D/D | P/D         | Total   | Damaged | D/D           | P/D  | Sample No.       |
| <b>Surfacing Material</b>        |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| Ceiling                          |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| Walls                            |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| North                            | 02/9A                   |       |         | ✓           | 59150            | N       |     |             | M 59150 | N       |               |      | M 59150-01       |
| South                            | 8-19B                   |       |         | ✓           | 8250             | N       |     |             | M 8250  | N       |               |      | M 8250-01        |
| East                             | 8-19B                   |       |         | ✓           | 8250             | N       |     |             | M 8250  | N       |               |      | M 8250-01        |
| West                             |                         |       |         | ✓           | 4150/50150       | N       |     |             | M 4150  | N       |               |      | M 4150-01        |
| Other                            |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| <b>Thermal System Insulation</b> |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| Pipe                             |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| Duct                             |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| Fixture                          |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| Ceiling Tiles                    |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| Floor Tiles                      | 148H                    |       |         | ✓           | 59150            | N       |     |             | M 59150 | N       |               |      | M 59150-01       |
| Window Caulk                     |                         |       |         |             |                  |         |     |             |         |         |               |      |                  |
| Concrete                         | 3B                      |       |         | ✓           | 47LF             | N       |     |             | M 47LF  | N       |               |      | M 47LF-01        |
| Concrete                         | 44A                     |       |         | ✓           | 47LF             | N       |     |             | M 47LF  | N       |               |      | M 47LF-01        |

\* = plaster only -

D/D - Degree of Damage  
 M - Minor  
 S - Significant

P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)  
 N - Not Significant (Accessible for O.M.C.)



Space ID No.: U7.11C

---

211

11/10/20

10/28/01  
HIGH MODERATE

LOW/NONE

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

DATE

 $21' \times 16' 11''$ 

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable |
|----------------------------------|-------------------------|-------|---------|-------------|
| <b>Surfacing Material</b>        |                         |       |         |             |
| Ceiling                          |                         |       |         |             |
| Walls                            |                         |       |         |             |
| North                            | 02                      |       |         |             |
| South                            | WOOD-GLASS              |       |         |             |
| East                             | B<BOOKSHELVES>          |       |         |             |
| West                             | 8                       |       |         |             |
| Other                            | 8<BOOKSHELVES>          |       |         |             |
| <b>Thermal System Insulation</b> |                         |       |         |             |
| Pipe                             |                         |       |         |             |
| Duct                             | 003                     |       |         |             |
| Fixture                          |                         |       |         |             |
| <b>Miscellaneous Material</b>    |                         |       |         |             |
| Ceiling Tiles                    |                         |       |         |             |
| Floor Tiles                      | 149H                    |       |         |             |
| Window Caulk                     | 246C                    |       |         |             |

D/D - Degree of Damage

M - Minor

**S - Significant**

**P/D - Potential for Damage**

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 47.11D

Type of Space: SOUTHWEST STAIRS (F1)

**Ceiling Height:**

10 FT 11 INCH

HIGH MODERATE LOW NONE

**Potential for Air Erosion:**

Continuance of Vibration: HIGH MODERATE LOW/NONE

$\langle 5 \times 4/10 \rangle$  STAGE 1 FLIGHT  
BELOW; HOC: 9'8"

[illegible]

D/D - Degree of Damage

**M - Minor**

### S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Aesthetic)







**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

**1115 South Avenue**

Building ID No.: 7.11

7.11

Date of Inspection:

8/28/20

Influence of Vibration: HIGH MODERATE LOW/NONE

**LOWANONE**

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

DATE RECEIVED

8 FT 11 INCH  
Climbing Height:

ACT NOC: 3'

Space ID No.: M7.11G

Type of Space: REFERENCE AREA

**Ceiling Height:**

8 FT 11 INCH  
Climbing Height:
$$\left( \frac{14' \times 8'}{29'9 \times 7'} \right)^+$$
[illegible]

~~A~~ = plaster only

**D/D** - Degree of Damage  
**M** - Minor  
**S** - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)











Building Name: Rundel  
Building Address: 115 South Avenue  
Building ID No.: 7.11  
Date of Inspection: 8/29/01  
Influence of Vibration: HIGH

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 7F7-11A  
Type of Space: REPAIR / INSPECTION AREA  
Ceiling Height: 10 FT 0 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

8'0" x 29'6"  
4'1" x 17'3"

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

\* ON EXTERIOR WINDOWS

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/29/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 1F7.11B  
Type of Space: PERIODICALS CHILDREN'S LIBRARY  
Ceiling Height: 18 FT 0 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

79' X 49'6"

| Type of Material          | Homogeneous Area ID No. | Color                  | Friable | Non-Friable | Assumed ACBM |         |     |     | Tested ACBM |         |     |     | ACM AHERA  |     | Removal Priority |      |
|---------------------------|-------------------------|------------------------|---------|-------------|--------------|---------|-----|-----|-------------|---------|-----|-----|------------|-----|------------------|------|
|                           |                         |                        |         |             | Total        | Damaged | D/D | P/D | Total       | Damaged | D/D | P/D | Sample No. | Y/N |                  | Rank |
|                           |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| Surfacing Material        |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| Ceiling                   |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| Walls                     |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| North                     | 02                      |                        |         |             | 3871SE       | N       |     |     | M           | 3871SE  |     |     |            |     | M11C-10C-10C     | 2    |
| South                     | 80                      |                        |         |             | 1422SE       | N       |     |     | M           | 1422SE  | N   |     |            |     | M11C-10C-10C     | 2    |
| East                      | 198                     |                        |         |             | 1422SE       | N       |     |     | M           | 1422SE  | N   |     |            |     | M11C-10C-10C     | 2    |
| West                      | 80                      |                        |         |             | 311SE        | N       |     |     | M           | 311SE   | N   |     |            |     | M11C-10C-10C     | 2    |
| Other areas               |                         |                        |         |             | 891SE        | N       |     |     | M           | 891SE   | N   |     |            |     | M11C-10C-10C     | 2    |
| DECKING PATENTED          | 198                     |                        |         |             | 2570SE       | N       |     |     | M           | 2570SE  |     |     |            |     |                  | 2    |
| Thermal System Insulation |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| Pipe                      |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| Duct                      |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| Fixture                   |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| Miscellaneous Material    |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| Ceiling Tiles             |                         |                        |         |             |              |         |     |     |             |         |     |     |            |     |                  |      |
| Floor Tiles               | 148A                    | CONCRETE WOOD FLOORING |         |             | 3871SE       | N       |     |     | M           | 3871SE  |     |     |            |     |                  | 2    |
| Window Caulk              | 248C                    |                        |         |             | 1422SE       | N       |     |     | M           | 1422SE  | N   |     |            |     | M11C-10C-10C     | 2    |
| COVE MOLDING              | 300                     |                        |         |             | 290LF        | N       |     |     | M           | 290LF   |     |     |            |     |                  | 2    |
| COVE MASTIC               | 44A                     |                        |         |             | 290LF        | N       |     |     | M           | 290LF   |     |     |            |     |                  | 2    |
| WINDOW CAULK              | 245D                    |                        |         |             | 120LF        | N       |     |     | M           | 120LF   |     |     |            |     |                  | 2    |
| COVE MOLDING              | 244C                    |                        |         |             | 79LF         | N       |     |     | M           | 79LF    |     |     |            |     |                  | 2    |
| FLOOR TILES               | 124                     | 124A                   |         |             | 150SF        | N       |     |     | M           | 150SF   |     |     |            |     |                  | 2    |

\* NO MASTIC - NAILED ON

D/D - Degree of Damage  
M - Minor

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)



Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:

7.11

Date of Inspection:

8/29/01

Influence of Vibration:

HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.:

7F 7.11C

Type of Space:

ELECTRICAL MECHANICAL AREA (STAIR/BOILER)

Ceiling Height:

18 FT 0 INCH

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

Potential for Air Erosion:

LOW/NONE

108'6 x 41'9"

| Type of Material          | Homogeneous Area ID No.    | Color | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material |         |     |     | ACM Y/N | AHERA Rank | Removal Priority |             |
|---------------------------|----------------------------|-------|---------|-------------|--------------|---------|-----|-----|------------------|---------|-----|-----|---------|------------|------------------|-------------|
|                           |                            |       |         |             | Total        | Damaged | D/D | P/D | Total            | Damaged | D/D | P/D |         |            |                  |             |
|                           |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  | Tested ACBM |
| Surfacing Material        |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Ceiling                   |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Walls                     |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| North                     | 02                         |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| South                     | 80 (WOODEN BOARDS/PLASTER) |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| East                      | 80 (WOODEN BOARDS/PLASTER) |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| West                      | 80 (WOODEN BOARDS/PLASTER) |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Other                     | 80 (WOODEN BOARDS/PLASTER) |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Thermal System Insulation |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Pipe                      |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Duct                      |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Fixture                   |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Miscellaneous Material    |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Ceiling Tiles             |                            |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Floor Tiles               | 148A                       |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| Window Caulk              | 248C                       |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| PIPE MOLDING              | *444A                      |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |
| WINDOW CRACK              | 245D                       |       |         |             |              |         |     |     |                  |         |     |     |         |            |                  |             |

\*NO MASTIC-NAILED ON

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Applicable)

Building Name: Rundel  
Building Address: 115 South Avenue  
Building ID No.: 7.11  
Date of Inspection: 8/30/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: IF7.11D  
Type of Space: CONFERENCE ROOM  
Ceiling Height: 9 FT 6 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

15'3 x 13'3

| Type of Material          | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |       |         | ACM AHERA Y/N | Rank | Removal Priority |
|---------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|------------------|-------|---------|---------------|------|------------------|
|                           |                         |       |         |             | Total        | Damaged | D/D | P/D              | Total | Damaged |               |      |                  |
| Surfacing Material        |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Ceiling                   |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Walls                     |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| North                     | 8                       |       |         |             |              |         |     |                  |       |         |               |      |                  |
| South                     | 8/wood slat             |       |         |             | 126 SF       | N       |     |                  |       |         |               |      |                  |
| East                      | 8                       |       |         |             | 20 SF        | N       |     |                  |       |         |               |      |                  |
| West                      | 8                       |       |         |             | 145 SF       | N       |     |                  |       |         |               |      |                  |
| Other                     | 8                       |       |         |             | 145 SF       | N       |     |                  |       |         |               |      |                  |
| Thermal System Insulation |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Pipe                      |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Duct                      |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Fixture                   |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Miscellaneous Material    |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Ceiling Tiles             |                         |       |         |             |              |         |     |                  |       |         |               |      |                  |
| Floor Tiles               | Asph/47                 |       |         |             | 202 SF       | N       |     |                  |       |         |               |      |                  |
| Window Caulk              | 2486                    |       |         |             | 54 SF        | N       |     |                  |       |         |               |      |                  |
| DOVE MOLDING              | 70                      |       |         |             | 18.5 LF      | N       |     |                  |       |         |               |      |                  |
| DOVE MASTIC               | 44A                     |       |         |             | 18.5 LF      | N       |     |                  |       |         |               |      |                  |
| PT MASTIC                 | AB21M                   |       |         |             | 202 SF       | N       |     |                  |       |         |               |      |                  |
|                           | 14B                     |       |         |             | 202 SF       | N       |     |                  |       |         |               |      |                  |

★ FLOOR TILE ONLY

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for ACM Only)

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/30/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 1F7.11 E  
Type of Space: FICTION AREA  
Ceiling Height: 12 FT ONCH  
HOC: 8'8"

Potential for Air Erosion: HIGH MODERATE LOW/NONE

31' x 78'

| Type of Material              |  | Homogeneous Area ID No. | Color              | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |         |         | ACM AHERA Rank | Removal Priority |            |     |      |          |  |
|-------------------------------|--|-------------------------|--------------------|---------|-------------|--------------|---------|-----|------------------|---------|---------|----------------|------------------|------------|-----|------|----------|--|
|                               |  |                         |                    |         |             | Total        | Damaged | D/D | P/D              | Total   | Damaged | D/D            | P/D              | Sample No. | Y/N | Rank | Priority |  |
| Surfacing Material            |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Ceiling                       |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Walls                         |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| North                         |  | 02                      |                    |         |             | 2410 SF      | N       |     | M                | 2410 SF | N       |                | M                | 1111E-CARL | Y   | 2    | 6        |  |
| South                         |  | 0C                      |                    |         |             | 558 SF       | N       |     | M                | 558 SF  | N       |                | M                | 1111E-CARL | Y   | 1    | 7        |  |
| East                          |  | 0C                      |                    |         |             | 558 SF       | N       |     | M                | 558 SF  | N       |                | M                | 1111E-CARL | Y   | 1    | 7        |  |
| West                          |  | 0C                      | WOODEN BRACKS (MS) |         |             | 1404 SF      | N       |     | M                | 1404 SF | N       |                | M                | 1111E-CARL | Y   | 1    | 7        |  |
| Other                         |  | 0C                      |                    |         |             | 676 SF       | N       |     | M                | 676 SF  | N       |                | M                | 1111E-CARL | Y   | 1    | 7        |  |
| PARTITION WALL (WOOD & GLASS) |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Thermal System Insulation     |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Pipe                          |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Duct                          |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Fixture                       |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Miscellaneous Material        |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Ceiling Tiles                 |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Floor Tiles                   |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| Window Caulk                  |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| COVE MOLDING                  |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| FLOOR TILES                   |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| WINDOW CAULK                  |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| COVE MOLDING                  |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |
| COVE MASTIC                   |  |                         |                    |         |             |              |         |     |                  |         |         |                |                  |            |     |      |          |  |

\* NO MASTIC - N/AILED ON

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally New & Acceptable)

Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:  
Date of Inspection:

7.11  
8/30/01

Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: IF 7.11F  
Type of Space: HALLWAY  
Ceiling Height: 8 FT 2 INCH (5' x 11')

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | Suspect Material |     | ACM AHERA Rank | Removal Priority |            |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|-------------|-------|---------|------------------|-----|----------------|------------------|------------|
|                                  |                         |       |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged | D/D              | P/D |                |                  | Sample No. |
| <b>Surfacing Material</b>        |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| Ceiling                          |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| Walls                            |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| North                            | 9                       |       | ✓       |             | 160 SF       | N       |     | N           |       |         |                  |     |                |                  |            |
| South                            | 8 - WOODPANELING        |       | ✓       |             | 57 SF        | N       |     | S           |       |         |                  |     |                | 2                | 6          |
| East                             | WOODPANELING            |       |         |             |              |         |     |             |       |         |                  |     |                | 1                | 7          |
| West                             | 8                       |       | ✓       |             | 123 SF       | N       |     | S           |       |         |                  |     |                | 1                | 7          |
| Other                            | WOOD / GLASS            |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| Pipe                             |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| Duct                             |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| Fixture                          |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| Ceiling Tiles                    |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| Floor Tiles                      | 48A                     |       |         | ✓           | 160 SF       | N       |     | M           |       |         |                  |     |                | 2                | 6          |
| Window Caulk                     |                         |       |         |             |              |         |     |             |       |         |                  |     |                |                  |            |
| COVE MOLDING                     | 73                      |       | ✓       |             | 40 SF        | N       |     | M           |       |         |                  |     |                | 2                | 6          |
| COVE MOLDING                     | 44A                     |       | ✓       |             | 40 SF        | N       |     | M           |       |         |                  |     |                | 2                | 6          |
|                                  | 204                     |       | ✓       |             | 36 SF        | N       |     | M           |       |         |                  |     |                | 2                | 6          |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)



Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:

7.11

Date of Inspection:

9/30/01

Influence of Vibration:

HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 7F7.11 H

Type of Space: LENOVA AREA

Ceiling Height:

12 FT 2 INCH

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

62'6" X 106'

| Type of Material                 | Homogeneous Area ID No. | Color              | Friable | Non-Friable | Assumed ACBM |         |     |     | Tested ACBM |         |     |     | ACM AHERA Y/N | Rank | Removal Priority |            |   |
|----------------------------------|-------------------------|--------------------|---------|-------------|--------------|---------|-----|-----|-------------|---------|-----|-----|---------------|------|------------------|------------|---|
|                                  |                         |                    |         |             | Total        | Damaged | D/D | P/D | Total       | Damaged | D/D | P/D |               |      |                  |            |   |
|                                  |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  | Sample No. |   |
| <b>Surfacing Material</b>        |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| Ceiling                          |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| Walls                            |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| North                            | 07                      | WOOD / B (ASSUMED) |         | ✓           | 16305F       | N       |     |     | M           | 16305F  | N   |     |               | M    | 16305F           | 2          | 6 |
| South                            |                         | WOOD / B (ASSUMED) |         | ✓           | 7205F        | N       |     |     | M           | 7205F   | N   |     |               | M    | 7205F            | 1          | 7 |
| East                             |                         | WOOD / B (ASSUMED) |         | ✓           | 7205F        | N       |     |     | M           | 7205F   | N   |     |               | M    | 7205F            | 1          | 7 |
| West                             |                         | WOOD / B (ASSUMED) |         | ✓           | 15305F       | N       |     |     | M           | 15305F  | N   |     |               | M    | 15305F           | 1          | 7 |
| Other                            |                         | WOOD / B (ASSUMED) |         | ✓           | 17105F       | N       |     |     | M           | 17105F  | N   |     |               | M    | 17105F           | 1          | 7 |
| <b>Thermal System Insulation</b> |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| Pipe                             |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| Duct                             |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| Fixture                          |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| <b>Miscellaneous Material</b>    |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| Ceiling Tiles                    | 71A                     | GLASS / METAL      |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| Floor Tiles                      | 155                     |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| Window Caulk                     |                         |                    |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |   |
| FLOOR TILES                      | 148A                    |                    |         | ✓           | 160789F      | N       |     |     | M           |         |     |     |               |      |                  | 2          | 6 |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

100







4'9 x 10'7

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

Building Name: Rundel  
Building Address: 115 South Avenue  
Building ID No.: 7.11  
Date of Inspection: 8/30/01  
Influence of Vibration: HIGH MODERATE (LOW) NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 1F7.1/L  
Type of Space: HALLWAY  
Ceiling Height: 8 FT 4 INCH

Potential for Air Erosion: HIGH MODERATE (LOW) NONE

Potential for Air Erosion: HIGH MODERATE (LOW) NONE

(19'3" x 12') - 12SF

| Type of Material          | Homogeneous Area ID No. | Color               | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | ACM AHERA |     | Removal Priority |
|---------------------------|-------------------------|---------------------|---------|-------------|--------------|---------|-----|-------------|-------|---------|-----------|-----|------------------|
|                           |                         |                     |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged | D/D       | P/D |                  |
| Surfacing Material        |                         |                     |         |             |              |         |     |             |       |         |           |     |                  |
| Ceiling                   |                         |                     |         |             |              |         |     |             |       |         |           |     |                  |
| Walls                     | 9                       |                     |         |             |              |         |     |             |       |         |           |     |                  |
| North                     | 19's                    | TEXTURED PAPER / 8C | ✓       |             | 231SP        | N       |     |             |       |         |           |     |                  |
| South                     |                         |                     | ✓       |             | 30SF         | N       |     |             |       |         |           |     |                  |
| East                      |                         | TEXTURED PAPER / 8C | ✓       |             | 100SF        | N       |     |             |       |         |           |     |                  |
| West                      | 12' 8C                  |                     | ✓       |             | 100SF        | N       |     |             |       |         |           |     |                  |
| Other                     | 8C                      |                     | ✓       |             | 100SF        | N       |     |             |       |         |           |     |                  |
| Thermal System Insulation |                         |                     |         |             |              |         |     |             |       |         |           |     |                  |
| Pipe                      |                         |                     |         |             |              |         |     |             |       |         |           |     |                  |
| Duct                      |                         |                     |         |             |              |         |     |             |       |         |           |     |                  |
| Fixture                   |                         |                     |         |             |              |         |     |             |       |         |           |     |                  |
| Miscellaneous Material    |                         |                     |         |             |              |         |     |             |       |         |           |     |                  |
| Ceiling Tiles             |                         |                     |         |             |              |         |     |             |       |         |           |     |                  |
| Floor Tiles               | 11A / 111A              |                     |         |             | 231SP        | N       |     |             |       |         |           |     |                  |
| Window Caulk              | 246C                    |                     | ✓       |             | 30SF         | N       |     |             |       |         |           |     |                  |
| CEMENT MORTAR             | 73                      |                     | ✓       |             | 8LF          | N       |     |             |       |         |           |     |                  |
| JOINT MASTIC              | 44A                     |                     | ✓       |             | 8LF          | N       |     |             |       |         |           |     |                  |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 2F7.11K

Type of Space: CONFERENCE ROOM (EAST SIDE)

Ceiling Height: 9 FT 5 INCH

HIGH MODERATE LOW NONE

### Potential for Air Erosion:

| Influence of Vibration:    | HIGH       | MODERATE   | LOW/NONE   |
|----------------------------|------------|------------|------------|
| 1. Frequency of Vibration  | 100-200 Hz | 200-400 Hz | 400-800 Hz |
| 2. Amplitude of Vibration  | 0.5-1.0 mm | 1.0-2.0 mm | 2.0-4.0 mm |
| 3. Duration of Vibration   | 1-2 hours  | 2-4 hours  | 4-8 hours  |
| 4. Direction of Vibration  | Vertical   | Horizontal | Diagonal   |
| 5. Intensity of Vibration  | High       | Moderate   | Low        |
| 6. Frequency of Vibration  | 100-200 Hz | 200-400 Hz | 400-800 Hz |
| 7. Amplitude of Vibration  | 0.5-1.0 mm | 1.0-2.0 mm | 2.0-4.0 mm |
| 8. Duration of Vibration   | 1-2 hours  | 2-4 hours  | 4-8 hours  |
| 9. Direction of Vibration  | Vertical   | Horizontal | Diagonal   |
| 10. Intensity of Vibration | High       | Moderate   | Low        |

13'2" x 14'10"

D/D - Degree of Damage  
M - Minor

**P/D - Potential for Damage**

Building Name: Rundel  
 Building Address: 115 South Avenue

Building ID No.: 7.11  
 Date of Inspection: 9/31/01  
 Influence of Vibration: HIGH MODERATE LOW NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 1F7.110  
 Type of Space: ELEVATOR BALCONY  
 Ceiling Height: 8 FT 3 INCH

Potential for Air Erosion: HIGH MODERATE LOW NONE  
 (6' x 4')  
 (15' x 5')

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |         |     | ACM AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|------------------|---------|-----|----------------|------------------|
|                                  |                         |       |         |             | Total        | Damaged | D/D | Total            | Damaged | D/D |                |                  |
| <b>Surfacing Material</b>        |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Ceiling                          |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Walls                            |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| North                            | 9                       |       | ✓       |             | 99sf         | N       |     | M                |         |     |                |                  |
| South                            | 8                       |       | ✓       |             | 157sf        | N       |     | m                | 157sf   | N   |                | 6                |
| East                             | 8-19B                   |       | ✓       |             | 120sf        | N       |     | m                | 120sf   | N   |                | 7                |
| West                             |                         |       | ✓       |             | 120sf        | N       |     | m                | 120sf   | N   |                | 7                |
| Other                            | 19B                     |       | ✓       |             | 120sf        | N       |     | m                | 120sf   | N   |                | 7                |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Pipe                             |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Duct                             |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Fixture                          |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Ceiling Tiles                    |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Floor Tiles                      |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Window Caulk                     |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| COVE MOLDING                     | 73                      | TAN   |         |             | 25LF         | N       |     | m                | 25LF    | N   |                | 6                |
| COVE MOLDING                     | 44A                     | WHITE |         |             | 25LF         | N       |     | m                | 25LF    | N   |                | 6                |

★ PLASTER ONLY



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: ZF7.11Q

Type of Space: STANDARD

Ceiling Height: 9 FT 7 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

 $2' \times 3' 11$ 

13'10x 6'8

**Building ID No.:**

**Date of Inspection:**

Influence of Vibration: HIGH MODERATE LOW/NONE

| Type of Material                 | Homogeneous Area ID No. | Color     | Friable | Non-Friable |
|----------------------------------|-------------------------|-----------|---------|-------------|
| <b>Surfacing Material</b>        |                         |           |         |             |
| Ceiling                          |                         |           |         |             |
| Walls                            | 9 METAL-CONCRETE        | STAINLESS | ✓       |             |
| North                            | 40                      |           |         |             |
| South                            | 40 AB                   |           |         |             |
| East                             | 40                      |           | ✓       |             |
| West                             | 40-198                  |           | ✓       |             |
| Other                            |                         |           |         |             |
| <b>Thermal System Insulation</b> |                         |           |         |             |
| Pipe                             |                         |           |         |             |
| Duct                             |                         |           |         |             |
| Fixture                          |                         |           |         |             |
| <b>Miscellaneous Material</b>    |                         |           |         |             |
| Ceiling Tiles                    |                         |           |         |             |
| Floor Tiles                      | 147                     |           |         |             |
| Window Caulk                     |                         |           |         |             |

D/D - Degree of Damage  
M - Minor  
S - Severe

**P/D - Potential for Damage**





**Building Name:** Rundel  
**Building Address:** 115 South Avenue

**Space ID No.:**

SF7.15

Type of Space: MEAS RCM

ELIS ROHM

**Ceiling Height:**

511

Building ID No.: 7.11

## 7.11

**Date of Inspection:**

9/3/0

| Influence of Vibration: | HIGH | Moderate | LOW/NONE |
|-------------------------|------|----------|----------|
| <b>Slip/St.</b>         | 0.80 | 0.60     | 0.40     |

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

(1418 x 710)

[illegible]D/D - Degree of Damage  
M - Minor

**P/D - Potential for Damage**  
**M - Minor (Generally Not Accessible)**



**Building Name:** Runde  
**Building Address:** 115 South Avenue

**Space ID No.:**

Space ID No.: 157.114  
Type of Space: CUSTODIANS CLOSET

Type of Space: CUSTOMS CLOSET  
Ceiling Height: 1

8 FT 4 INCH

HIGH MODERATE LOW/NONE

### Potential for Air Erosion:

**Influence of Vibration: HIGH MODERATE LOW/NONE**

9/31/01

112

**Building ID No.:**

**Date of Inspection:**

## Influence of Vibration

6, 7, 8, 9

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable |
|----------------------------------|-------------------------|-------|---------|-------------|
| <b>Surfacing Material</b>        |                         |       |         |             |
| Ceiling Walls                    | 9                       |       |         |             |
| North                            | TEXTURED PAPER / BC     |       |         |             |
| South                            | TEXTURED PAPER / BC     |       |         |             |
| East                             | TEXTURED PAPER / BC     |       |         |             |
| West                             | TEXTURED PAPER / BC     |       |         |             |
| Other                            |                         |       |         |             |
| <b>Thermal System Insulation</b> |                         |       |         |             |
| Pipe                             |                         |       |         |             |
| Duct                             |                         |       |         |             |
| Fixture                          |                         |       |         |             |
| <b>Miscellaneous Material</b>    |                         |       |         |             |
| Ceiling Tiles                    |                         |       |         |             |
| Floor Tiles                      | 1-9                     |       |         |             |
| Window Caulk                     |                         |       |         |             |

**D/D - Degree of Damage**  
**M - Minor**

**P/D - Potential for Damage**

Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:

7.11

Date of Inspection:

3/31/01

Influence of Vibration:

HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 1F7.11V

Type of Space: LITERACY

Ceiling Height: 8 FT 4 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE  
(13'4 x 18)  
(7'10 x 5'9)

| Type of Material                 | Homogeneous Area ID No.     | Color | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | ACM/AHERA |     | Removal Priority |
|----------------------------------|-----------------------------|-------|---------|-------------|--------------|---------|-----|-------------|-------|---------|-----------|-----|------------------|
|                                  |                             |       |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged | D/D       | P/D |                  |
| <b>Surfacing Material</b>        |                             |       |         |             |              |         |     |             |       |         |           |     |                  |
| Ceiling                          |                             |       |         |             |              |         |     |             |       |         |           |     |                  |
| Walls                            |                             |       |         |             |              |         |     |             |       |         |           |     |                  |
| North                            | 9A                          |       |         |             | 205 SF       | N       |     |             |       |         |           |     |                  |
| South                            | 8                           |       |         |             | 13 x 84      | N       |     |             |       |         |           |     |                  |
| East                             | TEXURED PAPER / BC          |       |         |             | 13 x 84      | N       |     |             |       |         |           |     |                  |
| West                             | 19B                         |       |         |             | 13 x 84      | N       |     |             |       |         |           |     |                  |
| Other                            | TEXURED PAPER / BC - FANDED |       |         |             | 13 x 84      | N       |     |             |       |         |           |     |                  |
| <b>Thermal System Insulation</b> |                             |       |         |             |              |         |     |             |       |         |           |     |                  |
| Pipe                             |                             |       |         |             | 48 SF        | N       |     |             |       |         |           |     |                  |
| Duct                             |                             |       |         |             |              |         |     |             |       |         |           |     |                  |
| Fixture                          |                             |       |         |             |              |         |     |             |       |         |           |     |                  |
| <b>Miscellaneous Material</b>    |                             |       |         |             |              |         |     |             |       |         |           |     |                  |
| Ceiling Tiles                    | 100B                        |       |         |             |              |         |     |             |       |         |           |     |                  |
| Floor Tiles                      | 14B                         |       |         |             |              |         |     |             |       |         |           |     |                  |
| Window Caulk                     |                             |       |         |             |              |         |     |             |       |         |           |     |                  |
| COVE MOLDING                     | 3B                          |       |         |             |              |         |     |             |       |         |           |     |                  |
| COVE MASTIC                      | 44A                         |       |         |             |              |         |     |             |       |         |           |     |                  |

D/D - Degree of Damage  
M - Minor  
S - Significant

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/31/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2F7.11W  
 Type of Space: STRAZUELL Foyer  
 Ceiling Height: 8 FT 4 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE  
 (6'2 x 7'8) (45)  
 (4'10 x 8'6) 45

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |            |            |            | Tested ACBM |         |     |     | ACM Y/N | AHERA Rank | Removal Priority |  |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|------------|------------|------------|-------------|---------|-----|-----|---------|------------|------------------|--|
|                                  |                         |       |         |             | Total        | Damaged    | D/D        | P/D        | Total       | Damaged | D/D | P/D |         |            |                  |  |
|                                  |                         |       |         |             | Sample No.   | Sample No. | Sample No. | Sample No. |             |         |     |     |         |            |                  |  |
| <b>Surfacing Material</b>        |                         |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| Ceiling Walls                    |                         |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| North                            | 9A                      |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| South                            | 8C                      |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| East                             | 8C                      |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| West                             | 8C                      |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| Other                            | 8C                      |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| Pipe                             |                         |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| Duct                             |                         |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| Fixture                          |                         |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| Ceiling Tiles                    | 180B                    |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| Floor Tiles                      | 111A/111AM              |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| Window Caulk                     |                         |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| QUE-MOD/MSY                      | 73                      |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |
| QUE-MOD/MSY                      | 44A                     |       |         |             |              |            |            |            |             |         |     |     |         |            |                  |  |

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/31/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM Space ID No.: 1F7.11X  
 Type of Space: WOMEN'S ROOM  
 Ceiling Height: 9 FT 5 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE  
 7' x 5'

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material Tested ACBM |       |         | ACM AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|------------------------------|-------|---------|----------------|------------------|
|                                  |                         |       |         |             | Total        | Damaged | D/D | P/D                          | Total | Damaged |                |                  |
| <b>Surfacing Material</b>        |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| Ceiling                          |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| Walls                            |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| North                            | 9A                      |       |         |             |              |         |     |                              |       |         |                |                  |
| South                            | 97/18C                  |       |         |             |              |         |     |                              |       |         |                |                  |
| East                             | 97/18C                  |       |         |             |              |         |     |                              |       |         |                |                  |
| West                             | 97/18C                  |       |         |             |              |         |     |                              |       |         |                |                  |
| Other                            |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| Pipe                             |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| Duct                             |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| Fixture                          |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| Ceiling Tiles                    |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| Floor Tiles                      |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| Window Caulk                     |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| COVE MOLDING                     |                         |       |         |             |              |         |     |                              |       |         |                |                  |
| COVE MASTIC                      |                         |       |         |             |              |         |     |                              |       |         |                |                  |

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

**Building Name:**  
**Building Address:**

Rundel  
115 Sol

**Building ID No.:**

**Date of Inspection:**

Influence of Vibration: HIGH MODERATE LOW/NONE

### Potential for Air Erosion:

**Space ID No.:**

Type of Space: STAIRWELL TO UPPER STACK  
Ceiling Height: 7'-11"

7 FT 7 INCH

HIGH MODERATE LOW/NONE

2'10x 12'6

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable |
|----------------------------------|-------------------------|-------|---------|-------------|
| <b>Surfacing Material</b>        |                         |       |         |             |
| Ceiling                          |                         |       |         |             |
| Walls                            | 9A                      |       |         |             |
| North                            | 146                     |       |         |             |
| South                            | (TEAR) BRICK / AC       |       |         |             |
| East                             |                         |       |         |             |
| West                             | (CRACKED PAINT) / AC    |       |         |             |
| Other                            |                         |       |         |             |
| <b>Thermal System Insulation</b> |                         |       |         |             |
| Pipe                             |                         |       |         |             |
| Duct                             |                         |       |         |             |
| Fixture                          |                         |       |         |             |
| <b>Miscellaneous Material</b>    |                         |       |         |             |
| Ceiling Tiles                    | 14/B/A                  |       |         |             |
| Floor Tiles                      |                         |       |         |             |
| Window Caulk                     |                         |       |         |             |
| COVE HOLDING                     | 73                      |       |         |             |
| COVE MASTIC                      | 41/A                    |       |         |             |

**D/D - Degree of Damage**  
**M - Minor**

### P/D - Potential for Damage

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 1F7-112  
Type of Space: STARKWELL  
Ceiling Height: 9 FT 7 INCH

Building ID No.: 7.11  
 Date of Inspection: 8/31/01  
 Influence of Vibration: HIGH MODERATE ~~LOW/NONE~~

Potential for Air Erosion: HIGH MODERATE LOW NONE

6'7 x 13'6

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Severe

**P/D - Potential for Noise**



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 1F7.11AA

Type of Space: LOBBY / SECURIN STAIRWAY  
Ceiling Height: 7'-0" / 7'-10"

428 6776

9 FT 6 INCH

10' x 5' 2"

**HIGH MODERATE LOW/NONE**

### Potential for Air Erosion:

~~HIGH~~ MODERATE LOW NONE

### Influence of Vibration:

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable |
|----------------------------------|-------------------------|-------|---------|-------------|
| <b>Surfacing Material</b>        |                         |       |         |             |
| Ceiling                          |                         |       |         |             |
| Walls                            |                         |       |         |             |
| North                            | 02 <MARBLE>             |       |         | ✓           |
| South                            |                         |       |         |             |
| East                             | 8C <MARBLE>             |       |         | ✓           |
| West                             | 8C <MARBLE>             |       |         | ✓           |
| Other                            | 8C <MARBLE>             |       |         | ✓           |
| <b>Thermal System Insulation</b> |                         |       |         |             |
| Pipe                             |                         |       |         |             |
| Duct                             |                         |       |         |             |
| Fixture                          |                         |       |         |             |
| <b>Miscellaneous Material</b>    |                         |       |         |             |
| Ceiling Tiles                    |                         |       |         |             |
| Floor Tiles                      | MARBLE STRIPS           |       |         |             |
| Window Caulk                     |                         |       |         |             |

**D/D - Degree of Damage**  
**M - Minor**

**P/D - Potential for Damage**



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 2C-711A  
Type of Space: FOUR 10 2ND FLOOR  
Ceiling Height:

Type of Space: EDUCATION INCH  
Ceiling Height: 11 FT

Potential for Air Erosion: HIGH MODERATE LOW/NONE

(23425)

| Influence of Vibration: | HIGH | MODERATE | LOW/NONE |
|-------------------------|------|----------|----------|
| Person:                 | 2    | 3        | 0        |

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

**P/D - Potential for Damage**

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/21/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2F-7116  
Type of Space: STAIR WBL  
Ceiling Height: 11 FT - INCH  
27' LBNJ.  
(5x7) 2ND FLOOR LANDING  
(5x5) 2ND TO 1ST FLOOR LANDING

15 x 28 108 1258  
90 148 268  
774  
Potential for Air Erosion: 1172  
28 112

| Type of Material          |                     | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     |     | Tested ACBM |         |     |     | ACM AHERA  | Removal Priority |      |
|---------------------------|---------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|-----|-------------|---------|-----|-----|------------|------------------|------|
|                           |                     |                         |       |         |             | Total        | Damaged | D/D | P/D | Total       | Damaged | D/D | P/D | Sample No. | Y/N              | Rank |
| Surfacing Material        |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| Ceiling                   |                     |                         |       |         |             | 185 SF       | N       |     |     |             |         |     |     |            |                  |      |
| Walls                     |                     |                         |       |         |             | 77 SF        | N       |     |     |             |         |     |     |            |                  |      |
| North                     | 9                   | WHT/gray                | ✓     |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| South                     | 8                   | orange                  | ✓     |         |             | 55 SF        | N       |     |     |             |         |     |     |            |                  |      |
| East                      | 8                   |                         | ✓     |         |             | 407 SF       | N       |     |     |             |         |     |     |            |                  |      |
| West                      | 8                   |                         | ✓     |         |             | 352 SF       | N       |     |     |             |         |     |     |            |                  |      |
| Other                     | 8/open to 2nd floor |                         | ✓     |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| Thermal System Insulation |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| Pipe                      |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| Duct                      |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| Fixture                   |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| Miscellaneous Material    |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| Ceiling Tiles             |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| Floor Tiles               | A330                | cream+BLK (MARBLE)      | ✓     |         |             | 6LF          | N       |     |     |             |         |     |     |            |                  |      |
| Window Caulk              | A450                | gray                    | ✓     |         |             | 1118 LF      | N       |     |     |             |         |     |     |            |                  |      |
| "                         | A480                | TAN                     | ✓     |         |             |              |         |     |     |             |         |     |     |            |                  |      |
| STAIRS = MARBLE           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |
|                           |                     |                         |       |         |             |              |         |     |     |             |         |     |     |            |                  |      |

D/D - Degree of Damage  
M - Minor

1774  
344

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

**Building ID No.:**

7.11

---

711

14/01/2019

704

**Ceiling Height:**

Ceiling Height: HALFWAY - 2nd Floor

**Date of Inspection:**

9461

---

9/4/6

160  
120  
120  
120

27  
19

12 FT - INCH

|                         | LOW | MODERATE | HIGH | MODERATE | HIGH | MODERATE | LOW/NONE |
|-------------------------|-----|----------|------|----------|------|----------|----------|
| Influence of Vibration: |     |          |      |          |      |          |          |

$\frac{1}{\partial \text{Potential for A}} = \frac{1}{24}$

1

(12 x 12)

| Type of Material                 | Homogeneous Area ID No. | Color            | Friable | Non-Friable |
|----------------------------------|-------------------------|------------------|---------|-------------|
| <b>Suspect Material</b>          |                         |                  |         |             |
| <b>Assumed ACBM</b>              |                         |                  |         |             |
| <b>Tested ACBM</b>               |                         |                  |         |             |
| Total                            | Damaged                 | D/D              | P/D     | Total       |
| Damaged                          | D/D                     | P/D              | D/D     | P/D         |
| Sample No.                       |                         |                  |         |             |
| ACM Y/N                          | AHERA Rank              | Removal Priority |         |             |
| <b>Surfacing Material</b>        |                         |                  |         |             |
| Ceiling Walls                    | 9                       | (?)              | ✓       | 1572 SF     |
| North                            | B                       | cream            | ✓       | 144 SF      |
| South                            | B                       |                  | ✓       | "           |
| East                             | B                       |                  | ✓       | 1572 SF     |
| West                             | B                       |                  | ✓       | "           |
| Other                            |                         |                  | ✓       | 1572 SF     |
| <b>Thermal System Insulation</b> |                         |                  |         |             |
| Pipe                             | -                       |                  |         |             |
| Duct                             | -                       |                  |         |             |
| Fixture                          | -                       |                  |         |             |
| <b>Miscellaneous Material</b>    |                         |                  |         |             |
| Ceiling Tiles                    | 71A                     | curtains         |         |             |
| Floor Tiles                      | A311C                   |                  |         |             |
| Window Caulk                     | 248C                    | tan              |         |             |
| Linedoor Miter                   | A311CM                  |                  |         |             |
| Core Moldings (wood)             | 70                      | MARON            |         |             |
| " - Plastic                      | 46A                     | TAN              |         |             |
| Window Caulk                     | 245D                    | gray             |         |             |
| Windows                          |                         |                  |         |             |

**D/D - Degree of Damage**  
**M - Minor**

**P/D - Potential for Damage**

Space ID No.: 2F711D  
Type of Space: STAFF BATH  
Ceiling Height:

Potential for Air Erosion: HIGH MODERATE LOW/NONE

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

Space ID No.: 2F-71E

Type of Space: Historian's office

Ceiling Height: 9 FT - INCH

**Potential for Air Erosion:** HIGH MODERATE LOW/NONE

(91xh1)

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

**P/D - Potential for Damage**  
**M - Minor (Generally Not Accessible)**  
**N - Not Significant / Accessible**





**Building Name:** Rundel  
**Building Address:** 115 South

**Space ID No.:**

**Type of Space:**

**Ceiling Height:**

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

| Influence of Vibration:   | HIGH             | MODERATE           | LOW/NONE        |
|---------------------------|------------------|--------------------|-----------------|
| 1. Frequency of Vibration | 100-200 Hz       | 20-100 Hz          | Below 20 Hz     |
| 2. Amplitude of Vibration | 0.1-0.5 mm       | 0.05-0.1 mm        | Below 0.05 mm   |
| 3. Duration of Exposure   | Continuous       | Intermittent       | Short-term      |
| 4. Direction of Vibration | Vertical         | Horizontal         | Rotational      |
| 5. Environmental Factors  | High Temperature | Normal Temperature | Low Temperature |
| 6. Material Properties    | Brittle          | Plastic            | Elastic         |
| 7. Structural Design      | Stiff            | Flexible           | Resilient       |
| 8. Maintenance            | Neglected        | Regular            | Proactive       |
| 9. Load Conditions        | Overload         | Normal             | Underload       |
| 10. Seismic Activity      | High             | Medium             | Low             |

**MODERATE LOW/NONE**

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Total  | Damaged | D/D | P/D | Total  | Damaged | D/D | P/D | Sample No. | ACM AHERA Y/N | Rank | Removal Priority |
|----------------------------------|-------------------------|-------|---------|-------------|--------|---------|-----|-----|--------|---------|-----|-----|------------|---------------|------|------------------|
| <b>Surfacing Material</b>        |                         |       |         |             |        |         |     |     |        |         |     |     |            |               |      |                  |
| Ceiling                          |                         |       |         |             |        |         |     |     |        |         |     |     |            |               |      |                  |
| Walls                            | 9                       |       |         |             | 144 SF | N       |     | M   |        |         |     |     |            |               |      |                  |
| North                            | 198                     | cream |         |             | 108 SF | N       |     | M   |        |         |     |     |            |               | 2    | 6                |
| South                            | 198                     |       |         |             | 108 SF | N       |     | M   |        |         |     |     |            |               | 2    | 6                |
| East                             | 8                       |       |         |             | 108 SF | N       |     | M   |        |         |     |     |            |               | 2    | 6                |
| West                             | 198                     |       |         |             | 108 SF | N       |     | M   | 108 SF | N       |     |     |            |               | 1    | 7                |
| Other                            |                         |       |         |             | 108 SF | N       |     | M   |        |         |     |     |            |               | 2    | 6                |
| <b>Thermal System Insulation</b> |                         |       |         |             |        |         |     |     |        |         |     |     |            |               |      |                  |
| Pipe                             |                         |       |         |             |        |         |     |     |        |         |     |     |            |               |      |                  |
| Duct                             |                         |       |         |             |        |         |     |     |        |         |     |     |            |               |      |                  |
| Fixture                          |                         |       |         |             |        |         |     |     |        |         |     |     |            |               |      |                  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |        |         |     |     |        |         |     |     |            |               |      |                  |
| Ceiling Tiles (N/A)              | 198B                    | W/LX  |         |             | 144 SF | N       |     | M   |        |         |     |     |            |               |      |                  |
| Floor Tiles                      | 198C                    | Tan   |         |             | 576 SF | N       | S   | M   | 576 SF | N       |     |     |            |               | 2    | 6                |
| Window Caulk                     | A31D                    | UNK   |         |             | 144 SF | N       |     | M   | 144 SF | N       |     |     |            |               | 2    | 6                |
| "                                | A31D                    | UNK   |         |             | 144 SF | N       |     | M   | 144 SF | N       |     |     |            |               | 1    | 7                |
| Over Mold (N/A)                  | 7D                      | Tan   |         |             | 336 SF | N       |     | M   | 336 SF | N       |     |     |            |               | 2    | 6                |
| "                                | 49A                     | Tan   |         |             | 336 SF | N       |     | M   | 336 SF | N       |     |     |            |               | 2    | 6                |

D/D - Degree of Damage  
M - Minor  
S - Significant

**P/D - Potential for Damage**  
**M - Minor (Generally Not Accessible)**

## Rundel

**115 South Avenue**

**Building ID No.:**

7.11

**Date of Inspection:**

9/4/01

**Influence of Vibration: HIGH MODERATE LOW/NONE**

**MODERATE**

### Potential for Air Erosion:

**HIGH MODERATE LOW/NONE**

(12th 9)

Space ID No.: 2C-71114

Type of Space: STORAGE

**Ceiling Height:**

9 FT INCH

[illegible]

DiD - Degree of Damage

**M - Minor**

**S - Significant**

**P/D - Potential for Damage**

**M**

Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:  
Date of Inspection:

7.11  
9/4/01

Influence of Vibration:

HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2F-711I

Type of Space: LOCAL HISTORY / GENERAL USE LIBRARY

Ceiling Height:

9' FT - INCH (ENTRY)  
12' - PLAT MAP (30 x 52) (ENTRY / PLAT MAP AREA)

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

(33x34) MICROFILM RECOVERY AREA

| Type of Material                 | Homogeneous Area ID No. | Color       | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | ACM AHERA Rank | Removal Priority |     |
|----------------------------------|-------------------------|-------------|---------|-------------|--------------|---------|-----|-------------|-------|---------|----------------|------------------|-----|
|                                  |                         |             |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged |                |                  | D/D |
| <b>Surfacing Material</b>        |                         |             |         |             |              |         |     |             |       |         |                |                  |     |
| Ceiling                          |                         |             |         |             |              |         |     |             |       |         |                |                  |     |
| Walls                            |                         |             |         |             |              |         |     |             |       |         |                |                  |     |
| North (18' of 18)                | 9                       | cream       | ✓       |             | 2682 SF      | N       |     |             |       |         |                |                  |     |
| South (162 SF)                   | 10B                     |             | ✓       |             | 678 SF       | N       |     |             |       |         |                |                  |     |
| East                             | 8                       |             | ✓       |             | 768 SF       | N       |     |             |       |         |                |                  |     |
| West                             | 8                       |             | ✓       |             | 567 SF       | N       |     |             |       |         |                |                  |     |
| Other                            | 8                       |             | ✓       |             | 567 SF       | N       |     |             |       |         |                |                  |     |
| <b>Thermal System Insulation</b> |                         |             |         |             |              |         |     |             |       |         |                |                  |     |
| Pipe                             |                         |             |         |             |              |         |     |             |       |         |                |                  |     |
| Duct                             |                         |             |         |             |              |         |     |             |       |         |                |                  |     |
| Fixture                          |                         |             |         |             |              |         |     |             |       |         |                |                  |     |
| <b>Miscellaneous Material</b>    |                         |             |         |             |              |         |     |             |       |         |                |                  |     |
| Ceiling Tiles (NOD)              | 180B                    | WH          |         |             |              |         |     |             |       |         |                |                  |     |
| Floor Tiles                      | 148A                    |             |         |             |              |         |     |             |       |         |                |                  |     |
| Window Caulk                     | 248C                    | tan         | ✓       |             | 2682 SF      | N       |     |             |       |         |                |                  |     |
| Cove Molding (New)               | 38                      | BRN         | ✓       |             | 348 SF       | Y       |     |             |       |         |                |                  |     |
| " " (New)                        | 40R                     | cream       | ✓       |             | 78 SF        | N       |     |             |       |         |                |                  |     |
| Cove Molding                     | 497L                    | BLK granite | ✓       |             | 78 SF        | N       |     |             |       |         |                |                  |     |
| " " (New)                        |                         |             | ✓       |             |              |         |     |             |       |         |                |                  |     |
| Window Caulk                     | 245D                    | grey        | ✓       |             | 48 SF        | N       |     |             |       |         |                |                  |     |

\* plaster only  
(19R = 2/10 ranking)

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
S - Significant

Building Name:

Building Address:

Rundel

115 South Avenue

Building ID No.:

7.11

Date of Inspection:

9/4/01

Influence of Vibration:

HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.:

2F-711J

Type of Space:

GENEALOGY LIBRARY

Ceiling Height:

12 FT. 1 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

32 x 46

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |     |         |     | Suspect Material |     |         |     | ACM AHERA Rank | Removal Priority |  |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|-----|---------|-----|------------------|-----|---------|-----|----------------|------------------|--|
|                                  |                         |       |         |             | Total        |     | D/D     |     | Total            |     | D/D     |     |                |                  |  |
|                                  |                         |       |         |             | Damaged      | D/D | Damaged | D/D | Damaged          | D/D | Damaged | D/D |                |                  |  |
| <b>Surfacing Material</b>        |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Ceiling                          | 9                       | Cream | ✓       |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Walls                            |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| North wall                       | 8                       |       | ✓       |             |              |     |         |     |                  |     |         |     |                |                  |  |
| South wall                       | 8                       |       | ✓       |             |              |     |         |     |                  |     |         |     |                |                  |  |
| East fireplace                   | 8                       |       | ✓       |             |              |     |         |     |                  |     |         |     |                |                  |  |
| West wall                        | 8                       |       | ✓       |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Other                            |                         |       | ✓       |             |              |     |         |     |                  |     |         |     |                |                  |  |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Pipe                             |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Duct                             |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Fixture                          |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Ceiling Tiles                    |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Floor Tiles                      | 148A                    |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Window Caulk                     | 245D                    |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Cable Molding                    | 38                      |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| " " Mastic                       | 48A                     |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Window Caulk                     | 48C                     |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |
| Cable Molding                    | A92                     |       |         |             |              |     |         |     |                  |     |         |     |                |                  |  |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/10/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

Room-By-Room Inspection Form  
 Space ID No.: 2C-711K  
 Type of Space: HALLWAY  
 Ceiling Height: 10 FT — INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE  
 (10 x 66)

| Type of Material                 | Homogeneous Area ID No. | Color  | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | ACM AHERA Rank | Removal Priority |     |     |
|----------------------------------|-------------------------|--------|---------|-------------|--------------|---------|-----|-------------|-------|---------|----------------|------------------|-----|-----|
|                                  |                         |        |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged |                |                  | D/D | P/D |
|                                  |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| <b>Surfacing Material</b>        |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| Ceiling                          |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| Walls                            |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| North                            | 66'                     | —      | ✓       |             | 660 SF       | N       |     |             |       |         |                |                  |     |     |
| South                            |                         | Orange | ✓       |             | 660 SF       | N       |     |             |       |         |                |                  |     |     |
| East                             | 10'                     | ↓      | ✓       |             | "            | N       |     |             |       |         |                |                  |     |     |
| West                             |                         | ↓      | ✓       |             | 100 SF       | N       |     |             |       |         |                |                  |     |     |
| Other                            |                         | ↓      | ✓       |             | 100 SF       | N       |     |             |       |         |                |                  |     |     |
| <b>Thermal System Insulation</b> |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| Pipe                             |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| Duct                             |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| Fixture                          |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| <b>Miscellaneous Material</b>    |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| Ceiling Tiles                    | 71A                     | Green  |         |             |              |         |     |             |       |         |                |                  |     |     |
| Floor Tiles                      | A21C                    |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| Window Caulk                     |                         |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| Acoustic Material                | A21C M                  |        |         |             |              |         |     |             |       |         |                |                  |     |     |
| Other Material (M)               | A21C M                  | Green  |         |             |              |         |     |             |       |         |                |                  |     |     |
| " " (M)                          | A21C M                  | Tan    |         |             |              |         |     |             |       |         |                |                  |     |     |

Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:  
Date of Inspection:  
Influence of Vibration:

7.11  
9/4/01  
HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2C-711 L  
Type of Space: FILE STORAGE  
Ceiling Height: 9 FT 1 INCH

2348  
x 6/8

Potential For Air Erosion:

HIGH MODERATE LOW/NONE

(19 x 35)  
(11 x 20) (NEAR OF STORAGE)

| Type of Material          | Homogeneous Area ID No. | Color  | Friable   | Non-Friable | Assumed ACBM |         |     |     | Tested ACBM |         |     |     | ACM AHERA Rank | Removal Priority |                  |
|---------------------------|-------------------------|--------|-----------|-------------|--------------|---------|-----|-----|-------------|---------|-----|-----|----------------|------------------|------------------|
|                           |                         |        |           |             | Total        | Damaged | D/D | P/D | Total       | Damaged | D/D | P/D |                |                  |                  |
|                           |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  | Suspect Material |
| Surfacing Material        |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Ceiling                   |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Walls                     |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| North                     | 35' + 20'               | 40/8'  | tan/brown |             |              |         |     |     |             |         |     |     |                |                  |                  |
| South                     | "                       | 40/8'  | tan       |             |              |         |     |     |             |         |     |     |                |                  |                  |
| East                      | 19'                     | 8      | green     |             |              |         |     |     |             |         |     |     |                |                  |                  |
| West                      |                         | 40/198 | tan/brown |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Other                     |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Thermal System Insulation |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Pipe                      |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Duct                      |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Fixture                   |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Radiator                  |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Miscellaneous Material    |                         |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Ceiling Tiles (new)       | 18DB                    |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Floor Tiles               | 124                     |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Window Caulk              | 240C                    |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Love molybdenum           | 33                      |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| " " MACAC                 | 48A                     |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| Window Latch              | 245D                    |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |
| ET Mastic                 | 124B                    |        |           |             |              |         |     |     |             |         |     |     |                |                  |                  |

D/D - Degree of Damage  
M - Minor  
S - Significant

13/40/13  
\* plaster only

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/4/09  
 Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2F-711M  
 Type of Space: FILE STORAGE  
 Ceiling Height: 9 FT — INCH  
(13 x 29)

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | ACM AHERA Rank | Removal Priority |     |     |            |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|-------------|-------|---------|----------------|------------------|-----|-----|------------|
|                                  |                         |       |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged |                |                  | D/D | P/D | Sample No. |
|                                  |                         |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| <b>Surfacing Material</b>        |                         |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| Ceiling                          |                         |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| Walls                            |                         |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| North                            | 13'                     | WH    |         |             | 377SF        | N       |     |             |       |         |                |                  |     |     |            |
| South                            | 40                      | green |         |             | 117SF        | N       |     |             |       |         |                |                  |     |     |            |
| East                             | 29'                     | tan   |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| West                             | 40                      | tan   |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| Other                            | 40                      | v     |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| Pipe                             |                         |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| Duct                             |                         |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| Fixture                          |                         |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| Ceiling Tiles (new)              | 1200B                   |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| Floor Tiles                      | 1200                    |       |         |             |              |         |     |             |       |         |                |                  |     |     |            |
| Window Caulk                     | 245D                    |       |         |             | 377SF        | N       |     |             |       |         |                |                  |     |     |            |
| Window Cable                     | 248C                    |       |         |             | 111F         | N       |     |             |       |         |                |                  |     |     |            |
| Cable Modem/Router               | 38                      | Brn   |         |             | 1044F        | N       |     |             |       |         |                |                  |     |     |            |
| " " Modem                        | 418A                    | Green |         |             | 7LF          | N       |     |             |       |         |                |                  |     |     |            |
| FT. Modem                        | 124A                    | Blk   |         |             | 7LF          | N       |     |             |       |         |                |                  |     |     |            |
|                                  |                         |       |         |             | 377SF        | N       |     |             |       |         |                |                  |     |     |            |

D/D - Degree of Damage  
 M - Minor  
 S - Significant

P/D - Potential for Damage  
 M - Minor (Generally Not Applicable)





**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 2f-711D

Type of Space: Office

Ceiling Height: 10 FT — INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

Incidence of Vibration: **HIGH** **MODERATE** **LOW/NONE**

$$(13 \times 20)$$

| Type of Material          | Homogeneous Area ID No. | Color      | Friable | Non-Friable | Suspect Material |         |     |     |             |         |        |     | ACM AHERA Rank | Removal Priority |
|---------------------------|-------------------------|------------|---------|-------------|------------------|---------|-----|-----|-------------|---------|--------|-----|----------------|------------------|
|                           |                         |            |         |             | Assumed ACBM     |         |     |     | Tested ACBM |         |        |     |                |                  |
|                           |                         |            |         |             | Total            | Damaged | D/D | P/D | Total       | Damaged | D/D    | P/D |                |                  |
| Surfacing Material        |                         |            |         |             |                  |         |     |     |             |         |        |     |                |                  |
| Ceiling                   | 9                       |            |         |             | 260 SF           | N       |     |     |             | M       |        |     |                |                  |
| Walls                     |                         |            |         |             |                  |         |     |     |             |         |        |     |                |                  |
| North                     | 19B                     | WHT        |         |             | 136 SF           | N       |     |     |             | M       |        |     | 2              | 6                |
| South                     | 8                       |            |         |             | "                | N       |     |     |             | M       |        |     | 2              | 6                |
| East                      | 8                       |            |         |             | 200 SF           | N       |     |     |             | M       | 127116 |     | 1              | 7                |
| West                      | 8                       |            |         |             | "                | N       |     |     |             | M       |        |     | 1              | 7                |
| Other                     |                         |            |         |             |                  | N       |     |     |             | M       |        |     | 1              | 7                |
| Thermal System Insulation |                         |            |         |             |                  |         |     |     |             |         |        |     |                |                  |
| Pipe                      |                         |            |         |             |                  |         |     |     |             |         |        |     |                |                  |
| Duct                      |                         |            |         |             |                  |         |     |     |             |         |        |     |                |                  |
| Fixture                   |                         |            |         |             |                  |         |     |     |             |         |        |     |                |                  |
| Miscellaneous Material    |                         |            |         |             |                  |         |     |     |             |         |        |     |                |                  |
| Ceiling Tiles             | 1600B                   |            |         |             |                  |         |     |     |             |         |        |     |                |                  |
| Floor Tiles               | 14B                     |            |         |             |                  |         |     |     |             |         |        |     |                |                  |
| Window Caulk              | 245D                    | gray       |         |             | 240 SF           | N       |     |     |             | M       |        |     | 2              | 6                |
| Window Caulk              | A311D                   |            |         |             | 16 LF            | N       |     |     |             | M       |        |     | 2              | 6                |
| Window Caulk              | 240C                    | tan        |         |             | 570 LF           | N       |     |     |             | M       | 257116 |     | 1              | 7                |
| Window Caulk              | A311M                   | white/grey |         |             | 240 LF           | N       |     |     |             | M       | 127116 |     | 2              | 6                |
| FT                        | 124                     | unsmooth   |         |             | 240 SF           | N       |     |     |             | M       |        |     | 2              | 6                |
| FT Wash C                 | 124A                    | blk        |         |             | 240 SF           | N       |     |     |             | M       |        |     | 2              | 6                |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

**115 South Avenue**

**Building ID No.:**

7.11

**Date of Inspection:**

$$\frac{10716}{111}$$

|                         | LOW | MODERATE | HIGH | LOW/NONE |
|-------------------------|-----|----------|------|----------|
| Influence of Vibration: |     |          |      |          |

**HIGH MODERATE LO**

### Potential for Air Erosion:

**HIGH MODERATE LOW/NONE**

$$(6 \times 45)$$
Space ID No.: 2f-711P

**Type of Space:**

**Ceiling Height:**

10 FT. — INCH

| Type of Material                 | Homogeneous Area ID No. | Color  | Friable | Non-Friable | Suspect Material |         |     |             |       |         | ACM | AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|--------|---------|-------------|------------------|---------|-----|-------------|-------|---------|-----|------------|------------------|
|                                  |                         |        |         |             | Assumed ACBM     |         |     | Tested ACBM |       |         |     |            |                  |
|                                  |                         |        |         |             | Total            | Damaged | D/D | P/D         | Total | Damaged |     |            |                  |
| <b>Surfacing Material</b>        |                         |        |         |             |                  |         |     |             |       |         |     |            |                  |
| Ceiling                          |                         |        |         |             |                  |         |     |             |       |         |     |            |                  |
| Walls                            |                         |        |         |             |                  |         |     |             |       |         |     |            |                  |
| North                            | 9                       | -      | ✓       |             | 270 SF           | N       |     |             |       |         |     |            |                  |
| South                            | 8                       |        | ✓       |             | 60 SF            | N       |     |             |       |         |     |            |                  |
| East                             | 8                       |        | ✓       |             | "                | N       |     |             |       |         |     |            |                  |
| West                             | 8                       |        | ✓       |             | 450 SF           | N       |     |             |       |         |     |            |                  |
| Other                            | 8                       |        | ✓       |             | "                | N       |     |             |       |         |     |            |                  |
| <b>Thermal System Insulation</b> |                         |        |         |             |                  |         |     |             |       |         |     |            |                  |
| Pipe                             |                         |        |         |             |                  |         |     |             |       |         |     |            |                  |
| Duct                             |                         |        |         |             |                  |         |     |             |       |         |     |            |                  |
| Fixture                          |                         |        |         |             |                  |         |     |             |       |         |     |            |                  |
| <b>Miscellaneous Material</b>    |                         |        |         |             |                  |         |     |             |       |         |     |            |                  |
| Ceiling Tiles                    | 71A                     | cream  |         |             |                  |         |     |             |       |         |     |            |                  |
| Floor Tiles                      | A311C                   | orange |         |             |                  |         |     |             |       |         |     |            |                  |
| Window Caulk                     |                         |        | ✓       |             | 270 SF           | N       |     |             |       |         |     |            |                  |
| Linoleum/Asph                    | A311C                   |        | ✓       |             | 270 SF           | N       |     |             |       |         |     |            |                  |
| Con. Material                    | 7D                      | maroon | ✓       |             | 70 SF            | N       |     |             |       |         |     |            |                  |
| " " Mortar                       | 49A                     | cream  | ✓       |             | 70 SF            | N       |     |             |       |         |     |            |                  |

**DiD - Degree of Damage**

**M - Minor**

### S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/16/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM  
 Space ID No.: 2F-711Q  
 Type of Space: OFFICE-LOCAL HISTORY  
 Ceiling Height: 10 FT — INCH  
 Potential for Air Erosion: HIGH MODERATE LOW/NONE (12x15)

| Type of Material                 | Homogeneous Area ID No. | Color  | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material |         |     |     | ACM/AHERA Rank | Removal Priority |            |
|----------------------------------|-------------------------|--------|---------|-------------|--------------|---------|-----|-----|------------------|---------|-----|-----|----------------|------------------|------------|
|                                  |                         |        |         |             | Total        | Damaged | D/D | P/D | Total            | Damaged | D/D | P/D |                |                  |            |
|                                  |                         |        |         |             |              |         |     |     |                  |         |     |     |                |                  | Sample No. |
| <b>Surfacing Material</b>        |                         |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Ceiling                          |                         |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Walls                            |                         |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| North                            | 15'                     | Wht    | ✓       |             | 180 SF       | N       |     |     |                  |         |     |     |                |                  |            |
| South                            | 8                       | cream  | ✓       |             | 150 SF       | N       |     |     |                  |         |     |     |                |                  |            |
| East (wall above)                | 8                       | ↓      | ✓       |             | "            | N       |     |     |                  |         |     |     |                |                  |            |
| West                             | 12                      | ↓      | ✓       |             | 120 SF       | N       |     |     |                  |         |     |     |                |                  |            |
| Other                            | 8                       | ↓      | ✓       |             | "            | N       |     |     |                  |         |     |     |                |                  |            |
| <b>Thermal System Insulation</b> |                         |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Pipe                             |                         |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Duct                             |                         |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Fixture                          |                         |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Miscellaneous Material           |                         |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Ceiling Tiles (new)              | 180 B                   |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Floor Tiles                      | 148                     |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Window Caulk                     | 245 D                   | gray   |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Base (hold down)                 | 70                      |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| " (Herc)                         | 48 A                    | orange |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Window/Land                      | 248 C                   | tau    |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| Window                           | 241 D                   |        |         |             |              |         |     |     |                  |         |     |     |                |                  |            |
| " Glue                           | 231 D M                 | UNIL   |         |             |              |         |     |     |                  |         |     |     |                |                  |            |

D/D - Degree of Damage  
 M - Minor  
 S - Significant

P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)

**Rundel**  
**115 South Avenue**

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2F-711R  
Type of Space: LOCAL HISTORY OFFICES  
Ceiling Height:

Building ID No.:

**Date of Inspection:**

|                         | LOW | MODERATE | HIGH |
|-------------------------|-----|----------|------|
| Influence of Vibration: | LOW | MODERATE | HIGH |

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

(14 x 43)

| Type of Material          | Homogeneous Area ID No. | Color  | Friable | Non-Friable | Suspect Material |         |     |     |       |             |     |     |            |  | ACM AHERA Y/N | Rank | Removal Priority |
|---------------------------|-------------------------|--------|---------|-------------|------------------|---------|-----|-----|-------|-------------|-----|-----|------------|--|---------------|------|------------------|
|                           |                         |        |         |             | Assumed ACBM     |         |     |     |       | Tested ACBM |     |     |            |  |               |      |                  |
|                           |                         |        |         |             | Total            | Damaged | D/D | P/D | Total | Damaged     | D/D | P/D | Sample No. |  |               |      |                  |
| Surfacing Material        |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| Ceiling                   |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| Walls                     |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| North (71 or 198)         | 9                       |        |         |             |                  | 602 SF  | N   |     |       |             |     |     |            |  |               |      |                  |
| South                     | 8                       | cream  |         |             |                  | 63 SF   | N   |     |       |             |     |     |            |  |               | 2    | 6                |
| East                      | 14                      |        |         |             |                  | 174 SF  | N   |     |       |             |     |     |            |  |               | 1    | 7                |
| West                      | 43                      |        |         |             |                  | 387 SF  | N   |     |       |             |     |     |            |  |               | 1    | 7                |
| Other                     | 8                       |        |         |             |                  | "       | N   |     |       |             |     |     |            |  |               | 1    | 7                |
|                           | 8                       |        |         |             |                  | 387 SF  | N   |     |       |             |     |     |            |  |               | 1    | 7                |
| Thermal System Insulation |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| Pipe                      |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| Duct                      |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| Fixture                   |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| Miscellaneous Material    |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| Ceiling Tiles (new)       | 1806                    |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| Floor Tiles               | 148                     |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
| Window Caulk              | 2450                    | gray   |         |             |                  | 102 SF  | N   |     |       |             |     |     |            |  |               | 2    | 6                |
| "                         | 2482                    | gray   |         |             |                  | 172 SF  | N   |     |       |             |     |     |            |  |               | 2    | 6                |
| Cove molding              | 70                      | maroon |         |             |                  | 7 LF    | N   |     |       |             |     |     |            |  |               | 2    | 6                |
| "                         | 48A                     | maroon |         |             |                  | 7 LF    | N   |     |       |             |     |     |            |  |               | 2    | 6                |
| Linoleum                  | A311D                   | (wood) |         |             |                  | 602 SF  | N   |     |       |             |     |     |            |  |               | 2    | 6                |
| "                         | A311DM                  | glue   |         |             |                  | 602 SF  | N   |     |       |             |     |     |            |  |               | 1    | 7                |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               | 2    | 6                |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       |             |     |     |            |  |               |      |                  |
|                           |                         |        |         |             |                  |         |     |     |       | </          |     |     |            |  |               |      |                  |

\* PLASTER ONLY  
(198 = 635K ranking = 2/16)

D/D - Degree of Damage  
M - Minor  
S - Significant

**P/D - Potential for Damage**  
**M - Minor (Generally Not Accessible)**

# ROOM-BY-ROOM INSPECTION FORM

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/6/61  
 Influence of Vibration: HIGH MODERATE LOW/NONE

Space ID No.: 2F-7.11S  
 Type of Space: MEN'S BATH  
 Ceiling Height: 9 FT — INCH  
 Potential for Air Erosion: HIGH MODERATE LOW/NONE (11 x 12)

| Type of Material          | Homogeneous Area ID No. | Color     | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material |         |     |     | ACM AHERA Rank | Removal Priority |
|---------------------------|-------------------------|-----------|---------|-------------|--------------|---------|-----|-----|------------------|---------|-----|-----|----------------|------------------|
|                           |                         |           |         |             | Total        | Damaged | D/D | P/D | Total            | Damaged | D/D | P/D |                |                  |
|                           |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| Surfacing Material        |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| Ceiling                   |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| Walls                     |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| North                     | 9                       |           | ✓       |             | 132 SF       | N       |     |     | M                |         |     |     |                | 2                |
| South                     | 8                       |           | ✓       |             | 108 SF       | N       |     |     | M                |         |     |     |                | 1                |
| East                      | 198                     |           | ✓       |             | "            | N       |     |     | M                |         |     |     |                | 7                |
| West                      | 198                     |           | ✓       |             | 99 SF        | N       |     |     | M                |         |     |     |                | 6                |
| Other                     | 9                       |           | ✓       |             | 99 SF        | N       |     |     | M                |         |     |     |                | 6                |
| Thermal System Insulation |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| Pipe                      |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| Duct                      |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| Fixture                   |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| Miscellaneous Material    |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| Ceiling Tiles (NIB)       | 1206                    |           |         |             | 132 SF       | N       |     |     | M                |         |     |     |                | 2                |
| Floor Tiles               | 124                     | unlabeled |         | ✓           | 132 SF       | N       |     |     | M                |         |     |     |                | 2                |
| Window Caulk              |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| PT INSUL.                 | 124A                    | blk       |         | ✓           | 132 SF       | N       |     |     | M                |         |     |     |                | 2                |
| Door Moldings             | 38                      | BR        |         | ✓           | 35 SF        | N       |     |     | M                |         |     |     |                | 2                |
| " " MISCH                 | 48A                     | cream     |         | ✓           | 85 SF        | N       |     |     | M                |         |     |     |                | 2                |
| STORAGE CLOSET = (3 x 4)  |                         |           |         |             |              |         |     |     |                  |         |     |     |                |                  |
| PT                        | 124                     | cream oak |         | ✓           | 12 SF        | N       |     |     | M                |         |     |     |                | 2                |
| C                         | 124A                    | blk       |         | ✓           | 12 SF        | N       |     |     | M                |         |     |     |                | 2                |
| N Wall = 198              | 198                     | cream     | ✓       |             | 45 SF        | N       |     |     | M                |         |     |     |                | 2                |
| Ceiling = 15'             |                         |           |         |             |              |         |     |     |                  |         |     |     |                | 2                |
| E, W, S, &                | 9                       | cream     | ✓       |             | 360 SF       | N       |     |     | M                |         |     |     |                | 1                |
|                           |                         |           |         |             |              |         |     |     |                  |         |     |     |                | 7                |

Building Name:  
Building Address:

Rundel  
115 South Avenue

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 26-711T

16 panes

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

10 1/8

Building ID No.:  
Date of Inspection:

7.11  
9/16/01

Influence of Vibration: HIGH MODERATE LOW/NONE

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

(11 x 14)

| Type of Material          | Homogeneous Area ID No. | Color     | Friable | Non-Friable | Suspect Material |         |     |             |       |         | ACM AHERA Rank | Removal Priority |
|---------------------------|-------------------------|-----------|---------|-------------|------------------|---------|-----|-------------|-------|---------|----------------|------------------|
|                           |                         |           |         |             | Assumed ACBM     |         |     | Tested ACBM |       |         |                |                  |
|                           |                         |           |         |             | Total            | Damaged | D/D | P/D         | Total | Damaged |                |                  |
| Surfacing Material        |                         |           |         |             |                  |         |     |             |       |         |                |                  |
| Ceiling                   |                         |           |         |             | 154 SF           | N       |     |             |       |         |                |                  |
| Walls                     |                         |           |         |             |                  |         |     |             |       |         |                |                  |
| North                     | 9                       | cream     |         |             |                  |         |     |             |       |         |                |                  |
| South                     | 8                       |           |         |             | 121 SF           | N       |     |             |       |         |                |                  |
| East                      | 108                     |           |         |             | "                | N       |     |             |       |         |                |                  |
| West                      | 8                       |           |         |             | 154 SF           | Y       | S   |             |       |         |                |                  |
| Other                     | 108                     |           |         |             | "                | N       |     |             |       |         |                |                  |
| Thermal System Insulation |                         |           |         |             |                  |         |     |             |       |         |                |                  |
| Pipe                      | Copper                  | unwrapped |         |             |                  |         |     |             |       |         |                |                  |
| Duct                      | (new)                   | D/D       |         |             |                  |         |     |             |       |         |                |                  |
| Fixture                   | Acoustical              |           |         |             |                  |         |     |             |       |         |                |                  |
| Miscellaneous Material    |                         |           |         |             |                  |         |     |             |       |         |                |                  |
| Ceiling Tiles             |                         |           |         |             |                  |         |     |             |       |         |                |                  |
| Floor Tiles               | 124                     |           |         |             |                  |         |     |             |       |         |                |                  |
| Window Caulk              | 846D                    |           |         |             |                  |         |     |             |       |         |                |                  |
| ET MISC                   | 124A                    |           |         |             |                  |         |     |             |       |         |                |                  |
| Window Caulk              | 248C                    |           |         |             |                  |         |     |             |       |         |                |                  |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/6/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2F-711A  
 Type of Space: LOCAL HISTORICAL STORAGE  
 Ceiling Height: 1st level = 6 FT 2nd level = 6 FT INCH  
HIGH MODERATE LOW/NONE (14 x 44) (14 x 44)

Potential for Air Erosion:

| Type of Material          | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |   |         |   |        | Suspect Material |       |   |         |   | ACM AHERA Y/N | Rank | Removal Priority |     |     |            |
|---------------------------|-------------------------|-------|---------|-------------|--------------|---|---------|---|--------|------------------|-------|---|---------|---|---------------|------|------------------|-----|-----|------------|
|                           |                         |       |         |             | Total        |   | Damaged |   | D/D    | P/D              | Total |   | Damaged |   |               |      |                  | D/D | P/D | Sample No. |
|                           |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Surfacing Material        |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Ceiling                   |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Walls                     |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| North                     | 9                       | Wht   | ✓       |             | 616 SF       | N |         |   |        |                  |       |   |         |   |               | 2    | 6                |     |     |            |
| South                     | 8                       |       | ✓       |             | 168 SF       |   |         |   |        |                  |       |   |         |   |               | 1    | 7                |     |     |            |
| East                      | 8                       |       | ✓       |             | "            |   |         |   |        |                  |       |   |         |   |               | 1    | 7                |     |     |            |
| West (33' of 198)         | 198/8                   |       | ✓       |             | 528 SF       |   |         |   |        |                  |       |   |         |   |               | 1    | 7                |     |     |            |
| Other (336 SF)            |                         |       | ✓       |             | 396/132 SF   |   |         |   |        |                  |       |   |         |   |               | 1    | 7                |     |     |            |
| Thermal System Insulation |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Pipe (painted)            |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Duct                      | 003                     |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Fixture                   |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| 3 radiators               |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Miscellaneous Material    |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Ceiling Tiles             |                         |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Floor Tiles               | 124                     |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| Window Caulk              | 245D                    | gray  |         |             | 616 SF       | N |         |   |        |                  |       |   |         |   |               | 2    | 6                |     |     |            |
| PT masonry                | 124A                    |       | ✓       |             | 344 SF       | N |         |   |        |                  |       |   |         |   |               | 2    | 6                |     |     |            |
| Window Caulk              | 248C                    | tan   | ✓       |             | 616 SF       | N |         |   |        |                  |       |   |         |   |               | 2    | 6                |     |     |            |
| Metal chairs to 2nd level |                         |       | ✓       |             | 308 SF       | Y | M       | M | 308 SF | Y                | M     | M | GENERAL | Y |               | 2    | 6                |     |     |            |
| Love masonry              | 38                      | brn   |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
| " N masonry               | 48A                     | cream | ✓       |             | 194 SF       | N |         |   |        |                  |       |   |         |   |               | 2    | 6                |     |     |            |
| 2nd level =               |                         |       | ✓       |             | 194 SF       | N |         |   |        |                  |       |   |         |   |               | 2    | 6                |     |     |            |
| PT                        | A34H                    |       |         |             |              |   |         |   |        |                  |       |   |         |   |               |      |                  |     |     |            |
|                           | A34HM                   | blk   | ✓       |             | 462 SF       | Y | S       | M |        |                  |       |   |         |   |               | 2    | 6                |     |     |            |
| PT-board                  | A34D                    | brn   | ✓       |             | 462 SF       | N |         |   |        |                  |       |   |         |   |               | 1    | 7                |     |     |            |
|                           |                         |       | ✓       |             | 194 SF       | N |         |   |        |                  |       |   |         |   |               | 2    | 6                |     |     |            |

\* PLASTER ONLY

D/D - Degree of Damage  
 M - Minor  
 S - Significant

P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)

# ROOM-BY-ROOM INSPECTION FORM

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/6/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

Space ID No.: 2F-711V  
 Type of Space: SMALL HALL  
 Ceiling Height: 11 FT — INCH  
 (6 x 6)  
 (6 x 11)

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material                 | Homogeneous Area ID No. | Color                          | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |         |     | ACM AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|--------------------------------|---------|-------------|--------------|---------|-----|-------------|---------|-----|----------------|------------------|
|                                  |                         |                                |         |             | Total        | Damaged | D/D | Total       | Damaged | D/D |                |                  |
| <b>Surfacing Material</b>        |                         |                                |         |             |              |         |     |             |         |     |                |                  |
| Ceiling                          |                         |                                |         |             |              |         |     |             |         |     |                |                  |
| Walls                            |                         |                                |         |             | 162 SF       | N       |     |             |         |     |                |                  |
| North                            | 9                       | Wht                            | ✓       |             |              |         |     |             |         |     | 2              | 6                |
| South                            | 10B                     |                                | ✓       |             | 121 SF       | N       |     |             |         |     | 2              | 6                |
| East                             | 8                       |                                | ✓       |             | 121 SF       | N       |     |             |         |     | 1              | 7                |
| West                             |                         | per to total (history storage) |         |             | —            |         |     |             |         |     |                |                  |
| Other                            | 8                       | Wht                            | ✓       |             | 171 SF       | N       |     |             |         |     | 1              | 7                |
| <b>Thermal System Insulation</b> |                         |                                |         |             |              |         |     |             |         |     |                |                  |
| Pipe                             |                         |                                |         |             |              |         |     |             |         |     |                |                  |
| Duct                             |                         |                                |         |             |              |         |     |             |         |     |                |                  |
| Fixture                          |                         |                                |         |             |              |         |     |             |         |     |                |                  |
| <b>Miscellaneous Material</b>    |                         |                                |         |             |              |         |     |             |         |     |                |                  |
| Ceiling Tiles                    |                         |                                |         |             |              |         |     |             |         |     |                |                  |
| Floor Tiles (Unileum)            | A31K                    | gray/brick                     |         | ✓           | 156 SF       | N       |     |             |         |     | 2              | 6                |
| Window Caulk                     |                         |                                |         |             |              |         |     |             |         |     |                |                  |
| Cove (Unileum)                   | 70                      | Maroon                         |         | ✓           | 36 LF        | N       |     |             |         |     | 2              | 6                |
| " " Mastic                       | 48A                     | Cream                          |         | ✓           | 36 LF        | N       |     |             |         |     | 2              | 6                |
| Unileum glue                     | A31CM                   | BLK                            |         | ✓           | 156 SF       | N       |     |             |         |     | 2              | 6                |
| PT (10/4/94)                     | 124                     | enamelant                      |         | ✓           | 10 SF        | N       |     |             |         |     | 2              | 6                |
| PT Mastic                        | 124A                    |                                |         | ✓           | 10 SF        | N       |     |             |         |     | 2              | 6                |

D/D - Degree of Damage  
 M - Minor  
 S - Significant

5  
21  
24

P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 2F-711W

Type of Space: Room 225

Ceiling Height: 11 FT - INCH

HIGH MODERATE LOW/NONE

## Potential for Air Erosion:

| Influence of Vibration: |   | HIGH | MODERATE | LOW/NONE |
|-------------------------|---|------|----------|----------|
| 1                       | 1 | 1    | 1        | 1        |
| 2                       | 1 | 1    | 1        | 1        |
| 3                       | 1 | 1    | 1        | 1        |
| 4                       | 1 | 1    | 1        | 1        |
| 5                       | 1 | 1    | 1        | 1        |
| 6                       | 1 | 1    | 1        | 1        |
| 7                       | 1 | 1    | 1        | 1        |
| 8                       | 1 | 1    | 1        | 1        |
| 9                       | 1 | 1    | 1        | 1        |
| 10                      | 1 | 1    | 1        | 1        |
| 11                      | 1 | 1    | 1        | 1        |
| 12                      | 1 | 1    | 1        | 1        |
| 13                      | 1 | 1    | 1        | 1        |
| 14                      | 1 | 1    | 1        | 1        |
| 15                      | 1 | 1    | 1        | 1        |
| 16                      | 1 | 1    | 1        | 1        |
| 17                      | 1 | 1    | 1        | 1        |
| 18                      | 1 | 1    | 1        | 1        |
| 19                      | 1 | 1    | 1        | 1        |
| 20                      | 1 | 1    | 1        | 1        |
| 21                      | 1 | 1    | 1        | 1        |
| 22                      | 1 | 1    | 1        | 1        |
| 23                      | 1 | 1    | 1        | 1        |
| 24                      | 1 | 1    | 1        | 1        |
| 25                      | 1 | 1    | 1        | 1        |
| 26                      | 1 | 1    | 1        | 1        |
| 27                      | 1 | 1    | 1        | 1        |
| 28                      | 1 | 1    | 1        | 1        |
| 29                      | 1 | 1    | 1        | 1        |
| 30                      | 1 | 1    | 1        | 1        |
| 31                      | 1 | 1    | 1        | 1        |
| 32                      | 1 | 1    | 1        | 1        |
| 33                      | 1 | 1    | 1        | 1        |
| 34                      | 1 | 1    | 1        | 1        |
| 35                      | 1 | 1    | 1        | 1        |
| 36                      | 1 | 1    | 1        | 1        |
| 37                      | 1 | 1    | 1        | 1        |
| 38                      | 1 | 1    | 1        | 1        |
| 39                      | 1 | 1    | 1        | 1        |
| 40                      | 1 | 1    | 1        | 1        |
| 41                      | 1 | 1    | 1        | 1        |
| 42                      | 1 | 1    | 1        | 1        |
| 43                      | 1 | 1    | 1        | 1        |
| 44                      | 1 | 1    | 1        | 1        |
| 45                      | 1 | 1    | 1        | 1        |
| 46                      | 1 | 1    | 1        | 1        |
| 47                      | 1 | 1    | 1        | 1        |
| 48                      | 1 | 1    | 1        | 1        |
| 49                      | 1 | 1    | 1        | 1        |
| 50                      | 1 | 1    | 1        | 1        |
| 51                      | 1 | 1    | 1        | 1        |
| 52                      | 1 | 1    | 1        | 1        |
| 53                      | 1 | 1    | 1        | 1        |
| 54                      | 1 | 1    | 1        | 1        |
| 55                      | 1 | 1    | 1        | 1        |
| 56                      | 1 | 1    | 1        | 1        |
| 57                      | 1 | 1    | 1        | 1        |
| 58                      | 1 | 1    | 1        | 1        |
| 59                      | 1 | 1    | 1        | 1        |
| 60                      | 1 | 1    | 1        | 1        |
| 61                      | 1 | 1    | 1        | 1        |
| 62                      | 1 | 1    | 1        | 1        |
| 63                      | 1 | 1    | 1        | 1        |
| 64                      | 1 | 1    | 1        | 1        |
| 65                      | 1 | 1    | 1        | 1        |
| 66                      | 1 | 1    | 1        | 1        |
| 67                      | 1 | 1    | 1        | 1        |
| 68                      | 1 | 1    | 1        | 1        |
| 69                      | 1 | 1    | 1        | 1        |
| 70                      | 1 | 1    | 1        | 1        |
| 71                      | 1 | 1    | 1        | 1        |
| 72                      | 1 | 1    | 1        | 1        |
| 73                      | 1 | 1    | 1        | 1        |
| 74                      | 1 | 1    | 1        | 1        |
| 75                      | 1 | 1    | 1        | 1        |
| 76                      | 1 | 1    | 1        | 1        |
| 77                      | 1 | 1    | 1        | 1        |
| 78                      | 1 | 1    | 1        | 1        |
| 79                      | 1 | 1    | 1        | 1        |
| 80                      | 1 | 1    | 1        | 1        |
| 81                      | 1 | 1    | 1        | 1        |
| 82                      | 1 | 1    | 1        | 1        |
| 83                      | 1 | 1    | 1        | 1        |
| 84                      | 1 | 1    | 1        | 1        |
| 85                      | 1 | 1    | 1        | 1        |
| 86                      | 1 | 1    | 1        | 1        |
| 87                      | 1 | 1    | 1        | 1        |
| 88                      | 1 | 1    | 1        | 1        |
| 89                      | 1 | 1    | 1        | 1        |
| 90                      | 1 | 1    | 1        | 1        |
| 91                      | 1 | 1    | 1        | 1        |
| 92                      | 1 | 1    | 1        | 1        |
| 93                      | 1 | 1    | 1        | 1        |
| 94                      | 1 | 1    | 1        | 1        |

(33x64)

[illegible]

DiD - Degree of Damage

**M - Minor**

### S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

# ROOM-BY-ROOM INSPECTION FORM

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/6/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

Space ID No.: 2C-711X  
 Type of Space: SMALL OFFICE  
 Ceiling Height: 11 FT 1 INCH  
 Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |         |     | ACM AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|------------------|---------|-----|----------------|------------------|
|                                  |                         |       |         |             | Total        | Damaged | D/D | Total            | Damaged | D/D |                |                  |
| <b>Surfacing Material</b>        |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Ceiling Walls                    | 9                       | white | ✓       |             | 88 SF        | N       |     | M                |         |     |                |                  |
| North                            | 8                       |       | ✓       |             | 88 SF        | N       |     | M                |         |     | 2              | 6                |
| South                            | 8                       |       | ✓       |             | "            | N       |     | M                |         |     | 1              | 7                |
| East                             | 8                       |       | ✓       |             | 121 SF       | N       |     | M                |         |     | 1              | 7                |
| West                             | 8                       |       | ✓       |             | "            | N       |     | M                |         |     | 1              | 7                |
| Other                            | 8                       |       | ✓       |             |              | N       |     | M                |         |     | 1              | 7                |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Pipe                             |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Duct                             |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Fixture                          |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Ceiling Tiles                    |                         |       |         |             |              |         |     |                  |         |     |                |                  |
| Floor Tiles                      | 14B                     |       |         | ✓           | 88 SF        | N       |     | M                |         |     | 2              | 6                |
| Window Caulk                     | 24B1                    | tan   |         | ✓           | 88 SF        | N       |     | M                |         |     | 2              | 6                |
| " "                              | 24B2                    | grey  |         | ✓           | 101 SF       | N       |     | M                |         |     | 2              | 6                |
| Door Weatherstripping            | 7D                      | matte |         | ✓           | 24 SF        | N       |     | M                |         |     | 2              | 6                |
| " " Mast                         | 48A                     | cream |         | ✓           | 24 SF        | N       |     | M                |         |     | 2              | 6                |
| PT Mast                          | 124                     | cream |         | ✓           | 88 SF        | N       |     | M                |         |     | 2              | 6                |
| PT Mast                          | 104A                    | blk   |         | ✓           | 88 SF        | N       |     | M                |         |     | 2              | 6                |



**Building Name:**

**Building Address:** 115 South Avenue

**Building ID No.:**

Date of Inspection: 9/6/01

| Influence of Vibration: |   | HIGH | MODERATE | LOW/NONE |
|-------------------------|---|------|----------|----------|
| 1                       | 1 | 1    | 1        | 1        |
| 2                       | 1 | 1    | 1        | 1        |
| 3                       | 1 | 1    | 1        | 1        |
| 4                       | 1 | 1    | 1        | 1        |
| 5                       | 1 | 1    | 1        | 1        |
| 6                       | 1 | 1    | 1        | 1        |
| 7                       | 1 | 1    | 1        | 1        |
| 8                       | 1 | 1    | 1        | 1        |
| 9                       | 1 | 1    | 1        | 1        |
| 10                      | 1 | 1    | 1        | 1        |
| 11                      | 1 | 1    | 1        | 1        |
| 12                      | 1 | 1    | 1        | 1        |
| 13                      | 1 | 1    | 1        | 1        |
| 14                      | 1 | 1    | 1        | 1        |
| 15                      | 1 | 1    | 1        | 1        |
| 16                      | 1 | 1    | 1        | 1        |
| 17                      | 1 | 1    | 1        | 1        |
| 18                      | 1 | 1    | 1        | 1        |
| 19                      | 1 | 1    | 1        | 1        |
| 20                      | 1 | 1    | 1        | 1        |
| 21                      | 1 | 1    | 1        | 1        |
| 22                      | 1 | 1    | 1        | 1        |
| 23                      | 1 | 1    | 1        | 1        |
| 24                      | 1 | 1    | 1        | 1        |
| 25                      | 1 | 1    | 1        | 1        |
| 26                      | 1 | 1    | 1        | 1        |
| 27                      | 1 | 1    | 1        | 1        |
| 28                      | 1 | 1    | 1        | 1        |
| 29                      | 1 | 1    | 1        | 1        |
| 30                      | 1 | 1    | 1        | 1        |
| 31                      | 1 | 1    | 1        | 1        |
| 32                      | 1 | 1    | 1        | 1        |
| 33                      | 1 | 1    | 1        | 1        |
| 34                      | 1 | 1    | 1        | 1        |
| 35                      | 1 | 1    | 1        | 1        |
| 36                      | 1 | 1    | 1        | 1        |
| 37                      | 1 | 1    | 1        | 1        |
| 38                      | 1 | 1    | 1        | 1        |
| 39                      | 1 | 1    | 1        | 1        |
| 40                      | 1 | 1    | 1        | 1        |
| 41                      | 1 | 1    | 1        | 1        |
| 42                      | 1 | 1    | 1        | 1        |
| 43                      | 1 | 1    | 1        | 1        |
| 44                      | 1 | 1    | 1        | 1        |
| 45                      | 1 | 1    | 1        | 1        |
| 46                      | 1 | 1    | 1        | 1        |
| 47                      | 1 | 1    | 1        | 1        |
| 48                      | 1 | 1    | 1        | 1        |
| 49                      | 1 | 1    | 1        | 1        |
| 50                      | 1 | 1    | 1        | 1        |
| 51                      | 1 | 1    | 1        | 1        |
| 52                      | 1 | 1    | 1        | 1        |
| 53                      | 1 | 1    | 1        | 1        |
| 54                      | 1 | 1    | 1        | 1        |
| 55                      | 1 | 1    | 1        | 1        |
| 56                      | 1 | 1    | 1        | 1        |
| 57                      | 1 | 1    | 1        | 1        |
| 58                      | 1 | 1    | 1        | 1        |
| 59                      | 1 | 1    | 1        | 1        |
| 60                      | 1 | 1    | 1        | 1        |
| 61                      | 1 | 1    | 1        | 1        |
| 62                      | 1 | 1    | 1        | 1        |
| 63                      | 1 | 1    | 1        | 1        |
| 64                      | 1 | 1    | 1        | 1        |
| 65                      | 1 | 1    | 1        | 1        |
| 66                      | 1 | 1    | 1        | 1        |
| 67                      | 1 | 1    | 1        | 1        |
| 68                      | 1 | 1    | 1        | 1        |
| 69                      | 1 | 1    | 1        | 1        |
| 70                      | 1 | 1    | 1        | 1        |
| 71                      | 1 | 1    | 1        | 1        |
| 72                      | 1 | 1    | 1        | 1        |
| 73                      | 1 | 1    | 1        | 1        |
| 74                      | 1 | 1    | 1        | 1        |
| 75                      | 1 | 1    | 1        | 1        |
| 76                      | 1 | 1    | 1        | 1        |
| 77                      | 1 | 1    | 1        | 1        |
| 78                      | 1 | 1    | 1        | 1        |
| 79                      | 1 | 1    | 1        | 1        |
| 80                      | 1 | 1    | 1        | 1        |
| 81                      | 1 | 1    | 1        | 1        |
| 82                      | 1 | 1    | 1        | 1        |
| 83                      | 1 | 1    | 1        | 1        |
| 84                      | 1 | 1    | 1        | 1        |
| 85                      | 1 | 1    | 1        | 1        |
| 86                      | 1 | 1    | 1        | 1        |
| 87                      | 1 | 1    | 1        | 1        |
| 88                      | 1 | 1    | 1        | 1        |
| 89                      | 1 | 1    | 1        | 1        |
| 90                      | 1 | 1    | 1        | 1        |
| 91                      | 1 | 1    | 1        | 1        |
| 92                      | 1 | 1    | 1        | 1        |
| 93                      | 1 | 1    | 1        | 1        |
| 94                      | 1 | 1    | 1        | 1        |

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

(4420)

Space ID No.: 2f-711Z

Type of Space: \_\_\_\_\_

Ceiling Height: 10 FT. — INCH

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for Cleaning)

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible, Exposed, or Critical)



**Building Name:** Rundel  
**Building Address:** 115 South

Space ID No.: 2F-711AC

Type of Space:  
Ceiling Height:

7 FT      7 INCH      (1<sup>st</sup> LEVEL)      (9 x 36)  
7      7      (2<sup>ND</sup> LEVEL)      (9 x 36)

### Potential for Air Erosion:

LOW/NONE

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

**115 South Avenue**

**Building ID No.:**

**Date of Inspection:**

|                         | LOW      | MODERATE | HIGH |
|-------------------------|----------|----------|------|
| Influence of Vibration: | LOW/NONE | MODERATE | HIGH |

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

Space ID No.:

Type of Space:

**Ceiling Height:**

1 FT - INCH

(33440)

[illegible]

D/D - Degree of Damage  
M - Minor

**P/D - Potential for Damage**



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 2F-7145

Type of Space: Small covered, v.l.

**Ceiling Height:** \_\_\_\_\_

Building ID No.: 7.11

Date of Inspection: 9/1/01

|                         | HIGH | Moderate | LOW/NONE |
|-------------------------|------|----------|----------|
| Influence of Vibration: | HIGH | Moderate | LOW/NONE |

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

(11 x 23) conference  
(11 x 10) small office

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable |
|----------------------------------|-------------------------|-------|---------|-------------|
| <b>Surfacing Material</b>        |                         |       |         |             |
| Ceiling Walls                    | 9                       | Wht   | ✓       |             |
| North                            | B                       |       | ✓       |             |
| South                            | B                       |       | ✓       |             |
| East                             | B                       |       | ✓       |             |
| West                             | B                       |       | ✓       |             |
| Other                            |                         |       | ✓       |             |
| <b>Thermal System Insulation</b> |                         |       |         |             |
| Pipe                             | (new)                   | DOB   |         |             |
| Duct                             |                         |       |         |             |
| Fixture                          |                         |       |         |             |
| <b>Miscellaneous Material</b>    |                         |       |         |             |
| Ceiling Tiles                    |                         |       |         |             |
| Floor Tiles                      | 148A                    |       |         |             |
| Window Caulk                     | 245D                    |       |         |             |
| " "                              | 248C                    |       |         |             |
| Cove molding                     | A42                     |       |         |             |
| Small parts:                     |                         |       |         |             |
| (1x10) 7-10                      |                         |       |         |             |
| MAUS-E.S+W                       | B                       |       |         |             |
| -N 14' x 148                     | 148B (wood + glass)     |       |         |             |
| FLOOR                            | 148A                    |       |         |             |

D/D - Degree of Damage  
M - Minor

**P/D - Potential for Damage**

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 9/16/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2C-711AF  
Type of Space: CHILDREN'S BOOK STORAGE  
Ceiling Height: 9 FT INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE  
(44x32)

| Type of Material          | Homogeneous Area ID No. | Color        | Friable         | Non-Friable | Assumed ACBM |         |     | Suspect Material |         |     | ACM AHERA Y/N | Rank | Removal Priority |
|---------------------------|-------------------------|--------------|-----------------|-------------|--------------|---------|-----|------------------|---------|-----|---------------|------|------------------|
|                           |                         |              |                 |             | Total        | Damaged | D/D | Total            | Damaged | D/D |               |      |                  |
| Surfacing Material        |                         |              |                 |             |              |         |     |                  |         |     |               |      |                  |
| Ceiling                   |                         |              |                 |             |              |         |     |                  |         |     |               |      |                  |
| Walls                     |                         |              |                 |             | 1408 SF      |         |     |                  |         |     |               |      |                  |
| North                     | 44                      | 1A/B         | cream (painted) | ✓           |              |         |     |                  |         |     |               |      |                  |
| South                     |                         | 1/B          |                 | ✓           | 396 SF       | N       |     |                  |         |     |               |      |                  |
| East                      | 32                      | 1/B          |                 | ✓           | "            | N       |     |                  |         |     |               |      |                  |
| West                      |                         | 1/B          |                 | ✓           | 288 SF       | N       |     |                  |         |     |               |      |                  |
| Other                     |                         | 1/B          |                 | ✓           | "            | N       |     |                  |         |     |               |      |                  |
| Thermal System Insulation |                         |              |                 |             |              |         |     |                  |         |     |               |      |                  |
| Pipe                      |                         |              |                 |             |              |         |     |                  |         |     |               |      |                  |
| Duct                      |                         |              |                 |             |              |         |     |                  |         |     |               |      |                  |
| Fixture                   |                         |              |                 |             |              |         |     |                  |         |     |               |      |                  |
| Miscellaneous Material    |                         |              |                 |             |              |         |     |                  |         |     |               |      |                  |
| Ceiling Tiles             | A17A                    |              |                 | ✓           | 1408 SF      | N       |     |                  |         |     |               |      |                  |
| Floor Tiles               | 148A                    |              |                 |             | 1408 SF      | N       |     |                  |         |     |               |      |                  |
| Window Caulk              | 249C                    | Tan          |                 | ✓           | 876 SF       | N       |     |                  |         |     |               |      |                  |
| "                         | 245D                    | Gray         |                 | ✓           | 244 SF       | N       |     |                  |         |     |               |      |                  |
| (1/2 OF WALLS)            | A92                     | BULK GRANITE |                 |             |              |         |     |                  |         |     |               |      |                  |

(1A ON TOP OF PLASTER)  
(GULLEN BOARD)

Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:

7.11

Date of Inspection:

9/6/01

Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.:

2F-711A6

Type of Space:

Picture Book Storage

Ceiling Height:

9 FT - INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

(18 x 29)

| Type of Material                 | Homogeneous Area ID No. | Color         | Friable | Non-Friable | Suspect Material |         |             |     | Total | D/D | P/D | Sample No. | ACM AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|---------------|---------|-------------|------------------|---------|-------------|-----|-------|-----|-----|------------|----------------|------------------|
|                                  |                         |               |         |             | Assumed ACBM     |         | Tested ACBM |     |       |     |     |            |                |                  |
|                                  |                         |               |         |             | Total            | Damaged | D/D         | P/D |       |     |     |            |                |                  |
| <b>Surfacing Material</b>        |                         |               |         |             |                  |         |             |     |       |     |     |            |                |                  |
| Ceiling                          | 9                       |               |         |             | 522 SF           | N       |             |     |       |     |     |            |                |                  |
| Walls                            |                         |               |         |             |                  |         |             |     |       |     |     |            |                |                  |
| North                            | 25' 110A/B              | Wht           |         |             | 261 SF           | N       |             |     |       |     |     |            | 2              | 6                |
| South                            |                         | Wht (painted) |         |             | "                | N       |             |     |       |     |     |            | 1              | 7                |
| East                             | 18'                     |               |         |             | 162 SF           | N       |             |     |       |     |     |            | 1              | 7                |
| West                             |                         |               |         |             | "                | N       |             |     |       |     |     |            | 1              | 7                |
| Other                            |                         |               |         |             |                  |         |             |     |       |     |     |            | 1              | 7                |
| <b>Thermal System Insulation</b> |                         |               |         |             |                  |         |             |     |       |     |     |            |                |                  |
| Pipe                             |                         |               |         |             |                  |         |             |     |       |     |     |            |                |                  |
| Duct                             |                         |               |         |             |                  |         |             |     |       |     |     |            |                |                  |
| Fixture                          |                         |               |         |             |                  |         |             |     |       |     |     |            |                |                  |
| <b>Miscellaneous Material</b>    |                         |               |         |             |                  |         |             |     |       |     |     |            |                |                  |
| Ceiling Tiles (NEW)              | 1808                    | Wht           |         |             |                  |         |             |     |       |     |     |            |                |                  |
| Floor Tiles                      | 148A                    |               |         |             |                  |         |             |     |       |     |     |            |                |                  |
| Window Caulk                     | 248C                    | tan           |         |             |                  |         |             |     |       |     |     |            |                |                  |
| (1/3 of wall)                    | A92                     | blk granite   |         |             |                  |         |             |     |       |     |     |            |                |                  |
| Window (wall)                    | 245D                    | grog          |         |             |                  |         |             |     |       |     |     |            |                |                  |

16A ON TOP OF PLASTER (GROUTED BRICK)

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/6/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM  
 Space ID No.: 2F-711AH  
 Type of Space: STAFF STAIRWELL  
 Ceiling Height: 114 FT — INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

(718) 1st Landing  
 (718) 2nd Landing

| Type of Material                 | Homogeneous Area ID No. | Color     | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | ACM AHRA Y/N | Rank | Removal Priority |
|----------------------------------|-------------------------|-----------|---------|-------------|--------------|---------|-----|-------------|-------|---------|--------------|------|------------------|
|                                  |                         |           |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged |              |      |                  |
| <b>Surfacing Material</b>        |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Ceiling                          | 9                       |           |         |             |              | 112 SF  |     |             |       |         |              |      |                  |
| Walls                            |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| North                            | 40                      | cream tan | ✓       |             |              |         | N   |             |       |         |              |      |                  |
| South                            | 40                      |           |         |             |              |         |     |             |       |         |              |      |                  |
| East                             | 40                      |           |         |             |              |         |     |             |       |         |              |      |                  |
| West                             | 40                      |           |         |             |              |         |     |             |       |         |              |      |                  |
| Other                            | 40                      |           |         |             |              |         |     |             |       |         |              |      |                  |
| <b>Thermal System Insulation</b> |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Pipe (painted & unpainted)       |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Duct                             |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| <b>Fixture</b>                   |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Plaster Fitting                  |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| <b>Miscellaneous Material</b>    |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Ceiling Tiles                    |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Floor Tiles                      |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Window Caulk                     |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Metal Shims                      | A143C                   | BLK       |         |             |              |         |     |             |       |         |              |      |                  |
| Concrete Gaps                    |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Closest (2x7)                    |                         |           |         |             |              |         |     |             |       |         |              |      |                  |
| Ceiling 4'                       | 9                       | cream tan | ✓       |             |              | 212 SF  | N   |             |       |         |              |      |                  |
| FLOOR                            | 149                     |           |         |             |              |         |     |             |       |         |              |      |                  |
| WALLS                            | 40                      | tan       |         |             |              |         |     |             |       |         |              |      |                  |
| PIPE                             | 003                     | (new)     |         |             |              |         |     |             |       |         |              |      |                  |

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/6/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM · Space ID No.: 2F-711AI  
 Type of Space: ELEVATOR FOYER  
 Ceiling Height: 9 FT — INCH (8x12)  
 Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material                 | Homogeneous Area ID No. | Color      | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | ACM Y/N | AHJRA Rank | Removal Priority |
|----------------------------------|-------------------------|------------|---------|-------------|--------------|---------|-----|-------------|-------|---------|---------|------------|------------------|
|                                  |                         |            |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged |         |            |                  |
| <b>Surfacing Material</b>        |                         |            |         |             |              |         |     |             |       |         |         |            |                  |
| Ceiling                          |                         |            |         |             |              |         |     |             |       |         |         |            |                  |
| Walls                            | 9                       | WH         | ✓       |             | 96 SF        | N       |     |             |       |         |         |            |                  |
| North                            | 198                     | cream      | ✓       |             | 72 SF        | N       |     |             |       |         |         | 2          | 6                |
| South                            | 8                       |            | ✓       |             |              |         |     |             |       |         |         | 2          | 6                |
| East (elevator)                  | 198                     |            | ✓       |             | 72 SF        | N       |     |             |       |         | N       | 1          | 7                |
| West                             | 8                       |            | ✓       |             | 108 SF       | N       |     |             |       |         |         | 2          | 6                |
| Other                            |                         |            | ✓       |             | 108 SF       | N       |     |             |       |         |         | 1          | 7                |
| <b>Thermal System Insulation</b> |                         |            |         |             |              |         |     |             |       |         |         |            |                  |
| Pipe                             |                         |            |         |             |              |         |     |             |       |         |         |            |                  |
| Duct                             |                         |            |         |             |              |         |     |             |       |         |         |            |                  |
| Fixture                          |                         |            |         |             |              |         |     |             |       |         |         |            |                  |
| <b>Miscellaneous Material</b>    |                         |            |         |             |              |         |     |             |       |         |         |            |                  |
| Ceiling Tiles (New)              | 120B                    | WH         |         |             |              |         |     |             |       |         |         |            |                  |
| Floor Tiles                      | A31C                    | Brick only |         |             |              |         |     |             |       |         |         |            |                  |
| Window Caulk                     |                         |            | ✓       |             | 96 SF        | N       |     |             |       |         |         | 2          | 6                |
| Door Caulk (New)                 | TD                      | Maroon     | ✓       |             | 24 SF        | N       |     |             |       |         |         | 2          | 6                |
| " " (New)                        | 48A                     | cream      | ✓       |             | 24 SF        | N       |     |             |       |         |         | 2          | 6                |
| Limestone Glue                   | A31CM                   | BLK        | ✓       |             | 96 SF        | N       |     |             |       |         |         | 2          | 6                |

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 9/6/01

Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2F-7111AT  
Type of Space: OUTREACH OFFICES  
Ceiling Height: 11 FT - INCH

(32 x 46) (LARGE AREA)  
(15 x 20) (OPEN OFFICE)

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material                 | Homogeneous Area ID No. | Color        | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |       |         | ACM AHERA Rank | Removal Priority |     |     |            |
|----------------------------------|-------------------------|--------------|---------|-------------|--------------|---------|-----|------------------|-------|---------|----------------|------------------|-----|-----|------------|
|                                  |                         |              |         |             | Total        | Damaged | D/D | P/D              | Total | Damaged |                |                  | D/D | P/D | Sample No. |
|                                  |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| <b>Surfacing Material</b>        |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Ceiling                          |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Walls                            |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| North                            | 9                       | WH           | ✓       |             | 1772 SF      |         |     |                  |       |         |                |                  |     |     |            |
| South                            | 8                       | CREAM        | ✓       |             | 352 SF       |         |     |                  |       |         |                |                  |     |     |            |
| East                             | 8                       |              | ✓       |             | "            |         |     |                  |       |         |                |                  |     |     |            |
| West                             | 8                       |              | ✓       |             | 726 SF       |         |     |                  |       |         |                |                  |     |     |            |
| Other                            | 8                       |              | ✓       |             | "            |         |     |                  |       |         |                |                  |     |     |            |
| <b>Thermal System Insulation</b> |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Pipe                             |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Duct                             |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Fixture                          |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| <b>Miscellaneous Material</b>    |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Ceiling Tiles                    |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Floor Tiles                      | 148A                    |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Window Caulk                     | 248C                    | TAN          |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
|                                  | 245D                    | GREY         |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Plastic/Sheet/Door               | 148                     |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| (3x6) Floor                      | 149                     | TAN          |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Plaster                          | 9                       |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Ceiling 8'                       | 8                       | WH           | ✓       |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Walls                            |                         | CREAM        |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| Pipe - outside                   |                         |              |         |             |              |         |     |                  |       |         |                |                  |     |     |            |
| IN OFFICES                       | A92                     | PINK/GRANITE |         |             |              |         |     |                  |       |         |                |                  |     |     |            |

D/D - Degree of Damage  
M - Minor

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/16/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 2F-711A  
 Type of Space: OUTREACH MANAGER'S OFFICE  
 Ceiling Height: 11 FT - INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE (11 x 15)

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |     |         |     | Suspect Material |     |         |     | ACM AHERA Rank | Removal Priority |   |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|-----|---------|-----|------------------|-----|---------|-----|----------------|------------------|---|
|                                  |                         |       |         |             | Total        |     | D/D     |     | Total            |     | D/D     |     |                |                  |   |
|                                  |                         |       |         |             | Damaged      | P/D | Damaged | P/D | Damaged          | P/D | Damaged | P/D |                |                  |   |
| <b>Surfacing Material</b>        |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |   |
| Ceiling Walls                    | 9                       | WH    | ✓       |             | 165 SF       |     |         |     |                  |     |         |     |                |                  |   |
| North (wood window)              | 193                     | cream | ✓       |             | 165 SF       |     |         |     |                  |     |         |     |                |                  | 6 |
| South (tile wood door)           | 8                       |       | ✓       |             | "            |     |         |     |                  |     |         |     |                |                  | 6 |
| East (177)                       | 8                       |       | ✓       |             | 121 SF       |     |         |     |                  |     |         |     |                |                  | 7 |
| West                             | 8                       |       | ✓       |             | "            |     |         |     |                  |     |         |     |                |                  | 7 |
| Other                            |                         |       | ✓       |             |              |     |         |     |                  |     |         |     |                |                  | 7 |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |   |
| Pipe                             | -                       |       |         |             |              |     |         |     |                  |     |         |     |                |                  |   |
| Duct                             | -                       |       |         |             |              |     |         |     |                  |     |         |     |                |                  |   |
| Fixture                          | -                       |       |         |             |              |     |         |     |                  |     |         |     |                |                  |   |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |   |
| Ceiling Tiles                    | 148A                    |       |         |             |              |     |         |     |                  |     |         |     |                |                  |   |
| Floor Tiles                      | 248A                    |       |         |             |              |     |         |     |                  |     |         |     |                |                  |   |
| Window Caulk                     |                         |       |         |             |              |     |         |     |                  |     |         |     |                |                  |   |
| Cove Molding                     | 44                      | BR    | ✓       |             | 114          |     |         |     |                  |     |         |     |                |                  | 6 |
| " " Molding                      | 38M                     | BR    | ✓       |             | 114          |     |         |     |                  |     |         |     |                |                  | 6 |

Building No.  
Building Address:

Rundel  
115 South Avenue

Building ID No.:  
Date of Inspection:

7.11  
8/30/01

Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3C-7.11A  
Type of Space: ENTRY  
Ceiling Height: 10 FT - INCH

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

HIGH MODERATE LOW/NONE

(23 x 31)

| Type of Material                 | Homogeneous Area ID No. | Color            | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |       |         | ACM AHERA Y/N | Rank | Removal Priority |
|----------------------------------|-------------------------|------------------|---------|-------------|--------------|---------|-----|------------------|-------|---------|---------------|------|------------------|
|                                  |                         |                  |         |             | Total        | Damaged | D/D | P/D              | Total | Damaged |               |      |                  |
| <b>Surfacing Material</b>        |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| Ceiling                          |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| Walls                            |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| North                            | 9                       | cream            | ✓       |             | 713 SF       | N       |     |                  |       |         |               |      | 2-6              |
| South                            | 8                       |                  | ✓       |             | 310 SF       | N       |     |                  |       |         |               |      |                  |
| East                             | 8                       |                  | ✓       |             | 310 SF       | N       |     |                  |       |         |               |      | 7                |
| West                             | 8                       |                  | ✓       |             | 230 SF       | N       |     |                  |       |         |               |      | 7                |
| Other                            |                         | open to hall     | ↓       |             |              |         |     |                  |       |         |               |      | 7                |
| <b>Thermal System Insulation</b> |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| Pipe                             |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| Duct                             |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| Fixture                          |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| <b>Miscellaneous Material</b>    |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| Ceiling Tiles                    |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| Floor Tiles                      | A230                    | tan w/ tan       |         | ✓           | 385 SF       | N       |     |                  |       |         |               |      | 2-6              |
| Window Caulk                     |                         |                  |         |             |              |         |     |                  |       |         |               |      |                  |
| PT Material                      | A334                    | red/brown w/ tan |         | ✓           | 385 SF       | N       |     |                  |       |         |               |      | 2-6              |
|                                  | A330 M                  | tan/brown        |         | ✓           | 713 SF       | N       |     |                  |       |         |               |      | 2-6              |
|                                  | A340                    | red/brown        |         | ✓           | 625 SF       | N       |     |                  |       |         |               |      | 2-6              |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3F-711B  
Type of Space: HALLWAY  
Ceiling Height: 10 FT - 1 INCH

- 6 windows
- 16 panes white crumbly

| Potential for Air Erosion: | HIGH | MODERATE | LOW/NONE |
|----------------------------|------|----------|----------|
| 12' x 140'                 |      |          |          |

**Influence of Vibration: HIGH MODERATE LOW/NONE**

[illegible]

D/D - Degree of Damage  
M - Minor

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/20/02  
 Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM Space ID No.: 3F-7-11C  
 Type of Space: STAIRWELL  
 Ceiling Height: 120 FT 1 INCH  
 Potential for Air Erosion: HIGH MODERATE LOW/NONE

Landing 6x11  
2nd landing 3x3

| Type of Material                 | Homogeneous Area ID No. | Color       | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material |         |     |     | ACM AHERA Rank | Removal Priority |             |
|----------------------------------|-------------------------|-------------|---------|-------------|--------------|---------|-----|-----|------------------|---------|-----|-----|----------------|------------------|-------------|
|                                  |                         |             |         |             | Total        | Damaged | D/D | P/D | Total            | Damaged | D/D | P/D |                |                  |             |
|                                  |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  | Tested ACBM |
| <b>Surfacing Material</b>        |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Ceiling                          |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Walls                            |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| North                            | 9                       | grey        | ✓       |             | 75%          | N       |     |     |                  |         |     |     |                |                  | 2           |
| South                            | 40                      | orange gold |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| East                             |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| West                             |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Other                            |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| <b>Thermal System Insulation</b> |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Pipe                             |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Duct                             |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Fixture                          |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| <b>Miscellaneous Material</b>    |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Ceiling Tiles                    |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Floor Tiles                      |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Window Caulk                     |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Metal Stairs                     |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Concrete Steps                   |                         |             |         |             |              |         |     |     |                  |         |     |     |                |                  |             |

D/D - Degree of Damage  
 M - Minor  
 S - Significant

P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)

Building Name: Rundel  
Building Address: 115 South Avenue

Building Name: Rundel  
Building Address: 115 South

Space ID No.: 3F-711D  
Type of Space: Auditorium  
Ceiling Height:

Building ID No.: 7.11

Date of Inspection: 8/30/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

Potential for Air Erosion: HIGH MODERATE LOW/NONE

$$(30 \times 54)$$

| Type of Material                 | Homogeneous Area ID No. | Color   | Friable | Non-Friable |
|----------------------------------|-------------------------|---------|---------|-------------|
| <b>Surfacing Material</b>        |                         |         |         |             |
| Ceiling                          | (metal pan) TIA         |         |         |             |
| Walls                            | 19B                     | cream   | ✓       |             |
| North                            | stage                   |         |         |             |
| South (All wood)                 | B                       | ↓       | ✓       |             |
| East                             | B                       |         | ✓       |             |
| West                             |                         |         |         |             |
| Other                            |                         |         |         |             |
| <b>Thermal System Insulation</b> |                         |         |         |             |
| Pipe                             |                         |         |         |             |
| Duct                             |                         |         |         |             |
| Fixture                          |                         |         |         |             |
| <b>Miscellaneous Material</b>    |                         |         |         |             |
| Ceiling Tiles                    | 47A                     | WH      | ✓       |             |
| Floor Tiles                      | 148A                    |         |         |             |
| Window Caulk                     | 2450                    | gray    | ✓       |             |
| Door Molding                     | 70                      | masonry | ✓       |             |
| " " Molding                      | 4912                    | tan     | ✓       |             |
| Stage Stairs (4x6)               |                         |         |         |             |
| Ceilings 70'                     | 9                       |         | ✓       |             |
| All walls                        | 0                       |         | ✓       |             |
| Wood steps                       | -                       |         |         |             |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

Building Name:  
Building Address:

**115 South Avenue**

Building ID No.:

711

**Date of Inspection:**

83001

**Influence of Vibration:** 230101 HIGH MODERATE LOW/NONE

**HIGH MODERATE LOW/NONE**

**Potential for Air Erosion:**

HIGH MODERATE LOW/NONE

$$(4 \times 10)$$

Space ID No.:

38-71E

Type of Space:

MECHANICAL PROPERTIES

**Ceiling Height:**

\_\_\_\_\_

[illegible]

D/D - Degree of Damage

### M - Minor

### S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accounted For)







Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:

7.11

Date of Inspection:

8/30/01

Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.:

3F-711K

Type of Space:

BATH ROOM

Ceiling Height:

10 FT — INCH

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

( 4x5 )

| Type of Material          | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |         |     | ACM AHERA Rank | Removal Priority |  |
|---------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|-------------|---------|-----|----------------|------------------|--|
|                           |                         |       |         |             | Total        | Damaged | D/D | Total       | Damaged | D/D |                |                  |  |
| Surfacing Material        |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| Ceiling                   |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| Walls                     |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| North                     | 9                       | WHT   | ✓       |             | 20 SF        | N       |     |             |         |     |                |                  |  |
| South                     | 8                       | Green | ✓       |             | 50 SF        | N       |     |             |         |     |                |                  |  |
| East                      | 8                       | Wood  | ✓       |             | 40 SF        | N       |     |             |         |     |                |                  |  |
| West                      | 8                       | ↓     | ✓       |             | 40 SF        | N       |     |             |         |     |                |                  |  |
| Other                     |                         |       | ✓       |             |              | N       |     |             |         |     |                |                  |  |
| Thermal System Insulation |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| Pipe                      |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| Duct                      |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| Fixture                   |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| Miscellaneous Material    |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| Ceiling Tiles             |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| Floor Tiles               |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| Window Caulk              |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| PT                        |                         |       |         |             |              |         |     |             |         |     |                |                  |  |
| PT Mastic                 |                         |       |         |             |              |         |     |             |         |     |                |                  |  |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Applicable)



Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/30/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 36-7111  
Type of Space: OFFICE  
Ceiling Height: 9 FT 2 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE  
(11417)

| Type of Material                 | Homogeneous Area ID No. | Color  | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | ACM Y/N | AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|--------|---------|-------------|--------------|---------|-----|-------------|-------|---------|---------|------------|------------------|
|                                  |                         |        |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged |         |            |                  |
| <b>Surfacing Material</b>        |                         |        |         |             |              |         |     |             |       |         |         |            |                  |
| Ceiling                          |                         |        |         |             |              |         |     |             |       |         |         |            |                  |
| Walls                            | 9                       |        |         |             | 187 SF       |         |     |             |       |         |         |            |                  |
| North                            | 8                       |        | ✓       |             |              | N       |     |             | M     |         |         | 2          | 6                |
| South                            | 19B                     |        | ✓       |             | 99 SF        | N       |     |             | M     |         |         | 1          | 7                |
| East                             | 8                       |        | ✓       |             | "            | N       |     |             | M     |         |         | 2          | 6                |
| West                             | 8                       |        | ✓       |             | 63 SF        | N       |     |             | M     |         |         | 1          | 7                |
| Other                            |                         |        | ✓       |             | "            | N       |     |             | M     |         |         | 1          | 7                |
| <b>Thermal System Insulation</b> |                         |        |         |             |              |         |     |             |       |         |         |            |                  |
| Pipe                             |                         |        |         |             |              |         |     |             |       |         |         |            |                  |
| Duct                             |                         |        |         |             |              |         |     |             |       |         |         |            |                  |
| Fixture                          |                         |        |         |             |              |         |     |             |       |         |         |            |                  |
| <b>Miscellaneous Material</b>    |                         |        |         |             |              |         |     |             |       |         |         |            |                  |
| Ceiling Tiles (New)              | 180B                    |        |         |             |              |         |     |             |       |         |         |            |                  |
| Floor Tiles                      | 146                     | White  |         |             |              |         |     |             |       |         |         |            |                  |
| Window Caulk                     |                         |        |         | ✓           | 187 SF       | N       |     |             | M     |         |         | 2          | 6                |
| Acoustical Material              | 70                      | Orange |         | ✓           | 9 LF         | N       |     |             | M     |         |         | 2          | 6                |
| " " Material                     | 49A                     | Tan    |         | ✓           | 9 LF         | N       |     |             | M     |         |         | 2          | 6                |
| PT                               | A22B                    |        |         | ✓           | 14 SF        | N       |     |             | M     |         |         | 2          | 6                |
| "                                | B329                    |        |         | ✓           | 14 SF        | N       |     |             | M     |         |         | 2          | 6                |
| ↓                                | A24D                    |        |         | ✓           | 14 SF        | N       |     |             | M     |         |         | 2          | 6                |
| PT Material                      | A22B/M                  | BL     |         | ✓           | 187 SF       | N       |     |             | M     |         |         | 2          | 6                |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor  
S - Significant



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3f-711N

Type of Space: Office

Ceiling Height: 9 FT — INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

615

**Influence of Vibration: HIGH MODERATE LOW/NONE**

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3F-711D

Type of Space: Category

Ceiling Height: 11 FT - INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

[illegible]



Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/30/01

Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 36-711Q  
Type of Space: Hallway  
Ceiling Height: 9 FT 1 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

(6 x 50)

| Type of Material          | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     |     | Tested ACBM |         |     |     | ACM AHERA Y/N | Rank | Removal Priority |
|---------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|-----|-------------|---------|-----|-----|---------------|------|------------------|
|                           |                         |       |         |             | Total        | Damaged | D/D | P/D | Total       | Damaged | D/D | P/D |               |      |                  |
| Surfacing Material        |                         |       |         |             |              |         |     |     |             |         |     |     |               |      |                  |
| Ceiling Walls             | 9                       |       |         |             | 300 SF       | N       |     |     |             |         |     |     |               |      |                  |
| North                     | 8                       | cream | ✓       |             | 450 SF       | N       |     |     |             |         |     |     |               | 2    | 6                |
| South                     | 8                       |       | ✓       |             | "            | N       |     |     |             |         |     |     |               | 1    | 7                |
| East                      | 8                       |       | ✓       |             | 54 SF        | N       |     |     |             |         |     |     |               | 1    | 7                |
| West                      | 8                       |       | ✓       |             | "            | N       |     |     |             |         |     |     |               | 1    | 7                |
| Other                     |                         |       | ✓       |             |              |         |     |     |             |         |     |     |               | 1    | 7                |
| Thermal System Insulation |                         |       |         |             |              |         |     |     |             |         |     |     |               |      |                  |
| Pipe                      |                         |       |         |             |              |         |     |     |             |         |     |     |               |      |                  |
| Duct                      |                         |       |         |             |              |         |     |     |             |         |     |     |               |      |                  |
| Fixture                   |                         |       |         |             |              |         |     |     |             |         |     |     |               |      |                  |
| Miscellaneous Material    |                         |       |         |             |              |         |     |     |             |         |     |     |               |      |                  |
| Ceiling Tiles (6x6)       | 1808                    | WH    |         |             |              |         |     |     |             |         |     |     |               |      |                  |
| Floor Tiles (6x6)         | A241                    |       |         | ✓           | 180 SF       | N       |     |     |             |         |     |     |               | 2    | 6                |
| Window Caulk              |                         |       |         |             |              |         |     |     |             |         |     |     |               |      |                  |
| Exterior                  | A242                    |       |         | ✓           | 180 SF       | N       |     |     |             |         |     |     |               | 2    | 6                |
| Plumbing                  | A241M                   |       |         | ✓           | 300 SF       | N       |     |     |             |         |     |     |               | 1    | 7                |
| Floor - Board             | A241D                   |       |         | ✓           | 1185 SF      | N       |     |     |             |         |     |     |               | 2    | 6                |

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3F-711C  
Type of Space: PERSONNEL OFFICE  
Ceiling Height:

Building ID No.: 7.11

Date of Inspection: 8/30/01

Influence of Vibration: HIGH MODERATE LOW/NONE

**Potential for Air Erosion:** HIGH MODERATE LOW/NONE

(30x17)

D/D - Degree of Damage  
M - Minor  
S - Significant

\* PLASTER ONLY

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:  
Date of Inspection:

7.11  
8/30/01

Influence of Vibration:

HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.:

3f-7.11S

Type of Space:

File Storage

Ceiling Height:

10 FT - INCH

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

(7 x 15)

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |   |         |  | Suspect Material |  |     |  | ACM AHERA Rank | Removal Priority |             |  |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---|---------|--|------------------|--|-----|--|----------------|------------------|-------------|--|
|                                  |                         |       |         |             | Total        |   | Damaged |  | D/D              |  | P/D |  |                |                  | Tested ACBM |  |
|                                  |                         |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| <b>Surfacing Material</b>        |                         |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| Ceiling                          |                         |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| Walls                            |                         |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| North                            | 9                       |       | ✓       |             | 91 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
| South                            | 8                       | cream | ✓       |             | 70 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
| East                             | 19B                     |       | ✓       |             | 70 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
| West                             | 13'                     |       | ✓       |             | 130 SF       | N |         |  |                  |  |     |  |                |                  |             |  |
| Other                            | 8                       | ↓     | ✓       |             | 130 SF       | N |         |  |                  |  |     |  |                |                  |             |  |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| Pipe                             |                         |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| Duct                             |                         |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| Fixture                          |                         |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| Ceiling Tiles (mm)               | 1806                    |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| Floor Tiles                      | 146                     |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| Window Caulk                     | 245D                    |       |         |             |              |   |         |  |                  |  |     |  |                |                  |             |  |
| FT -                             | A241                    | grey  | ✓       |             | 91 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
|                                  | A242                    |       | ✓       |             | 31P          | N |         |  |                  |  |     |  |                |                  |             |  |
|                                  | A242                    |       | ✓       |             | 25 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
|                                  | A242                    |       | ✓       |             | 25 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
| FT Masking                       | A242                    |       | ✓       |             | 40 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
| Window Caulk                     | A242                    |       | ✓       |             | 91 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
| One Way Window                   | A242                    | TAN   | ✓       |             | 48 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
| " " Window                       | 28                      | tan   | ✓       |             | 48 SF        | N |         |  |                  |  |     |  |                |                  |             |  |
|                                  | 48                      | tan   | ✓       |             | 48 SF        | N |         |  |                  |  |     |  |                |                  |             |  |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage



Building Name: Rundel  
Building Address: 115 South

Space ID No.: 3F-711F  
Type of Space: Bathroom / Storage  
Ceiling Height: 10 FT - INCH

| Potential for Air Erosion: | HIGH | MODERATE | LOW/NONE |
|----------------------------|------|----------|----------|
|                            |      |          | (5x5)    |

**Continuance of Vibration: HIGH MODERATE LOW/NONE**

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

**F/U - Potential for Damage**  
M - Minor / Concern 11. 1 + . . .

Building Name: Rundel  
Building Address: 115 South

**115 South Avenue**

Building ID No.: 7.11

9 FT - INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

HIGH MODERATE LOW/NONE

D/D - Degree of Damage  
M - Minor  
S - Significant

**P/D - Potential for Damage**  
**M - Minor (Generally Not Accessible)**

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/30/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM Space ID No.: 3C-7.11V  
 Type of Space: MACHINE ROOM  
 Ceiling Height: 9 FT - INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE (12x17)

| Type of Material                 | Homogeneous Area ID No. | Color     | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |         |     | ACM Y/N | AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|-----------|---------|-------------|--------------|---------|-----|-------------|---------|-----|---------|------------|------------------|
|                                  |                         |           |         |             | Total        | Damaged | D/D | Total       | Damaged | D/D |         |            |                  |
| <b>Surfacing Material</b>        |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| Ceiling                          |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| Walls                            |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| North                            | 9                       | -         | ✓       |             | 204 SF       | N       |     |             |         |     |         | 2          | 6                |
| South                            | 198                     | cream     | ✓       |             | 153 SF       | N       |     |             |         |     |         | 2          | 6                |
| East                             | 198                     |           | ✓       |             |              | N       |     |             |         |     |         | 2          | 6                |
| West                             | 198                     |           | ✓       |             | 108 SF       | N       |     |             |         |     |         | 2          | 6                |
| Other                            |                         |           | ✓       |             |              | N       |     |             |         |     |         | 2          | 6                |
| <b>Thermal System Insulation</b> |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| Pipe                             |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| Duct                             |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| Fixture                          |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| <b>Miscellaneous Material</b>    |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| Ceiling Tiles                    | 162                     |           | ✓       |             | 204 SF       | N       |     |             |         |     |         | 2          | 6                |
| Floor Tiles                      | 124                     | cream/tan |         | ✓           | 204 SF       | N       |     |             |         |     |         | 2          | 6                |
| Window Caulk                     |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| Core Material                    | 124A                    | blk       |         | ✓           | 204 SF       | N       |     |             |         |     |         | 2          | 6                |
| " "                              | 38                      | brn       |         | ✓           | 171 SF       | N       |     |             |         |     |         | 2          | 6                |
| " "                              | 49A                     | tan       |         | ✓           | 171 SF       | N       |     |             |         |     |         | 2          | 6                |
| Sink Room/SXS                    |                         |           |         |             |              |         |     |             |         |     |         |            |                  |
| Floor 124/124A                   | 124/124A                |           |         | ✓           | 25/25 SF     | N       |     |             |         |     |         | 2          | 6                |
| Crane 11'                        | 9                       |           | ✓       |             | 25 SF        | N       |     |             |         |     |         | 2          | 6                |
| Walls = 8 (E walls)              | 8                       |           | ✓       |             | 204 SF       | N       |     |             |         |     |         | 2          | 6                |
| Pipe                             | 003                     |           | -       |             |              |         |     |             |         |     |         | 1          | 7                |





**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3F-7-114

3F-7.14

Type of Space: DIRECTOR'S OFFICE

Ceiling Height: 9 FT - INCH

**Building ID No.:** 7.11

Date of Inspection: 8/30/01

| Influence of Vibration: |    | HIGH | Moderate | LOW/NONE |
|-------------------------|----|------|----------|----------|
| 1                       | 2  | 3    | 4        | 5        |
| 6                       | 7  | 8    | 9        | 10       |
| 11                      | 12 | 13   | 14       | 15       |
| 16                      | 17 | 18   | 19       | 20       |
| 21                      | 22 | 23   | 24       | 25       |
| 26                      | 27 | 28   | 29       | 30       |
| 31                      | 32 | 33   | 34       | 35       |
| 36                      | 37 | 38   | 39       | 40       |
| 41                      | 42 | 43   | 44       | 45       |
| 46                      | 47 | 48   | 49       | 50       |
| 51                      | 52 | 53   | 54       | 55       |
| 56                      | 57 | 58   | 59       | 60       |
| 61                      | 62 | 63   | 64       | 65       |
| 66                      | 67 | 68   | 69       | 70       |
| 71                      | 72 | 73   | 74       | 75       |
| 76                      | 77 | 78   | 79       | 80       |
| 81                      | 82 | 83   | 84       | 85       |
| 86                      | 87 | 88   | 89       | 90       |
| 91                      | 92 | 93   | 94       | 95       |
| 96                      | 97 | 98   | 99       | 100      |

Potential for Air Erosion: HIGH MODERATE LOW/NONE

[illegible]

D/D - Degree of Damage  
M - Minor

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

**Rundel**

**115 South Avenue**

Building ID No.: 7.11

**Date of Inspection:**

| Influence of Vibration: | HIGH | MODERATE | LOW/NONE |
|-------------------------|------|----------|----------|
| 8.30/b1                 |      |          |          |

Space ID No.: 3F-7.11Z

Type of Space: Bartholomew

Ceiling Height: 9 FT - INCH

**HIGH MODERATE LOW/NONE**

(4x7)

[illegible]

D/D - Degree of Damage

M - Minor

**S - Significant**

P/D - Potential for Damage

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3F-711A  
Type of Space: Small MTS Room  
Ceiling Height: 9 FT - INCH

 $(13 \times 14)$ 

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material          |       |        | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material |         |     |     | ACM AHERA  | Removal Priority |      |
|---------------------------|-------|--------|-------------------------|-------|---------|-------------|--------------|---------|-----|-----|------------------|---------|-----|-----|------------|------------------|------|
| Surfacing Material        |       |        |                         |       |         |             | Total        | Damaged | D/D | P/D | Total            | Damaged | D/D | P/D | Sample No. | Y/N              | Rank |
| Ceiling                   | Walls |        | 9                       | —     | ✓       |             | 182 SF       | ✓       |     |     | 1                |         |     |     |            |                  |      |
| North                     | 14'   | 198    |                         | cream | ✓       |             | 126 SF       | N       |     | m   |                  |         |     |     |            |                  | 2    |
| South                     |       | 8      |                         |       | ✓       |             | 126 SF       | N       |     | m   |                  |         |     |     |            |                  | 2    |
| East                      | 13'   | 8      |                         | ↓     | ✓       |             | 117 SF       | N       |     | m   |                  |         |     |     |            |                  | 1    |
| West                      |       | 8      |                         | ↓     | ✓       |             | "            | N       |     | m   |                  |         |     |     |            |                  | 1    |
| Other                     |       |        |                         |       | ✓       |             |              |         |     | m   |                  |         |     |     |            |                  | 1    |
| Thermal System Insulation |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
| Pipe                      |       | —      |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
| Duct                      |       | —      |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
| Fixture                   |       | —      |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
| Miscellaneous Material    |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
| Ceiling Tiles (GWS)       |       | 1808   |                         | WH    |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
| Floor Tiles               |       | 148    |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
| Window Caulk              |       | 246D   |                         | grey  | ✓       |             | 182 SF       | N       |     | m   |                  |         |     |     |            |                  | 2    |
| FT                        |       | A338   |                         |       | ✓       |             | 51P          | N       |     | m   |                  |         |     |     |            |                  | 2    |
| FT MFGIC                  |       | A338 m |                         |       | ✓       |             | 182 SF       | N       |     | m   |                  |         |     |     |            |                  | 2    |
|                           |       | A48C   |                         | TAN   | ✓       |             | 524 SF       | N       |     | m   |                  |         |     |     |            |                  | 2    |
|                           |       |        |                         |       |         |             |              |         |     | m   |                  |         |     |     |            |                  | 2    |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |
|                           |       |        |                         |       |         |             |              |         |     |     |                  |         |     |     |            |                  |      |

**D/D** - Degree of Damage  
**M** - Minor  
**S** - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Aesthetic)



P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/29/01

Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3C-7.11AC  
Type of Space: OFFICE  
Ceiling Height: 9 FT 1 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

(15 x 25)

| Type of Material           | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |         |     | ACM AHERA Y/N | Rank | Removal Priority |
|----------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|-------------|---------|-----|---------------|------|------------------|
|                            |                         |       |         |             | Total        | Damaged | D/D | Total       | Damaged | D/D |               |      |                  |
| Surfacing Material         |                         |       |         |             |              |         |     |             |         |     |               |      |                  |
| Ceiling                    | 9                       | -     | ✓       |             | 375 SF       | N       |     |             |         |     |               |      |                  |
| Walls                      |                         |       |         |             |              |         |     |             |         |     |               |      |                  |
| North                      | 15'                     | cream | ✓       |             | 135 SF       | N       |     |             |         |     |               | 2    | 6                |
| South                      | 8                       |       | ✓       |             | 135 SF       | N       |     |             |         |     |               | 2    | 6                |
| East                       | 25'                     |       | ✓       |             | 225 SF       | N       |     |             |         |     |               | 1    | 7                |
| West                       | 8                       |       | ✓       |             | "            | N       |     |             |         |     |               | 1    | 7                |
| Other                      |                         |       |         |             |              |         |     |             |         |     |               | 1    | 7                |
| Thermal System: Insulation |                         |       |         |             |              |         |     |             |         |     |               |      |                  |
| Pipe                       |                         |       |         |             |              |         |     |             |         |     |               |      |                  |
| Duct                       |                         |       |         |             |              |         |     |             |         |     |               |      |                  |
| Fixture                    |                         |       |         |             |              |         |     |             |         |     |               |      |                  |
| Miscellaneous Material     |                         |       |         |             |              |         |     |             |         |     |               |      |                  |
| Ceiling Tiles (new)        | 180B                    |       |         |             |              |         |     |             |         |     |               |      |                  |
| Floor Tiles                | 14B                     |       |         |             |              |         |     |             |         |     |               |      |                  |
| Window Caulk               | 24BC                    | TAN   |         |             |              |         |     |             |         |     |               |      |                  |
| " "                        | 2450                    | gray  |         |             |              |         |     |             |         |     |               |      |                  |
| PT                         | A33B                    |       |         |             | 375 SF       | N       |     |             |         |     |               | 2    | 6                |
|                            | A 239                   |       |         |             | 100 SF       | N       |     |             |         |     |               | 2    | 6                |
|                            | A 840                   |       |         |             | 100 SF       | N       |     |             |         |     |               | 2    | 6                |
| PT                         | A33B                    | BLK   |         |             | 50 SF        | N       |     |             |         |     |               | 2    | 6                |
| Overhead                   | 70                      | maxon |         |             | 375 SF       | N       |     |             |         |     |               | 2    | 6                |
| " "                        | 410                     | TAN   |         |             | 18 SF        | N       |     |             |         |     |               | 2    | 6                |
|                            |                         |       |         |             | 18 SF        | N       |     |             |         |     |               | 2    | 6                |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3f-711AQ.

Type of Space: Small Office

**Ceiling Height:**

9 FT — INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Influence of Vibration: |   | HIGH | Moderate | LOW/NONE |
|-------------------------|---|------|----------|----------|
| 1                       | 1 | 1    | 1        | 1        |
| 2                       | 1 | 1    | 1        | 1        |
| 3                       | 1 | 1    | 1        | 1        |
| 4                       | 1 | 1    | 1        | 1        |
| 5                       | 1 | 1    | 1        | 1        |
| 6                       | 1 | 1    | 1        | 1        |
| 7                       | 1 | 1    | 1        | 1        |
| 8                       | 1 | 1    | 1        | 1        |
| 9                       | 1 | 1    | 1        | 1        |
| 10                      | 1 | 1    | 1        | 1        |
| 11                      | 1 | 1    | 1        | 1        |
| 12                      | 1 | 1    | 1        | 1        |
| 13                      | 1 | 1    | 1        | 1        |
| 14                      | 1 | 1    | 1        | 1        |
| 15                      | 1 | 1    | 1        | 1        |
| 16                      | 1 | 1    | 1        | 1        |
| 17                      | 1 | 1    | 1        | 1        |
| 18                      | 1 | 1    | 1        | 1        |
| 19                      | 1 | 1    | 1        | 1        |
| 20                      | 1 | 1    | 1        | 1        |
| 21                      | 1 | 1    | 1        | 1        |
| 22                      | 1 | 1    | 1        | 1        |
| 23                      | 1 | 1    | 1        | 1        |
| 24                      | 1 | 1    | 1        | 1        |
| 25                      | 1 | 1    | 1        | 1        |
| 26                      | 1 | 1    | 1        | 1        |
| 27                      | 1 | 1    | 1        | 1        |
| 28                      | 1 | 1    | 1        | 1        |
| 29                      | 1 | 1    | 1        | 1        |
| 30                      | 1 | 1    | 1        | 1        |
| 31                      | 1 | 1    | 1        | 1        |
| 32                      | 1 | 1    | 1        | 1        |
| 33                      | 1 | 1    | 1        | 1        |
| 34                      | 1 | 1    | 1        | 1        |
| 35                      | 1 | 1    | 1        | 1        |
| 36                      | 1 | 1    | 1        | 1        |
| 37                      | 1 | 1    | 1        | 1        |
| 38                      | 1 | 1    | 1        | 1        |
| 39                      | 1 | 1    | 1        | 1        |
| 40                      | 1 | 1    | 1        | 1        |
| 41                      | 1 | 1    | 1        | 1        |
| 42                      | 1 | 1    | 1        | 1        |
| 43                      | 1 | 1    | 1        | 1        |
| 44                      | 1 | 1    | 1        | 1        |
| 45                      | 1 | 1    | 1        | 1        |
| 46                      | 1 | 1    | 1        | 1        |
| 47                      | 1 | 1    | 1        | 1        |
| 48                      | 1 | 1    | 1        | 1        |
| 49                      | 1 | 1    | 1        | 1        |
| 50                      | 1 | 1    | 1        | 1        |
| 51                      | 1 | 1    | 1        | 1        |
| 52                      | 1 | 1    | 1        | 1        |
| 53                      | 1 | 1    | 1        | 1        |
| 54                      | 1 | 1    | 1        | 1        |
| 55                      | 1 | 1    | 1        | 1        |
| 56                      | 1 | 1    | 1        | 1        |
| 57                      | 1 | 1    | 1        | 1        |
| 58                      | 1 | 1    | 1        | 1        |
| 59                      | 1 | 1    | 1        | 1        |
| 60                      | 1 | 1    | 1        | 1        |
| 61                      | 1 | 1    | 1        | 1        |
| 62                      | 1 | 1    | 1        | 1        |
| 63                      | 1 | 1    | 1        | 1        |
| 64                      | 1 | 1    | 1        | 1        |
| 65                      | 1 | 1    | 1        | 1        |
| 66                      | 1 | 1    | 1        | 1        |
| 67                      | 1 | 1    | 1        | 1        |
| 68                      | 1 | 1    | 1        | 1        |
| 69                      | 1 | 1    | 1        | 1        |
| 70                      | 1 | 1    | 1        | 1        |
| 71                      | 1 | 1    | 1        | 1        |
| 72                      | 1 | 1    | 1        | 1        |
| 73                      | 1 | 1    | 1        | 1        |
| 74                      | 1 | 1    | 1        | 1        |
| 75                      | 1 | 1    | 1        | 1        |
| 76                      | 1 | 1    | 1        | 1        |
| 77                      | 1 | 1    | 1        | 1        |
| 78                      | 1 | 1    | 1        | 1        |
| 79                      | 1 | 1    | 1        | 1        |
| 80                      | 1 | 1    | 1        | 1        |
| 81                      | 1 | 1    | 1        | 1        |
| 82                      | 1 | 1    | 1        | 1        |
| 83                      | 1 | 1    | 1        | 1        |
| 84                      | 1 | 1    | 1        | 1        |
| 85                      | 1 | 1    | 1        | 1        |
| 86                      | 1 | 1    | 1        | 1        |
| 87                      | 1 | 1    | 1        | 1        |
| 88                      | 1 | 1    | 1        | 1        |
| 89                      | 1 | 1    | 1        | 1        |
| 90                      | 1 | 1    | 1        | 1        |
| 91                      | 1 | 1    | 1        | 1        |
| 92                      | 1 | 1    | 1        | 1        |
| 93                      | 1 | 1    | 1        | 1        |
| 94                      | 1 | 1    | 1        | 1        |
|                         |   |      |          |          |

(10x16)

| Type of Material                 | Homogeneous Area ID No. | Color  | Friable | Non-Friable | Suspect Material |         |     |             |       |         | ACM AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|--------|---------|-------------|------------------|---------|-----|-------------|-------|---------|----------------|------------------|
|                                  |                         |        |         |             | Assumed ACBM     |         |     | Tested ACBM |       |         |                |                  |
|                                  |                         |        |         |             | Total            | Damaged | D/D | P/D         | Total | Damaged |                |                  |
| <b>Surfacing Material</b>        |                         |        |         |             |                  |         |     |             |       |         |                |                  |
| Ceiling Walls                    |                         |        |         |             |                  | 160 SF  |     |             |       |         |                |                  |
| North                            | 9                       | -      | ✓       |             |                  |         | N   |             |       | M       |                | 2                |
| South                            | 8                       | cream  | ✓       |             |                  | 90 SF   | N   |             |       | M       |                | 1                |
| East                             | 19B                     |        | ✓       |             |                  | "       | N   |             |       | M       |                | 2                |
| West                             | 8                       | ↓      | ✓       |             |                  | 144 SF  | N   |             |       | M       |                | 1                |
| Other                            | 8                       | ↓      | ✓       |             |                  | "       | N   |             |       | M       |                | 1                |
| <b>Thermal System Insulation</b> |                         |        |         |             |                  |         |     |             |       |         |                |                  |
| Pipe                             |                         |        |         |             |                  |         |     |             |       |         |                |                  |
| Duct                             |                         |        |         |             |                  |         |     |             |       |         |                |                  |
| Fixture                          |                         |        |         |             |                  |         |     |             |       |         |                |                  |
| <b>Miscellaneous Material</b>    |                         |        |         |             |                  |         |     |             |       |         |                |                  |
| Ceiling Tiles (A.I.D.)           | 180B                    |        |         |             |                  |         |     |             |       |         |                |                  |
| Floor Tiles                      | 14B                     |        |         |             |                  |         |     |             |       |         |                |                  |
| Window Caulk                     |                         |        |         |             |                  |         |     |             |       |         |                |                  |
| FF                               | A32B                    |        | ✓       |             |                  | 160 SF  | N   |             |       | M       |                | 2                |
|                                  | 339                     |        | ✓       |             |                  | 157 SF  | N   |             |       | M       |                | 2                |
|                                  | 340                     |        | ✓       |             |                  | 157 SF  | N   |             |       | M       |                | 2                |
|                                  | ✓ 338M                  |        | ✓       |             |                  | 140 SF  | N   |             |       | M       |                | 2                |
| FF MORTAR                        |                         |        | ✓       |             |                  | 160 SF  | N   |             |       | M       |                | 2                |
| Core MORTAR                      | 70                      | maroon | ✓       |             |                  | 36 SF   | N   |             |       | M       |                | 2                |
| " A MORTAR                       | 49A                     | tan    | ✓       |             |                  | 50 SF   | N   |             |       | M       |                | 2                |

D/D - Degree of Damage

M - Minor

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)



Space ID No.: 3F-711AF  
Type of Space: Office  
Ceiling Height: 11 FT - INCH

(14, 30)

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (General); Not A







Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/2/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM Space ID No.: 3F-711A1  
 Type of Space: MEN'S BATH / LOCKER RM  
 Ceiling Height: 11 FT — INCH  
 Potential for Air Erosion: HIGH MODERATE LOW/NONE

(5x5) ENTRY  
 (14x14) LOCKER ROOM  
 (6x12) BATHROOM

| Type of Material                 | Homogeneous Area ID No. | Color              | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material |         |     |     | ACM/AHERA Y/N | Rank | Removal Priority |
|----------------------------------|-------------------------|--------------------|---------|-------------|--------------|---------|-----|-----|------------------|---------|-----|-----|---------------|------|------------------|
|                                  |                         |                    |         |             | Total        | Damaged | D/D | P/D | Total            | Damaged | D/D | P/D |               |      |                  |
| <b>Surfacing Material</b>        |                         |                    |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| Ceiling                          |                         |                    |         |             | 293 SF       |         |     |     |                  |         |     |     |               |      |                  |
| Walls                            |                         |                    |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| North (14x14)                    | 9                       | Wk                 | ✓       |             | 13 SF        | N       |     |     |                  |         |     |     |               | 2    | 6                |
| South                            | 10/8                    | tan                | ✓       |             | 13 SF        | N       |     |     |                  |         |     |     |               | 1    | 7                |
| East                             |                         |                    | ✓       |             | 13 SF        | N       |     |     |                  |         |     |     |               | 1    | 7                |
| West                             |                         |                    | ✓       |             | 13 SF        | N       |     |     |                  |         |     |     |               | 1    | 7                |
| Other                            |                         |                    | ✓       |             | 13 SF        | N       |     |     |                  |         |     |     |               | 1    | 7                |
| <b>Thermal System Insulation</b> |                         |                    |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| Pipe (Bathroom)                  | 003                     | (copper) unwrapped |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| Duct                             |                         |                    |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| Fixture                          |                         |                    |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| <b>Miscellaneous Material</b>    |                         |                    |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| Ceiling Tiles                    |                         |                    |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| Floor Tiles                      | A341                    |                    |         | ✓           | 181 SF       | N       |     |     |                  |         |     |     |               | 2    | 6                |
| Window Caulk                     |                         |                    |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| Et-Mastic                        | A341m                   | Black              |         | ✓           | 203 SF       | N       |     |     |                  |         |     |     |               | 1    | 7                |
| Et-Border                        | A340                    |                    |         | ✓           | 112 SF       | N       |     |     |                  |         |     |     |               | 2    | 6                |
| Bathroom (6x12)                  |                         |                    |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| Plugs                            | 149                     | tan                |         |             |              |         |     |     |                  |         |     |     |               |      |                  |
| Walls                            | 4618                    | tan                |         | ✓           | 3% SF        | N       |     |     |                  |         |     |     |               | 1    | 7                |

D/D - Degree of Damage  
 M - Minor  
 S - Significant

P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)  
 N - Not Significant (Accessible for ACM Only)



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3f-711A5

Type of Space: JANITOR CLOSET

Ceiling Height: 11 FT - INCH

(5x5)

**HIGH MODERATE LOW/NONE**

### Potential for Air Erosion:

### Influence of Vibration: HIGH MODERATE LOW/NONE

**DiD - Degree of Damage**

P/D - Potential for Damage

Building Name: Rundel  
Building Address: 115 South Avenue

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3F-711AK  
Type of Space: LOW/SE  
Ceiling Height: 9 FT - INCH

Building ID No.: 7.11  
Date of Inspection: 8/3/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

Potential for Air Erosion: HIGH MODERATE LOW/NONE

(21 x 24)

| Type of Material                 | Homogeneous Area ID No. | Color  | Friable | Non-Friable | Suspect Material |         |             |     | ACM Y/N | AHRA Rank | Removal Priority |     |            |  |
|----------------------------------|-------------------------|--------|---------|-------------|------------------|---------|-------------|-----|---------|-----------|------------------|-----|------------|--|
|                                  |                         |        |         |             | Assumed ACBM     |         | Tested ACBM |     |         |           |                  |     |            |  |
|                                  |                         |        |         |             | Total            | Damaged | D/D         | P/D | Total   | Damaged   | D/D              | P/D | Sample No. |  |
| <b>Surfacing Material</b>        |                         |        |         |             |                  |         |             |     |         |           |                  |     |            |  |
| Ceiling Walls                    | 9                       | -      | ✓       |             | 504 SF           | N       |             |     | M       | 216 SF    | N                |     |            |  |
| North                            | 8                       | cream  | ✓       |             | 216 SF           | N       |             |     | M       | 216 SF    | N                |     |            |  |
| South                            | 8                       |        | ✓       |             | "                |         |             |     |         | 216 SF    | N                |     |            |  |
| East                             | 8                       |        | ✓       |             | 189 SF           |         |             |     |         | 189 SF    | N                |     |            |  |
| West                             | 8                       |        | ✓       |             | "                |         |             |     |         | 189 SF    | N                |     |            |  |
| Other                            |                         |        |         |             |                  |         |             |     |         |           |                  |     |            |  |
| <b>Thermal System Insulation</b> |                         |        |         |             |                  |         |             |     |         |           |                  |     |            |  |
| Pipe                             |                         |        |         |             |                  |         |             |     |         |           |                  |     |            |  |
| Duct                             |                         |        |         |             |                  |         |             |     |         |           |                  |     |            |  |
| Fixture                          |                         |        |         |             |                  |         |             |     |         |           |                  |     |            |  |
| <b>Miscellaneous Material</b>    |                         |        |         |             |                  |         |             |     |         |           |                  |     |            |  |
| Ceiling Tiles (New)              | 1806                    | Wk     |         |             |                  |         |             |     |         |           |                  |     |            |  |
| Floor Tiles                      | 148                     |        |         |             |                  |         |             |     |         |           |                  |     |            |  |
| Window Caulk                     | 408                     | tan    |         |             |                  |         |             |     |         |           |                  |     |            |  |
| FT mastic                        | A341m                   | BLK    |         |             |                  |         |             |     |         |           |                  |     |            |  |
| Cable Whipling                   | 70                      | maroon |         |             |                  |         |             |     |         |           |                  |     |            |  |
| " " mastic                       | 49A                     | tan    |         |             |                  |         |             |     |         |           |                  |     |            |  |

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/14/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM  
 Space ID No.: 3F-7.11AL

Type of Space: LADIES LOCKER RM/BATH  
 Ceiling Height: 9 FT --- INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE  
 (15x24) Locker Rm  
 (13x14) Bathroom

| Type of Material                 | Homogeneous Area ID No. | Color           | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material Tested ACBM |         |     |     | ACM AHERA Rank | Removal Priority |            |
|----------------------------------|-------------------------|-----------------|---------|-------------|--------------|---------|-----|-----|------------------------------|---------|-----|-----|----------------|------------------|------------|
|                                  |                         |                 |         |             | Total        | Damaged | D/D | P/D | Total                        | Damaged | D/D | P/D |                |                  |            |
|                                  |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  | Sample No. |
| <b>Surfacing Material</b>        |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Ceiling                          | 9                       | WHT             | ✓       |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Walls                            | 198/40                  | tan             |         |             | 3605K        | N       |     |     |                              |         |     |     |                |                  |            |
| North (7'0" x 18')               | 40                      | tan             |         |             | 435K         | N       |     |     |                              |         |     |     |                |                  | 6          |
| South                            |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  | 6          |
| East                             |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| West                             |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Other                            |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| <b>Thermal System Insulation</b> |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Pipe                             | 003                     | asphalt wrapped |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Duct                             |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Fixture                          |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| <b>Miscellaneous Material</b>    |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Ceiling Tiles                    | 143                     |                 |         |             | 3605K        | N       |     |     |                              |         |     |     |                |                  | 6          |
| Floor Tiles                      |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Window Caulk                     |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| PF                               | A340                    |                 |         |             | 1325K        | N       |     |     |                              |         |     |     |                |                  | 6          |
|                                  | A341                    |                 |         |             | 1145K        | N       |     |     |                              |         |     |     |                |                  | 6          |
|                                  | A342                    |                 |         |             | 1145K        | N       |     |     |                              |         |     |     |                |                  | 6          |
|                                  | A341M                   | BLK             |         |             | 3605K        | N       |     |     |                              |         |     |     |                |                  | 6          |
| Armstrong Bathroom (13x14)       |                         |                 |         |             |              |         |     |     |                              |         |     |     |                |                  | 7          |
| Walls                            | 140                     | tan             |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Ceiling                          | 9                       | WHT             | ✓       |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Grid                             | 149                     | tan             |         |             | 1825K        | N       |     |     |                              |         |     |     |                |                  | 6          |
| Tile                             | 003                     |                 |         |             |              |         |     |     |                              |         |     |     |                |                  |            |

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/21/01

Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3F-711AM

Type of Space: DINING ROOM

Ceiling Height: 11 FT 2 INCH

(17x24)

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material          | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material Tested ACBM |         |     |     | ACM AHERA Rank | Removal Priority |            |
|---------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|-----|------------------------------|---------|-----|-----|----------------|------------------|------------|
|                           |                         |       |         |             | Total        | Damaged | D/D | P/D | Total                        | Damaged | D/D | P/D |                |                  |            |
|                           |                         |       |         |             |              |         |     |     |                              |         |     |     |                |                  | Sample No. |
| Surfacing Material        |                         |       |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Ceiling Walls             | 9                       | WH    | ✓       |             | 408 SF       | Y       | S   | M   |                              |         |     |     |                |                  |            |
| North (14' x 6' 8")       | 40/B                    |       | ✓       |             | 43 SF        | N       |     |     |                              |         |     |     |                |                  | 6          |
| South                     |                         |       | ✓       |             | 13 SF        |         |     |     |                              |         |     |     |                |                  | 7          |
| East                      |                         |       | ✓       |             | 13 SF        |         |     |     |                              |         |     |     |                |                  | 7          |
| West                      |                         |       | ✓       |             | 13 SF        |         |     |     |                              |         |     |     |                |                  | 7          |
| Other                     |                         |       | ✓       |             | 13 SF        |         |     |     |                              |         |     |     |                |                  | 7          |
| Thermal System Insulation |                         |       |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Pipe (painted +)          | A000A 003               | WH    | ✓       |             | 3 LF         | N       |     |     |                              |         |     |     |                |                  | 6          |
| Duct plaster over         | 0047A                   | grey  | ✓       |             | 15 DLF       | N       |     |     |                              |         |     |     |                |                  | 6          |
| Fixtures/pipes/fittings   | 008                     | grey  | ✓       |             | 10 LF        | N       |     |     |                              |         |     |     |                |                  | 6          |
| Miscellaneous Material    |                         |       |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Ceiling Tiles             |                         |       |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Floor Tiles               | 309                     |       |         |             |              |         |     |     |                              |         |     |     |                |                  |            |
| Window Caulk              | 2450                    | grey  | ✓       |             | 4 DLF        | N       |     |     |                              |         |     |     |                |                  | 6          |
| " "                       | 248C                    | grey  | ✓       |             | 3 LF         | N       |     |     |                              |         |     |     |                |                  | 6          |
| ET mastic                 | 309 M                   | BLK   | ✓       |             | 4 DLF        | N       |     |     |                              |         |     |     |                |                  | 6          |



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3F-711 AD  
Type of Space: Vending Room  
Ceiling Height: 8 FT --- INCH

(12+14)

**HIGH MODERATE LOW/NONE**

### Potential for Air Erosion:

**Influence of Vibration: HIGH MODERATE LOW/NONE**

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable |
|----------------------------------|-------------------------|-------|---------|-------------|
| <b>Surfacing Material</b>        |                         |       |         |             |
| Ceiling Walls                    | 71A                     |       |         |             |
| North                            | 12' 198                 | cream | ✓       |             |
| South                            | 8                       |       | ✓       |             |
| East                             | 8                       |       | ✓       |             |
| West                             | 8                       |       | ✓       |             |
| Other                            |                         |       |         |             |
| <b>Thermal System Insulation</b> |                         |       |         |             |
| Pipe                             | (painted)               |       |         |             |
| Duct                             |                         |       |         |             |
| Fixture                          |                         |       |         |             |
| <b>Miscellaneous Material</b>    |                         |       |         |             |
| Ceiling Tiles (NW)               | 1806                    | Wk    |         |             |
| Floor Tiles                      | 309                     |       |         |             |
| Window Caulk                     | 30910                   | BK    |         |             |

A water damaged

**D/D - Degree of Damage**  
**M - Minor**

### P/D - Potential for Damage

**Rundel**  
**115 South Avenue**

**Building Name:**  
**Building Address:**

Space ID No.: 3C-711A

Type of Space: STALEWELL / DEWATON

Ceiling Height: 31' 0" / 9.45 m

8 FT — INCH (LANDING COVER)

LANDING (4x11)

HIGH MODERATE LOW/NONE

### Potential for Air Erosion:

| Influence of Vibration: |              | HIGH | MODERATE | LOW/NONE |
|-------------------------|--------------|------|----------|----------|
| a) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| b) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| c) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| d) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| e) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| f) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| g) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| h) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| i) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| j) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| k) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| l) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| m) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| n) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| o) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| p) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| q) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| r) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| s) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| t) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| u) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| v) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| w) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| x) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| y) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |
| z) Vibration            | 1) Vibration | 100% | 100%     | 100%     |
|                         | 2) Vibration | 100% | 100%     | 100%     |

| Type of Material                 | Homogeneous Area ID No. | Color    | Friable | Non-Friable |
|----------------------------------|-------------------------|----------|---------|-------------|
| <b>Surfacing Material</b>        |                         |          |         |             |
| Ceiling                          |                         |          |         |             |
| Walls                            | 9                       | At grey  | ✓       |             |
| North                            | 40                      | many old |         |             |
| South                            |                         |          |         |             |
| East                             |                         |          |         |             |
| West                             |                         |          |         |             |
| Other                            |                         |          |         |             |
| <b>Thermal System Insulation</b> |                         |          |         |             |
| Pipe                             |                         |          |         |             |
| Duct                             |                         |          |         |             |
| Fixture                          |                         |          |         |             |
| <b>Miscellaneous Material</b>    |                         |          |         |             |
| Ceiling Tiles                    | A142C                   | BK       |         |             |
| Floor Tiles                      |                         |          |         |             |
| Window Caulk                     |                         |          |         |             |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

## Rundel

**115 South Avenue**

7.11.2

---

**7.11**

83/21/01

Influence of Vibration: 2/5/01 HIGH MODERATE LOW/NONE

**HIGH MODERATE LOW**

E LOW/NONE

### Potential for Air Erosion:

**HIGH MODERATE LOW/NONE**

 $(5 \times 7)$ 

# ROOM-BY-ROOM INSPECTION FORM

**Space ID No.:**

3F-711A0

**Type of Space:**

Type of Space: MECHANICAL SHAFTWAY

**Ceiling Height:**

\_\_\_\_\_ FT \_\_\_\_\_ INCH (+to Roof)

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)



**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3C-711A2

Type of Space: ALL WAY

**Ceiling Height:** \_\_\_\_\_

6 FT 1 INCH

**HIGH MODERATE LOW/NONE**

### Potential for Air Erosion:

**Influence of Vibration: HIGH MODERATE LOW/NONE**

(6 x 121) LONG PORTFOLIO  
(7 x 19) SHORT PORTFOLIO

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)



Building Name:  
Building Address:

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3F-711AT  
Type of Space: OFFICES  
Ceiling Height: 10 FT - INCH

Building ID No.:  
Date of Inspection: 8/21/01

Influence of Vibration: HIGH MODERATE LOW/NONE

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

(15x20)

| Type of Material          | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |         |     | ACM AHERA Y/N | Rank | Removal Priority |
|---------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|------------------|---------|-----|---------------|------|------------------|
|                           |                         |       |         |             | Total        | Damaged | D/D | Total            | Damaged | D/D |               |      |                  |
| Surfacing Material        |                         |       |         |             |              |         |     |                  |         |     |               |      |                  |
| Ceiling                   |                         |       |         |             |              |         |     |                  |         |     |               |      |                  |
| Walls                     | 9                       |       |         |             | 300 SF       | N       |     |                  |         |     |               |      |                  |
| North (14' x 8')          | 40/B                    | W/K   | ✓       |             | 135 SF       | N       |     |                  |         |     |               | 2    | 6                |
| South                     | 15'                     | tan   | ✓       |             | 135 SF       | N       |     |                  |         |     |               | 1    | 7                |
| East                      | 19/B                    | ↓     | ✓       |             | 135 SF       | N       |     |                  |         |     |               | 1    | 7                |
| West (14' x 8')           | 40/B                    | cream | ✓       |             | 200 SF       | N       |     |                  |         |     |               | 2    | 6                |
| Other                     |                         | tan   | ✓       |             | 135 SF       | N       |     |                  |         |     |               | 1    | 7                |
| Thermal System Insulation |                         |       |         |             |              |         |     |                  |         |     |               |      |                  |
| Pipe                      |                         |       |         |             |              |         |     |                  |         |     |               |      |                  |
| Duct                      | 603                     |       |         |             |              |         |     |                  |         |     |               |      |                  |
| Fixture                   |                         |       |         |             |              |         |     |                  |         |     |               |      |                  |
| Miscellaneous Material    |                         |       |         |             |              |         |     |                  |         |     |               |      |                  |
| Ceiling Tiles             |                         |       |         |             |              |         |     |                  |         |     |               |      |                  |
| Floor Tiles               | 14B                     |       |         |             |              |         |     |                  |         |     |               |      |                  |
| Window Caulk              | 4450                    |       |         |             |              |         |     |                  |         |     |               |      |                  |
| " "                       | 248C                    | grey  | ✓       |             | 300 SF       | N       |     |                  |         |     |               | 2    | 6                |
| Cove Molding              | 3B                      | TAN   | ✓       |             | 348 SF       | N       |     |                  |         |     |               | 2    | 6                |
| " "                       | 44B                     | brn   | ✓       |             | 50 SF        | N       |     |                  |         |     |               | 2    | 6                |
| FT                        | A33B                    | tan   | ✓       |             | 50 SF        | N       |     |                  |         |     |               | 2    | 6                |
| ↓                         | 1A 38A                  |       | ✓       |             | 140 SF       | N       |     |                  |         |     |               | 2    | 6                |
|                           | 234D                    |       | ✓       |             | 140 SF       | N       |     |                  |         |     |               | 2    | 6                |
| PT Molding                | A338M                   | BLK   | ✓       |             | 70 SF        | N       |     |                  |         |     |               | 2    | 6                |
|                           |                         |       |         |             | 300 SF       | N       |     |                  |         |     |               | 2    | 6                |

\* PLASTER ONLY

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/31/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3A-711AU  
 Type of Space: "FRIENDS" OFFICE  
 Ceiling Height: 10 FT 1 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE (19420)

| Type of Material                 | Homogeneous Area ID No. | Color    | Friable | Non-Friable | Assumed ACBM |         |     | Suspect Material |         |     | ACM AHERA Rank | Removal Priority |
|----------------------------------|-------------------------|----------|---------|-------------|--------------|---------|-----|------------------|---------|-----|----------------|------------------|
|                                  |                         |          |         |             | Total        | Damaged | D/D | Total            | Damaged | D/D |                |                  |
| <b>Surfacing Material</b>        |                         |          |         |             |              |         |     |                  |         |     |                |                  |
| Ceiling                          |                         |          |         |             |              |         |     |                  |         |     |                |                  |
| Walls                            |                         |          |         |             |              |         |     |                  |         |     |                |                  |
| North (partially)                | 40/8                    | WHT      | ✓       |             | 380 SF       | N       |     | M                |         |     |                | 2                |
| South                            | 19                      | CREAM    | ✓       |             | 190 SF       | N       |     | M                |         |     |                | 1                |
| East                             | 20                      | ↓        | ✓       |             | "            | N       |     | M                |         |     |                | 1                |
| West                             | 19B                     | CREAM    | ✓       |             | 200 SF       | N       |     | M                |         |     |                | 1                |
| Other                            |                         |          |         |             | "            | N       |     | M                |         |     |                | 2                |
| <b>Thermal System Insulation</b> |                         |          |         |             |              |         |     |                  |         |     |                |                  |
| Pipe                             |                         |          |         |             |              |         |     |                  |         |     |                |                  |
| Duct                             |                         |          |         |             |              |         |     |                  |         |     |                |                  |
| Fixture                          |                         |          |         |             |              |         |     |                  |         |     |                |                  |
| <b>Miscellaneous Material</b>    |                         |          |         |             |              |         |     |                  |         |     |                |                  |
| Ceiling Tiles                    |                         |          |         |             |              |         |     |                  |         |     |                |                  |
| Floor Tiles                      | 14B                     |          |         |             |              |         |     |                  |         |     |                |                  |
| Window Caulk                     | 245D                    | GRAY TAN |         |             | 40 SF        | N       |     | M                |         |     |                | 2                |
| PT                               | 248C                    |          |         |             | 40 SF        | N       |     | M                |         |     |                | 2                |
|                                  | A33B                    |          |         |             | 151 SF       | N       |     | M                |         |     |                | 2                |
|                                  | A339                    |          |         |             | 151 SF       | N       |     | M                |         |     |                | 2                |
|                                  | A34D                    |          |         |             | 185 SF       | N       |     | M                |         |     |                | 2                |
| PT Mesh                          | A33Bm                   | BLU      |         |             | 380 SF       | N       |     | M                |         |     |                | 2                |
| Core Insulation                  | 3B                      |          |         |             | 181 SF       | N       |     | M                |         |     |                | 2                |
| " " Mesh                         | 49A                     |          |         |             | 181 SF       | N       |     | M                |         |     |                | 2                |

D/D - Degree of Damage  
 M - Minor  
 S - Significant

P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)  
 N - Not Significant (Accessible for O M Only)

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 2/21/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 36-711AY  
Type of Space: ACQUISITIONS OFFICE  
Ceiling Height: 9 FT — INCH

(13 x 33)

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material |         |     |     | ACM AHERA Rank | Removal Priority |             |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|-----|------------------|---------|-----|-----|----------------|------------------|-------------|
|                                  |                         |       |         |             | Total        | Damaged | D/D | P/D | Total            | Damaged | D/D | P/D |                |                  |             |
|                                  |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  | Tested ACBM |
| <b>Surfacing Material</b>        |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Ceiling                          |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Walls                            |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| North                            | 13'                     |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| South                            |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| East                             | 33'                     |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| West                             |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Other                            |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Pipe                             |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Duct                             |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Fixture                          |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Ceiling Tiles (new)              | 180B                    |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Floor Tiles                      | 117                     |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Window Caulk                     | 2450                    |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| Overhead                         | 502                     |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| " " " "                          | 494                     |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| " " " "                          | 480                     |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |
| " " " "                          | 117m                    |       |         |             |              |         |     |     |                  |         |     |     |                |                  |             |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)  
S - Significant (Excluded Accessible)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3f-711AW

Type of Space: ACQUISITIONS OFFICE

Ceiling Height: 9 FT - INCH

$$(22 \times 30)$$

HIGH MODERATE LOW/NONE

### Potential for Air Erosion:

|                         | LOW | MODERATE | HIGH | LOW/NONE |
|-------------------------|-----|----------|------|----------|
| Influence of Vibration: |     |          |      |          |

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3F-711AX  
Type of Space: Office  
Ceiling Height:

| Type of Material                 | Homogeneous Area ID No. | Color       | Friable | Non-Friable |
|----------------------------------|-------------------------|-------------|---------|-------------|
| <b>Surfacing Material</b>        |                         |             |         |             |
| Ceiling                          | 71A                     |             |         |             |
| Walls                            | B                       | cream       | ✓       |             |
| North                            | 19B                     |             | ✓       |             |
| South                            | 103                     |             | ✓       |             |
| East                             | 19B                     |             | ✓       |             |
| West                             | 19B                     |             | ✓       |             |
| Other                            |                         |             |         |             |
| <b>Thermal System Insulation</b> |                         |             |         |             |
| Pipe                             | -                       |             |         |             |
| Duct                             | -                       |             |         |             |
| Fixture                          | -                       |             |         |             |
| <b>Miscellaneous Material</b>    |                         |             |         |             |
| Ceiling Tiles (SAT)              | 173                     |             | ✓       |             |
| Floor Tiles                      | 117                     | grey w/ tan | ✓       |             |
| Window Caulk                     | -                       |             |         |             |
| PT Mastic                        | 117m                    |             | ✓       |             |
| Coil Molding                     | 58                      | grey        | ✓       |             |
| " " Molding                      | 49A                     | tan         | ✓       |             |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/31/01

Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3C-711AY  
Type of Space: 0866e  
Ceiling Height: 10 FT — INCH

Potential for Air Erosion:

HIGH MODERATE LOW/NONE

(14 & 14)

| Type of Material                 | Homogeneous Area ID No. | Color      | Friable | Non-Friable | Assumed ACBM |         |     | Tested ACBM |       |         | ACM AHERA |     | Removal Priority |
|----------------------------------|-------------------------|------------|---------|-------------|--------------|---------|-----|-------------|-------|---------|-----------|-----|------------------|
|                                  |                         |            |         |             | Total        | Damaged | D/D | P/D         | Total | Damaged | D/D       | P/D |                  |
| <b>Surfacing Material</b>        |                         |            |         |             |              |         |     |             |       |         |           |     |                  |
| Ceiling                          |                         |            |         |             |              |         |     |             |       |         |           |     |                  |
| Walls                            |                         |            |         |             |              |         |     |             |       |         |           |     |                  |
| North                            | 198                     |            | ✓       |             | 196SF        | N       |     |             | m     | 196SF   | N         |     | 4                |
| South                            | 198                     |            | ✓       |             | 196SF        | N       |     |             | m     |         |           |     | 2                |
| East                             | 198                     |            | ✓       |             | 140SF        | N       |     |             | m     |         |           |     | 2                |
| West                             | 198                     |            | ✓       |             | 140SF        | N       |     |             | m     |         |           |     | 2                |
| Other                            | 198                     |            | ✓       |             | 140SF        | N       |     |             | m     |         |           |     | 2                |
| <b>Thermal System Insulation</b> |                         |            |         |             |              |         |     |             |       |         |           |     |                  |
| Pipe                             |                         |            |         |             |              |         |     |             |       |         |           |     |                  |
| Duct                             |                         |            |         |             |              |         |     |             |       |         |           |     |                  |
| Fixture                          |                         |            |         |             |              |         |     |             |       |         |           |     |                  |
| <b>Miscellaneous Material</b>    |                         |            |         |             |              |         |     |             |       |         |           |     |                  |
| Ceiling Tiles                    | 173A                    | WH         | ✓       |             | 196SF        | N       |     |             | m     |         |           |     | 2                |
| Floor Tiles                      | 148                     |            |         |             | 196SF        | N       |     |             | m     |         |           |     | 2                |
| Window Caulk                     | 245D                    | grey       | ✓       |             | 40           | N       |     |             | m     |         |           |     | 2                |
| " "                              | 842C                    | BRN        | ✓       |             | 248IP        | N       |     |             | m     |         |           |     | 2                |
| Ceiling Insulation               | 38                      | BRN        | ✓       |             | 534          | N       |     |             | m     |         |           |     | 2                |
| " " Fiberglass                   | 49A                     | tan        | ✓       |             | 534          | N       |     |             | m     |         |           |     | 2                |
| PT                               | 117                     | grey/black | ✓       |             | 196SF        | N       |     |             | m     |         |           |     | 2                |
| FT Insulation                    | 117M                    | grey/black | ✓       |             | 196SF        | N       |     |             | m     |         |           |     | 2                |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)



Building Name:  
Building Address:

Rundel  
115 South Avenue

Building ID No.:  
Date of Inspection:

7.11  
8/3/01

Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3F-711AZ  
Type of Space: office/reception  
Ceiling Height: 9 FT 1 INCH

(11 x 15)

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material          | Homogeneous Area ID No. | Color    | Friable | Non-Friable | Assumed ACBM |         |     |     | Suspect Material |         |     |     | ACM/AHERA Rank | Removal Priority |             |    |
|---------------------------|-------------------------|----------|---------|-------------|--------------|---------|-----|-----|------------------|---------|-----|-----|----------------|------------------|-------------|----|
|                           |                         |          |         |             | Total        | Damaged | D/D | P/D | Total            | Damaged | D/D | P/D |                |                  |             |    |
|                           |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  | Tested ACBM |    |
| Surfacing Material        |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  |             |    |
| Ceiling                   |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  |             |    |
| Walls                     |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  |             |    |
| North                     | 15'                     | W/lt     | ✓       |             | 165 SF       | N       |     |     |                  |         |     |     |                |                  | 2           | 6  |
| South                     |                         | Green    | ✓       |             | 135 SF       | N       |     |     |                  |         |     |     |                |                  | 1           | 7  |
| East                      | 11'                     |          | ✓       |             | "            | N       |     |     |                  |         |     |     |                |                  | 1           | 7  |
| West                      |                         |          | ✓       |             | 99 SF        | N       |     |     |                  |         |     |     |                |                  | 1           | 7  |
| Other                     |                         |          | ✓       |             | "            | N       |     |     |                  |         |     |     |                |                  | 1           | 7  |
| Thermal System Insulation |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  |             |    |
| Pipe                      |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  |             |    |
| Duct                      |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  |             |    |
| Fixture                   |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  |             |    |
| Miscellaneous Material    |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  |             |    |
| Ceiling Tiles             | 171                     |          | ✓       |             | 165 SF       | N       |     |     |                  |         |     |     |                |                  | 2           | 6  |
| Floor Tiles               | 148                     |          |         | ✓           | 165 SF       | N       |     |     |                  |         |     |     |                |                  | 2           | 6  |
| Window Caulk              |                         |          |         |             |              |         |     |     |                  |         |     |     |                |                  |             |    |
| Pl. Mesh                  | 111                     | 800 dot. |         | ✓           | 165 SF       | N       |     |     |                  |         |     |     |                |                  | 2           | 10 |
|                           | A-111M                  | 811C     |         | ✓           | 165 SF       | N       |     |     |                  |         |     |     |                |                  | 2           | 6  |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)

**Rundel**  
**115 South Avenue**

**Building Name:**  
**Building Address:**

Space ID No.: 3F-711BA  
Type of Space: WORK/COPY ROOM  
Ceiling Height: \_\_\_\_\_

Ceiling Height: 9 FT - 1 INCH

$$(17 + 29)$$

Potential for Air Erosion: HIGH MODERATE LOW/NONE

**Influence of Vibration: HIGH MODERATE LOW/NONE**

[illegible]

\* PLASTER ONLY

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)

**Rundel**  
**115 South Avenue**

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3F-71188

Type of Space: "DEVELOPMENT/PHOTO" ROOM  
Ceiling Height:

**Building ID No.:**

Date of Inspection: 8/24/11

|                         | LOW | MODERATE | HIGH | LOW | MODERATE | HIGH |
|-------------------------|-----|----------|------|-----|----------|------|
| Influence of Vibration: | LOW | MODERATE | HIGH | LOW | MODERATE | HIGH |

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

Ceiling Height: 9 FT — INCH

$$(13 \times 23)$$
[illegible]

~~A~~ CARPET OVER PLASTER WALLS.

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)

Building Name:  
Building Address:

Space ID No.: 3F-711BC  
Type of Space: STORE ROOM  
Ceiling Height: 10 FT - INCH

**Building ID No.:**

**Date of Inspection:**

|                         | LOW | MODERATE | HIGH | MODERATE | HIGH | MODERATE | LOW/NONE |
|-------------------------|-----|----------|------|----------|------|----------|----------|
| Influence of Vibration: |     |          |      |          |      |          |          |

HIGH MODERATE LOW/NONE

7x14

[illegible]

**S - Significant**

N - Not Significant (Accessible for O M Only)

Building Name: Rundel  
Building Address: 115 South Avenue

Building ID No.: 7.11  
Date of Inspection: 8/3/01  
Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3F-711BD  
Type of Space: Office  
Ceiling Height: 9 FT 1 INCH

Potential for Air Erosion: HIGH MODERATE LOW/NONE (11412)

| Type of Material                 | Homogeneous Area ID No. | Color | Friable | Non-Friable | Assumed ACBM |         |     |     | Tested ACBM |         |     |     | ACM AHERA Rank | Removal Priority |   |
|----------------------------------|-------------------------|-------|---------|-------------|--------------|---------|-----|-----|-------------|---------|-----|-----|----------------|------------------|---|
|                                  |                         |       |         |             | Total        | Damaged | D/D | P/D | Total       | Damaged | D/D | P/D |                |                  |   |
| <b>Surfacing Material</b>        |                         |       |         |             |              |         |     |     |             |         |     |     |                |                  |   |
| Ceiling                          |                         |       |         |             |              |         |     |     |             |         |     |     |                |                  |   |
| Walls                            |                         |       |         |             |              |         |     |     |             |         |     |     |                |                  |   |
| North                            | 9                       |       | ✓       |             | 132 SF       | N       |     |     |             |         |     |     |                | 2                | 4 |
| South                            | 8                       |       | ✓       |             | 108 SF       | N       |     |     |             |         |     |     |                | 1                | 7 |
| East                             | 8/window wood           |       | ✓       |             | "            | N       |     |     |             |         |     |     |                | 1                | 7 |
| West                             | 8                       |       | ✓       |             | 99 SF        | N       |     |     |             |         |     |     |                | 1                | 7 |
| Other                            | 8                       |       | ✓       |             | "            | N       |     |     |             |         |     |     |                | 1                | 7 |
| <b>Thermal System Insulation</b> |                         |       |         |             |              |         |     |     |             |         |     |     |                |                  |   |
| Pipe                             |                         |       |         |             |              |         |     |     |             |         |     |     |                |                  |   |
| Duct                             |                         |       |         |             |              |         |     |     |             |         |     |     |                |                  |   |
| Fixture                          |                         |       |         |             |              |         |     |     |             |         |     |     |                |                  |   |
| <b>Miscellaneous Material</b>    |                         |       |         |             |              |         |     |     |             |         |     |     |                |                  |   |
| Ceiling Tiles                    | 171                     |       | ✓       |             | 132 SF       | N       |     |     |             |         |     |     |                | 2                | 6 |
| Floor Tiles                      | 148                     |       | ✓       |             | 132 SF       | N       |     |     |             |         |     |     |                | 2                | 6 |
| Window Caulk                     | 245D                    |       | ✓       |             | 41P          | N       |     |     |             |         |     |     |                | 2                | 6 |
| " "                              | 246C                    |       | ✓       |             | 248LP        | N       |     |     |             |         |     |     |                | 2                | 6 |
| FF                               | 111                     |       | ✓       |             | 132 SF       | N       |     |     |             |         |     |     |                | 2                | 6 |
| FF mastic                        | 111                     |       | ✓       |             | 132 SF       | N       |     |     |             |         |     |     |                | 2                | 6 |

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)









Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 8/31/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

# ROOM-BY-ROOM INSPECTION FORM

Space ID No.: 3F-7116H  
 Type of Space: LADIES ROOM  
 Ceiling Height: 10 FT — INCH

FRONT ENTRANCE (8x9)  
BATHROOM (6x12)

Potential for Air Erosion: HIGH MODERATE LOW/NONE

| Type of Material                 | Homogeneous Area ID No. | Color             | Friable | Non-Friable | Assumed ACBM |  |         |  | Suspect Material |  |     |  | ACM AHERA Rank | Removal Priority |             |  |
|----------------------------------|-------------------------|-------------------|---------|-------------|--------------|--|---------|--|------------------|--|-----|--|----------------|------------------|-------------|--|
|                                  |                         |                   |         |             | Total        |  | Damaged |  | D/D              |  | P/D |  |                |                  | Tested ACBM |  |
|                                  |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| <b>Surfacing Material</b>        |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| Ceiling                          |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| Walls                            |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| North                            | 9                       | cream             | ✓       |             | 144 SF       |  |         |  |                  |  |     |  |                |                  |             |  |
| South                            | 8                       | cream             | ✓       |             | 98 SF        |  |         |  |                  |  |     |  |                |                  |             |  |
| East                             | 8                       | ↓                 | ✓       |             | "            |  |         |  |                  |  |     |  |                |                  |             |  |
| West                             | 8                       | ↓                 | ✓       |             | 126 SF       |  |         |  |                  |  |     |  |                |                  |             |  |
| Other                            | 8/1000                  | ↓                 | ✓       |             | "            |  |         |  |                  |  |     |  |                |                  |             |  |
| <b>Thermal System Insulation</b> |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| Pipe                             |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| Duct                             | 003                     |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| Fixture                          |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| <b>Miscellaneous Material</b>    |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| Ceiling Tiles                    |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| Floor Tiles                      | A338                    |                   |         | ✓           | 53 SF        |  |         |  |                  |  |     |  |                |                  |             |  |
| Window Caulk                     |                         |                   |         |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| FT ↓                             | A339                    |                   |         | ✓           | 53 SF        |  |         |  |                  |  |     |  |                |                  |             |  |
| FT Mastic                        | A340                    |                   |         | ✓           | 35 SF        |  |         |  |                  |  |     |  |                |                  |             |  |
| Bathroom = (3' of 8) walls       | A338M                   |                   |         | ✓           | 144 SF       |  |         |  |                  |  |     |  |                |                  |             |  |
| Floor                            | 8/197                   | wall w/ pink tile | ✓       |             | 30 SF        |  |         |  |                  |  |     |  |                |                  |             |  |
| Ceiling                          | 149                     | tile              | ✓       |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
| Pipe                             | 9                       |                   | ✓       |             |              |  |         |  |                  |  |     |  |                |                  |             |  |
|                                  | 173                     |                   | ✓       |             | 165 SF       |  |         |  |                  |  |     |  |                |                  |             |  |
|                                  | 003                     |                   |         |             | 7 SF         |  |         |  |                  |  |     |  |                |                  |             |  |

D/D - Degree of Damage  
 M - Minor  
 S - Significant

P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)  
 N - Not Significant (Accessible for O M Only)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: 3C-7116T

Type of Space: STARWELL

**Ceiling Height:**

20 FT INCH

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

## 2- STAIR LANDINGS (3x3)

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O & M Only)

**Building Name:** Rundel  
**Building Address:** 115 South Avenue

Space ID No.: P-711A

$$\begin{array}{r} 194 \\ 65 \\ \hline 129 \end{array}$$

Type of Space: Penthouse - "L"

**Ceiling Height:**

8 FT — INCH = Plot form (24 x 15)

**Potential for Air Erosion:** HIGH MODERATE LOW/NONE

Influence of Vibration; HIGH MODERATE LOW/NONE

[illegible]

D/D - Degree of Damage

**M - Minor**

### S - Significant

### P/D - Potential for Damage

**M - Minor (Generally Not Accessible)**

**N - Not Significant (Accessible for OM Only)**



**Rundel**  
**115 South Avenue**

## Rundel

**115 South Avenue**

## 7.11

|     |
|-----|
| 911 |
|-----|

**HIGH MODERATE LOW/NONE**

### Potential for Air Erosion:

HIGH MODERATE LOW/NONE

**Space ID No.:**

Type of Space:

**Ceiling Height:**

9 FT - INCH

 $(10 \times 12)$ 

P-711C

EEVATON

10

NCH

—

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)  
S - Significant (Easily Accessible)

**Building Name:**  
**Building Address:**

**Building Name:**  
**Building Address:**

**Building ID No.:**

**Date of Inspection:**

### Influence of Vibration: HIGH MODERATE LOW/NONE

### Potential for Air Erosion:

**HIGH MODERATE LOW/NONE**

(21711)

Space ID No.: P-7110

**Type of Space:**

**Ceiling Height:**

5 FT — INCH

**HIGH MODERATE LOW/NONE**

[illegible]

D/D - Degree of Damage  
M - Minor  
S - Significant

P/D - Potential for Damage  
M - Minor (Generally Not Accessible)  
N - Not Significant (Accessible for O M Only)  
S - Significant (Easily Accessible)

Building Name: Rundel  
 Building Address: 115 South Avenue  
 Building ID No.: 7.11  
 Date of Inspection: 9/16/01  
 Influence of Vibration: HIGH MODERATE LOW/NONE

ROOM-BY-ROOM INSPECTION FORM Space ID No.: P-711E  
 Type of Space: MAIN PENTHOUSE  
 Ceiling Height: 20 FT -- INCH


Potential for Air Erosion: HIGH MODERATE LOW/NONE  
 26 x 109

| Type of Material                 | Homogeneous Area ID No. | Color          | Friable | Non-Friable | Assumed ACBM |         |     |     | Tested ACBM |         |     |     | ACM AHERA Y/N | Rank | Removal Priority |            |
|----------------------------------|-------------------------|----------------|---------|-------------|--------------|---------|-----|-----|-------------|---------|-----|-----|---------------|------|------------------|------------|
|                                  |                         |                |         |             | Total        | Damaged | D/D | P/D | Total       | Damaged | D/D | P/D |               |      |                  |            |
|                                  |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  | Sample No. |
| <b>Surfacing Material</b>        |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| Ceiling                          |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| Walls                            |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| North                            | 26'                     | gray           |         | ✓           | 520 SF       |         |     |     |             |         |     |     |               |      |                  |            |
| South                            | 109'                    |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| East                             |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| West                             |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| Other                            |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| <b>Thermal System Insulation</b> |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| Pipe                             | AD66A                   | WH             | ✓       | ✓           | 1-810LF      |         |     |     |             |         |     |     |               |      |                  |            |
| Duct                             | DOGO                    | COXK           | ✓       | ✓           | 2-30LF       |         |     |     |             |         |     |     |               |      |                  |            |
|                                  | DO13                    | WH/GREY        | ✓       | ✓           | 1-850LF      |         |     |     |             |         |     |     |               |      |                  |            |
| Fixture                          | DO2                     | BLK            | ✓       | ✓           | 2-75LF       |         |     |     |             |         |     |     |               |      |                  |            |
| INSULATION                       | DO2B                    | WH             | ✓       | ✓           | 2-150LF      |         |     |     |             |         |     |     |               |      |                  |            |
| <b>Miscellaneous Material</b>    |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| Ceiling Tiles                    |                         |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| Floor Tiles                      | 147                     |                |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| Window Caulk                     | 240A                    | WH             | ✓       | ✓           | 2-40LF       |         |     |     |             |         |     |     |               |      |                  |            |
| Flex. Duct Conn.                 | 0030                    | BLK            |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |
| TSC - PIPE                       | 004                     | BLK (over 600) |         |             |              |         |     |     |             |         |     |     |               |      |                  |            |

D/D - Degree of Damage  
 M - Minor  
 S - Significant

P/D - Potential for Damage  
 M - Minor (Generally Not Accessible)  
 N - Not Significant (Accessible)

**KEYNOTES:**

[illegible]

# EXISTING RUNDEL MEMORIAL BUILDING LOWER STACKS REMODELING FLOOR PLAN

SCALE: 1/8" = 1'-0"

### R1.1

**NEW  
PUBLIC LIBRARY  
ROCHESTER PUBLIC LIBRARY  
115 SOUTH AVENUE  
ROCHESTER, NY 14604  
TEL: 716/548-7446  
FACSIMILE: 716/426-1757**

CONTRACT NO.

TOP FLOOR

REAR OFFICE

REAR OFFICE


BOTTOM FLOOR

REAR OFFICE

REAR OFFICE







**ELMER J. ALMOGOST, D.C.**  
 507 E. 10TH STREET  
 DENVER, CO 80202  
 303-733-1616

**WILLIAMS & ASSOCIATES,  
ARCHITECT, INC.**  
1100 Broadway Avenue - Suite 100  
New York, New York 10018  
212-691-1100

**WILSON JENNIFER, P.C.**  
**ATTORNEYS AT LAW**  
**10000 WILSON ROAD**  
**ANN ARBOR MI 48106**

**United Construction  
Professional Association Inc.**  
c/o Jerry Connel, 10000  
Industrial Blvd., Suite 100  
Houston, TX 77036  
713/661-1111

**WATSON ASSOCIATES**  
30000 100th Avenue  
Broomfield, CO 80020  
303-440-1400  
303-440-1401

**CHRYSLER CREDIT CORP.**  
**CHRYSLER CREDIT CORP.**  
**CHRYSLER CREDIT CORP.**  
**CHRYSLER CREDIT CORP.**  
**CHRYSLER CREDIT CORP.**

**NEW  
PUBLIC LIBRARY**

1  
 2  
 3  
 4  
 5  
 6  
 7  
 8  
 9  
 10  
 11  
 12  
 13  
 14  
 15  
 16  
 17  
 18  
 19  
 20  
 21  
 22  
 23  
 24  
 25  
 26  
 27  
 28  
 29  
 30  
 31  
 32  
 33  
 34  
 35  
 36  
 37  
 38  
 39  
 40  
 41  
 42  
 43  
 44  
 45  
 46  
 47  
 48  
 49  
 50  
 51  
 52  
 53  
 54  
 55  
 56  
 57  
 58  
 59  
 60  
 61  
 62  
 63  
 64  
 65  
 66  
 67  
 68  
 69  
 70  
 71  
 72  
 73  
 74  
 75  
 76  
 77  
 78  
 79  
 80  
 81  
 82  
 83  
 84  
 85  
 86  
 87  
 88  
 89  
 90  
 91  
 92  
 93  
 94  
 95  
 96  
 97  
 98  
 99  
 100  
 101  
 102  
 103  
 104  
 105  
 106  
 107  
 108  
 109  
 110  
 111  
 112  
 113  
 114  
 115  
 116  
 117  
 118  
 119  
 120  
 121  
 122  
 123  
 124  
 125  
 126  
 127  
 128  
 129  
 130  
 131  
 132  
 133  
 134  
 135  
 136  
 137  
 138  
 139  
 140  
 141  
 142  
 143  
 144  
 145  
 146  
 147  
 148  
 149  
 150  
 151  
 152  
 153  
 154  
 155  
 156  
 157  
 158  
 159  
 160  
 161  
 162  
 163  
 164  
 165  
 166  
 167  
 168  
 169  
 170  
 171  
 172  
 173  
 174  
 175  
 176  
 177  
 178  
 179  
 180  
 181  
 182  
 183  
 184  
 185  
 186  
 187  
 188  
 189  
 190  
 191  
 192  
 193  
 194  
 195  
 196  
 197  
 198  
 199  
 200  
 201  
 202  
 203  
 204  
 205  
 206  
 207  
 208  
 209  
 210  
 211  
 212  
 213  
 214  
 215  
 216  
 217  
 218  
 219  
 220  
 221  
 222  
 223  
 224  
 225  
 226  
 227  
 228  
 229  
 230  
 231  
 232  
 233  
 234  
 235  
 236  
 237  
 238  
 239  
 240  
 241  
 242  
 243  
 244  
 245  
 246  
 247  
 248  
 249  
 250  
 251  
 252  
 253  
 254  
 255  
 256  
 257  
 258  
 259  
 260  
 261  
 262  
 263  
 264  
 265  
 266  
 267  
 268  
 269  
 270  
 271  
 272  
 273  
 274  
 275  
 276  
 277  
 278  
 279  
 280  
 281  
 282  
 283  
 284  
 285  
 286  
 287  
 288  
 289  
 290  
 291  
 292  
 293  
 294  
 295  
 296  
 297  
 298  
 299  
 300  
 301  
 302  
 303  
 304  
 305  
 306  
 307  
 308  
 309  
 310  
 311  
 312  
 313  
 314  
 315  
 316  
 317  
 318  
 319  
 320  
 321  
 322  
 323  
 324  
 325  
 326  
 327  
 328  
 329  
 330  
 331  
 332  
 333  
 334  
 335  
 336  
 337  
 338  
 339  
 340  
 341  
 342  
 343  
 344  
 345  
 346  
 347  
 348  
 349  
 350  
 351  
 352  
 353  
 354  
 355  
 356  
 357  
 358  
 359  
 360  
 361  
 362  
 363  
 364  
 365  
 366  
 367  
 368  
 369  
 370  
 371  
 372  
 373  
 374  
 375  
 376  
 377  
 378  
 379  
 380  
 381  
 382  
 383  
 384  
 385  
 386  
 387  
 388  
 389  
 390  
 391  
 392  
 393  
 394  
 395  
 396  
 397  
 398  
 399  
 400  
 401  
 402  
 403  
 404  
 405  
 406  
 407  
 408  
 409  
 410  
 411  
 412  
 413  
 414  
 415  
 416  
 417  
 418  
 419  
 420  
 421  
 422  
 423  
 424  
 425  
 426  
 427  
 428  
 429  
 430  
 431  
 432  
 433  
 434  
 435  
 436  
 437  
 438  
 439  
 440  
 441  
 442  
 443  
 444  
 445  
 446  
 447  
 448  
 449  
 450  
 451  
 452  
 453  
 454  
 455  
 456  
 457  
 458  
 459  
 460  
 461  
 462  
 463  
 464  
 465  
 466  
 467  
 468  
 469  
 470  
 471  
 472  
 473  
 474  
 475  
 476  
 477  
 478  
 479  
 480  
 481  
 482  
 483  
 484  
 485  
 486  
 487  
 488  
 489  
 490  
 491  
 492  
 493  
 494  
 495  
 496  
 497  
 498  
 499  
 500  
 501  
 502  
 503  
 504  
 505  
 506  
 507  
 508  
 509  
 510  
 511  
 512  
 513  
 514  
 515  
 516  
 517  
 518  
 519  
 520  
 521  
 522  
 523  
 524  
 525

\_\_\_\_\_


**SECRET**

• • • • •

| DATE     | DESCRIPTION            | AMOUNT | BALANCE  |
|----------|------------------------|--------|----------|
| 1/1/00   | OPENING BALANCE        |        | 100.00   |
| 1/15/00  | PAYROLL                | 50.00  | 50.00    |
| 2/1/00   | RECEIVED FROM CUSTOMER | 75.00  | 125.00   |
| 2/15/00  | PAYROLL                | 50.00  | 75.00    |
| 3/1/00   | RECEIVED FROM CUSTOMER | 100.00 | 175.00   |
| 3/15/00  | PAYROLL                | 50.00  | 125.00   |
| 4/1/00   | RECEIVED FROM CUSTOMER | 125.00 | 250.00   |
| 4/15/00  | PAYROLL                | 50.00  | 200.00   |
| 5/1/00   | RECEIVED FROM CUSTOMER | 150.00 | 350.00   |
| 5/15/00  | PAYROLL                | 50.00  | 300.00   |
| 6/1/00   | RECEIVED FROM CUSTOMER | 175.00 | 475.00   |
| 6/15/00  | PAYROLL                | 50.00  | 425.00   |
| 7/1/00   | RECEIVED FROM CUSTOMER | 200.00 | 625.00   |
| 7/15/00  | PAYROLL                | 50.00  | 575.00   |
| 8/1/00   | RECEIVED FROM CUSTOMER | 225.00 | 800.00   |
| 8/15/00  | PAYROLL                | 50.00  | 750.00   |
| 9/1/00   | RECEIVED FROM CUSTOMER | 250.00 | 1000.00  |
| 9/15/00  | PAYROLL                | 50.00  | 950.00   |
| 10/1/00  | RECEIVED FROM CUSTOMER | 275.00 | 1225.00  |
| 10/15/00 | PAYROLL                | 50.00  | 1175.00  |
| 11/1/00  | RECEIVED FROM CUSTOMER | 300.00 | 1475.00  |
| 11/15/00 | PAYROLL                | 50.00  | 1425.00  |
| 12/1/00  | RECEIVED FROM CUSTOMER | 325.00 | 1750.00  |
| 12/15/00 | PAYROLL                | 50.00  | 1700.00  |
| 1/1/01   | RECEIVED FROM CUSTOMER | 350.00 | 2050.00  |
| 1/15/01  | PAYROLL                | 50.00  | 2000.00  |
| 2/1/01   | RECEIVED FROM CUSTOMER | 375.00 | 2375.00  |
| 2/15/01  | PAYROLL                | 50.00  | 2325.00  |
| 3/1/01   | RECEIVED FROM CUSTOMER | 400.00 | 2725.00  |
| 3/15/01  | PAYROLL                | 50.00  | 2675.00  |
| 4/1/01   | RECEIVED FROM CUSTOMER | 425.00 | 3100.00  |
| 4/15/01  | PAYROLL                | 50.00  | 3050.00  |
| 5/1/01   | RECEIVED FROM CUSTOMER | 450.00 | 3500.00  |
| 5/15/01  | PAYROLL                | 50.00  | 3450.00  |
| 6/1/01   | RECEIVED FROM CUSTOMER | 475.00 | 3925.00  |
| 6/15/01  | PAYROLL                | 50.00  | 3875.00  |
| 7/1/01   | RECEIVED FROM CUSTOMER | 500.00 | 4375.00  |
| 7/15/01  | PAYROLL                | 50.00  | 4325.00  |
| 8/1/01   | RECEIVED FROM CUSTOMER | 525.00 | 4850.00  |
| 8/15/01  | PAYROLL                | 50.00  | 4800.00  |
| 9/1/01   | RECEIVED FROM CUSTOMER | 550.00 | 5350.00  |
| 9/15/01  | PAYROLL                | 50.00  | 5300.00  |
| 10/1/01  | RECEIVED FROM CUSTOMER | 575.00 | 5875.00  |
| 10/15/01 | PAYROLL                | 50.00  | 5825.00  |
| 11/1/01  | RECEIVED FROM CUSTOMER | 600.00 | 6425.00  |
| 11/15/01 | PAYROLL                | 50.00  | 6375.00  |
| 12/1/01  | RECEIVED FROM CUSTOMER | 625.00 | 7000.00  |
| 12/15/01 | PAYROLL                | 50.00  | 6950.00  |
| 1/1/02   | RECEIVED FROM CUSTOMER | 650.00 | 7600.00  |
| 1/15/02  | PAYROLL                | 50.00  | 7550.00  |
| 2/1/02   | RECEIVED FROM CUSTOMER | 675.00 | 8225.00  |
| 2/15/02  | PAYROLL                | 50.00  | 8175.00  |
| 3/1/02   | RECEIVED FROM CUSTOMER | 700.00 | 8875.00  |
| 3/15/02  | PAYROLL                | 50.00  | 8825.00  |
| 4/1/02   | RECEIVED FROM CUSTOMER | 725.00 | 9550.00  |
| 4/15/02  | PAYROLL                | 50.00  | 9500.00  |
| 5/1/02   | RECEIVED FROM CUSTOMER | 750.00 | 10250.00 |
| 5/15/02  | PAYROLL                | 50.00  | 10200.00 |
| 6/1/02   | RECEIVED FROM CUSTOMER | 775.00 | 10975.00 |
| 6/15/02  | PAYROLL                | 50.00  | 10925.00 |
| 7/1/02   | RECEIVED FROM CUSTOMER | 800.00 | 11725.00 |
| 7/15/02  | PAYROLL                | 50.00  | 11675.00 |
| 8/1/02   | RECEIVED FROM CUSTOMER | 825.00 | 12500.00 |
| 8/15/02  | PAYROLL                | 50.00  | 12450.00 |
| 9/1/02   | RECEIVED FROM CUSTOMER | 850.00 | 13300.00 |
| 9/15/02  | PAYROLL                | 50.00  | 13250.00 |
| 10/1/02  | RECEIVED FROM CUSTOMER | 875.00 | 14125.00 |
| 10/15/02 | PAYROLL                | 50.00  | 14075.00 |
| 11/1/02  | RECEIVED FROM CUSTOMER | 900.00 | 15025.00 |
| 11/15/02 | PAYROLL                | 50.00  | 14975.00 |
| 12/1/02  | RECEIVED FROM CUSTOMER | 925.00 | 15900.00 |
| 12/15/02 | PAYROLL                | 50.00  | 15850.00 |
| 1/1/03   | RECEIVED FROM CUSTOMER | 950.00 | 16800.00 |
| 1/15/03  | PAYROLL                | 50.00  | 16750.00 |
| 2/1/03   | RECEIVED FROM CUSTOMER | 975.00 |          |

CONFIDENTIAL

**UNDEL MEMO  
BUILDING**



### **THIRD LEVEL PLAN**

**SCALE: 15-14** **Transit 10 AUGUST 1977**

BUILDING ENGINEER  
- 404-7833  
- D RUE


# RUNDEL LIBRARY 115 SOUTH AVENUE


BUILDING NAME/ADDRESS


BUILDING NO.

7.11

SHEET #1







**ABELLA ASSOCIATES, P. C.**  
**ANALYTICAL LABORATORY**  
**300 STATE STREET**  
**ROCHESTER, NY 14614**  
**(716) 454-6110**

TEM ELAP # 10837

**SAMPLE DATE: 09/06/2001**

**PROJECT LOCATION:** Rundel Library (PO#391536)

Date: 11/12/01

ND - None Detected CELL-Cellulose JC - Joint Compound MIN - Mineral GLASS - Fiberglass <1 = Trace PLAS - Plaster  
P - Friable PLM analytical result N - NOB PLM analytical result T - TEM analytical result  
G-Gravimetric Matrix Reduction. Sample residue weight <1% of original sample weight, TEM not required.

Polarized-light microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can be used to determine if this material can be considered to be non-asbestos containing.





# LU ENGINEERS

Civil and Environmental  
2230 Penfield Road  
Penfield, NY 14526-1922

Job #: 4208-00

Job Name: City of Rochester

Date: 9/6/01

Name: M. JOHNSON

## ASBESTOS BULK SAMPLE LOG

| SAMPLE NUMBER  | SAMPLE LOCATION                                | MATERIAL TYPE             | AMOUNT | CONDITION | NOTES                 |
|----------------|------------------------------------------------|---------------------------|--------|-----------|-----------------------|
| 3F-711E-FB-RL1 | SERVING ROOM FLOOR                             | BLACK MASTIC UNDER GRFT   | TBD    | good      |                       |
| 2F-711E-WL-RL2 | MONROE COUNTY HISTORIAN'S OFFICE               | WOOD GRAINED LINOLEUM     | TBD    | good      |                       |
| P-711E-FB-RL3  | PENTHOUSE - ELEVATOR MACHINE ROOM - SOUTH WALL | FIRE BRICK (?)            | TBD    | good      |                       |
| P-711E-TI-RL4  | BOILER FEED TANK (MAIN PENTHOUSE)              | TANK INSULATION           | TBD    | good      |                       |
| P-711E-DI-RL5  | MAIN PENTHOUSE DUCT                            | DUCT INSULATION           | TBD    | good      |                       |
| P-711E-CPI-RL6 | MAIN PENTHOUSE PIPE / CAST IRON                | CORK-LIKE PIPE INSULATION | TBD    | good      |                       |
| P-711E-WW-RL7  | MAIN PENTHOUSE WINDOW                          | WHITE WINDOW CAULK        | TBD    | poor      | BETWEEN GLASS + FRAME |
|                |                                                |                           |        |           |                       |
|                |                                                |                           |        |           |                       |
|                |                                                |                           |        |           |                       |





Polarized-light microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy (TEM) is currently the only method that can be used to determine if this material can be considered to be non-asbestos containing.



**LaBella Associates, P.C.**  
**Analytical Laboratory**  
**300 State Street**  
**Rochester, New York 14614**  
**(716) 454-6110 FAX 454-3066**

391536

LBL Job # 45401

**Client:** LM Engineers

**Project #** 42-8-00-219

**Site Address:** Rundel Library  
115 South Avenue

**Site Description:** Rundel Library

Sample Technician: Eric Detweiler / Mike Johnson

Pre-Abatement ☐

**Work in Progress** ☐

## Finals

PCM ☐ TEM ☐

### Observations/Comments

REQUESTED ANALYSIS: AIR-FIBERS \_\_\_\_\_ BULK ASBESTOS ☒ OTHER \_\_\_\_\_

**FIELD DATA SHEET SUPPLIED WITH SAMPLES: YES/NO**

[illegible][illegible][illegible][illegible]

Relinquished by: \_\_\_\_\_

Date: \_\_\_\_\_

**Carrier:** \_\_\_\_\_

Number of Samples: 7

Received By: Matt Smith

Date: 9/4/01

Fax Results To: \_\_\_\_\_

Tech. Contact/Pager #: \_\_\_\_\_



# LU ENGINEERS

Civil and Environmental  
2230 Penfield Road  
Penfield, NY 14526-1922

Job #: 4208-00-2A

Job Name: City of Rochester

Date: 6/31/01

Name: SF/ED

## ASBESTOS BULK SAMPLE LOG

| SAMPLE NUMBER  | SAMPLE LOCATION                                    | MATERIAL TYPE         | AMOUNT | CONDITION | NOTES                                                                   |
|----------------|----------------------------------------------------|-----------------------|--------|-----------|-------------------------------------------------------------------------|
| 457.11A-MF-RL  | UPPER STACK 10' FROM MECHANICAL ROOM/MENSROOM      | GREY MUDDIED FITTING  | TBD    | EXPOSED   | ~ 1 SEM                                                                 |
| 457.11A-MPV-RL | UPPER STACK - NEXT TO MECHANICAL ROOM/MENS ROOM    | WHITE MGG PIPE WRAP   | TBP    | GOOD      |                                                                         |
| 47.11F-CP-RL   | MEZZANINE LEVEL SCIENCE BALCONY                    | WHITE CEILING PLASTER | TBD    | GOOD      |                                                                         |
| 47.11C-PVC-RL  | 1ST FLOOR SOUTH LIBRARY NON FICTION AREA           | CREAM WALL PLASTER    | TBD    | GOOD      |                                                                         |
| 47.11D-PVC-RL  | 1ST FLOOR CONFERENCE ROOM/ELEVATOR FLYER - ENDSIDE | GREY WALL PLASTER     | TBD    | GOOD      | BENIGN TEXTURED WALL PAPER                                              |
| 47.11D-RL      | 1ST FLOOR - WESTSIDE CONFERENCE ROOM               | WHITE WALL PLASTER    | TBD    | GOOD      | OVER GREY PLASTER                                                       |
| 47.11E-WWC-RL  | 1ST FLOOR - WESTSIDE WINDOWS                       | WINDOW CRACK - TAN    | TBD    | GOOD      | WHEN WINDOW WAS REPAIRED SAMPLE IS TAN; ALTHOUGH IS WHITE IN APPEARANCE |
|                |                                                    |                       |        |           |                                                                         |
|                |                                                    |                       |        |           |                                                                         |
|                |                                                    |                       |        |           |                                                                         |