## 68-92 Genesee Street Abandoned Chemicals Lab Pack/ Disposal October 16, 2015

	Waste Description	Quantity/ Volume	Waste Code
1	WASTE TETRACHLOROETHENE (LIQUID)	50 GAL.	D039; F002
2	WASTE TETRACHLOROETHENE (SOLID)	800 LBS	D039; F002
3	WASTE AEROSOLS, FLAMMABLE	10 LBS	D001
4	WASTE TETRACHLOROETHENE (SOLID)	600 LBS	D039; F002
5	WASTE TETRACHLOROETHENE (SOLID)	1200 LBS	D039; F002
6	WASTE SODIUM HYDROXIDE SOLUTION	10 GALS	D002
7	WASTE TETRACHLOROETHENE (LIQUID-MIXTURE)	100 GAL.	D039; F002
8	WASTE TETRACHLOROETHENE (SOLID-MIXTURE)	30 LBS	D039; F002
9	UN2810, WASTE TOXIC, LIQUIDS, ORGANIC, N.O.S.	300 LBS.	U080; D039; F002
10	UN2014 WASTE HYDROGEN PEROXIDE, AQUEOUS	50 LBS	D001; D002
11	UN3264 WASTE CORROSIVE LIQUID, ACIDIC, INORGANIC	5 LBS	D002
12	UN3108 WASTE ORGANIC PEROXIDE (SOLID)	1 LBS	D001
13	UN3266 WASTE CORROSIVE LIQUID, BASIC, INORGANIC	300 LBS.	D002
14	UN3264 WASTE CORROSIVE LIQUID, ACIDIC, INORGANIC	60 LBS	D002
15	UN1993 WASTE FLAMMABLE LIQUIDS, N.O.S.	20 LBS.	D001
16	UN1993 WASTE FLAMMABLE LIQUIDS, N.O.S.	200 LBS.	D001; D008
17	UN1993 WASTE FLAMMABLE LIQUIDS, N.O.S.	40 LBS.	D001
18	UN1993 WASTE FLAMMABLE LIQUIDS, N.O.S.	300 LBS.	D001
19	NON-RCRA, NON-DOT SOLIDS (LAUNDRY BEADS)	400 LBS	N/A
	NON-RCRA, NON-DOT REGULATED MATERIALS (FABRIC		
20	SOFTENER POWDER)	105 GALS.	N/A
	NON-RCRA, NON-DOT REGULATED MATERIALS (WATER		
21	SOFTENER)	10 GALS.	N/A
22	NON-RCRA, NON-DOT REGULATED MATERIALS (SEDIMENT)	400 LBS.	N/A
	NON-RCRA, NON-DOT REGULATED MATERIALS (LABPACKED		
23	CHEMICALS)	300 LBS.	N/A
	NON-RCRA, NON-DOT REGULATED MATERIALS (LABPACKED		
24	CHEMICALS)	50 LBS.	N/A
25	UN2810, TOXIC, LIQUIDS, ORGANIC, N.O.S.	15 LBS.	N/A