

Table 1. Interior inspections for deteriorated paint (visual inspections).	Year 1 7/1/06- 6/30/07	Year 2 7/1/07- 6/30/08	Year 3 7/1/08- 6/30/09	Year 4 7/1/09- 6/30/10	Year 5 7/1/10- 6/30/11	Year 6 7/1/11 – 6/30/12
Units inspected for deteriorated interior paint	16449	11607	13355	16766	14656	14048
Number (%) units failing deteriorated interior paint inspection	958 (6%)	1380 (12%)	699 (5%)	684 (4%)	733 (5%)	711 (5%)
Number (%) units passing interior paint inspection	15491 (94%)	10227 (88%)	12656 (95%)	16082 (96%)	13923 (95%)	13337 (95%)

Table 2. Dust wipe tests in units passing visual inspections in the designated high risk area.	Year 1 7/1/06- 6/30/07	Year 2 7/1/07- 6/30/08	Year 3 7/1/08- 6/30/09	Year 4 7/1/09- 6/30/10	Year 5 7/1/10- 6/30/11	Year 6 7/1/11 – 6/30/12
Units referred for dust wipe test*	3850	5778	5320	5607	5068	3033
Number (%) referred units that received dust wipe test**	2850 (74%)	4606 (80%)	4654 (87%)	4940 (88%)	4785 (94%)	3071 (101%)
Number (%) of units passing dust wipe test	2420 (85%)	3936 (85%)	4242 (91%)	4518 (91%)	4354 (91%)	2691 (88%)
Number of units cleared (outstanding) after failing dust wipe test	428(2)	669(1)	411(1)	418(4)	430(1)	379(1)

* Units located in “high risk areas” that pass an interior inspection for deteriorated paint were referred for dust wipe testing.

** Note that units *referred* in one year may not be *tested* until following year

Table 3. Inspections for exterior lead hazards (deteriorated paint or bare soil)	Year 1 7/1/06- 6/30/07	Year 2 7/1/07- 6/30/08	Year 3 7/1/08- 6/30/09	Year 4 7/1/09- 6/30/10	Year 5 7/1/10- 6/30/11	Year 6 7/1/11 – 6/30/12
Buildings inspected for exterior lead hazards	10548	10619	8612	11110	8684	7599
Number (%) of buildings passing exterior lead hazards inspection	8588 (81%)	9391 (88%)	7339 (85%)	9934 (89%)	7339 (85%)	6515 (86%)

Table 1. Interior inspections for deteriorated paint (visual inspections).	Year 7 7/1/12 – 6/30/13	Year 8 7/1/13 – 6/30/14	Year 9 7/1/14 – 6/30/15	Year 10 7/1/15 – 6/30/16	Year 11 7/1/16 – 6/30/17	Year 12 7/1/17 – 6/30/18	Year 13 7/1/18 – 6/30/19
Units inspected for deteriorated interior paint	13485	15268	13838	12002	12541	12891	16124
Number (%) units failing deteriorated interior paint inspection	405 (3%)	235 (2%)	380 (3%)	552 (5%)	732 (6%)	1126 (9%)	869 (5%)
Number (%) units passing interior paint inspection	13080 (97%)	15033 (98%)	13458 (97%)	11450 (95%)	11809 (94%)	11765 (91%)	15255 (95%)

Table 2. Dust wipe tests in units passing visual inspections in the designated high risk area.	Year 7 7/1/12 – 6/30/13	Year 8 7/1/13 – 6/30/14	Year 9 7/1/14 – 6/30/15	Year 10 7/1/15 – 6/30/16	Year 11 7/1/16 – 6/30/17	Year 12 7/1/17 – 6/30/18	Year 13 7/1/18 – 6/30/19
Units referred for dust wipe test*	2554	2637	2899	3066	3097	2958	3003
Number (%) referred units that received dust wipe test**	2061 (81%)	2363 (90%)	2794 (96%)	2620 (86%)	2842 (92%)	2670 (90%)	2663 (89%)
Number (%) of units passing dust wipe test	1834 (89%)	2153 (91%)	2560 (92%)	2388 (91%)	2597 (91%)	2422 (91%)	2406 (90%)
Number of units cleared (outstanding) after failing dust wipe test	226(1)	208(2)	234(0)	232(0)	239(6)	232(16)	223(35)

* Units located in “high risk areas” that pass an interior inspection for deteriorated paint were referred for dust wipe testing.

** Note that units *referred* in one year may not be *tested* until following year

Table 3. Inspections for exterior lead hazards (deteriorated paint or bare soil)	Year 7 7/1/12 – 6/30/13	Year 8 7/1/13 – 6/30/14	Year 9 7/1/14 – 6/30/15	Year 10 7/1/15 – 6/30/16	Year 11 7/1/16 – 6/30/17	Year 12 7/1/17 – 6/30/18	Year 13 7/1/18 – 6/30/19
Buildings inspected for exterior lead hazards	8450	7912	8124	8277	9228	9508	10061
Number (%) of buildings passing exterior lead hazards inspection	7409 (88%)	7032 (89%)	7254 (89%)	6963 (84%)	7587 (82%)	7578 (80%)	8270 (82%)

City of Rochester Lead Ordinance Years 1-15 (7/1/06 – 6/30/21)

August 9, 2021

Table 1. Interior inspections for deteriorated paint (visual inspections).	Year 14 7/1/19- 6/30/20	Year 15 7/1/20- 6/30/21				TOTAL
Units inspected for deteriorated interior paint	10554	11013				204597
Number (%) units failing deteriorated interior paint inspection	685 (6%)	599 (5%)				10748 (5%)
Number (%) units passing interior paint inspection	9869 (94%)	10414 (95%)				193849 (95%)

Table 2. Dust wipe tests in units passing visual inspections in the designated high risk area.	Year 14 7/1/19- 6/30/20	Year 15 7/1/20- 6/30/21				TOTAL
Units referred for dust wipe test*	2031	1860				52761
Number (%) referred units that received dust wipe test**	1867 (92%)	1853 (100%)				46639 (88%)
Number (%) of units passing dust wipe test	1728 (93%)	1744 (94%)				41993 (90%)
Number of units cleared (outstanding) after failing dust wipe test	148(18)	101(19)				4578(46)

* Units located in “high risk areas” that pass an interior inspection for deteriorated paint were referred for dust wipe testing.

** Note that units *referred* in one year may not be *tested* until following year

Table 3. Inspections for exterior lead hazards (deteriorated paint or bare soil)	Year 14 7/1/19- 6/30/20	Year 15 7/1/20- 6/30/21				TOTAL
Buildings inspected for exterior lead hazards	8104	8489				135325
Number (%) of buildings passing exterior lead hazards inspection	6717 (83%)	7262 (86%)				115178 (85%)