

City of Rochester Lead Ordinance Years 1-11 (7/1/06 – 6/30/17)

July 25, 2017

Table 1. Interior inspections for deteriorated paint (visual inspections).	Year 1 7/1/06-6/30/07	Year 2 7/1/07-6/30/08	Year 3 7/1/08-6/30/09	Year 4 7/1/09-6/30/10	Year 5 7/1/10-6/30/11
Units inspected for deteriorated interior paint	16449	11607	13355	16766	14656
Number (%) units failing deteriorated interior paint inspection	958 (6%)	1380 (12%)	699 (5%)	684 (4%)	733 (5%)
Number (%) units passing interior paint inspection	15491 (94%)	10227 (88%)	12656 (95%)	16082 (96%)	13923 (95%)

Table 2. Dust wipe tests in units passing visual inspections in the designated high risk area.	Year 1 7/1/06-6/30/07	Year 2 7/1/07-6/30/08	Year 3 7/1/08-6/30/09	Year 4 7/1/09-6/30/10	Year 5 7/1/10-6/30/11
Units referred for dust wipe test*	3850	5778	5320	5607	5068
Number (%) referred units that received dust wipe test**	2850 (74%)	4606 (80%)	4654 (87%)	4940 (88%)	4785 (94%)
Number (%) of units passing dust wipe test	2420 (85%)	3936 (85%)	4242 (91%)	4518 (91%)	4354 (91%)
Number of units cleared (outstanding) after failing dust wipe test	424(6)	666(4)	408(4)	412(10)	426(5)

* Units located in “high risk areas” that pass an interior inspection for deteriorated paint were referred for dust wipe testing.

** Note that units *referred* in one year may not be *tested* until following year

Table 3. Inspections for exterior lead hazards (deteriorated paint or bare soil)	Year 1 7/1/06-6/30/07	Year 2 7/1/07-6/30/08	Year 3 7/1/08-6/30/09	Year 4 7/1/09-6/30/10	Year 5 7/1/10-6/30/11
Buildings inspected for exterior lead hazards	10548	10619	8612	11110	8684
Number (%) of buildings passing exterior lead hazards inspection	8588 (81%)	9391 (88%)	7339 (85%)	9934 (89%)	7339 (85%)

City of Rochester Lead Ordinance Years 1-11 (7/1/06 – 6/30/17)

July 25, 2017

Table 1. Interior inspections for deteriorated paint (visual inspections).	Year 6 7/1/11- 6/30/12	Year 7 7/1/12 – 6/30/13	Year 8 7/1/13 – 6/30/14	Year 9 7/1/14 – 6/30/15	Year 10 7/1/15 – 6/30/16	Year 11 7/1/16 – 6/30/17	TOTAL
Units inspected for deteriorated interior paint	14048	13485	15268	13838	12002	12541	154015
Number (%) units failing deteriorated interior paint inspection	711 (5%)	405 (3%)	235 (2%)	380 (3%)	552 (5%)	732	7469 (5%)
Number (%) units passing interior paint inspection	13337 (92%)	13080 (97%)	15033 (98%)	13458 (97%)	11450 (95%)	11809 (94%)	146546 (95%)

Table 2. Dust wipe tests in units passing visual inspections in the designated high risk area.	Year 6 7/1/11- 6/30/12	Year 7 7/1/12 – 6/30/13	Year 8 7/1/13 – 6/30/14	Year 9 7/1/14 – 6/30/15	Year 10 7/1/15 – 6/30/16	Year 11 7/1/16 – 6/30/17	TOTAL
Units referred for dust wipe test*	3033	2554	2637	2899	3066	3097	42909
Number (%) referred units that received dust wipe test**	3071 (101%)	2061 (81%)	2363 (90%)	2794 (96%)	2620 (86%)	2842 (92%)	37586 (88%)
Number (%) of units passing dust wipe test	2691 (88%)	1834 (89%)	2153 (91%)	2560 (92%)	2388 (91%)	2597 (91%)	33693 (90%)
Number of units cleared (outstanding) after failing dust wipe test	376(4)	220(7)	204(6)	212(22)	214(18)	209(36)	3814(79)

* Units located in “high risk areas” that pass an interior inspection for deteriorated paint were referred for dust wipe testing.

** Note that units *referred* in one year may not be *tested* until following year

Table 3. Inspections for exterior lead hazards (deteriorated paint or bare soil)	Year 6 7/1/11- 6/30/12	Year 7 7/1/12 – 6/30/13	Year 8 7/1/13 – 6/30/14	Year 9 7/1/14 – 6/30/15	Year 10 7/1/15 – 6/30/16	Year 11 7/1/16 – 6/30/17	TOTAL
Buildings inspected for exterior lead hazards	7599	8450	7912	8124	8277	9228	99163
Number (%) of buildings passing exterior lead hazards inspection	6515 (86%)	7409 (88%)	7032 (89%)	7254 (89%)	6963 (84%)	7587 (82%)	85351 (86%)

