

PRESENTATION FOR
Midtown Plaza
Asbestos Abatement Project Update
Rochester, New York

Presented by:



LiRo Engineers, Inc.



Paradigm
Environmental Services, Inc.




December 17, 2009

Agenda

- Abatement Progress Summary
- Progress Photo Review
- Workforce Update
- Regulatory and Air Monitoring Update
- Progress Regarding Future Development
- Site Tour

Progress Summary



Progress Photos



Mall Southwest Work Area West End

Progress Photos



Mall Preparation Work

Progress Photos



Mall Preparation Work

Progress Photos



Mall 1st Floor Hard Wall Construction

Progress Photos



Mall 2nd Floor Hard Wall Construction

Progress Photos



Mall 2nd Floor Removal of Decorative Beams

Progress Photos



McCurdy's 6th Floor Soft Demolition

Progress Photos



Tower 14th Floor Above Ceiling Demolition

Progress Photos



Tower 14th Floor Above Ceiling Demolition

Progress Photos



Tower 11th Floor Decontamination Unit Entrance

Progress Photos



Tower 14th Floor Above Ceiling Demolition

Progress Photos



Tower 13th Floor Under Containment

Progress Photos



Tower 12th Floor Under Containment

Progress Photos



Tower 12th Floor Post Abatement and Clearance

Progress Photos



Tower 14th Floor Post Abatement and Clearance

Progress Photos



McCurdy's 4th Floor Soft Demolition

Progress Photos



McCurdy's 6th Floor Containment

Progress Photos



McCurdy's Mechanical Room Under Containment

Project Monitoring

- Paradigm Oversight Activities
- Air Sampling Results
- DOL/OSHA Compliance

Future Site Development

- Tower Reuse
- PAETEC